Folder No. 1

MISSION MG 8 - PRACTICE MISSION 7 OCT 44

2-5239-91

# TACTICAL MISSION REPORTS

PRACTICE MISSION F.O. \*8

73 NING - 497 + 499 BOMB GPS.

OCT. 7, 1944

CONFIDENTIAL

#### CONSOLIDATED MISSION REPORT

Practice Mission Field Order No. 8

497th & 499th Bombardment Groups

#### 7 October 44

#### Index

- A Summary of Mission
- B Weather Data
- °C Basic Data
- D Enemy Fighter Attacks
- E Bombing Data
- F Group Specialists Reports

CONFIDENTIAL

9,5939-9

CONSOLIDATED MISSION REPORT

Wing: 73d Wing

CONFIDENTIAL

Date: 12 October 1944

Mission No. 8

By:

Date of Mission: 7 October 1944

SUMMARY

NARRATIVE SUMMARY: 497th Group

On 7 October 1944, seven B-29 aircraft, two from the 870th Bomb Squadron and five from the 871st Bomb Squadron, took off without escort from advance base, Walker Army Air Field, at 1236 GCT to attack the bombing range on Cayo Traviesa. Of these, two aircraft returned early as follows:

A/0 #641 (871st) Returned to Walker immediately after take off due to oil leak.

A/C #655 (871st) Landed at Herington at 1510 GCT. Fuel transfer pump inoperative.

The remaining five aircraft attacked the primary target.

There were no personnel casualties nor any aircraft lost, missing or damaged. Opposition from enemy aircraft was light, consisting of several attacks from each of approximately ten P-51's in the vicinity of Tampa, Florida. Attacks were reported to have been poorly coordinated, lack of knowledge of speed of B-29 apparently causing some confusion on the part of the fighters. Gunners indicated that fighters made themselves vulnerable to machine gun fire from B-29s.

Each aircraft was loaded with four 500 pound M43 practice bombs. A total bomb load of 7 x 4 x 500: 14,000 pounds. Of these, 19 bombs (9,500 pounds) were dropped on the primary target. There were no obstructions to visual bombing of the target, visibility being unlimited. The bomb impact pattern was good, with the average mean point of impact at approximately 1,100' circular, 129' over and 1,082' to the right.

All aircraft landed safely at Herington, last aircraft at 0251 GCT, 8 October 1944.

NARRATIVE SUMMARY: 499th Group

Sixteen B-29s (6 - 877th, 5 - 878th and 5 - 879th Squadrons) took off from SHAAF, Salina, Kansas, 1245 to 1301 GCT, 7 October 1944, to attack Cayo Traviesa (21° 58N 81° 50W) in accordance with 73d Wing F.O. 9.

The Section assembled at 4,000 ft. at Neosho (30° 00N 88° 42W) in route formation for the advance to the target. The section formation

consisted of the three-plane lead element and three four-plane "boxes". Col. Samuel R. Harris, Group Commander, and Lt. Col. George A. Shealey, Group S-3, in A/C #4644, accompanied the mission as an observer spare.

The advance to the initial point was made through a front at Little Rock, Arkansas and 8/10 towering cumulus from the Gulf of Mexico to landfall on the northern shore of Cuba. Weather over the target was CAVU. Route back no change.

Five A/C aborted, including the entire lead element and No. 1 and No. 4 planes of the second element. All abortives were due to mechanical failures.

The remaining 11 ships, including the observer spare, continued to the target and dropped 36 - 500 lb. M43 practice bombs on the primary target from 30,000 feet at 1930 to 1941 GCT. The axis of attack was 91° T. Two bombs were dropped on the Secondary Target and two on the Alternate Target. Four bombs hung up in effective A/C and were brought back. Eight bombs were jettisoned and 12 others brought back by non-effective A/C.

Although only 11 A/C bombed the targets and 4 bombs did not release, first phase photo interpretation reveals 45 bombs hit in the Primary Target area. This is due to other planes over the target the same day.

Of the 45 bomb hits plotted by the PI, 7 were from 400 to 1,000 feet from the center of the target, 20 from 1,000 to 2,000 feet, 10 from 2,000 to 3,000 feet and 8 hits had a circular error of more than 3,000 feet.

The mission was intercepted both during the advance to the target and the Withdrawal. Twenty-six fighters made a total of 50 passes at the bombers, including 3 AT-6s, 2 BT-13-As at Independence, Kansas, 9 P-47s at Leesburg, Florida, 6 P-51s and 5 P-47s at Tampa, Florida, and 1 BT-13 at Chanute, Kansas. No attacks were made in the target area.

Attacks were made all around the clock from both high and level. P-51s did not attack. P-47s attacked from 12 to 6 o'clock with a few coordinated beam attacks at 3 and 9 o'clock, making from 4 to 5 passes each, and breaking away from 50 to 300 yards. Trainer fighters, because of their lack of speed were unable to repeat passes. Except for P-47s which used 2 and 3 plane sections in attacks, all other attacks were by single ships without organized plan. Since the B-29 gunners were equipped with live ammunition they tracked fighters in sights only. No gun cameras were installed.

Thirteen A/C including non-effectives returned directly to SHAAF, landing between 2020 GCT, 7 October 1944, and 0331 GCT, 8 October 1944.

One non-effective, A/C #4665, landed at Tulsa, Oklahoma, at 0020 GCT, 8 October 1944, for fuel and repairs before proceeding to SHAAF, landing at 0250 GCT, 8 October 1944.

One effective, A/C #4670, landed on a 3,000 foot runway at Stuttgart,

CONFIDENTIAL

Arkansas, because of engine trouble and proceeded to SHAAF 8 October, landing at 2000 GCT.

Two non-effectives have not returned to this base. A/C #4659 landed at Montgomery, Alabama because of carburetor failure and A/C #4682 landed at Batista Field because of broken fuel transfer lines and No. 2 engine failure.

Practically all of the mechanical failures which caused abortives occurred at 30,000 feet. In general, the effective A/C considered the mission a success. Their chief criticisms were based on the failure to fly the mission according to flight plan. Specifically, the mission was flown in level flight at less speed than briefed and climbs were made too fast.


The aborting of the entire lead element and the No. 1 and No. 4 A/C of the second element was most unusual and scarcely could be reasonably anticipated. It resulted in some confusion as to the ultimate leader, but the fact that the Section proceeded to its objective indicates that considerable initiative and air discipline were exhibited.

A/C #4669, piloted by Major C. E. Anderson, 879th Squadron, originally scheduled as a spare, filled in and led the formation over the target.

COM	CINCILLAL	THIS FORM BE AYAO MAYAR HOR LAND
		VERTICAL CRUCITO
FROM	SOAM SI YE	SOURCE STATE FORECA
NIII EACE		FORECAST RESIDENTE RESIDENTE A SECONDA NO.
MILEAGE		
30,000		
20,000		
4		
10,000		BERNOOM CHANGE CONTRACTOR
Ta'		
30,000 30,000		
30,000		
20,000		
10,000		
SEA LEVEL		
111 111	GREEN LINE - 0° ISOTHERM	GHT TURBULENCE BLUE LINE -COLD FRONT
	PURPLE LINE - DASHED- OPTIMUM FLIGHT ALTITUDE	TIANDE AADAM DIALE DAN DOLLER DINNER OF
* *	The second secon	EAVY TURBULENCE PURPLE LINE-OCCLUDED FRONT
Forecast		The same of the sa
orecast		
Actual 1		Manuage Course Library Lands

THIS FORM BECOMES C-O-N-F-I-D-E-N-T-I-A-L FOR SEVEN DAYS
WHEN CURRENT WEATHER IS ENTERED

VERTICAL CROSS-SECTION






FLAK CLOCK

DOES NOT APPLY

WIND	FROM	TARGET
	MPH	Degree
Date	Computed	From Trading
	ROUT	TES RECOMMENDED
IN		
OTTO		
OUT		

FORMATIONS

Formation Out: 499th Bomb Group.



No other information available. (Corrective action being taken).

497th & 499th Bomb Groups
12 Oct 44

FO No. 8 Mission 7 Oct 44

100

#### Basic Data

- 1. Time of Take-Off:
  - a. 497th Bomb Gp from Walker Army Air Base, first A/C 0737 to last A/C 0754 CWT.
  - b. 499th Bomb Gp from Salina Army Air Base, first A/C 0745 to last A/C 0801 CWT.
- 2. Time of Landing:
  - a. Herington AAB, 497th Bomb Gp 5 A/C landed from 2137 to 2151 CWT.
  - b. Salina AAB, 499th Bomb Gp 11 A/C landed from 1520 to 2231 CWT.
- 3. Squadron Assembly: None. Assembly by Group.
- 4. Group Assembly:
  - a. Tulsa, Oklahoma at 4,000.
  - b. Neosho, Missouri at 4,000.

- 5. Wing Assembly: None
- 6. A/C Returning Early:
  - a. 497th Bomb Group
    - (1) A/C No. 655 return Herington, 1010 CWT, fuel transfer pump out.
    - (2) A/C No. 641 return Walker 0755 CWT, broken oil line.
  - b. 499th Bomb Group
    - (1) A/C No. 682, landed Batista, Cuba, 1445 CWT, two broken fuel lines and No. 2 engine runaway prop.
    - (2) A/C No. 659, landed Maxwell field, 1422 CWT, No. 3 engine feathered, broken carburator diaphragm.
    - (3) A/C No. 650, returned Salina, 1520 CWT, turbos out.
    - (4) A/C No. 665, landed Tulsa, fuel transfer out.
    - (5) A/C No. 658, landed Stuttgart, Ark, Nos 1 and 4 prop governors out.

CONFIDENTIAL

C

	型 · 型 · 型 · 型 · 型 · 型 · 型 · 型 · 型 · 型 ·		
FROM  36°10N - 96°-00'  32°25N - 90°-00'  27°00N - 85°-50'  23°30N - 85°-30'	TIME 1400 1600 1800 2000	IAS 203 200 195 190	ALT 4000 5000 20,000 30,000
499th Bomb Gp.			
37°-00 - 94°-37 W 32°-17 - 90°-25 W 27°-03 - 86°-20 W 23°-14 - 82°-16 W	1400 1600 1800 2000	202 190 187 189	4372 4000 19,478 26,444
8. Route Back:			
497th Bomb Gp.			
29°-30N - 84°-30 W 33°-42N - 90°010 W 37°-35N - 95°-00 W	2200 2400 0200	190 190 198	15,000 10,000 6,500
499th Bomb Gp			
30°-27N - 84 - 19W 34°-15N - 90°- 05W 37°-40N - 95°- 28W	2200 2400 0200	196 194 194	18,288 9,988 6,699
9. 497th Bomb Gp.	PLACE	TIME	ALT
I. P.	21°-54 - 82°-40W	1929	29,000
499th Bomb Gp.			
I. P.	21°-48 - 81°52W	1929	28,900

#### 10. Targets Attack Data:

- a. A/C attacking targets

  - (1) Primary: 16 A/C (20) Secondary: 2 A/C (3) Last Resort: 1 A/C
- b. Times over target:

  - (1) 1434 1445 (2) 1450 1500 (3) 1517 1520
- c. Heading and altitude from IP to Target: 91° at 30,000.
- d. Heading and altitude over Target: Same
- e. Breakaway: None
- f. Rally Point: None CONFIDENTIAL

- g. Extra Runs: None
- h. Reasons for Failure to Attack: None
- 11. Escort Data: None

497th & 499th Bomb Groups
12 Oct 44
A-3

FO No. 8 Mission 7 Oct 44

Loss & Damage

- 12. Casualties Personnel: None.
- 13. A/C Lost: None.
- 14. A/C Missing: None.
- 15. Total A/C Failing to Return: None.
- 16. Damage to A/C: None.

### CONSTITUTED FINETOWREPC

Group or Wing

Date

AA & AIR TO AIR BOMBING

F.O. No.

Mission No.

Date of Mission

17. Enemy A. A. Fire:

Nil

18. Our Tactics VS A.A.:

Nil

19. Air to Air Bombing and Rockets:

Nil

CONFIDENTIAL CONSOLIDATED MISSION REPORT P.O. No. Group or Wing Mission No. Date COMBAT DATA Date of Mission By 20. Analysis of attacks by enemy A/C Totals Legend Attacks Attacks Level Level From Above 14 From Above - - -From Below ----From Below Enemy Aircraft Low E/A Destroyed Destroyed E/A Probably Probably Destroyed Desroyed E/A Damaged Damaged Note: If any attacks made Number by 2-engine fighters, mark Claimed Where possible show O on outside of line. Each time of attack and mark to represent one attype A/C attacking tack unless specified to contrary. 21. Yards at which E/A opened fire(correlate this with direction of attack in comment) Yards No. A/C Firing Comments 22. Types of enemy A/C attacking (Names & numbers) 497th BG - 10 P-51 1 BT-13 2 P-47 6 P-51 499th BG - 3 AT6 499th BG - 3 AT6

2 P-47

3 P-47

23. Type and accuracy enemy fire & type Projectile: (Range to which E/A pressed home attack) 24. Enemy A/C markings: U.S.

### CONSOLIDATED MISSION REPORT

Group or Wing

Date

COMBAT DATA (continued)

F.O. No.

Mission No.

Date of Mission

25. Enemy Tactics: 3 AT-6 and 2 BT-13A single attack from 8-10-2-4 o'clock - both high and level positions breakaway at 300 yds.

Attackers too slow for repeat attacks.

-2 P-47 attacked from 12 o'clock high - Broke away

at 400 yds to 6 & 9 o'clock

2 P-47 attacked from 3 & 9 o'clock - Broke away at

20 ft.

6 P-51 did not attack

3 P-47 pursuit curves. 3 & 9 o'clock - Both sides

at once - Broke away at 50 yds. made 5 passes each.

1 BT-13 attacked from 1 & 6 o'clock - Made one

double pass

attacks varied back to 6 o'clock each ship made at least 4 passes

10 P-51 attacked in pairs, from high at eight and
nine and out and down between three and five, using pursuit curve,

nine and out and down between three and five, using pursuit curve, pressing attack to 350 yds. Pairs were widely separated and in some cases developed into single attacks. Attacks poorly coordinated and A/C apparently misjudged speed of B-29 (190 IAS at 20,000), however P-51's had no difficulty in making three to four attacks each.

26. Enemy Formations: organized plan

3 AT-6 and 2 BT-13A single ships attacking without

2 P-47 Single ship

2 P-47 Single ship

6 P-51 3 two plane formations

3 P-47 3 plane formation

1 BT-13 Single plane

6 P-47 Pairs in trail

10 P-51 Approached in elements of two; attacked in elements of two or singly and broke away singly.

27. Our Tactics and Firepower VS Enemy A/C: Held formation and trailed in sights and no evasive action taken.

28. Results of Hits on E/A:

Nil

28a. Claims by A/C and by Gun Position:

Nil

### CONFIDENTIAL REPORT

Group or Wing

Date

OBSERVATIONS & CREW COMMENTS

F.O. No.

Mission No.

Date of Mission

29. Expenditure of Ammunition: 499th BG - Total Rds Loaded - .50 Cal 16,000 - 20 mm 1,040 - Fired - 50 Cal 8,880, 20 mm 440. 497th BG-Total Rds Loaded - .50 Cal 7,000 - 20mm 300 - Fired .50, 4,685- 20mm 101. 30. Our Observed Losses by E/A: Nil

31. Our Observed Losses by A/A: Nil

499th Bomb Group 32. Observations:

Navy Blimp escorted 2 - 1 stack cargo ships 1100T 5 BTs	1525	10 mi SE Key West 25 mi NW Neos-	B-29 - 29,000
1 B-17 4 B-29s Convoy 15 ships	1650 1510 1648	34°20N 90°12W	3100 3100 3100
15 coastal freighters (small cargo 90°T	1230	coast. 28°30N 87°40W	16000
15 BT 13 (In training maneuvers)	0837	10 mi West of	
14 AT 6s (In training maneuvers) Barge: B-25 5 B-17s 40 single engine planes on ground 3 Freighters 2700m 5 K	0850 1700 1400 2040 1540 1530	Coffeyville, Ks 30 mi NW Neosho Off Gulf Coast Near Neosho Hendricks Fld. Key West Halfway fr Keys	4000 4000 4000 23,000 29,000
1 Tug and 5 Double Barges 280°T 3K 1 B-29 taking off 360°T 6 P-47s 5 PT-19s circling pattern 50 A/C 14 Fighters, others	1222 1820 1625 1016	to Cuba Off coast Maxwell Fld. Leesburg Pine Bluff Lauvel AAF	29,000 8000 20000 4600 4600
unidentified. Freighter 6000 ton 230°T 12K Merchant Liner 314°T Freighter 8M ton 330°T 18K Freighter 5M ton 200°T 10K Tug pulling barge Freighter 5M ton 090°T 10K 2 small boats 35°T 7K 4 Patrol Boats 2 small boats	1225 1700 1750 1242 1407 1522 1527 1633	Gulf Gulf (28°20N 87°25W) 23°39N 83°49W 24°10N 81°40W 24°10N 81°40W 24°28N 81°40W 24°28N 81°40W 27°40N 83°10W	13000 6000 4800 20000 30000 20000 20000 17500
2 PBYs Ground CONFIDE	1755	Pensacola	12000

### CONSOLIDATED MISSION REPORT

#### OBSERVATION & CREW COMMENTS

32. Observations: 497th Bomb Group

3	PBYs at 4,000' H40° Liberty Ship H250°	1200	30°30N 80°10W 28°27N 86°56W	10,000
	Unidentified cessels	1235	28020N 86050W	15,000
	probably tankers on			
	surface H 33008Kts			
1	Tanker H 280 5Kts.	1245	27°41N 86°18W	15,000
	on surface			

- 33. Comments on Maps, Charts, and Photos Used: Nil
- 34. Crew Suggestions: 497th Bomb Group and 499th Bomb Group.
  - 1. Mild evasive action would have confused fighters
  - 2. Formations: Too slow on level flight too fast climb to 30,000 feet Wing elements do not hold position in bad weather. 50 miles difference in air speeds Speed not less than 190 air speed Formation flown too slow Plan sound but did'nt work on this mission were pulling rated power at 30,000 feet altitudes too variable in penetrating fronts- speed to slow
- 35. Functioning of Oxygen Systems: Normal
- 36. Functioning of Clothing Personal Equipment: Norman
- 37. Cameras: None
- 38. Technical Failures: 497th Bomb Group

#### A/C #425 -

- 1. Defrosting system inoperative
- 2. Fuel guage out

- 3. Fuel shut off valve out and could not transfer fuel from top bomb bay.
- 4. Upper forward turret gun charger or air compressor failed to work
- 5. Jam in lower forward turret and left gun in lower aft
- turret 6. Only two guns in forward turret could fire

### CONSOLIDATED MISSION REPORT

#### OBSERVATION & CREW COMMENTS

#### 38. (continued)

#### A/C #431 -

1. No. 1 cyli nder head temperature guage out

2. Engineers R/C guage out

3. No. 2 carburetor temperature guage out

4. No. 2 oil pressure low

5. CP gyro inoperative

6. Gun charger on upper turret inoperative

7. Right landing light did not retract

8. Liaison dynamo out 9. Blister dynamo out

10. CFC did not work

#### A/C #413 -

- 1. Upper aft, lower aft, and tail guns did not fire
- 2. No. 2 prop ran up to 2600 rpm's

#### A/C #627 -

1. Bomb bay doors had to be closed by emergency system

#### A/C #628 -

- 1. Bomb rack malfunction
- 2. Tail gun jammed
- 3. Navigator could not fire upper forward turret
- 4. SCR 718 working part time only

Communications - Walker command station poor. Static interfered.

Radar - Inoperative at high altitude over target area in A/C #413. Low sensitivity on A/C #628, all others satisfactory

Central Fire Control - No Comments

Essential Elements of Information - Impossible to contact Radio Buoy.

Only two A/C were able to receive MO's

CONSOLIDATED MISSION REP

OBSERVATIONS & CREW COMMENTS

### CONFIDENTIAL

#### 38. (Continued)

#### 499th Bomb Group:

1. A/C #674 radio interphone out - Bomb rack malfunction

2. A/C #651 Intervelometer malfunction

3. A/C #665 Turbo supercharger going on & off

4. A/C #658 prop congealed oil causing fluctuation of props. fuel transfer system is too indefinite

5. A/C #666 Dynamotor burned out on ATC radio set & radar went out near coast.

6. A/C #650 Inverters failed. Two sets of inverter relays should be installed

7. A/C #679 Upper turret failed to fire reason unknown

Communications - AFCE aileron control became ineffective when bombaedier switched into command set-receiver becomes ineffective in other positions- A/C #677 Interference from WX A/C #674

Radar - Non-operative (blown fuze) #658; cut out at 25,000 #661; out on #666; RFC would'nt lock transmitter #647; Radar inoperative - altimeter went out could not differenceate land & water #683; Indicator jambed #650; Unsatisfactory #674; Alt. inverter & brushes out #651; Pressurizeing App. out #644; out at 30000 OK at 25000 #665.

Central Fire Control - Malfunction tail gun plane #661
Only operated partially #658
Ejection jaw of left gun in #5 turret failed on plane #665
Frozen guns - jam in 20 mm tail cannon in plane #651

COMFIDENTIAL

- 4 -

GROUP 499 DATE 12 OCT 44 E. A. POWELL

CONSOLIDATED MISSION REPORT

BOMBING DATA

### CONFIDENTIAL

MISSION BATISTA DATE 7 OCT 山山

Second

Second

Second

I

IIAB

39 BOMB DATA (NO & TYPE BY A/C)							40 TARGET ATTACK DATA										
A/C NO.	SQ NO.	NO.	BOMB LOAFUZI SIZE		TICE	NO. BOMBS TARGET		NO BOMBS BROUGHT BACK	TIME	ALTITUDE	HEADING T	IAS	WIND	BOMB	LENGTH OF RUN	SIGHTING	RELEASE
4674	NO	4	500	NO	M101A2	4 Cayo Traviesa		RE	1440	27400	910	170	Z	2	2	Primary	2
4683	P	4	500	刊	M101A2	11		TUR	1439	30000	900	195	F	B	T	Second	R
1677	VA	4	500	2万	MIO1A2	11		NE	1441	29000	880	185	LVA VA	NA NA	100	Primary	N
1647	ILA	4	500		MIOLA2	11		16	1436	30700	91°	195	TI.	I	TI	Second	I
1644	BLE	2	500		M101A2	11			1438	30000	920	195	BLI	BL	BI	Primary	BI
661	1	4	500		MIOLA2	11			1445	28800	91°	195	F)			Primary	<u> </u>
.669		4	500		M101A2	1 Cayo Traviesa 1 Peninsula Dezapata 2 Man Key			1440	31750 31730 30700	350° 360°					Second Primary Primary	
666	and the second second	4	500		MlOlA2	4 Cayo Traviesa			1431	30100	900	185				Second	
651		2	500		MlOlA2	1 Cavo Traviesa 1 Peninsula Dezapata			1500	29300	2700	175				Primary Primary	
667		4	500		M101A2	4 Cayo Traviesa			1439	31800	910	195				Second	
670		4	500		MIOLA2	11			1441	31870	910	180				Primary	
OTAL		40	20000					16									
								497TH B	OMBARDM	ENT GROUP							
27	TON	4	500	S	MIOIAZ	4 Cayo Traviesa	H	RE	1438	31900	900	195	3	NOS	NO	Primary	S
25	7	4	500	1	MIOIAZ	11	TT	DI	1438	32000	900	195		7		Second	F

1438 32100

1438 32700

0 9

M101A2 3 Cayo Traviesa

M101A2 4 Cayo Traviesa

MIOLAZ

500

500

B 4 500 B 19 9500

431

413

900

900

195

195

W

H

497 & 499 Gp 12 Oct 1944 E A POWELL


FO 8 & 9
BATISTA
7 Oct 1944

- 41. 5/10 coverage unrestricted visibility.
- 42. Not available.
- 43. Not available.
- 44. Fair.
- 45. Not available.
- 46. None.
- 47. None available.

CONFIDENTIAL

\_\_\_\_\_

## CONSCIDATED MISSION REPORT BOMB IMPACT DATA




(4) SUMMARY OF BOMB DAMAGES:

OBSERVED RESULTS (FIRES, VOLUME OF SMOKE COLOR OF SMOKE HEIGHT OF SMOKE COLUMN WHEN LAST SEEN, ETC.)

NONE

### CONSCLIDATED ENTSSION REPORT



#### (4) SUMMARY OF BOMB DAMAGE:

OBSERVED RESULTS (FIRES, VOLUME OF SMOKE, COLOR OF SMOKE, HEIGHT OF SMOKE COLUMN WHEN LAST SEEN, ETC.)

P.I. DAMAGE ASSESSMENT EVALUATION

7 BOMBS - 15. 5% WITHIN 1000' OF AIMING PT. 27 BOMBS - 60 % WITHIN 2000' OF AIMING PT. 37 BOMBS - 82 % WITHIN 3000' OF AIMING PT.

8 BOMBS - 18 % OF TOTAL MORE THAN 3000 FROM AIMING PT. 45 BOMB IMPACTS SHOWN ON STRIKE PHOTOGRAPHS....

Prepared BY P.I. FROM PHOTOGRAPHS..........

#### GROUP BOMBARDIER'S REPORT

- 1. 16 A/C bombed Cayo Traviesa 2 A/C bombed Peninsula Dezapata 1 A/C bombed Man Key
- 2. Visual bombing was accomplished.
- 3. Bombing was done according to plan.
- 4. Target was obscured for 2 planes bombed secondary target.
- 5. Sources of error are not available.
- 6. Results were Fair to Good.
- 7. 5/10 cloud cover unrestricted visibility.
- 8. No reason for failure to bomb.
- 9. No bombing equipment failure.
- 10. Arming wires returned. Not available.

#### GROUP NAVIGATOR'S REPORT

Nothing available at this time.

#### GUNNERY

Report on 499th Bombardment Group.

- 1. b. (1) 19 Aircraft on mission.
  (2) Guns loaded cold.
  (3) Only equipment failure d Only equipment failure due to faulty switch procedure and improper interphone procedure - Gun failures due to improper preflight. Excess oil should never have been on guns. Improper headspacing seems to have occured frequently.
  - (4) Recommend stress be put on gunners preflight and on interphone commands, there is no reason for guns freezing or having faulty ammunition if the gunner will preflight properly.
  - (5) As far as gunnery is concerned it is felt some good lessons were learned due to poor preparation for the mission by the gunners themselves. It is a good thing it was only a Batista mission as far as gunnery is concerned.

CONFIDENTIAL

#### GUNNERY

Report on 497th Bombardment Group.

1. b. (1) 5 aircraft on mission. (2) Guns loaded cold.

- (3) Equipment failure as a whole due to charger trouble, this seems to point to faulty maintenance. As the 499th Group had no charger failures. Improper headspacing probably caused many failures.
- (4) Recommend armament sections take more care in charger installations and headspace adjustments and that gunners be more careful on preflight checks.
- (5) Gunnery mission no good except for lessons learned due to failures.

- 56. Engineering Officer and Flight Engineer's Report.
  Report covers data on 497th Group only. Data on 499th not available. Corrective action is being taken.
  - A. Aircraft Malfunctions:
    - 1. Aircraft failing to take off:
      - a. A/C No. 426: No 1 tachometar out and No 4 booster pump inoperative.
      - b. A/C No 626: Flat tire found at pre-flight. Recommended action thorough pre-flight by ground crew several hours before mission.
      - c. A/C No 412: No 2 tachometer out due to insufficient slack in leads.
    - 2. Aircraft failing to attack target:
      - a. A/C No 641: Severe oil leak No 1 nacelle appeared to come from oil cooler. Investigation indicated oil tank filled too full causing leak from expansion. Recommended action more thorough pre-flight by both combat and ground crew.
      - b. A/C No 655: Transfer system failed. Preliminary investigation indicated transfer pumps damaged by residue in lines from previous pump failure. Recommended action thorough flushing of all transfer lines after fuel transfer pump failure. Possible installation of screens at pump ports.
  - B. Battle Damage: None.

- C. Analysis of Cruise Control:
  - 1. No ships failed to return due to lack of fuel.
  - 2. Data on A/C completing mission:

anning the state of the state o			NAME AND ADDRESS OF THE OWNER, WHEN THE OWNER,	nation		Potal for				
A/C	Fuel	Posi	tion	Flying	Distance	Fuel	Total	Tot Dist	Tot Fuel	Fuel
No.	Aboard	Fl	No	Time	Air Mi		Time	Air Mi	Used	Remain'g
4627	7975	1	1	8:50	2230	5061	14:30	3500	6865	1110
3425	8070	1	2	8:45	2235	4070	14:00	3365	6736	1334
4628	8070	1	3	7:20	2400	4236	13:50	3475	6900	1170
3431	8065	2	4	8:45	2228		14:10	3464	6805	1260
3413	8070	2	5	8:47	2200		14:05	3340	698.5	1085

- 3. Above data indicates that cruise control was carried out satisfactorily.
- D. Functioning of Intercommunication system: Satisfactory.

#### COMMUNICATIONS

COMMAND RADIO: VHF radio transmission was very satisfactory.

LIAISON RADIO: Contact with ground stations was difficult due to high atmospheric disturbances. Position reports were forwarded through Galveston for relay by teletype by some radio operators. Severe arcing of knife switch reported due to icing of antenna. Following is summary of messages:

STRIKE REPORTS: Strike message was transmitted on 15515 kc.

Not received by ground station due to disturbances. The lead

A/C of one unit failed to transmit strike message due to 6 B-29

A/C preceding them over target. Later learned six lead A/C be
longed to another organization on separate mission.

RADIO BEACON: Signals transmitted were not received by any A/C due to disturbances. One operator in A/C which had left formation reported reception of beacon signals GP instead of Y.

MISCELLANEOUS REMARKS: Radio operators fail to listen in prior to transmitting. Incomplete logs were turned in.

CONFIDENTIAL



