

Top Timbers 62 7
Deck (No 23 Average) 47 1/2 0 0 0 0 13 0 0 13

Wales ... 22.6... 42x 4 1/2 43x 4 1/2

Hold Be
Deck Be
Ceiling 't
Hold Be
Deck Be

Extract from Mr. Alexander's letter
Dated 3rd March 1863.

With reference to the query about the imperfections observed in the frames of the King's van hoe, the screws which were buckled ~~were~~ opened were cramped together church bolts put in to secure the parts where objected to - On receiving your letter of the 24th ultimo, I called Sup^r Ball's attention to the subject, and requested them to state what had been done with a view to show the propriety of care in similar cases.

Ex^h Sell off



© 2019

Lloyd's Register
Foundation

DUMOS-0223

Treena
bolts in
bolts in
in Flat
... Incl
in the T
La
scribed
and
N
ng at

The Frame is cross chocked with iron Butt at each end of the chock.

The Main piece of Rudder is

The Main Keelson is Red Pine

and — free from all defects.

The Main piece of Wind