


Area Remaining to be Filled



Spillway  
Barricade  
end of concrete wall  
Sheet piles  
Round piles  
Rip-Rap  
1+00  
Site of old break (lost 1912)  
shipped in, mud filling and  
break wall  
Veil moved out showing fracture  
Exposing reinforcing  
Round piles  
Sheet piling  
3+00  
Veil moved out at  
fracture joint  
4+00  
Rip-Rap  
5+00  
Sink holes 3' dia. 3' deep  
6+00  
Round piles  
Veil moved out, joint  
fractured, reinforcing  
exposed  
Rip-Rap  
Break in wall  
8+00  
Rip-Rap  
Break in wall  
9+00  
Break in wall  
10+00  
Sand Bank  
11+00  
Break in wall  
12+00  
13+00  
14+00  
Sand Bank  
15+00  
Break in wall  
16+00  
Break in wall  
17+00  
18+00  
Break in wall  
19+00

0.0 holes  
Washout  
Holes filled with  
brush and dry  
material  
Average Ele. 8.5  
5.00  
Holes being filled with  
brush and dry material

Fill being driven  
these installed  
Piles filled with brush  
and dry material

Colling Ave - Sewer