DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

GHQ/SCAP Records (RG 331, National Archives and Records Service)

Description of contents

(1) Box no. 2932

(2) Folder title/number: (26)
Nihon Jukagaku Kogyo K.K.

(3) Date: Jan. 1947

(4) Subject:

Classification	Type of record
9230, 9621	c, k

(5) Item description and comment:
i) Amagasaki, Hyogo
ii) Contagious Disease Horse Sheds Himeji Division?

(6) Reproduction: (Yes) No

(7) Film no. Sheet no.

(Compiled by *National Diet Library*)

化学

研究

研究

答問

工場主出

Nihon Jukagaku

四通

一通貸下

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

日本重化学
高田 理
藤井 理
尼塚令同

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179018

A WRITTEN OPINION

1. Chlor-Sulphuric Acid Factory was sold to Takeda Yakuhin Kogyo Co. Ltd. and Tannic Composition was sold to Tekkosha of Yamagata Prefecture, before these equipments were designated as Reparation Plants.
Permit to remove them is at present being filed with the Hyogo Military Government Company.

2. The Office room are now being used for the Reparation Offices.

3. Electric Motor, Oilswitch are parts of Sulphuric Acid equipments. If thse are taken the function of the designated suphuric acid equipments would be destroyed.

4. Based upon the above ressons, we beg for your consideration.

Kankichi Kitamura
Directing Manager.

Nihon Jukagaku Kogyo Col, Ltd.
No. 14 Minamihatsusima, Amagasaki
City. Hyogo-ken

MGP 37

REPARATIONS PLANTS MATERIALS

賠償工場ノ資材

PAGE 1 OF 3 PAGES
頁中ノ第 頁

DATE: January 15 1947
日附

NAME OF PLANT, LABORATORY, OR ARSENAL:
工場, 研究所又ハ兵器廠ノ名稱 Nihon Jukagakee Kogyo Co., Ltd.

General Contractors Association of Hyogo Prefecture Branch - CONTRACTOR CO., Ltd. T. Takaoka.

LOCATION:
所在地 No. 14, Minamihatsushima-cyo, Amagasaki, Hyogoken

SIGNATURE OF OWNER OR CUSTODIAN:
所有者又ハ管理人ノ署名 Kankichi Kitamura

** SIGNATURE OF LOCAL JAPANESE LIAISON OFFICER:
當該地區日本連絡官ノ署名 Y. Asai

MATERIAL STOCKS (NOT INSTALLED) 在庫資材表 (施設ニ含マレザルモノ)

ITEM DESCRIPTION 品目名稱	UNIT 單位	QUANTITY 數量	TOTAL ESTIMATED WEIGHT 見積總重量	NUMBER OF CARLOADS 積込貨車數	CONDITION *** 狀態	REMARKS 摘要

* *Owner or custodian to attach statement if he desires.*
所有者又ハ管理人ハ必要ニ應ジ說明書ヲ添附ノコト.

** *Prefectural Japanese Liaison Officer to attach statement if he desires.*
當該地區連絡官ハ必要ニ應ジ說明書ヲ添附ノコト.

*** *Describe as New, Good, or Poor. "Good" will indicate "suitable for general use." "Poor" will indicate "not suitable for reuse."*
狀態欄ニハ新品, 良品, 不良品ト記載ノコト. 良品ハ一般使用ニ適スルモノ. 不良品ハ再使用ニ適サザルモノヲ示ス.

Eighth Army Printing Plant-Buonpoda
2798

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

INSTALLED MATERIALS AND SUPPLIES 施設済ノ資材

ITEM DESCRIPTION	UNIT	QUANTITY	TOTAL ESTIMATED WEIGHT	NUMBER OF CARLOADS	REMARKS
	単位	数量	概算重量	入貨車数	
3 phase 2nduction motor (Cage rotor Type) (220V. 1140 r.p.m)	5HP	2	130 L.B.S x 2	Good	need small Repair maker Shibaura E.W.
3 P. Gas proof Hand operating oil switch	220V 50A	4	120 L.B.S x 4	Good	maker Hirai E.W
3 phase 2nduction motor (Cage rotor Type)	1HP	1	100 L.B.S	Good	need small Repair maker Shibaura E.W
3 P. Gas proof Hand operating oil switch	220V 20A	1	60 L.B.S	Good	maker Hirai E.W
3phase 2nduction motor (cage rotor Type) (220V. 1140 r.p.m)	1/2HP	2	300 L.B.S x 2	poor	need large repair maker Shibaura E.W

地方府縣米軍軍政府係官專用欄 FOR USE BY PREFECTURAL MILITARY GOVERNMENT TEAM ONLY. STRIKE OUT WORDS NOT APPLICABLE AND FILL IN BLANK SPACES.

IS (NOT) AN ENEMY SURRENDERED FACILITY
IS (NOT) A REPARATION FACILITY.
IS (NOT) PRODUCING FOR OCCUPATION FORCES.
IF SO, GIVE PROCUREMENT DEMAND NUMBERS OR DATA REGARDING ORDERS FOR DEPENDENT HOUSING:

HAS (NOT) BEEN TURNED BACK TO HOME MINISTRY
IS (NOT) OPERATING.
ANY OBJECTION TO REMOVAL OF ABOVE ITEMS:

CORRESPONDENCE OR ACTION IS (NOT) PENDING TO REMOVE PLANT FROM REPARATIONS LIST.
CORRESPONDENCE OR ACTION IS (NOT) PENDING FOR (REOPENING) (CLOSING) THE PLANT.
STATEMENT AS TO WHETHER MACHINERY OR EQUIPMENT IN PLANT WILL BE JEOPARDIZED BY REMOVAL OF ABOVE ITEM:

PLANT NO.: _____ SERIAL NO. OF FORM: _____ DATE: _____ MIL GOVT OFFICER: _____ PREFECTURE: _____

RESTRICTED E.O. 12065 SECTION 3-402/NNDG NO.

Séinsetée Tannin Plant
part of timber

thickness	with	length	Spaken	
0.25	0.5	9.6	"	50
0.25	0.5	2.5	"	56
0.5	0.5	9.6	"	11
0.8	0.8	8.2	"	16
0.8	0.8	9.0	"	4
0.6	0.8	5.0	"	21
0.5	0.5	10.0	"	16
0.25	0.5	18.0	"	40
0.25	0.5	8.0	"	134
0.5	0.5	20.0	"	10
0.25	0.5	10.0	"	12
0.6	0.6	16.0	"	8
0.5	0.7	25.0	"	8
0.5	07	12.0	"	8
0.5	0.7	10.0	"	8
0.5	0.5	14.0	"	16
0.6	0.6	16.0	"	8
0.25	0.5	5.0	"	28
0.25	0.5	3.0	"	14
0.25	0.5	16.0	"	24
		7.0	"	32

Reparation Plants with out indicate

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

0.5	0.7	12.0	"	8
0.5	0.7	10.0	"	8
0.5	0.5	14.0	"	16
0.6	0.6	16.0	"	8
0.25	0.5	5.0	"	28
0.25	0.5	3.0	"	14
0.25	0.5	16.0	"	24
0.5	0.5	7.0	"	32
0.5	0.5	8.0	"	28
0.5	0.5	10.0	"	24
0.6	0.6	8.0	"	8
0.5	0.5	5.0	"	16
0.5	0.5	6.0	"	8
0.4	0.4	7.0	"	8
0.25	0.5	12.0	"	14
0.25	0.5	4.0	"	11
0.25	0.5	48.0	"	8
0.25	0.5	60.0	"	2
Round timber				
Top end	0.5	28.0	"	32
"	0.6	10.0	"	2
"	0.6	18.0	"	32
"	0.6	7.0	"	8
"	0.5	34.0	"	8
"	0.5	16.0	"	116
Total timber	thick		Kokra	257

0.25	0.5	5.0	"	28		
0.25	0.5	3.0	"	14		
0.25	0.5	16.0	"	24		
0.5	0.5	7.0	"	32		
0.5	0.5	8.0	"	28		
0.5	0.5	10.0	"	24		
0.6	0.6	8.0	"	8		
0.5	0.5	5.0	"	16		
0.5	0.5	6.0	"	8		
0.4	0.4	7.0	"	8		
0.25	0.5	12.0	"	14		
0.25	0.5	4.0	"	11		
0.25	0.5	45.0	"	8		
0.25	0.5	60.0	"	2		
Round timber						
Top end	0.5	28.0	"	32		
"	0.6	10.0	"	2		
"	0.6	18.0	"	32		
"	0.6	7.0	"	8		
"	0.5	34.0	"	8		
"	0.5	16.0	"	116		
Total timber	thick		Koku	257		5
Board	0.05		tubo	240		
Slate			"	150	6425 kg	1

Reparation Plants without indicate

Seinsetic Tannin Plant

Steel Skeleton construction

Part of steel

unit	m.m.	Maker	
L	100 × 100 × 13 × 1,650	"	62
L	100 × 100 × 13 × 4,800	"	12
L	65 × 65 × 8 × 2,150	"	21
L	65 × 65 × 8 × 800	"	12
L	100 × 100 × 13 × 800	"	4
L	100 × 100 × 13 × 4,600	"	8
L	100 × 100 × 13 × 6,000	"	8
L	100 × 100 × 13 × 1,700	"	56
L	65 × 65 × 8 × 2,400		45
L	65 × 65 × 8 × 700	"	2
L	100 × 100 × 13 × 3,600		16
L	100 × 100 × 13 × 6,400	"	14
L	100 × 100 × 13 × 4,000		14
L	100 × 100 × 13 × 1,200	"	24
L	100 × 100 × 13 × 450		15
L	65 × 65 × 8 × 450	"	5
L	100 × 100 × 13 × 1,150		78
L	65 × 65 × 8 × 2,000	"	18
L	50 × 50 × 6 × 2,400		2
L	50 × 50 × 6 × 2,000		19

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDX NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

L	100 × 100 × 13 × 1,200		24			
L	100 × 100 × 13 × 450		15			
L	65 × 65 × 8 × 450	"	5			
L	100 × 100 × 13 × 1,150		78			
L	65 × 65 × 8 × 2,000	"	18			
L	50 × 50 × 6 × 2,400		2			
L	50 × 50 × 6 × 2,000		19			
L	50 × 50 × 6 × 1,600		16			
L	50 × 50 × 6 × 2,300	"	4			
L	65 × 65 × 8 × 700	"	12			
Total				14 Ton	2	
Foring thickness	Room with	Part of timber length	Syaku			Reparation Plants without indicate
0.4	0.4	15.00	"	12		
0.4	0.4	10.0	"	3		
0.18	0.18	10.0	"	12		
0.6	0.4	20.0	"	4		
0.4	0.6	6.0	"	2		
0.35	0.35	10.0	"	44		
0.35	0.35	6.0	"	11		
0.4	0.6	24.0	"	6		
0.4	0.6	12.0	"	12		
0.4	0.4	5.0	"	18		
0.35	0.15	7.0	"	26		
Total timber			Koku	24		
Slate			tubo	37	1,830 kg	

摘 要

Chlor Sulphonic acid Plant

Part of timber

Reparation Plants without indicate

thickness	with	length	System			
0.5	0.5	9.0	"	15		
0.5	0.5	18.0	"	14		
0.5	0.5	10.0	"	23		
0.4	0.4	10.0	"	19		
0.4	0.2	13.0	"	17		
0.5	0.5	13.0	"	14		
0.5	0.6	12.0	"	6		
0.35	0.15	6.0	"	95		
0.4	0.5	12.0	"	6		
0.4	0.4	12.0	"	85		
0.4	0.6	23.0	"	20		
0.4	0.6	20.0	"	20		
0.4	0.4	8.0	"	10		
0.4	0.4	6.0	"	36		
0.2	0.4	6.0	"	36		
0.2	0.4	7.0	"	24		
0.4	0.6	16.0	"	2		
Board	0.05		Tubo	85		
Total timber			Kaku	91	4,137.5 kg	2
Plate			"	115	5,700 kg	1

Reparation Plants without

DECLASSIFIED E.O. 12065 SECTION 3-402/NND NO.

0.4	0.6	20.0	"	20		
0.4	0.4	10.0	"	10		
0.4	0.4	6.0	"	36		
0.2	0.4	6.0	"	36		
0.2	0.4	7.0	"	24		
0.4	0.6	16.0	"	2		
Board	0.05		tubo	88		
Total timber			Koku	91	1,137.5 kg	2
Plate			"	118	5,700 kg	1

Reparation Plants without indicate

Work mans office

part of timber

thickness	with	length	Syoku			
0.35	0.35	10.0	"	73		
0.5	0.35	10.0	"	11		
0.5	0.35	12.0	"	4		
0.4	0.5	20.0	"	6		
0.4	0.4	7.0	"	12		
0.35	0.35	12.0	"	19		
0.15	0.15	10.0	"	15		
Board 0.1	0.5		Tubo	13.5		
Total timber			Koku	28	350 kg	1
Plate			Tubo	29.0	1,435.5 kg	
Horizontally sliding window				20		
6×6						

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDC NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

A WRITTEN OPINION

1. Electric Sub station, Converting Room, Sulphuric Acid Room, Sulphuric Tower are designated as Reparation Plants. If the iron frames, lumbers, slates are taken sway, the designated equipments would rust by rain and fall into unrepairable condition.

2. Five parsons are now livingin the arehouse. If this Building is taken over, a new building must be built for these persos.

3. Electric Motor, Oilswitch are parts of Sulphuric Acid equipment, If thes are taken the function of the designated Sulphuric Acid equipments would be destroyed.

4. If the Building of the Filtning Room is takem, the equipment would be destroyed.

5. Based upon the above ressons, we beg for yourvconsideration.

Kanichi Kitamura

Directing Manager
Nihon Jukagaku Kogyo Co., Ltd.
No.14 Minamihatsushima, Amagasaki
City, Hyogo Prefecture.

MGP 37

REPARATIONS PLANTS MATERIALS

PAGE 2 OF 3 PAGES
頁中ノ第 頁

NAME OF PLANT, LABORATORY, OR ARSENAL:
工場, 研究所又ハ兵器廠ノ名稱 Nihon Jukagaku Kogyo Co., Ltd. 賠償工場ノ資材

DATE:
日附 15 January 1947

LOCATION:
所在地 No. 14 Minamihatsushima, Amagasaki City.

CONTRACTOR'S REPRESENTATIVE:
General Contractors Association of Japan, Hyogo Prefecture Branch
SIIGUMI T. Hanba
Y. Asai

SIGNATURE OF OWNER OR CUSTODIAN: Hyogo-ken
所有者又ハ管理人ノ署名

當該地區日本連絡官ノ署名

Kankichi Kitamura

MATERIAL STOCKS (NOT INSTALLED) 在庫資材表 (施設ニ含マレザルモノ)

ITEM DESCRIPTION	UNIT	QUANTITY	TOTAL ESTIMATED WEIGHT	NUMBER OF CARLOADS	CONDITION ***	REMARKS
品目名稱	單位	數量	見積總重量	積込貨車數	狀態	摘要

* *Owner or custodian to attach statement if he desires.*
所有者又ハ管理人ハ必要ニ應ジ說明書ヲ添附ノコト.

** *Prefectural Japanese Liaison Officer to attach statement if he desires.*
當該地區連絡官ハ必要ニ應ジ說明書ヲ添附ノコト.

*** *Describe as New, Good, or Poor. "Good" will indicate "suitable for general use." "Poor" will indicate "not suitable for reuse."*
狀態欄ニハ新品, 良品, 不良品ト記載ノコト. 良品ハ一般使用ニ適スルモノ. 不良品ハ再使用ニ適サザルモノヲ示ス.

Eighth Army Printing Plant Boonjude
2798

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Electric substation

trans former { P.V 3300 V / S.V 220 V }	300 Kvp 3		very crood	with as fallows
trans former { P.V 3300 V / S.V 110 V }	20 K.VA 1		very crood	$\frac{3}{8}$" × 4" Bus bar 60 ℓ
High Tension oil switch with O.C.B.	300A 1		very crood	2) B.S"00 Rubber Coverd strand wire 300 ℓ
Low Tension switch Board (3 ϕ knife switch marble pannel)	300A3	with V and A mater	very crood	3) 3" H.T Perum 2 usulator 90
" " "	300A3	with V and A mater	very crood	4) 3" L.T Perum 2 usulator 300
Low Tension switch Board (2 ϕ knife switch marble pannel)	300A1	with V and A mater	very crood	5) wall Busling 23.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Water Filting Room (沪水室)

Part of timber (木材之部)

thickness (厚) with (幅) length (長)

0.5	0.5	18.0	Syahia	12
0.5	0.5	12.6	"	4
0.5	0.5	18.0	"	12
0.4	0.4	12.6	"	6
0.2	0.4	12.6	"	28
0.5	0.5	12.0	"	12
0.2	0.4	17.0	"	15
0.5	0.5	28.0	"	4
0.5	0.5	12.0	"	2
0.5	0.5	9.0	"	4
0.5	0.5	6.0	"	2
0.5	0.5	9.5	"	3
0.4	0.5	14.0	"	2
0.4	0.4	60.0	"	3
0.35	0.35	10.0	"	30
0.35	0.35	4.0	"	4
0.4	0.4	6.0	"	5
0.4	0.4	7.0	"	10
0.3	0.2	4.3	"	8
0.4	0.4	3.0	"	10
0.2	0.4	9.0	"	[illegible]

Reparation Plants with out ordicate

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

0.35	0.35	10.0	"	30
0.35	0.35	4.0	"	4
0.4	0.4	6.0	"	5
0.4	0.4	7.0	"	10
0.3	0.2	4.3	"	8
0.4	0.4	3.0	"	10
0.2	0.4	9.0	"	16
0.35	0.35	10.0	"	15
Round timber			Kokoe	
top end				
0.5		10.0	"	30
0.6		15.5	"	10
0.6		15.0	"	2
total timber			Koha	95
Board 0.05			Tubo	156
Slate			"	60
Horizontally siding window			Shat	12
Store 3×3 House (倉庫)				
Part of tailer.				
thickness	Wide	Length	Sgaho	10
0.35	0.35	120		
0.35	0.35	10.5	"	30
0.4	0.4	120	"	5
0.4	0.6	29.0	"	8
0.4	0.6	15.0	"	16
0.4	0.4	6.0	"	8
0.5	0.12	10.5	"	20
0.4	0.4	6.0	"	16
0.35	[illegible]		"	7

Reparation Plants with out indicate

044	0.6	15.0	"	16		
044	0.4	6.0	"	8		
05	0.12	10.5	"	20		
044	0.4	6.0	"	16		
035	0.15	120	"	7		
035	0.15	20	"	28		
035	0.35	12.0	"	45		
0.35	035	4.0	"	12		
0.40	0.40	10.0	"	6	550.0 kg	
total timber - - - - - - - - - -				44		
Slate - - - - - - - - - - - - - - - -			tube	42	2079 kg	
Board	0.05		"	66		Reparation Plant with out indicate
Horizontelly siding window 6×6				5		
Transformer Room (變壓所) Part of timber						
thickness	with	length				
0.4	0.4	26.0	"	14		
0.4	0.4	6.0	"	13		
0.1	0.15	6.0	"	150		
0.45	0.45	12.0	"	4		
0.45	0.6	18.0	"	5		
0.2	0.4	10.0	"	14		
0.75	0.35	12.0	"	14		
Board	0.05					
total timber			tube	16		

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

0.45	0.6	180	"	8				
0.2	0.4	10.0	"	14				
0.75	0.35	12.0	"	14				
Board	0.05							
total timber			tablo	16				
Slate	"			16.5	20.6 kg	25		
Horezontally siding window			"	16	7920 kg			
6 × 6				5				
Converting Room (ห้องแปรรูป)								
Slate			m2	516	17.740 kg		1	
Steel skeleton construction								
Part of steel unit MM								
Pl	60 × 6 × 300			312				
L	75 × 75 × 6 × 7.500			48				
L	50 × 50 × 6 × 4.000			16				
L	90 × 90 × 8 × 7.500			8				
L	65 × 65 × 6 × 8.000			10				
L	50 × 50 × 6 × 1.800			5				
L	65 × 65 × 6 × 1.200			10				
L	65 × 65 × 6 × 540			10				

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDC NO.

∠ 50 × 50 × 6 × 4.000	16
∠ 90 × 90 × 8 × 7.500	8
∠ 65 × 65 × 6 × 5.000	10
∠ 50 × 50 × 6 × 1.800	5
∠ 65 × 65 × 6 × 1.200	10
∠ 65 × 65 × 6 × 540	10
∠ 65 × 65 × 6 × 1.500	10
∠ 65 × 65 × 6 × 1.800	10
∠ 75 × 75 × 9 × 4.500	20
∠ 100 × 75 × 10 × 14.500	16
∠ 65 × 65 × 8 × 1.650	20
∠ 75 × 75 × 6 × 14.500	4
∠ 40 × 40 × 5 × 1.200	30
∠ 40 × 40 × 5 × 700	16
∠ 50 × 50 × 6 × 8.000	4
∠ 50 × 50 × 6 × 12000	8
∠ 50 × 50 × 6 × 11.500	1
∠ 50 × 50 × 6 × 3.000	5
∠ 50 × 50 × 6 × 2000	14
∠ 50 × 50 × 6 × 1.000	15
∠ 50 × 50 × 6 × 7.000	1
∠ 50 × 50 × 6 × 5.000	15
∠ 50 × 50 × 6 × 4000	6
∠ 50 × 50 × 6 × 3.600	6
∠ 50 × 50 × 6 × 1.200	3
∠ 50 × 50 × 6 × 1.700	3
∠ 50 × 50 × 6 × 1.400	3
∠ 65 × 65 × 8 × 600	3
∠ 75 × 75 × 9 × 1.750	1

L 50 × 50 × 6 × 12000		8			
L 50 × 50 × 6 × 11.500		1			
L 50 × 50 × 6 × 3.000		5			
L 50 × 50 × 6 × 2.000		14			
L 50 × 50 × 6 × 1.000		15			
L 50 × 50 × 6 × 7.000		1			
L 50 × 50 × 6 × 5.000		15			
L 50 × 50 × 6 × 4000		6			
L 50 × 50 × 6 × 3.600		6			
L 50 × 50 × 6 × 1.200		3			
L 50 × 50 × 6 × 1.700		3			
L 50 × 50 × 6 × 1.400		3			
L 65 × 65 × 8 × 600		3			
L 75 × 75 × 9 × 1.750		6			
L 150 × 75 × 10 × 4.200		8			
total steel 16 ton					
Tower Room 各硫酸塔上 20				2	
Slate	m²	271	3.255kg		
Sulphusic acid Room 硫酸室					
Slate	m²	115	1725kg		

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDC NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [redacted]

HYOGO LIAISON OFFICE

REMARKS

NAME OF PLANT: NIPPON JYUKAGAKU KOGYO K.K.

Reconverted use, subject to P.D., of the equipments and materials attached to the buildings accomodating facilities designated for reparation is considered inappropriate from the stanpoint of preservation of the reparation machinary with the single exception of those equipments and materials pertaining to the storage Place for ones.

Rituji Yokobe

LOCAL LIAISON OFFICER

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

A WRITTEN OPINION

1. Hot Cottroll (Shujin-Sochi)? Material Warehouse, Furnace, Sulphiric Acid Tank are designated as Reparation Plants. If the iron frames, lumbers, slates are taken away, these equipments would rust by rain and fall into unrepairable condition.

2. Because the 12 tons of remade Leads are required for repairs, it is being petitioned to the Hyogo Prefectural Governer, to retain there.

3. Electric Motor, Oilswitch are parts of Sulphuric Acid equipments. If thes are taken the function of the designated Sulphuric Acid equipments would be destroyed.

4. Based upon the above ressons, we beg for your consideration.

Kankichi Kitamura

Directing Manager
Nihon Jukagaku Kogyo Co., Ltd.
No.14 Minamihatsushima, Amagasaki City,
Hyogo Prefecture.

MGP 37

REPARATIONS PLANTS MATERIALS
賠償工場ノ資材

NAME OF PLANT, LABORATORY, OR ARSENAL:
工場，研究所又ハ兵器廠ノ名稱 Nihon Jukagaku Kogyo Co. Ltd

LOCATION:
所在地 No. 14, Minamihatsushima, Amagasaki City, Hyogo-ken.

SIGNATURE OF OWNER OR CUSTODIAN:
所有者又ハ管理人ノ署名 Kankichi Kitamura

General Contractors Association of Japan
Hyogo Prefecture Branch

TAKATAGUMI
K. Takata

** SIGNATURE OF LOCAL JAPANESE LIAISON OFFICER:
當該地區日本連絡官ノ署名 Y. Asai

DATE:
日附 15 January 1947

MATERIAL STOCKS (NOT INSTALLED) 在庫資材表（施設ニ含マレザルモノ）

ITEM DESCRIPTION 品目名稱	UNIT 單位	QUANTITY 數量	TOTAL ESTIMATED WEIGHT 見積總重量	NUMBER OF CARLOADS 積込貨車數	CONDITION *** 狀態	REMARKS 摘要
Brick	Sheet	3,000	6 ton	1	Good	
Lead ingot	ton	12	12 ton	2	Good	

* *Owner or custodian to attach statement if he desires.*
所有者又ハ管理人ハ必要ニ應ジ說明書ヲ添附ノコト.

** *Prefectural Japanese Liaison Officer to attach statement if he desires.*
當該地區連絡官ハ必要ニ應ジ說明書ヲ添附ノコト.

*** *Describe as New, Good, or Poor. "Good" will indicate "suitable for general use." "Poor" will indicate "not suitable for reuse."*
狀態欄ニハ新品，良品，不良品ト記載ノコト. 良品ハ一般使用ニ適スルモノ. 不良品ハ再使用ニ適サザルモノヲ示ス.

Eighth Army Printing Plant Boeryuda
2/2/48

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

3 phase Induction motor (cage motor (220V 1735 R P m)	Type	1	300 L.B.S	Good	Suitable general use maker Shibaura E.W
3 p. Gas proof Hand operating oil Switch	2200 / 10A	1	120 LBS	Good	makes Hirai E.W
B.S #14 x 2 Lead covered cable (For Low Voltage		1,000 ft		Good	
3/4 ϕ Conduit Tube		40 ft		Good	
B.S #00 Over head Distribution wire (Rubber covered)		3000 ft		poor very injured by Gas and Rain	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

INSTALLED MATERIALS AND SUPPLIES 施設濟ノ資材

ITEM DESCRIPTION 品目·名稱	UNIT 單位	QUANTITY 數量	TOTAL ESTIMATED WEIGHT 見積總重量	NUMBER OF CARLOARDS 積込貨車數	REMARKS 摘要
	1/2HP	1			

地方府縣米軍軍政府係官專用欄 FOR USE BY PREFECTURAL MILITARY GOVERNMENT TEAM ONLY. STRIKE OUT WORDS NOT APPLICABLE AND FILL IN BLANK SPACES.

IS (NOT) AN ENEMY SURRENDERED FACILITY
IS ([redacted]) A REPARATION FACILITY.
IS (NOT) PRODUCING FOR OCCUPATION FORCES.
IF SO, GIVE PROCUREMENT DEMAND NUMBERS OR DATA REGARDING ORDERS FOR DEPENDENT HOUSING:

HAS (NOT) BEEN TURNED BACK TO HOME MINISTRY
IS (NOT) OPERATING.
ANY OBJECTION TO REMOVAL OF ABOVE ITEMS: No, sulphuric acid equipment is damaged beyond repair and removal of buildings or materials would not cause further damage.

CORRESPONDENCE OR ACTION IS ([redacted]) PENDING TO REMOVE PLANT FROM REPARATIONS LIST.
CORRESPONDENCE OR ACTION IS (NOT) PENDING FOR (REOPENING) ([redacted]) THE PLANT.
STATEMENT AS TO WHETHER MACHINERY OR EQUIPMENT IN PLANT WILL BE JEOPARDIZED BY REMOVAL OF ABOVE ITEM:
No, machinery, in opinion of this headquarters, is already worthless and cannot be further damaged.

PLANT NO.: 13-81 SERIAL NO. OF FORM: Hyge 32 DATE: 30 Jan. 1947 MIL GOVT OFFICER: Albert B. Holtz, Lt. PREFECTURE: Hyogo

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Timber

Thickness	Width	Length		in Shaken
0.2	0.6	7.0		30
0.2	0.4	7.0	1	60
0.25	0.25	12.0	1	36
1.2	0.2	8.0	1	20
1.2	0.2	8.0	1	34

Top end

			in Shaken
0.45	11.50	1	20
0.6	11.50	1	4
0.8	14.00	1	2
0.5	10.00	1	60
0.5	15.00	1	60
0.3	10.00	1	378
1.0	20.00	1	6
0.3	15.00	1	12

Total Timber — Koken 87 10,870 Kg 2

Slate — Tubo 270 4,050 Kg 0.5

Hot cattrall plant

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

			12		
Total Timber		Kalen	87	10.870 kg	2
		Tube	270	4.050 kg	0.5
Slate					
Hat cattrall plant					
Slate		Tube	1312		
Kiln Furnace		m^2	2140.25		
Slate					
Steel Skelton Construction					
	m.m 11.500	pc	24		
pl 160 x 9	450	"	12		
pl 550 x 9	450	"	312		
pl 90 x 9	11.500	"	48		
L — 75 x 75 x 9	10.000	"	26		
L — 50 x 50 x 6	2.000	"	10		
L — 50 x 50 x 6	3.000	"	24		
L — 50 x 50 x 6	1000	"	6		
L — 50 x 50 x 6	18.000	"	15		
L — 50 x 50 x 6	7.000	"	4		
L — 50 x 50 x 6	1.000	"	14		
L — 50 x 50 x 6	5.000	"	12		
L — 75 x 75 x 9	18.000	"	20		
L — 50 x 50 x 6	9.500	"	12		
L — 65 x 65 x 8	2.100	"	12		

L --	50x50x6	1000	"	6	
L --	50x50x6	18.000	"	15	
L --	50x50x6	7.000	"	4	
L --	50x50x6	1.000	"	14	
L --	50x50x6	8.000	"	12	
L --	95x95x9	18.000	"	20	
L --	80x80x6	9.500	"	12	
L --	65x65x8	2.100	"	12	
L --	65x65x8	1.100	"	12	
L --	50x50x6	2.200	"	6	
L --	95x95x9	1.900	"	12	
L --	65x65x6	1.300	"	12	
L --	50x50x6	1.300	"	36	
L --	50x50x6	1.000	"	19	
L --	90x75x7	5.500	"	24	
L --	50x50x6	5.000	"	4	
L --	50x50x6	6.000	"	16	
L --	50x50x6	5.000	"	10	
-	Total steel	-	Tons	24	
-	Strage Tanks	--			
-	Slate	--	Tons	80	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.