岩手県知事殿

評価対象物件（属化）の解除申請について

右について別紙の通り申請書を作成したので解除方御取計いを御願い致します。

記

一、東北民事部調

一、一連仙台通産局

一、岩手県庁

尚提出先・及び部数は左記の通りです。

一四

一一

一一

一一

富士産業株式会社岩手工場

管理代行人　松田敏夫

昭和二十五年十一月十二日

富岩路二五号二一號

Encl 5

評価対象物件（屑化）の解除許可申請書

昭和二十五年　月　日

申請者　住所　富士産業株式会社岩ケ谷工場
管理代行人　牧田
岩ケ谷和賀郡黒沢尻町

北地区
民事部司令官殿

二五場（コード番号一六一〇一）に属する左記物件について破壊を条件として解除を御願致します。

記

一、解除しようとする物件の明細

登録番号	名称	製造番号	型式能力	台数	備考

一六一〇一a	トラック	いすゞ	四四年型	七	一		コード番号一六一〇一aに対するアークシート三六頁使用許可施設中のアイテム番号五一
一三一〇一U			積載三				
一六一〇一a	トラック	いすゞ	四四年型	七	一	石同施設中のアイテム番号	五二
一三一〇一U	小型		積載三				
一六一〇一a	乗用車	ニッサン	三八年型	七	一	右同三七頁右同施設中のアイテム番号	五八
一三一〇一U			四人乗				
計					三		

解除を必要とする理由

別項記載のトラック及小型乗用車は長年の使用に老朽甚だしく従来修理は毎月高額の経費を要し来り現在に至りましたがこれ以上修理費を掛ける事は経済的にも無駄であり且又修理の価値もないので今回の申請が許可されればスクラップとして他に費却し代替への新車を一台購入したいと考へますので右條御審議の上御許可賜り度く御願い致します。

173

APPLICATION FOR RELEASE OF DESIGNATED EVALUATION ITEMS WITH CONDITION OF SCRAP DOWN

Date 1950

To : Commanding Officer of the T.C.A.R.

From : Applicant Iwate Factory of the Fuji Ind. Co.,

Chief custodian Toshio Matsuda.

Adress Kurosawajiri-machi, Waga-gun, Iwate-ken.

The application is submitted for the permission of scrap down the following Evaluation Items belonging to our factory whose Code No. is 16-01.

(1) Details of Items to be released.

Inventory No.	Name of Items	Makers	Type & capacity	No. of Items	Remarks
16-01a-317-U	Automobile -Truck	Isuzu	1944 3 tons	1	Evaluation plant Code No 16-01a Work sheet page 36 Section Authorized Use Item No. 51
16-01a-318-U	ditto	ditto	ditto	1	ditto Item No. 52
16-01a-327-U	Automobile Small Size	Nissan 1938 4Persons		1	ditto Page 37 Item No. 58
			Total	3	

(2) Reason of Necessity for Release.

These three vehicles are obsolete and time worn after their long time services. High cost of repairing has been required every month , but it's now quite in vain and not economic to disburse more than ever the expense for repairing. In otherwards, they are already worthless to be repaired, so if this application can be approved with the provision that these vehicles be used solely as scrap for melting down purposes, we shall sell them as scrap and we wish to buy a new automobile-truck as substitute. We beg your favourable considerations about this application.

Toshio Matsuda

Custodian of the Iwate Factory
of the Fuji Industrial Co.

(2) Reason of Necessity for Release.

These three vehicles are obsolete and time worn after their long time services. High cost of repairing has been required every month , but it's now quite in vain and not economic to disburse more than ever the expense for repairing. In otherwards, they are already worthless to be repaired, so if this application can be approved with the provision that these vehicles be used solely as scrap for melting down purposes, we shall sell them as scrap and we wish to buy a new automobile-truck as substitute. We beg your favourable considerations about this application.

Toshio Matsuda

Custodian of the Iwate Factory
of the Fuji Industrial Co.

TOHOKU FINANCE BUREAU

17 January 1951

TO: Chief, Tohoku Civil Affairs Region

SUBJECT: Submitting of a list of reparations equipment to be scrapped

1. Inclosed herewith is a list of reparations equipment to be scrapped, checked by your Headquarters.

2. Number of equipment is as follows.

Name of Arsenal	No. of Equipment
Tokyo 1st Military Arsenal Sendai Factory (24-4)	2
" (24-4p	82
Tagajo Naval Arsenal (24-5)	6
Osaka Military Arsenal (24-1)	10
Ominato Naval Arsenal (03-3)	249
The 41st Naval Aeronautical Arsenal Ominato Branch (03-4)	59
Total:	408 items

/s/t/MASAO MAEDA
Director
Tohoku Finance Bureau

Incl.: List (in trip.)

Encl 6

COPY

SUMMARY

Code No.: 24-4

Name of Arsenal: The 1st Tokyo Military Arsenal, Sendai Factory

Address: Haranomachi-odawara, Sendai, Miyagi Pref.

Total No. of Items Applied for Scrap 2

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED [illegible]

Code No.: 24-4

Name of Arsenal: The 1st Tokyo Military Arsenal, Sendai Factory

Address: Haranomachi-odawara, Sendai, Miyagi Prefecture

Classification: Single Purpose Machines Non-usable for Normal Peace Time Economy

Item	Inv. No.	Name of Machines	Remarks
	24-4-1486	Cut off lathe, hand chucking	Spindle bent
	1491	"	Motor missing

Total Number of Machinery ..... 2 items

SUMMARY

Code No.: 24-4P

Name of Arsenal: The 1st Tokyo Military Arsenal, Sendai Factory

Address: Haranomachi-odawara, Sendai, Miyagi Pref.

Total No. of Items Applied for Scrap.....82

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 24 - 4P

Name of Arsenal: The 1st Tokyo Military Arsenal Sendai Factory

Address: Haranomachi, Odawara, Sendai City, Miyagi Pref.

Classification: Major Component Parts Missing Or Broken

Item	Inv. No.	Name of Machine	Remarks
Modern, but non-repairable	7	Lathe, screw cutting	Motor missing
	10	Lathe, engine	"
	11	Lathe, turret (Excepting motor)	Spindle bent
	23	Lathe, engine	Motor missing
	24	"	"
	25	"	"
	26	"	"
	27	"	"
	29	"	"
	30	"	"
	31	"	"
	36	Hearth, electric	Electric distribution wrong
	37	Lathe, engine	Main spindle & motor missing
	38	Lathe	Motor missing
	41	Lathe, engine	"
	42	"	"
	59	"	"

Code No. 24 - 4P

Item	Inv. No.	Name of Machine	Remarks
Modern, but non-repairable	60	Lathe, engine	Motor missing
	63	"	"
	85	Lathe, turret	"
	86	Lathe, engine	"
	87	"	"
	88	"	"
	89	"	"
	104	Lathe, engine	"
	105	"	"
	106	"	"
	107	"	"
	108	"	"
	125	"	"
	136	Grinder	Main parts missing
	137	Lathe, engine	Motor & lead screw missing
	138	"	"
	139	"	Motor missing
	140	"	"
	160	Transformer, outdoor	Coil burnt

Total Number of Machines.....36 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 24 - 4P

Name of Arsenal: The 1st Tokyo Military Arsenal Sendai Factory

Address: Haranomachi, Odawara, Sendai City, Miyagi Pref.

Classification: Single Purpose Machine Not Usable For Normal Peace Time Economy

Item	Inv. No.	Name of Machine	Remarks
	43	Lathe, production	Motor missing
	44	"	"
	45	"	"
	46	"	"
	47	"	"
	48	"	"
	49	"	"
	55	Lathe, chucking	"
	56	"	"
	57	"	"
	64	Lathe, production	"
	65	"	"
	66	"	"
	84	"	"
	103	Lathe, chucking	"
	109	"	"
	110	"	"
	111	"	"

Code No. 24 - 4P

Item	Inv. No.	Name of Machine	Remarks
	112	Lathe, chucking	Motor missing
	113	"	"
	114	"	"
	115	"	"
	116	"	"
	117	"	"
	118	"	"
	119	Lathe, production	"
	120	"	"
	121	"	"
	122	"	"
	123	"	"
	124	"	"
	127	"	"
	128	"	"
	129	"	"
	130	"	"
	131	"	"
	132	"	"
	133	"	"
	134	"	"
	143	Dryer, electric	"
	144	"	"
	145	Furnace, electric	"

Code No. 24-4P

Item	Inv. No.	Name of Machine	Remarks
	140	Furnace, electric	Motor missing
	147	"	"
	148	"	"
	149	"	"

Total Number of Machine.....46 items

SUMMARY

Code No.: 24-5

Name of Arsenal: Tagajo Naval Arsenal

Address: Haranomachi-Odawara, Sendai, Miyagi Pref.

Total No. of Items Applied for Scrap.....6

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 24 - 5

Name of Arsenal: Sagajo Naval Arsenal

Address: Haranomachiodawara, Sendai City, Miyagi Prefecture

Classification: Major Component Parts Missing or Broken

Item	Inv. No.	Name of Machines	Remarks
Non-repairable	24-5-2367	Switch gear, pannel	All parts broken
	2385	Pump, turbine	Impeller missing
	2386	Switch gear, pannel	All parts broken
	2387	Switch, magnetic	"
	2389	Pump, turbine	Impeller worn
	2390	Internal combustion engine, gasoline	All attachments missing

Total Number of Machinery.....6 items

SUMMARY

Code No.: 24-1

Name of Arsenal: Osaka Military Arsenal

Address: Nagamachi, Sendai, Miyagi Pref.

Total No. of Items Applied for Scrap..... 10

LIST OF REPARATIONS MACHINERY TO BE CRAPPED DOWN

Code No.: 24 - 1

Name of Arsenal: Osaka Military Arsenal

Address: Nagamachi, Sendai, Miyagi Pref.

Classification: Major Component Parts Missing Or Broken

Item	Inv. No.	Name of Machine	Remarks
Obsolete	500	Lathe, engine, std.	1926 year made
	488	"	"
	492	"	"
	497	"	"
	503	"	"
	505	"	"
	501	"	"

Total Number of Machine..... 7 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 24-1

Name of Arsenal: Osaka Military Arsenal

Address: Nagamachi, Sendai, Miyagi Pref.

Classification: Major Component Parts Missing Or Broken

Item	Inv. No.	Name of Machine	Remarks
Modern & Non-Repairable	527	Milling Machine, knee type, horizontal, plain	Universal joint missing table lead screw broken

Total Numberof Machine..... 1 item

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 24-1

Name of Arsenal: Osaka Military Arsenal

Address: Nagamachi, Sendai, Miyagi Pref.

Classification: Economically Non-repairable

Item	Inv. No.	Name of Machine	Remarks
Badly worn	490	Lathe, engine, std.	Automatic feed wrong tail stock missing. 1920 year made.
	504	"	Carriage broken tool post, tail stock missing. 1920 year made.

Total Number of Machinery: 2 Items

SUMMARY SHEET BY PREFECTURE

Name of Prefecture: Aomori

Total No.: 308

Name of Plant	Code No.	No. of Item
Ominato Naval Arsenal	03-03	249
The 41st Naval Aeronautical Arsenal Ominato Branch	03-04	44
"	03-03	15

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 03-03

Name of Arsenal: Ominato Naval Arsenal

	Classification & Item					
	1a	1c	2b	3	4	Total
No. of Machines:	1	178	67	1	2	249

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 03-03

Name of Arsenal: Ominato Naval Arsenal

Address of Arsenal: 44 Ochikagawa, Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 1. Major Component Parts Missing or Broken

Item	Inv. No.	Name of Machine	Remarks
a. Obsolete	322	Dry dock, floating	Made in 1902

Total number of machinery..... 1 item

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-3

Name of Arsenal: Ominato Naval Arsenal

Address of Arsenal: 44 Ochikagawa, Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 1. Major Component Parts Missing or Broken

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	197-C	Internal Combustion Engine, Diesel	Cylinder damaged & frame broken
	367	Winding Machine	Parts missing & damaged
	369	"	"
	370	"	"
	371	"	"
	372	"	"
	373	"	"
	374	"	"
	450	D.C. Ammeter	Meter glass damaged & shunt missing
	454	D.C. Volt Ammeter	Shunt missing
	463	D.C. Voltmeter	"
	502	Portable Machine, Pneumatic Grinder	Air cock, nut & washer missing
	567	Portable Machine, Pneumatic Drill	"
	596	"	Piston cover broken, 5 volts missing

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	643	Portable Machine, Electric Drill	Bearing & gear missing
Repairable	644	"	Brush & gear damaged
	646	"	Gear & governor damaged
	649	"	Protector & cable missing, chuck damaged
	651	"	Handle missing, gear & chuck damaged
	652	"	Protector & chuck damaged
	654	"	Protector missing, chuck & cover damaged
	655	"	Motor damaged
	659	"	Chuck, bearing, brush, cable & cover missing
	663	"	Motor damaged
	669	Portable Machine, Pneumatic Riveter	Piston missing
	670	"	"
	671	"	Piston & hose joint missing
	672	"	"
	673	"	Piston missing
	674	"	Piston & hose joint missing
	675	"	"
	676	"	"
	677	"	"
	678	"	Piston missing

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	679	Portable Machine, Pneumatic Riveter	Piston & hose joint missing
	680	"	"
	681	"	"
	682	"	"
	683	"	"
	684	"	Piston missing, switch defective
	685	"	Piston & hose joint missing
	686	"	Piston damaged & hose joint missing
	687	"	"
	691	"	"
	692	"	"
	732	"	Piston damaged
	733	"	Piston missing
	734	"	"
	735	"	"
	736	"	"
	737	"	Piston & hose joint missing
	738	"	Piston missing
	739	"	"
	740	"	"
	741	"	"
	742	"	"
	743	"	"
	744	"	"

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	745	Portable Machine, Pneumatic Riveter	Piston missing
	746	"	"
	747	"	Piston missing & switch damaged
	748	"	Piston missing
	749	"	"
	750	"	Piston damaged
	751	"	Piston missing
	752	"	"
	753	"	"
	754	"	"
	755	"	"
	756	"	"
	757	"	"
	758	"	"
	759	"	"
	760	"	"
	761	"	"
	762	"	"
	763	"	"
	764	"	"
	765	"	"
	766	"	"
	767	"	"

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	769	Portable Machine Pneumatic Riveter	Piston missing
	770	"	"
	771	"	"
	772	"	"
	773	"	"
	774	"	"
	775	"	Piston hose joint missing
	776	"	Piston missing
	777	"	"
	778	"	"
	780	"	"
	781	"	Piston damaged
	783	"	Piston damaged & hose joint missing
	789	"	Piston missing
	814	"	Piston damaged
	823	"	Piston missing
	829	"	"
	865	Portable Machine Pneumatic Calking Hammer	Screw & valve damaged, piston rusty
	866	"	Hose joint missing, valve damaged
	870	"	"
	872	"	Valve damaged, cover missing
	873	"	"

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	875	Portable Machine Pneumatic Calking Hammer	Hose joint missing, valve damaged
	877	"	Piston rusty
	880	"	Valve damaged
	882	"	Piston rusty
	883	"	Piston rusty, valve damaged
	885	"	Piston damaged
	886	"	Piston damaged, hose joint missing
	887	"	Piston damaged
	902	"	"
	903	"	Piston damaged, hose joint missing
	929	Portable Machine Pneumatic Holder-on	"
	930	"	"
	931	"	"
	932	"	"
	933	"	Piston missing
	934	"	"
	935	"	"
	936	"	"
	937	"	"
	938	"	"
	939	"	"
	940	"	"
	941	"	"

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	942	Portable Machine Pneumatic Holder-on	Piston missing
	943	"	"
	952	"	Piston damaged
	955	"	Piston missing
	956	"	"
	957	"	"
	960	"	"
	961	"	"
	962	"	"
	963	"	"
	964	"	"
	965	"	"
	966	"	"
	967	"	"
	976	Portable Machine Pneumatic Jam Riveter	Piston missing
	977	"	"
	978	"	"
	979	"	"
	980	"	"
	981	"	"
	982	"	Piston, hose joint & spindle missing
	1076	Switch Gear, Panel	Marble board damaged
	1124	Chain Block (Excepting chain & hook) 7	Chain missing, spindle damaged

Code No. 03-3

Item		Inv. No.	Name of Machine	Remarks
c.	Modern, but Non-Repairable	1151	Chain Block (Excepting chain & hook)	Chain band & pin missing
		1153	"	Chain main wheel missing, chain wheel damaged
		1158	"	Parts missing
		1161	"	Chain wheel damaged
		1162	"	Chain & chain wheel damaged
		1164	"	
		1165	"	Chain wheel damaged
		1221	Surface Plate	In poor condition
		1222	"	"
		1223	"	"
		1224	"	"
		1225	"	"
		1242	"	"
		1284	Chain Block	Chain missing, spindle damaged
		1313	Gas Cutting Burner	Hose joint missing, switch damaged
		1327	"	Valve damaged
		1328	"	"
		1329	"	"
		1330	"	"
		1335	Oxygen Regulater	Gauge damaged
		1376	Pump-reciprocating Water	Water cylinder broken & cover & piston damaged

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-Repairable	1382	Blue Printing Machine	2 Motors, 1 fan, 1 heater, washing & drying equipment missing
	1410	Dynamo Meter	Gauge missing
	1418	Blue Printing Machine	2 Motors, 1 fan, 1 heater, washing & drying equipment missing
	1419	"	"
	1430	Cupola	Parts missing
	1490	Crusher	In poor condition
	1491	"	"
	1528	Jack, Hydraulic	Head damaged

Total Number of Machinery..... 178 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03 - 3

Name of Arsenal: Ominato Naval Arsenal

Address of Arsenal: 44 Ochikagawa, Ominato, Shimokita-gun, Aomori Pref.

Classification: 2. Others Economically Non-Repairable

Item	Inv. No.	Name of Machine	Remarks
b. Badly worn	208	Pump, Rotary (Excepting Motor)	Badly worn-out
	313	Guy Derrick	"
	314	"	"
	315	"	"
	316	Winch, Pneumatic Driven	"
	333	Paint Mixing Roller (Excepting Motor)	"
	476	Rivet Forge, Portable	Worn, fan cover damaged
	478	Furnace, Melting Oil	Burner missing
	699	Portable Machine Pneumatic Riveter	Badly worn-out
	785	"	"
	786	"	"
	787	"	"
	788	"	"
	793	"	"
	794	"	"
	795	"	"

Code No.: 03 - 3

Item	Inv. No.	Name of Machine	Remarks
b. Badly worn	796	Portable Machine Pneumatic Riveter	Badly worn-out
	797	"	"
	798	"	"
	809	"	"
	810	"	"
	811	"	"
	812	"	"
	813	"	"
	850	"	"
	864	"	"
	868	Portable Machine Pneumatic Cauking Hammer	"
	876	"	"
	878	"	"
	905	"	"
	906	"	"
	907	"	"
	908	"	"
	909	"	"
	910	"	"
	911	"	"
	912	"	"
	913	"	"
	914	"	"
	915	"	"

Code No. 03-3

Item		Inv. No.	Name of Machine	Remarks
b.	Badly worn	968	Portable Machine Pneumatic Holder-on	Badly worn-out
		969	"	"
		1159	Chain Block	"
		1178	Gas Welding Burner	"
		1286	Gas Welding Burner	"
		1290	Counter Shaft	"
		1292	Line Shaft	"
		1304	Gas Cutting Burner	"
		1305	"	"
		1306	"	"
		1307	"	"
		1309	"	"
		1312	"	"
		1315	"	"
		1316	"	"
		1317	"	"
		1318	"	"
		1319	"	"
		1340	Surface Plate	"
		1341	Augle Plate	"
		1493	Slidack	"
		1574	Spray Gun	"
		1586	Center Gauge	"
		1589	Block	"
		1590	"	"

Code No. 03-3

Item	Inv. No.	Name of Machine	Remarks
b. Badly worn	1591	Block	Badly worn-out
	1592	"	"

Total Number of Machinery.....67 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03 - 3

Name of Arsenal: Ominato Naval Arsenal

Address of Arsenal: 44 Ochikagawa, Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 3. Single Purpose Machines Unavailable For Normal Peace Time Economy

Item	Inv. No.	Name of Machine	Remarks
	1411	Boiler, High Pressure	Oil burner, 1 water gauge, feed pump missing

Total Number of Machinery.....1 item

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03 - 3

Name of Arsenal: Ominato Naval Arsenal

Address of Arsenal: 44 Ochikagawa, Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 4. Non-removable Equipment

Item	Inv. No.	Name of Machine	Remarks
	1372	Oil Tank	Non-removable
	1440	Dryer-furnace	"

Total Number of Machinery.....2 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code No.: 03 - 04

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Classification & Item

No. of Machines:	1c	2b	4	Total
	38	3	3	44

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-4

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Address of Arsenal: Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 1. Major Component Parts Missing Or Broken

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but non-repairable	2	Lathe, Engine, Std.	Motor, spindle, tail stock & tool post missing
	8	Grinding Machine, Drill Grinding	Motor & spindle missing
	16	Milling Machine, Horizontal	Motor, speed change gear & feed change gear missing
	18	Lathe, Engine, Std.	Motor, spron & tail spindle missing
	24	Shaper, Horizontal	Motor, power feed equipment missing
	25	Lathe, Bench	Motor & carriage missing
	26	Lathe, Engine, Std.	"
	27	"	Motor, tail stock & coolant system missing
	28	Grinder, Surface	Motor, table, table power feed system missing
	29	Drilling Machine, Upright	Spindle, sliding head & balance weight missing, motor & switch broken
	31	Grinder, Bench	All mechanical parts missing

Code No. 03-4

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but non-repairable	32	Lathe, Engine, Std.	Motor burned, tail stock, & rive clutch missing
	33	Grinder, Universal tool & Cutter	Motor & head stock missing
	34	Lathe, Bench	Motor & carriage missing
	40	Milling Machine, Bench	Motor, abbor & arbor support missing
	42	Grinder, Bench	Head stock, tail stock & wheel slide missing
	51	Bending Machine, Plate	Roller missing
	73	Drilling Machine, Upright	Table missing
	74	Crane, Hoist	3 motors missing
	98	Lathe, Spinning	Motor, tool post missing
	106	Drilling Machine, Upright	Motor, table & lead wire missing
	114	Router Machine	Motor, tool head & drive pulley missing
	117	Furnace, Electric	Door & switch gear missing
	123	Crane, Over Head	3 motors & electric equipment for driving room missing
	136	Furnace, Electric	2 thermostatts missing, switch missing
	166	Sand Mill	Motor & drive bevel gear missing
	173	Blue Printing Apparatus	Motor, paper winding roller, arc lamps missing

Code No. 03-4

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but non-repairable	174	Blue Printing Apparatus	Guide roller, winding roller & dryer missing
	176	Mixer	Motor missing, fan and arm broken
	188	Universal Machine	Motor, tail stock, arbor, arbor support, drilling missing
	194	Grinding Machine, External	3 motors & chuck missing
	196	Honning Machine, Internal	2 motors, table missing
	203	Generator, Rotary	Armature wrong
	206	Furnace Electric	2 thermocouples, meter missing, wire resistance, ammeter broken
	207	Grinding Machine, External	2 motors, wheel slide & chuck missing
	208	Boring Machine, Horizontal	Motor, table missing
	210	Grinding Machine, Stand	All measuring parts missing
	211	Generator Testing Machine	Measuring parys missing

Total Number of Machine..... 38 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-4

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Address of Arsenal: Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 2. Others Economically Non-Repairable

Item	Inv. No.	Name of Machine	Remarks
b. Badly worn	86	Sand Blast	Motor missing & condition worng
	89	Furnace, Electric	3 motors missing
	115	Hydraulic Press	Motor, oil pump, oil tank missing

Total Number of Machine..... 3 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-4

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Address of Arsenal: Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 4. Non-Removable Equipment

Item	Inv. No.	Name of Machine	Remarks
	150	Furnace, Coal	Brick made
	217	Furnace, Coal	"
	218	Vessel	Buried in the ground

Total Number of Machine..... 3 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03 - 4

Name of Arsenal: The 41st Naval Aeronautical Arsenal
Ominato Branch

Classification & Item	1c	2b	Total
Number of Machines:	14	1	15

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-4

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Address of Arsenal: Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 1. Major Component Parts Missing Or Broken

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but non-repairable	03-03-28	Lathe, Engine	Dead center, tool post missing
	87	"	Chuck, dead center, counter shaft & nut for crose feed screw missing
	88	"	Counter shaft, dead center, change gear, tool post & half nut missing
	89	" (Excepting counter shaft)	Change gear, chuck, half nut, tool post & tail stock missing
	90	" (Excepting counter shaft)	Change gear, chuck, tool post & dead center missing
	91	Lathe, Engine	Tail stock, tool post, chuck & counter shaft missing
	99	Universal Machine	Drilling table, tail stock, arbor, tool post missing
	101	Lathe, Engine	Tool post, tail stock, change gear missing
	127	Drilling Machine, Radial	Bed, table, spindle feed, drive gear missing
	142	Lathe, Engine	Motor, power feed drive gear, chuck missing

Code No.: 03-4

Item	Inv. No.	Name of Machine	Remarks
c. Modern, but Non-repairable	03-03-179	Grinding Machine, Tool	Spindle, counter shaft, cutter holder missing
	203	Milling Machine, Engraving	Motor & Pantograph missing
	266	Generator, Engine (Excepting generator)	Gasoline Engine missing
	271	Milling Machine, Engraving	Motor, Pantograph & milling spindle missing

Total Number of Machine..... 14 items

LIST OF REPARATIONS MACHINERY TO BE SCRAPPED DOWN

Code Number: 03-4

Name of Arsenal: The 41st Naval Aeronautical Arsenal Ominato Branch

Address of Arsenal: Ominato-machi, Shimokita-gun, Aomori Pref.

Classification: 2. Others Economically Non-Repairable

Item	Inv. No.	Name of Machine	Remarks
b.	Badly worn 03-03-95	Lathe, Engine (Excepting counter shaft)	Hanger bearing, belt shifter chuck, screw shaft for tail stock missing, nut for crose feed screw broken

Total Number of Machine..... 1 item

MLO (50)-1110

MH/ao

MIYAGI PREFECTURAL GOVERNMENT

27 Jan ary 1951

TO: Mr. Oliver L. Hobson
Chief Economics Officer
Tohoku Civil Affairs Region

SUBJECT: Application for Scrapping
Reparations Machinery

I wish you to harbor a favorable view on the attached application for scrapping reparations machines separately submitted by each of the three reparations plants in this prefecture.

/s/ Chozo Shishido for
AKIRA SAKAMOTO

Director
Commerce & Industry Dept.

Includes 7, 8, & 9

COPY

(Date) 8, January, 1951

Name of Plant : Nakagawa Sangyo Co., Ltd. Shiogama Plant.

Code No. : 24 — 03

Address : 25-Ipponmatsu, Kasagami, Shiogama Shi, Miyagi Pref..

Subject : Aircraft

It is requested that the undementioned items de released from reparation Custody for Melt-down Scrap.

Name of Items	Inventory No	Remark
Drilling Machine	24—03—30	Pinion missing
Drilling Machine	24—03—32	Pinion missing
Air Compresser (Motor 20H.P.)	24—03—39	Fly wheel missing. war damaged no scrap
Air Compresser	24—03—41	Crank rod and Pully missing
Mechanical Press	24—03—50	Foot broken
Knuckle Joint (Motor 2H.P.)		no scrap
Manual Press	24—03—53	Foot broken, Punch box broken
Drilling Machine	24—03—88	Spindle to pinion sticked
Drilling Machine	24—03—89	Spindle to pinion sticked
Drilling Machine	24—03—90	Spinidle to pinion sticked
Drilling Machine	24—03—91	Spinidle to pinion sticked
Drilling Machine	24—03—92	Spindle to pinion sticked
Drilling Machine	24—03—93	Spindle to pinion sticked
Riveting Machine	24—03—123	Punch box missing. Foot broken
Blower	24—03—124	Foot and fire bed broken
Blower	24—03—125	Foot and fire bed broken
Air Compresser	24—03—138	Piston to Cylinder Sticked
Grinding Machine	24—03—139	war damaged. Head missing
Grinding Machine	24—03—140	war damaged. Head missing

Incl 7

Name of Items	Inventory No.	Remark
Air Compresser	24 — 03 — 156	Fly wheel missing, war damaged
Manual Press	24 — 03 — 157	Fly wheel missing
Mechanical Press (Friction Spindle)	24 — 03 — 170	Fly wheel and screw shaft missing
Shearing Machine (Nibbling)	24 — 03 — 172	All shaft sticked. Punch box broken
Shrinking Machine	24 — 03 — 204	Punch Plate and Gear missing

Total No. 23

Director. Nobuo Nakagawa

(Signature) Nobuo Nakagawa

Representative of the Plant

(Date) January 1951.

Name of plant: Kayaba Sangyo K.K. Sendai kojo.

Code No. : 24-01

Address : 3# Hachihonmatsu Nagamachi Sendai-shi Miyagi Pref.

Subject :

It is requested that these undermentioned items de released from reparations custody for Melt-doun scrap

Name of Items	Inventory No.	Remak
Heating furnace	24-01-277	
"	" 278	
"	" 279	
"	" 280	
"	" 275	
"	" 283	
Heat treating furnace	" 310	
Furnace	" 311	
Heating furnace	" 315	
Press	" 634	Arm damaged
Shaper	" 598	
Centrifugal Separator	" 599	Legs brokened
Worthington pump	" 566	Cover brokened
Hardness tester	" 825	
"	" 822	
Air hammer	" 271	Crankshhft missing
Lathe	" 567	
"	" 476	
Drilling machine	" 562	
Lathe	" 484	
"	" 465	
"	" 486	
Milling machine	" 514	
"	" 546	
"	" 516	
Drilling machine	" 618	Spindle missing
"	" 615	"
"	" 620	"
"	" 622	"
"	" 617	"

Incl 8

Name of Items	Inventory No.	Remak
Steam engine	24-01-568	
"	" 553	
Compressor	" 102	Flywheel missing
Welding machine	" 757	
Milling machine	" 532	
Shearing machine	" 635	
Drilling machine	" 144	
Milling machine	" 233	
Cutoff sawing machine	" 234	
Lathe	" 423	
"	" 440	
"	" 456	
"	" 457	
"	" 462	
"	" 464	
"	" 469	
"	" 471	
"	" 475	
"	" 481	
"	" 485	
"	" 506	
"	" 513	
Grinder	" 530	
Magnafiux	" 537	
Milling machine	" 551	
Lathe	" 552	
"	" 554	
Cutoff sawing machine	" 560	
"	" 561	
Drilling machine	" 563	
Lathe	" 565	
"	" 595	
"	" 596	
Drilling machine	" 603	
"	" 604	
"	" 606	
"	" 614	
"	" 623	
"	" 625	
"	" 626	
"	" 636	
Lathe	" 569	
"	" 418	
"	" 428	
"	" 429	
"	" 437	
"	" 438	
"	" 467	
"	" 468	
"	" 470	
"	" 479	
"	" 478	
"	" 477	

Total 83 items

(Singna ture) _____

Representative of the plant

(Date) Jan. 26, 1951.

Name of Plant : Dainippon Kōkūki Co., Ltd.
(Present Name) : Hokuto Seisakusho Co., Ltd.
Code No. : 24-9
Address : #183 Higashi Hachibancho
Sendai City, Miyagi Pref.

Subject : It is requested that these under-mentioned items be released from reparations Custody for Melt-down Scrap.

Name of Items	Inventory No.	Remarks
1. Bending Machine	24-9-18	Broken
2. Bending Machine	24-9-24	Missing-Rolls

Encl 9

3. Lathe-Gap	24-9-31	Missing — Counter, Chark. Change Gears, Tool Head, Tail Stock, Handles, Parts — Automatic Feed Mechanism.
4. Lathe-Gap:	24-9-32	Missing — Counter, Chack Change Gears, Tool Head, Tail Stock, Handles, Appron, Lead Screw, Cone-Bearing.
5. Milling Machine	24-9-35	Missing — Counter, Index Head.
6. Milling Machine	24-9-36	Missing — Counter, Index Head.
7. Slotter	24-9-37	Missing — Tool Head, Counter, Handles.
8. Milling Machine	24-9-38	Missing — Counter, Working Table, Spindle, Universal-Joint, Index Head.
9. Drilling Machine	24-9-39	Missing — Counter, Pulley, Upper Cone, Under Cone, Cone Shaft, Bar-Belt drived, Table.

Representative of the Plant:
President: Hajime Hoshaku
Hajime Hoshaku
Dainippon Kokuki Co., Ltd.

NIIGATA PREFECTURAL GOVERNMENT

Sho No. 19 5 January 1951

TO : Chief, Tohoku Civil Affairs Region

SUBJECT: Application for Reparations Designated Machines & Equipments to be Scrapped

As an application for Reparations Designated Machines & Equipments to be scrapped has been submitted by three (3) reparations designated plants in the prefecture, i. e. Endo Kogyo Co., Ltd. (29-13), Ono Iron Works (Ono Tekko-sho) Co., Ltd., Plant No. 3 (29-15) and Niigata Sulphuric-Acid Co., Ltd., Ishiyama Plant (29-20), as per Enclosure, We wish to request your office to be good enough to gain an immediate approval to the above application.

1. As for six (6) Items placed under the application as per Enclosure, our office in charge is now identifying its fitness, despatching officials concerned to the spot.

2. After machines and equipments were authorized to be released, they will be used as scrap iron.

3. The machines and equipments placed under this application are all worn-out ones or ones partly burned out. Therefore, we believe it is most adequate to use them as scrap iron.

FOR THE GOVERNOR:

Sukeyuki Nosaka

SUKEYUKI NOSAKA
Vice Governor,
Niigata Pref. Govt. Office

Encl: 3

TO : THE GOVERNOR NIIGATA PREFECTURE

FROM : Custodian of Endo Kogyo Co., Ltd.

M. Endo

DATE : 19 Dec. 1950

FILE NO: Bai 63

SUBJECT: Application to the Scrap machine

I recognize that it is better to melt down the following burned designated reparation machines as scrap and utilije them as rew material for peace productions.

Here I submit an application pertaining the Scrap machines, please give the special attention and prompt permission for this note.

For the president
Custodian

M. Endo

Endo Kogyo Co., Ltd.

Code No. 29-13

Inventory No.	Machine name	Weight kg	Category	Remark
IA6 - 31	Lathe	1,000	2 C	Burned
IA6 - 32	"	1,000	2 C	"
IA6 - 33	"	1,000	2 C	"
IA6 - 48	"	1,250	2 C	"
Total	4 items	4,250 kgs		

For the president
Custodian

M. Endo

Ono Tekkosho, Ltd.

No. 3,770 4-chome, Irifune-cho, Niigata City.

To: Mr. Shonei Ozeda, Governor, Niigata Prefecture.

Date: 19 Dec. 1950

Subject: Application for permission to scrap down the reparations equipment.

1) Code No. and name of reparations equipment.

Cupola 1 set 29-15-IC4-1

2) Location of Reparations equipment.

No. 3 Plant, Ono Tekkosho, Ltd.
No. 3,770 4-chome, Irifune-cho, Niigata City.

3) Reparation equipment which desired to scrap down.

Inventory No.	Kind of equipment	Dimension	Quantity	Weight	Remarks
29-15-IC4-1	Cupola	Dia. 0.8 m Height 6.3 m	1	2,000 kg	

4) Reasons.

The cupola of our foundry shop which was designated as reparations equipment was so damaged and worn out by high temperature and gasses that it could be used barely by repeated repairs.

Recently, however, its conditions have became very dangerous and now we can not leave it. So, we should like to destroy it as scrap and utilize to law material.

For this cupola, we wish to constract the other new cupola at same location.

Please be kind enough to give us your prompt approval for the above and oblige.

Ono Tekkosho, Ltd.

Nakaichi Ozaki
President.

Name of Plant　　No. 3 Plant, Ono Tekkosho, Ltd.

Code No.　　29 - 15

Inventory No.	Machine Name	Weight	Category	Remarks
29 - 15 10 4 - 1	Cupola	2,000 kg	2	Superannuated and non-repairable

(Date) 20, Dec. 1950

Name of Plant : Ishiyama Plant, Niigata Ryusan Co.

Code No. : 29-20

Address : 600-4, Enoki, Niigata City

To. : Governor, Niigata Pref.

Subject : Application for Permission of Exempting Reparations Equipment from custody.

Sir,

It is requested that the undermentioned items be released from reparations custody for melt-down scrap.

Name of Items	Inventory No.	Remarks
Preheater	IA3-1	The said item is an equipment used only at the time of initially starting and closing operation of the whole plant, which has been employed since its initial installation in 1937.

In its present condition, the heat-exchanging part, especially, steel-pipes, is greatly erroded and damaged, moreover, its cast-iron part is deformed because of heat, and its furnace brick is cracked, consequently it is considered that its repairs and re-employment may be impossible.

If it be scrapped, the remaining material will consist of those mentioned below :

Raw steel	3,500 Kg.
Cast-iron	3,500 "
Brick	10,000 "
Heat-proof brick	11,000 "
Total	28,000 "

(Signature)

AKISAKU NAKAYAMA

Custodian, Ishiyama Plant,
Niigata Ryusan Co.

Akisaku Nakayama

Name of Plant : Ishiyama Plant, Niigata Ryusan Co.

Code No. : 29-20

Inv. No.	Machine Name	Weight	Category	Remarks
IA3-1	Preheater	28,000 Kg.	4	

Capt. JAMES/wmi
64-1158 Ext 433

AG 387.6( )CAS-EI

Reparations Scrap

CAS CPC/AD

1. The attached correspondence, subject as above, is forwarded for review.

2. This section concurs in the recommendation contained in the attached letter.

3. Request this section be informed of action taken.

1 Incl:
Ltr., Kyushu CAR,
dtd 29 Jan 51,
w/1 Incl (1 Cy w/d)

- W. P. S. - - - - - - - - - - - - - - - -

CA FILE COPY

3 FEB 1951

FEB Recd

F-116

B-068

KYUSHU CIVIL AFFAIRS REGION
GHQ SCAP
Fukuoka, Kyushu, Japan

MVW/ky

E 387.6

29 January 1951

SUBJECT: Reparations Scrap

TO : Chief, Civil Affairs Section
GHQ, SCAP
APO 500
ATTN: Reparations Section

Physical inspection reveals that the four (4) items listed on the attached application are of scrap value only. Therefore it is recommended that these items be released as melt down scrap.

FOR THE CHIEF:

1 Incl:
Application.

ELLSWORTH R. MOSMAN
Chief, Economics Section

Miike Dyestuff & Chemical Works,
Mitsui Chemical Industry Co., Ltd.
Omuta City, Fukuoka Pref.

TO: Headquarters, Kyushu Civil Affairs Region

FROM: Miike Dyestuff & Chemical Works,
Mitsui Chemical Industry Co., Ltd.

Date: January 24, 1951

Name of Plant: Tamana Plant

Code No.: 21 - 05

Address: 1011 Furushobara, Shimoide, Arao City, Kumamoto Pref.

The following is a list of machines which are believed to be scrap value only. It is requested that these equipment be released as melt down scrap.

1.	Name of Item	Inventory No.	Remarks
	Storage Tank	21 - 05	Made of steel. lying underground & intensely rusted
	Storage Tank	21 - 05	Made of steel. lying outdoor & intensely rusted.
	Precipitating Tank	21 - 05	Made of steel but the bottom and part of the body are intensely rusted
*	Storage Tank	21 - 05	The bottom and one side of the body are intensely rusted
	Total,	4	

* According to the authorization on Nov. 29, 1950, this item was transfered from the Tamana Plant (21-05) and is now placed in dead storage at the Dinitrochlorobenze Plant (07-35).

For the General Manager,

M. Yoshimoto

Masahiko Yoshimoto
Chief, General Affs. Dept.

Jul/2

AG 387.6( )CAS-EI Cost Report of Reparations Removal JOHANN/GCF/mo
64-1159-43

CAS CPC

1 The attached letter from Chugoku Civil Affairs Region, file CCAR 386.3, subject as above, dated 27 January 1951 is forwarded for your information.

1 Incl
Ltr, Chugoku CAR
dtd 27 Jan 51
w/1 Incl. 2 cys w/d

- W.P.S.- - - - - - - - - - - - - - - - - -

CA FILE COPY

FILE
Rec'd
2 FEB 1951
B-060
F-115

HEADQUARTERS
CHUGOKU CIVIL AFFAIRS REGION
APO 182

D/RFL/tk

CCAR 386.3 27 January 1951

SUBJECT: Cost Report of Reperations Removal

TO : Chief
Civil Affairs Section
GHQ, SCAP
APO 500

1. Reference is Operational Directive Number 11, Civil Affairs Section, GHQ, SCAP, 10 April 1950.

2. Forwarded herewith revised 'Report of Cost of Loading Reperations Equipment Aboard Ship' from plant 45-7 during the period 1 October 1949 to 3 October 1949.

3. Subject report was previously submitted and subsequently found to be in error.

1 Incl:
As indicated (in sex)

WILLIAM M. KEANE
Colonel, Arty
Chief

REVISED

REPORT OF COST OF LOADING REPARATION EQUIPMENT ABOARD SHIP

1. Code No. 45-07

2. Report Period 1 Oct. '49(Beginning), 3 Oct. '49(Ending)

3. Data of Cargo Loaded

(a) Pkge. Sizes (Met Ton)	(b) No. of Pkgs.	(c) Metric Tons	(d) Mes. Tons	(e) Rail (Registered Freight Car Tons)	(f) Vehicle [illegible]	(g) Lighter (Mes. Tons)
0 - 1.0	64	22.588	51.682			
1.1 - 2.0	2	3.197	5.469			
2.1 - 3.0	4	9.310	15.258			
3.0 - 4.0	3	10.395	100.989			
7.1 - 8.0	1	7.720	33.[illegible]69			
8.1 - 9.0	1	8.[illegible]30	4.[illegible]84			
13.1 - 14.0	1	13.[illegible]21[illegible]	21.609			
15.1 - 16.0	1	15.565	19.316			
16.1 - 17.0	1	16.480	20.639			
Total	78	106.500	273.065	106.[illegible]		[illegible].065

4. Cost of Loading cargo aboard ship:

Item	Cost (¥)
a. Operations at Warhouse and/or pier:	
Shorting within plan	"
Resorting into lighters	"
Freight for shipment	"
Loading lighters	28,855.00
Cargo for crane	"
Domurrage	"
Total	28,855.00
b. Lighterage	
Lighterage	66,600.00
Total	66,600.00
c. Stowage	
Unloading lighter	28,855.00
Checking Cargo.	"
Dunnage and lashing	"
Total	28,855.00
Grand Total	124,310.00

I certify, to my best of my knowledge and belief, that the above statement represents a true and accurate accounts of cost of loading reparations equipment aboard ships.

5 S. Katami
(Signature)

Chief of Accounting Sec.
of Fiscal Division
6 (Title) SCAP S.P.B.

ref 16

Capt. JAMES/sm
64-1158 Ext 43

AG 387.6( )CAS-EI Request for Release of Reparations Equipment (39-65)

QAS CPC/AD

1. The attached correspondence, subject as above, is forwarded for review.

2. This section concurs in the recommendation contained in the attached letter.

3. Request this section be informed of action taken.

1 Incl:
Ltr., Kanto CAR,
dtd 30 Jan 1951,
w/1 Incl (1 Cy w/d)

- W. P. S. - - - - - - - - - - - - - - - -

CA FILE COPY

2 FEB 1951
B-059

FEB Rec'd F-114

HEADQUARTERS
KANTO CIVIL AFFAIRS REGION
APO 500

JW/dp

30 JAN 1951

KEDI 387.6

SUBJECT: Request for Release of Reparations Equipment (39-65)

TO: Chief
Civil Affairs Section
General Headquarters
Supreme Commander for the Allied Powers
APO 500

1. Reference is made to inclosed memorandum, Kanto Liaison and Coordination Office, file KLO No 51-H, subject: "Request for Release from Reparations Custody of Fire Pump and Office Furnitures (39-65)," dated 18 January 1951.

2. Reference is a request for release of evaluated items.

3. Recommend approval as items are not suitable for reparations removal.

FOR THE CHIEF:

1 Incl
KLO No 51-H (in dupe)

GEO. B. NIBLOCK, Jr.
Lt Col, Infantry
Deputy Chief

KLO No. 51-H 18 January 1951

TO : Chief, Kanto Civil Affairs Region

FROM : Kanto Liaison & Coordination Office

SUBJECT : Request for Release from Reparations Custody of Fire Pump and Office Furnitures (39-65)

Transmitted herewith for your kind consideration is an application submitted by Nippon Gakki Seizo K.K., Hachiman Plant (39-65), through Shizuoka Prefectural Government, for release from reparations custody of one fire pump and office furnitures (171 items) as listed in the application.

KANTO
Liaison & Coordination Office

_____Director
Katsushiro Narita

(T. Yamaguchi, officer in charge)

Incl: As indicated

Incl 1/2

SHIZUOKA
PREFECTURAL GOVERNMENT

January 1951

TO: Chief, Headquarters, Kanto Civil Affairs Region

THRU: Kanto Liaison and Coordination Office

SUBJECT: Recommendation on Application for Release of Reparations Equipment (39-65) from Reparations Custody

1. Reference is made to letter from Nippon Gakki Seizo K.K., Hachiman-Kojo (Code No. 39-65)(Former Nippon Gakki Seizo K.K., Tokyo Seisakusho), dated 20 December 1950, subject: "Application for Release of Fire Pump & Office Furniture Equipment from Reparation Custody."

2. The applying plant was formerly located at No: 2,549, Shimogokubara, Chofu-machi, Kita-tama-gun, Tokyo-to but moved to the present location, No. 250, Nakazawa-cho, Hamamatsu-shi, by the authorization of GHQ, SCAP, dated 6 March 1950 and is being under custody and maintenance in non-operation.

3. Machinery and equipment under custody inthe above plant are as follows: 49 items inventoried by on 5/4, 42 items registered by evaluation and 2 items registered on Summary Sheet, viz. total 93 items.

The items applied for release herein are as follows: one (1) Fire Pump (evaluated) and Office Furnitures (171) registered on General Summary Sheet.

4. The fire pump needs repair for heavy damage, hereby being applied for release for the reason of being not usable.

Office furnitures (171) are desired to be used at main and branch office of the applicant (non-reparations), hereby being applied for release.

5. This letter is to recommend your approval confered on this application.

T. Okumura

TORAO OKUMURA
Chief, Commerce & Industry Dept.
Shizuoka Prefectural Government

Incl:
Application

Incl to: KLO NO. 51-H

APPLICATION FOR RELEASE OF FIRE PUMP AND OFFICE FURNITURE EQUIPMENT FROM REPARATION CUSTODY

Date: Dec. 20th, 1950.

To : Kanto Civil Affairs Regions

From: Chief Custodian, Nippon Gakki Seizo K.K., Hachiman-Kojo

Address: No.250, Nakazawa-cho, Hamamatsu, Shizuoka-ken

1. Name and Code No. of Plant:

Nippon Gakki Seizo K.K., Hachiman Kojo

Plant Code No. 39 - 65

2. Location of Plant:

No.250, Nakazawa-cho, Hamamatsu, Shizuoka-ken

Note: These equipments have been transferred from Tokyo Seisakusho (39-65) to Hachiman Kojo, Nippon Gakki Seizo K.K., Hamamatsu, by the approval, dated March 6th, 1950 of your headquarters.

3. Equipment to be released:

Evaluation Sheet No.	Inventory No.	Name	Specification	Quantity
Sheet 11 of 14 sheets	Evaluation No. 73	Fire Pump	Hand drive	1
On General Summary sheet	None	Office Furnitures	All sorts	171

Remarks: Refer to the evaluation sheet submitted from our Tokyo Seisakusho, Nippon Gakki Seizo K.K. (Code No.39-65)

4. Reason for release:

(a) Fire pump is now so defective that it is impossible to use same unless repaired.

(b) In order to meet a requirement of extending our office work, we wish to use the office furnitures freely in our head office and branches after repaired.

With this in view, it is urgently desired that your esteemed favourable consideration given to the application for release of fire pump and office furniture equipment from reparation custody.

NIPPON GAKKI SEIZO K.K.,HACHIMAN-KOJO

.....H. Aisa.....

Chief Custodian, H. Aisa

LIST OF THE EQUIPMENT TO BE RELEASED

Code No.: 39 - 65

Name of Plant: Nippon Gakki Seizo K.K.
Hachiman Kojo

Location: Shizuoka-ken

Evaluation Sheet No.	Inventory No.	Name	Specification	Quantity
Sheet 11 of 14 sheets	Evaluation No. 73	Fire Pump	Hand drive	1
On General Summary sheet	None	Office Furnitures	All sorts	171

Remarks:

Refer to the evaluation sheet submitted from our Tokyo Seisakusho, Nippon Gakki Seizo K. K. (Code No. 39 - 65)