

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination

Donkey

/Hu [Thin Copy for attaching to Report.] LONDON COPY.

Ltr. 4a.

NEWCASTLE-ON-TYNE, No. 106154

Lloyd's Register of Shipping.



Port Newcastle-on-Tyne.

9th May, 1949.

Dear Sirs,

With reference to the Survey now being held on the Steamer "EARL OF BUCHAN"

I beg to inform you that, in consequence of the condition of this vessel's Stern bush wood retaining ring

it will be my duty to recommend to the Committee that the same be renewed before the end of June, 1949.

as provided for in the Rules, extracts from which appear on the other side:—the continuance of the vessel's character in the Society's Register Book to be subject to the due fulfilment of this condition.


I am,

Yours faithfully,

Handwritten signature of the surveyor

Engineer Surveyor to Lloyd's Register.

To Messrs. R. Irvin & Co. Ltd. Fish Quay, North Shields.



© 2019 Lloyd's Register Foundation

2a.11.45

008608-008617-0102.1

before the end of June 1949.