

Length aloft ^{Feet.} 120.2 ^{Inches.} IN SHIP. || Extreme Breadth Outside ^{Feet.} 25.5 ^{Inches.} || Depth of Hold

Extract from Mr Martin's report dated August. 1864.

Called attention to a defective Plank of Ceiling in Hold, and recommended its removal. She has a Riding Keelson upon Main Keelson, both of them have vertical scarphs, and their horizontal Bolts are of Plain Iron, also called attention to Rule requiring such to be Galvanized, and to the objectionable practice of using Sawed Greenails, very frequently grain Cut & Knotty.

DUN 105-0488

	or Y.M. in Ship.	in Ship.	required per Rule		or Y.M. in Ship.	in Ship.	required per Rule	
Heel-Knee, & Deadw'd abaft	1/8		1/8	Transoms and throats of Hooks	1	Gal	1	Hold Beam } Bolts in }