

of Surveyors _____

Received from Chief Surveyors _____

NAME *Steel S.S. "SAINT FINTAN"*

Report *Js*

No. *41405*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey _____

When due _____

✱ 100. A-1. (Steel)



1 Dk (Steel) Well Deck

FPT 43L, APT 4L

BK 7", 3 BH, Cew, Plyths Av CP, Q 89' F 25' B on Q 10' Nely Off

Certificate of Classification, to be endorsed
"no bunnings not fitted," and the same
to be printed in the Register Book.

*See letter
21.10.21*



17.10.21

is concluded a webframe or other equivalent strengthening is fitted in the
machinery space and that the length of the bridge is as shown on the
plan of profile but the Surveyors should be requested to state if this is so

Js 29/10/21



© 2019

Lloyd's Register
Foundation

WT8-0179