




Catastrophic Accident During Final Launch Preparations For Safir SLV Launch at Semnan Launch Site 1

This information is time-sensitive GEINT provided to warn consumers of emerging events. Follow-on reporting may contain additional details or new information, which may change the current assessment.

(b)(1)

(b)(1)

Scorching and damage present only on northern side of launch pad



(b)(3) 50 USC 3024i

This product is not to be used as a source for derivative classification.