

Orbitus

Extract from M. Martin's Report, dated August, 1864.

Called attention to some Gunheart Trunnels lying about the Vessel for use, sawn; and although they were very well made, they did not appear to be free from sap - some seams of bottom open inside will require careful caulking with spun yarn for first thread, and a few Scarphs of Top timbers started off which required to be set close.

against Deadwood}

3/4 16

Pintles of the Rudder. ^{2 1/8} Counter 2 7/8

2 7/8 Treenails Inc

Timbering.—The Space between the Floor Timbers and Lower Foothooks is 2-3/2 Inches. The Space between the

between frames 3/4 to 1 3/8

DUN 105-0495