

AIRCRAFT ACTION REPORT

RESTRICTED
(Reclassify when filled out)

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

CONFIDENTIAL

REPORT No. 32

XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only).

- (a) Target(s) and Location(s) Kuma Shima and Shinawa Shima (b) Time Over Target(s) 0830/0815-1 (Zone)
(FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK)
- (c) Clouds Over Target Stratus - 1100 - 3/10
(BASE IN FEET, TYPE AND TENTHS OF COVER)
- (d) Visibility of Target Smoke Base (e) Visibility 10
(CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (MILES)
- (f) Bombing Tactics: Type None Bomb Sight Used _____
(LEVEL, GLIDE OR DIVE) (TYPE)
- Bombs Dropped per Run _____ Spacing _____ Altitude of Bomb Release _____
(NUMBER) (FEET) (FEET)
- (g) Number of Enemy Aircraft Hit on Ground: Destroyed 0 Probably Destroyed 0 Damaged 0

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO. A/C ATTACKING (k) SQUADRON	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO. HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
1 Warehouse, Teichian Town	-----	8 VC-91	1200 - Bds. .50 cal.	Numerous	Prob. Destroyed
2 Factory, T.A. 8666 "A" & "B"	-----	8 VC-91	1500 - Bds. .50 cal.	Numerous	Destroyed
3 Large Bldg., T.A. 8186 "B"	-----	8 VC-91	1000 - Bds. .50 cal.	Numerous	Prob. Destroyed
4 Santa Town	-----	8 VC-91	4700 - Bds. .50 cal.	Numerous	Serious
5 Motor Torpedo Boat T.A. 7370 "Y"	61' Long	1 VC-91	400 - Bds. .30 cal. 380 - Bds. .50 cal.	Numerous	Sunk
6 Truck, T.A. 7669 "U"	Medium Size	1 VC-91	100 - Bds. .50 cal.	Numerous	Serious
7 Truck, T.A. 7572 "Y"	Medium Size	1 VC-91	200 - Bds. .50 cal.	Numerous	Serious
8 Truck T.A. 7471	Medium Size	1 VC-91	200 - Bds. .50 cal.	Numerous	Serious

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

Target #1: A warehouse was strafed by incendiary bullets, caught on fire and was burning when the pilots retired.

Target #2: The mill which was strafed was completely ablaze and was razed prior to the departure of the pilots.

Target #3: A large building was set on fire and considerable smoke was noticed by the pilots coming from the building.

Target #4: Santa Town is a small ~~SETTLEMENT~~ village, and contains many small houses, the majority of which were strafed and a number of fires were started which were burning when the pilots left.

Target #5: At the ~~END~~ end of numerous strafing runs, the motor torpedo boat was well down in the water and appeared to be resting on/shallow bottom.

Each of the trucks in targets #5, #6 & #7 were thoroughly strafed and rendered inoperational. They must have been ~~AI~~ degassed because no explosions were noted, and they did not catch fire.

(p) Were Photographs Taken? Yes Photographs of Damage, When Taken, Should Be Attached By Staple.

AIRCRAFT ACTION REPORT

RESTRICTED
(Reclassify when
filled out)

CONFIDENTIAL

REPORT No. 32

XIII. MATERIAL DATA. (Comment freely on performance or suitability, following check list at left.
Use additional sheets if necessary).

ARMAMENT

- Guns, Gunsights
- Turrets
- Ammunition
- Bombs, Torpedoes
- Bomb Sights
- Bomb Releases

COMMUNICATIONS

- Radio, Radar
- Homing Devices
- Visual Signals
- Codes, Ciphers

RECOGNITION

- IFF
- Signals
- Battle Lights
- Procedures

PROTECTION

- Armor; Points and Angles of Fire Needing Further Protection
- Leak Proofing

EMERGENCY EQUIPMENT

- Parachutes
- Life Belts, Life Rafts
- Safety Belts
- Emergency Kits
- Rations, First Aid

NAVIGATIONAL EQUIPMENT

- Compasses
- Driftsights
- Octants
- Automatic Pilots
- Charts
- Field Lighting

INSTRUMENTS

- Flight
- Power Plant

OXYGEN SYSTEM

CAMOUFLAGE AND DECEPTION DEVICES

STRUCTURE

- Airframe
- Control Surfaces
- Control System
- Dive Flaps
- Landing Gear
- Heating System
- Flight Characteristics At Various Loadings

POWER PLANT

- Engines
- Engine Accessories
- Propellers
- Lubricating System
- Starters
- Exhaust Dampers

HYDRAULIC SYSTEM

ELECTRICAL SYSTEM

- Auxiliary Plant
- Lights

FUEL SYSTEM

FLIGHT CLOTHING

MAINTENANCE

BASE FACILITIES

- Plane Servicing Equipment
- Personnel Facilities

All of the trucks were rendered inoperational, but they must have been degassed because none of them either burned or exploded. There was considerable smoke NEE have over Okinawa so the pilot flew low most of the time, and started his strafing runs at 2000 feet. He strafed down to treetop levels.

No enemy planes were seen on either of the strikes and no anti-aircraft fire was encountered over any of the targets.

The first strike was composed of the following fighter pilots:

- Lt. F. M. Blanchard, Flight Leader
- Lt.(jg) J. W. Wilson
- Lt.(jg) H. L. Ofer
- Lt.(jg) H. Sunshine

- Lt. W. E. Ryan, Flight Leader
- Lt.(jg) J. C. Habbersett
- Lt.(jg) C. A. Custer
- Ens. J. M. Metzger

Lt.(jg) A. L. Smith flew the Army Air Observer and made the second strike.

None.

REPORT PREPARED BY:

APPROVED BY:

E. H. SPENCER, LT. A.C.I. OFFICER

F. M. BLANCHARD, LT., C.O.

20 April 45

SIGNATURE

RANK AND DUTY

SIGNATURE

RANK AND DUTY

DATE

A. W. PARKER, LT., A.C.I. OFFICER