

PIC-S - Report #14

KOMAKI A/F - 2662

SX15

① FUNCTION:

Combat fighter planes
Transport ~~supply~~ planes
New planes ~~tested~~ (Kagamiyama)
Flown to other fields
Better field than Kiyosu
{ Better concrete
{ Better drainage

② Surfacings

Pavement - concrete 20cm thick
Runway length - 60M wide
Remainder of field - 1200 m long
rough grass surface

③ Types of Planes

Fighters - Type 3 - ~~Type~~ } Average worst field
Ki-100 Modified Tony } Sq. under 65 - varied
± (65% or under operational at max time)

Transport - ~~old~~ ^{Sally} Type 97 (Modified bomber) - 7-9 present
Type 100 (Typical transport) on an average
Helen

New planes (To be Flown out) - 40-50 present on an average.

④ Dispersal

Within 5 sq. Km. - mostly along ^{N.S.} hwy. at east side of field.

W. side of field - blast shelters

E. side scattered along hwy.

latter more effective - but limited by nature of roads

(2 km to get ~~completely~~ ^{most widely} scattered planes in air)

Dispersed under cover
power along roads
other wise by manual
housepower - primitive
methods

Dispersed according to Type - Fighters nearby

Fuel etc. dispersed as at Kiyosu

F/A

- ①. KAWASAKI A/C Pl. - under construction about to be used
- ② Barracks
- ③ Offices Qts.
- ④ Pilots wireless Off.
- ⑤ Store houses
- ⑥ Magazine Ammo.
- ⑦ Shops
- ⑧ Garage
- ⑨ Shops + whses. - depot A/F materials
- ⑩ Doesn't belong to field (possibly A/A)
- ⑪ } Army hangars - used to bring in new
- ⑫ } planes from Kogonizakura (not used recently, no good a target)
- ⑬ Barracks
- ⑭ " (under const.)
- ⑮ A/F - Field Hdqts.
- ⑯ Off. Qts.

⑪ Bomb Damage
Roofing slams off
some damage to runway

A/A Defenses

Field expecting new A/A defenses hence new emplacements being built - no guns yet emplaced in new positions.

Electronics

Radio Beacon - Hdqts. at Komaki
Beacon on hill w. of Komaki simple direction finder
Another near Koyasu
" near Kogonizakura



65-716-UD S 110 1

3PR8M375-2

64-11-10-10

