

# ANNUAL SURVEYS.

28109

No. 431 Survey held at London Date Feb'y 11<sup>th</sup> 28<sup>th</sup> 1867  
 on the Barque Wynaud Master Wm Smith  
 Tonnage 596 Built at London When built 1854.  
 By whom built Bilbie Owners W. H. Lindall  
 Port belonging to London Destined Voyage Ceylon  
 If Surveyed Afloat or in Dry Dock "Britannia" & West India Docks.

*[Handwritten signature]*

Last Survey, No. 27450 Port of London Classed 13. A. 1.  
66

The present Condition of the

Decks <u>good</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>at the Openings</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Do Do at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Iron</u> When put on <u>1866</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

*Sighted the yellow metal sheathing. Caulked or overhauled caulking of topsides, waterway & Deck. Overhauled windlass & acc pieces to bits, and resecured them. I am of opinion she is entitled to remain as class'd Samuel's series*

Committee's Minute 5<sup>th</sup> March 1867 by M.A.S.

Character assigned 13 A 1

as class'd Samuel's series  
13. A. 1

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
Certificate (if required).

Foundation  
LON 651-0470



*March*



© 2019

Lloyd's Register  
Foundation