DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179018

c. Plant Code #32-92 (M/T) Showa Seiki KK (Rep Insp C/S, Incl 5; Plant Layout, Incl 6)

(1) Following are inspector's recommendations in allocating funds to repair and maintain buildings and machines damaged by the recent typhoon:

(a) Recommend repair of Bldgs 3 thru 7 and ~~Bldg 9.~~

(b) Number of machines stored, as compared to the number in operation, and the extent of damages to Bldgs 1, 2, 8, 10, 11 and 13 do not warrant allocation of funds.

(2) Items listed below, requested by plant to be released as scrap, were physically inspected and verified for scrap. Recommend release as melt-down scrap:

IB4-1	Power Hammer	Obsolete, uneconomical to repair
1A7-28	Horiz Milling	Major parts missing
1A7-15)	" "	Obsolete, worn, parts missing
16)	" "	uneconomical to repair
17)	" "	
1A7-8	Surface Grinder	Major parts broken
1A7-9	Vert Milling	Single purpose (drill)
1A7-12	" "	" " "

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179018

TUE	PM	
24 May WED	AM	Mr.Marks Takarazuka - Staple Food Surveillance Mr.Strollo Staple Food Program with Mr.Heinaman SCAP Osaka Mr.Chihara Nishinomiya-Amagasaki Staple Food Surveillance
25 May THU	AM	Mr. Marks Staple Food Program with Mr.Heinaman SCAP Osaka Mr. Strollo NRT meeting & joint surveillance Hyogo Mr.Chihara Staple Food Surveillance Nara
	PM	
26 May FRI	AM	Mr.Marks Staple Food Program with Mr.Heinaman SCAP Osaka Mr.Strollo Staple Food Surveillance Shiga Mr.Chihara Staple Food Surveillance Kyoto

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

M1-1e5(a) Economics

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

12 February 1951

SUBJECT: Expenditure of Funds for Building Repairs, Boki Seizo K.K., Haruki Plant, 32-28

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section Commerce and Industry Section

1. Expenditure from reparations funds of ¥175,267 for building repairs at subject plant, as recommended by your office in Inclosure 1, is approved.

2. It is requested that this headquarters be notified when the repair work is completed.

FOR THE CHIEF:

1 Incl:
Application for
building repairs,
Osaka PG

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-721

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Boki Seizo, Haruki 32-28.
Revised application
Plant already inspected.

Bldg Repairs.
Recommends approval Osaka Prf Estimate
7 ¥175,267

WHM

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179018

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date:

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant: Boki Seizo Kabushiki Kaisha Haruki plant

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

for Umajiro Yokota
YOSHIMITO MORIGUCHI
Head of 1st Commerce
Industry Section

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

Application for Maintenance Work

Jan., 1951

Kind of work Maintenance of Reparations Machines

Project Number: 32 Plant Number: 28

Plant Name : Boki Seizo Kabushiki Kaisha -- Haruki Plant

Plant Address : 1240, Haruki-cho, Kishiwada City

Description of work for which funds are requested:

Repair of Roofs

Justification for request: As Jane Typhoon raided so severely, roofs were broken in many places, and we must repair urgently to maintain the reparations machines.

Cost estimate:

	Custodian	Bureau of ~~W.I.T.I.~~ O.P.G.
Material Cost	¥ 123,300	123,300 ✓
Labour Cost	¥ 27,507	27,507 ✓
Transportation Cost	¥ 1,600	1,600 ✓
Miscellaneous Expenses	¥ 22,859	22,860 ✓
Total	¥ 175,266	175,267 ✓

Estimated by (Custodian)

S. Tsubomoto S. Tsubomoto dated Jan. 1951

Checked by (Osaka Bureau of ~~W.I.T.I.~~ O.P.G.)

Umajiro Yokota dated

Approved by Kinki Civil Affairs Region

dated

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175016

(1) Details of Wages Required:

Item		No. of Works	Unit Cost	Total	
Repairing of roofs	150 tsubo	tinner 30	¥ 538.00	¥ 16,140.00	16,140
		laborer 15	¥ 325.00	¥ 4,875.00	4,875
" of rain pipes	15 ken	tinner 1.5	¥ 538.00	¥ 807.00	807
		laborer 1.5	¥ 325.00	¥ 487.00	487
Scaffolding work		"Tobi" 10	¥ 431.00	¥ 4,310.00	4,310
Repairing of electric substation roofs	5 tsubo	tinner 1	¥ 563.00	¥ 563.00	563
		laborer 1	¥ 325.00	¥ 325.00	325
Total				¥ 27,507.00	27,507

(2) Details of Material Cost:

Item	Names of Materials	Quantity	Unit Cost	Total	
Repairing of roofs	Galvanized steel sheet #31 3 x 6	300	¥ 380.00	¥ 114,000.000	114,000
" of rain pipes	"	15	¥ 380.00	¥ 5,700.00	5,700
Scaffolding work	Material Hire for 30 pcs of log	7 days	¥ 300.00	¥ 2,100.00	2,100
Repairing of electric substation roofs	Tile	100	¥ 15.00	¥ 1,500.00	1,500
Total				¥ 123,300.00	123,300

(3) Details of fund for transportation of materials:

Name of Material	Weight	Quantity	Distance	Wagon	No. of Wagons	Cost	
Galvanized steel sheet	3,150 kg	315	Osaka - Haruki	Truck	1	¥ 1,600.00	1,600

(4) Miscellaneous Expenses:

15 % of total amount ¥ 150,019.00 X 0.15 ¥ 22,859.00 22,860

152,407

15241
7620
22861

Grand Total ..... ¥ 175,266.00 175,267

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

(5) Attached Documents:

(a) Brief Diagram 1

(b) Map of our plant 1

(6) Percentage of Non-U machines

100 %

Map of our Haruki Kojo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Sketch of the building in which reparation machine custodied.



(Red-letter shows the repair place.)

Transformer sub-station.





(Red-letter shows the repair place.)

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 1[illegible]

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

171-le5(4) Economics

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

12 February 1951

SUBJECT: Expenditure of Funds for Building Repairs, Showa Seiki Seizosho K.K., 32-92

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section Commerce and Industry Section

1. Expenditure from reparations funds of ¥18,963 for building repairs at subject plant, as recommended by your office in Inclosure 1, is approved.

2. It is requested that this headquarters be notified when the repair work is completed.

FOR THE CHIEF:

1 Incl:
Application for Maintenance, Osaka PG dtd 31 Jan 51

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-722

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Showa Seiki 32-92

Bldg Repairs

Plant 40% now operating.

Recommend approval of Osaka Pref. Estimate

of ¥18,963—

WHM

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 31 Jan 1951

To : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant; Showa Seiki Seizosho K.K.

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the Application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

YOSHIHIKO MOROZUMI
Head of 1st Commerce &
Industry Section

F O R Umajiro Takata

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Application for Maintenance Work

Kind of work Machine Manufacturing work.

Project Number : Plant Number (32-92 M/T)

Plant Name: Showa Seiki Seizosho K.K.

Plant Address: 13, 1-chome, Shintaka-Minami-dori, Higashiyodogawa-ku, Osaka.

Description of work for which funds are requested:

Damaged heavily by the last"Jane typhoon ", for the purpose of recovering and protecting the reparations machines which are kept in the works.

Justification for request:

Cost estimate:

	Custodian	O.P G.
Materials Cost	¥220,226.20	¥ 12,007 ✓
Labor Cost	¥ 99,863,30	¥ 4485 ✓
Transportation Cost	¥	¥ —
Miscellaneous Expenses	¥	¥ 2471 ✓
Total	¥320,089.50	¥ 18963 ✓

Estimated by (Custodian)

U. Nagasaka dated Dec. 2nd, 1950.

Checked by (O.P.G.

Umajiro Yokata dated 31 Jan 1951

Approved by Kinki Civil Affairs Region

_____ dated _____

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

I st Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	1.0	563.-	563.-
Rain - Pipes	0.2	538.-	107.60
Sundry Labourer	Nil		
Window glass	145 sq. m.	15.-	2,175.-
Replacement of Wooden Pillars	Nil		
		Grand Total	2,845.60

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	(Tiles	355 Pcs.	15.-	5,325.-
Rain - pipes	Galvanized steel sheets	1 sheet	280.-	280.-
Painting	Coal - tar	Nil		
Window glass	Glass	145 sq.m.	28.70	4,161.50
Replacement of Wooden Pillars	Wood Steel nails ..... Large-sizedIron nails...	300 m.m. Pcs.	38.-	114.-
		Total		9,880.50

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	.....	.....	...

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

a) Brief diagram 1

b) Map of our plant 1

(6) Stoppage 70.6 %

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

II nd. Factory.

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	0.3	563.-	168.90
Rain - Pipes	2.5	538.-	1,245.-
Sundry Labourer	0.2	513.-	102.-
Window glass	334 sq. m.	15.-	5,010.-
Replacement of Wooden Pillafs	Nil		
		GRAND Total	6,626.50

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	(Tiles	75	13.-	975.-
Rain - pipes		12 sheets	280.-	3,360.-
Painting	Coal - tar	Nil		
Window glass	glass	334 sq. m.	28.70	9,585.80
Replacement of Wooden Pillars	Wood	1 Pc.	230.-	230.-
	Steel nails	250 m.m.	38.-	95.-
	Large-sizeiron nails	....Pcs.		
		Total		14,245.80

(3) Details of Funds for Transportation of Materials:

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above (Nil)	. . .	. . .	. . .	.. .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:
a) Brief diagram

Nil

b) Map of our plant

(6) Stoppage 80 %

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

III rd. Factory.

(1) Details of Wages Required :

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	0.2	563.-	112.60
Rain - Pipes	1.0	538.-	538.-
Sundry Labourer	Nil		
Window glass	36 sq.m.	15.-	540.-
Replacement of Wooden Pillars	Nil		
		Total	1,190.60

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	15 pcs.	13.-	195.-
Rain - pipes		4	280.-	1,120.-
Painting	Nil			
Window glass	glass	36 sq. m.	28.70	1,033.20
Replacement of Wooden Pillars	Wood Steel nails Large-sizeiron	100 m.m.	38.-	38.-
		Total		2,386.20

(3) Details of Funds for Transportation of Matefials:

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	Nil	, . .	. . .	. . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:
a) Brief diagram Nil

b) Map of our plant Nil

(6) Stoppage 96.9%

------ -----------

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179818

IV th Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total	
Roofs 0.5 tubo	0.3 0.1	563.-	168.90	56 ✓
Rain-Pipes 6 Km	1.0 0.6	538.-	538.-	322 ✓
Sundty Labourer	Nil 0.8	260.-		208 ✓
Window glass Carpenter	152 sq.m. 0.1	15.- 513	2,280.-	51 ✓
Replacement of Wooden Pillars	Nil			

637 ✓

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	"Quantity	Unit Cost	Total	
Leak in the Roof	Tiles	55. 19	13.- 12	715.-	228 ✓
Rain - pipes	Galv. Iron Sheet	4 1.5	280.- 380	1,120.-	570 ✓
Window glass	glass wooden board	152 sq.m. 0.6	28.70 259	4,362.40	155 ✓
Painting	Nil				
Replacement of Wood Pillars	Wood ..... Steel nails..... Large-sized Iron	200 m.m. 100	38.- 30	76.-	30 ✓
		Total		6,273.40	983 ✓

%%%

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . . .	. . . .	. . .

(4) Miscellaneous Expences :

Nil 243

(5) Attached Documents:

Nil

(6) Stoppage 57.9 %

- - - - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

V th Factory

(1) Details of Wages Required :

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	Nil		
Rain - Pipes	0.2	538.-	107.60
Sundry Labourer	Nil		
Window glass	70 sq.m.	15.-	1,050.-
			1,157.60

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	Nil		
Rain - pipes	Galvanized steel sheet	1 sheet	280.-	280.-
Painting	Nil			
Window glass	glass	70 sq.m.	28.70	2,009.-
Replacement of Wooden Pillars		Nil		

Total 2,289.-

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	Nil	. . .	. . .	. . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents :

Nil

(6) Stoppage 72%

- - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

VI th Factory

(1) Details of Wages Required :

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	Nil		
Rain - Pipes 1.2km	0.2 0.12	538.-	107.60 64
Sundry Labourer	Nil 0.2	269	52
Window glags carpenter	0.15 83 sq.m.	513 15.-	1,245.- 76
Replacement of Wooden Pillars	Nil		
			1,352.60 192

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	Nil		
Rain - pipes	Galvanized steel sheets	0.3 ~~1~~ sheet	380 280.-	280.- 114
Painting	Nil			
Window glass	wooden boards ~~glass~~	1.5 ~~83 sq.m.~~	259 28.70	2,382.10 388
Replacement of Wooden Pillars	Wood Steel nails ..... 1 bale Large-sizedIron nails		280.-	280.- —
				2,942.10 502

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above		(Nil)	....	....

(4) Miscellaneous Expenses:

~~Nil~~ 104

(5) Attached Documents:

Nil

(6) Stoppage 95.7 %

- - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

VII th Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	Nil		
Rain - Pipes 2.5Km	8.4 0.25	538.-	215.20 134
Sundry Labourer	0.4 3.0 in total	20	1,589.- 104
Window glass carpenter	0.12 136 sq.m.	5-13 15.-	2,040.- 61
Replacement of Wooden Pillars	Nil	. . . .	. . . .
		Total	3,844.20 299

(2) Dejails of Material Cost :

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	. . .	. . .	. . .	
Rain - pipes	galvanized stal sheet	2 0.6	280 280.-	560.- 228
Painting	Nil			
Window glass	wooden boards glass	1.2 136 sq.m.	25-8 28.70	3,903.20 290
Replacement of Wooden Pillars	Wood	3 pcs.	120.-	360.-
	Steel nails	300 m.m.	38.-	114.-
	Large sizedIron	Nil		
	Cement	3 Bales	280.-	840.-
			Total	5,777.20 415

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	Nil			

(4) Miscellaneous Expenses: 122

Nil

(5) Attached Documents:

Nil

(6) Stoppage 70.6 %

- - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

VIII th Factory

(1) Details of Wages Required :

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	8.0	563.-	4,504.-
Rain - Pipes	3.0	538.-	1,614.-
Sundry Labourer	13	in total	4,594.-
Window glass	121 sq.m.	15.-	1,815.-
Replacement of Wooden Pillars	Nil		
			12,527.-

(2) Dejails of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	950	15.-	14,250.-
Rain - pipes		15	280.-	4,200.-
Painting	Nil			
Window glass	Glass	121 sq.m.	28.70	3,472.70
Replacement of Wooden Pillars	Wood			
	Steel nails.....	1,300 m.m.	38.-	494.-
	Large-sized Iron	Nil		
	cement	28 bales	280.-	7,840.-
		Total		30,256.70

(3) Details of Funds for Transportation of Materials:

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	.....	....	...

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

Nil

(6) Stoppage 63.6 %

- - - - - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

IX th Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	1.0	563.-	563.-
Rain - Pipes	2.0	538.-	1,076.-
Sundy Labourer	10	- 15.-	3,959.-
Window glass	14 sq.m.	15.-	210.-
Replacement of Wooden Pillars	Nil		
		Total . . .	6,908.-

(2) Details of Material Cost:

Kind of Repairing	Number of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	22	350.-	7,700.-
Rain - pipes		1	280.-	280.-
Painting	Nil	. . .	. . .	. . .
Window Glass 8	glass	14 sq. in.	28.70	401.80
Replacement of Wooden Pillars	Wood			
	Steel nails	450 m.m.	38.-	161.-
	Cement	15 bales	280.-	4,200.-
		Total		12,742.80

(3) Details of Funds for Transportation of Materials:

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . .	. . . .	. . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

Nil

(6) Stoppage 82.6 %

- - - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

X th Factory

1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	4.0	563.-	2,252.-
Rain - Pipes	1.0	538.-	538.-
Sundry Labourer	23	(Total)	11,357.-
Window glass	147 sq.m.	3.40	499.80
Replacement of Wooden Pillars	25.0	513.-	12,825.-
			27,471.80

(2) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	450	15.-	6,750.-
Rain - pipes		4	280.-	1,120.-
Painting	Nil	. . .	. . .	. . .
Window glass	Glass	147 sq.m.	28.70	4,218.90
Replacement of Wooden Pillars	Wood	In total		29,800.-
	Steel nail	2,300 m.m.	38.-	847.-
	Large-sized Iron	. . . .		
	Cement	3 bales	280.-	840.-
				43,575.90

(3) Details of Funds for Transportation of Materials:

Name of Materials	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . . .	. . . .	. . . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:
a) Brief diagram

b) Map of our plant

(6) Stoppage 33.3 %

- - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

XI th Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	4.0	563.-	2,252.-
Rain - Pipes	0.6	538.-	322.80
Sundry Labourer	. . .	Nil .	. . .
Window glass	23 sq.m.	3.40	78.20
Replacement of Wooden Pillars	Nil	. . .	. . .
			2,653.-

(2) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Tiles	280	15.-	4,200.-
Rain - pipes		2	280.-	560.-
Painting	Nil	. ..	. ...	. . .
Window glass	glass	23.sq.m.	28.70	660.10
Replacement of Wooden Pillars	Wood	- - - -	- - -	- - -
	Steel nails	150 m.m.	38.-	57.-
	Large-size Iron	- - - -	- - -	- - -
				5,477.10

(3) Details of Funds for Transportation of Materials:

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	- - - - - -	- - - -	- - -

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

a) Brief diagram

Nil

b) Map of our plant

(6) Stoppage 0%

- - - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

XII Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	Nil	. . . .	. . . .
Rain - Pipes	1.0	538.-	538.-
Sundry Labourer	Nil	. . . .	. . .
Window glass	55 sq.m.	3,40	187.-
Replacement of Wooden Pillars	Nil	. . .	. . . .

(2) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity.	Unit Cost	Total
Leak in the Roof	. . . . .	Nil	. . . .	. . .
Rain - pipes		3	280.-	840.-
Painting	Nil	. . . .	. . .	. . .
Window glass	glass	55 sq.m.	28.70	1,578.50
Replacement of Wooden Pillars	Wood . . . . . Nil Steel nails . . . . . Nil Large-size Iron . . . . Nil			
				2,418.50

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . . .	. . . .	. . . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

a) Brief diagram

b) Map of our plant

(6) Stoppage 50%

- - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

XIII Factory

(1) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	1.5	563.-	824.50
Rain - Pipes	2.0	538.-	1,076.-
Sundry Labourer	2.0	538.-	1,076.-
Replacement of Wooden Pillars	Nil	. . . .	. . . .
			4,046,50

(2) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof		135 pcs.	13.-	1,755.-
Rain - Pipes		7	280.-	1,960.-
Painting	Nil	. . . . .	. . . .	. . . .
Window glass	glass	70 sq.m.	28.70	2,009.-
Replacement of Wooden Pillars	Wood	. . . . .	. . . .	. . .
	Steel nails	. . . .	. . . .	. . .
	Large- sized Iron	. . .	. . . .	. . .
	Cement	3 bales	280.-	840.-
				6,564.-

(3) Details of Funds for Transportation of Materials :

Name of Material	weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . . .	. . .	. ..

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:

a) Brief diagram Nil

b) Map of our plant

(6) Stoppage 100 %

- - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

XIV Wooden Fence

(1) Details of Wages Required :

Kind of Repairing	Number of Work	Unit Cost	Total
Roofs	Nil	. . . .	. . .
Rain - Pipes	Nil	. . .	. . .
Sundry Labourer	Nil	. . .	. . .
Window glass	Nil	. . .	. . .
Replacement of wooden Pillars	Nil	. . .	. . .

(2) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total
Leak in the Roof	Nil	. . .	. . .	. . .
Rain Pipes	Nil	. . .	. . .	. . .
Painting	Nil	. . .	. . .	. . .
Window glass	Nil	. . .	. . .	. . .
Replacement of Wooden Pillars	Woode	in total		68,210.-
	Steel nails	10,000 m/m.	380.-	3,800.-
	Large-sized Iron	- - - - -	- - -	- - - - -
	Cement	12 bales	280.-	3,360.-
			Total	75,370.-

(3) Details of Funds for Transportation of Materials:

Name of Material	Weight	Number of Wagons	Unit Cost	Total
As total in (2) above	(Nil)	. . . .	. . . .	. . . .

(4) Miscellaneous Expenses:

Nil

(5) Attached Documents:
a) Brief diagram
b) Map of our plant

Nil

(6) Stoppage 70.5 %

- - - - - - - - - - - - - - - -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

株式会社昭和精機製造所 工場配置図



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

M11-1e5(2)

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Building Repairs and Maintenance of Equipment, Futaba Kikai, K.K., 32-101

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section of Commerce and Industry Dept.

1. Expenditure from reparations funds of ¥102,249 for building repairs and ¥35,055 for the maintenance of 60 items of reparations equipment at subject plant, as recommended by your office in Inclosures 1 and 2, respectively, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

2 Incls:
Applications, Osaka Pref Gov't
dtd 31 Jan 51
1-Building repairs
2-Maintenance

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-715

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

Futaba Kikai 32-101.

Maintenance

Surface cleaning 53 items 5336 points.

Partial overhauling 7 " 1120 "

60 " 6456 "

Labor:

Surface cleaning $\frac{5336}{200}$ = 27 mens.

Partial overhauling $\frac{1126}{100}$ = 11 "

38 men @ 480 18,240

Materials $\frac{6456}{100}$ = 66 @ 256 16,896.

Misc. Exp. 66 @ 4- 264

¥35,400

Recommend approval of Osaka Pref. estimate ¥35,055—

Bldg Repairs

Recommend approval of Osaka Pref. estimate ¥102,249—

Total recommended for approval ¥137,304—

WHM

6 Feb 1951

Mr. Frazee, ¥137,304 recommended for 32-101

JEH

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 31 January 1951

To : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

Futaba Kikai K.K.

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the Application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

~~YOSHIHIKO MOMOZUKI~~
For Head of 1st Commerce & Industry Section
Takaji Kono

Incl #1

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

Application for Maintenance Works

Kind of Works; Repâir of Buildings Code No.; 32-101

Project No.;

Plant Name; Futaba Kikai K.K.

Plant Address; 34 2-chome Takaida-naka Fuse-city Osaka

Description of work for which funds are requested;

Our plant was inflicted by Jane Typhoon on buildings in which the Designated Reparations machines were located. as follows we suffered much damage, we should repairing buildings destroyed.

Justification for request;

3 rd Machine Shop(3rd Tokki Kojo) inclined by Typhoon, is to be reinforced and other buildings are to be repaired.

Cost estimate	Custodian	O.P.G.
Material Cost	¥.502,438.80	¥. 65,186.-
Labor Cost	¥.160,596	¥. 22,167.-
Transportation Cost	¥.35,000	¥. 1,600.-
Miscellaneous Expences	¥.23,905	¥. 13,336.-
Total................	¥.721,939.80	¥. 102,249.-

Estimated by (custodian)

K. Moriya dated 25 Dec., 1950

Checked (O.P.G.)

T. Kono dated 31 January 1951

Approved by Kinki Civil Affairs Region)

__________ dated __________

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 770016

(1) Detail of Wages Required

Kind of Repairing	Name of Work man	No. of Works	Unit Cost	Cost	Checked by O.P.G.
a. 1st Shop					
Roofing	Roof-repairing man	~~8~~ 1	Y.563	Y.1.689	563.—
Inner repairing	Sundry labourer Carpenter	8 1	Y.~~513~~ 325	~~Y.4.~~104	325.—
"	Day-labour	8	Y.431	Y.3.448	
"	Handy-man	7	Y.238	Y.1.666	
Water-piping	Tinner	25	Y.538	Y.13.450	
Window-glass repairing	Glass-repairing man	3	Y.500	Y.1.500	
Total.....				Y.25.857	888.—
b. 2nd Machine Shop					
Roofing	Roof-repairing ma n	1	Y.563	Y.563	563.—
Inner repairing	Carpenter	3	Y.513	Y.1.539	1,539.—
"	Day-labour	3	Y.431	Y.1.293	
"	Handy-man	~~5~~ 3	Y.~~238~~ 260	Y.1.190	780.—
Water-piping	Tinner	25 45	Y.538	Y.13.450	2421.
Window glass	Sundry labourer Glass-repairing man	4.5 5	325 Y.500	Y.2.500	1462.—
Boarding	Carpenter	0.1	513		51
repairing	Sundry labourer	0.1	325		32
Total.....				Y.20.535	6,848.—
c. 3rd Special Machine Shop					
Reincorcing for falling down	Cappehter	~~50~~ 10	Y.513	Y.25.650	5,130.—
"	Day-labour	30	Y.431	Y.12.930	
"	Handy-man	~~50~~ 10	325 Y.~~238~~	Y.14.280	3,250.—
Roofing	Roof-repairing man	4 4	Y.563	Y.2.252	2,252.—
~~Repairing for~~	Sundry labourer ~~Plasterer~~	10 4	325 Y.~~538~~	Y.5.380	1,300.—
~~wall~~ & roof					
Water piping	18 km Tinner	~~35~~ 2	Y.538	Y.18.830	1,076.—
Window-glass repairing	Sundry labourer Glass-repairing man	2 5	325 Y.500	Y.2.500	650.—
Total.....				Y.81.822	13,658.—
d. Heat treating Shop					
~~Roofing repairing~~	~~Cappenter~~	~~3~~	~~Y.513~~	~~Y.1.539~~	
~~Roofing~~	~~Tinner~~	~~7~~	~~Y.538~~	~~Y.3.766~~	
~~Roof & Inner repairing~~	~~Day labour~~	~~2~~	~~Y.431~~	~~Y.862~~	
~~"~~	~~Handy man~~	~~5~~	~~Y.238~~	~~Y.1.190~~	
~~Window-glass repairing~~	~~Glass-repair-ing man~~	~~4~~	~~Y.500~~	~~Y.2.000~~	
~~Total.....~~				~~Y.9.357~~	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

e. Cast Iron Shop

Roofing	Roof-repairing man	10	Y.563	Y.5.630
Inner repairing	Carpenter	3	Y.513	Y.1.539
"	Day labour	5	Y.431	Y.2.155
Wall repairing	Handy-man	15	Y.238	Y.3.570
"	Plasterer	10	Y.538	Y.5.380
Window-glass repairing	Glass-repairing man	8	¥.500	¥.4.000
Total...........				¥.22.274

f. Wall & fence repairing

Fence repairing	Carpenter	1	¥.513	¥.513	513.–
"	Handy man	1	-Y.238 260	¥.238	260.–
Total...........				¥.751	773.–

Grand Total......... ¥.160.596 22,167.–

(2) Details of Materials Cost

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Cost	Checked by O.P.G.
a. 1 st Shop					
Roofing	Waved slate	18 sheet 21.5"tubo"	¥.900 400	¥.19.350	7,200.–
"	"Mune" slate	35"Ken"	¥.450	¥.16.200	
"	Wood	5 "koku"	¥.1.560	¥.7.800	
"	Nail	30 kgs	¥.40	¥.1.200	
Water-piping	Galvanized -steel	50 sheets	¥.380.	¥.19.000	
Window	Plate -glass	85 ft	¥.32	¥.2.720	
Other	Nail	16 "kan"	¥.30	¥.4.800	
Total............				¥.71.070	7,200.–
b. 2 nd Special Machine Shop					
Roofing	Waved slate	14 sheet 5.5 "tubo"	¥.900 400	¥.4.950	5,600.–
"	"mune" slate	35 10Ken "Ken"	¥.450	¥.15.750	¥500.–
"	Wood	3 "Koku"	¥.2.400	¥.7.200	
"	Nail	10 22 kgs	¥.40 55	¥.400	121.–
Water piping	Galva. steel	50 23 sheets	¥.380	¥.19.000	8,740.–
Roof-repaing	Nail	16 "kan"	¥.300	¥.4.800	345.–
Window / Boarding 1 stuhu	Plate-glass / Cryptomeria board	120 ft / 0.144 Koku	¥.32 2400	¥.3.840	
Total..........				¥.55.940	19,306.–
c. 3 rd Special Machine Shop					
Reinforcing for falling down	Wood	55.1 "koku" 2 koku	¥.1.500	¥.82.650	3,000.–
"	Iron frame	0.5 tons	¥.150.000	¥.75.000	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. ________

c. 3 rd Special Machine Shop (continued)

Reinforcing for falling down	Wire netting	300 kgs	¥.60	¥.18.000	
~~"~~	~~Nail~~	~~32"kan"~~	~~¥.300~~	~~¥.9.000~~	
~~"~~	~~Sand~~	~~3 "tubo"~~	~~¥.3.500~~	~~¥.10.500~~	
~~"~~	~~River sand~~	~~4"tubo"~~	~~¥.3.000~~	~~¥.12.000~~	
~~"~~	~~Cement~~	~~120 kgs~~	~~¥.280~~	~~¥.33.600~~	
Roofing	nail	~~30~~ 10 kgs	¥.~~40~~ 55	¥.1.200	550.-
"	Waved slate	~~26 "tubo"~~ 65 sheet	¥.~~900~~ 400.	¥.23.400	26,000.-
"	"mune" slate	~~19 "ken"~~ 5 ken	¥.450	¥.8.550	3,250.-
"	Galva. steel	~~70~~ 18 sheets	¥.380	¥.29.600	6,840.-
Window	Plate glass	784 ft	¥.32	¥.2.508.80	
Total............				¥.306.608.80	36,640.-

d. Heat treating Shop

Roofing	Galva.steel	35 sheets	¥.380	¥.13.300
Ridge of roof	"	6 "	¥. "	¥.2.280
Inner repairing	Wood	5 "koku"	¥.1.500	¥.7.500
"	Nail	8 "kan"	¥.300	¥.2.400
Window	Plate glass	70 ft	¥.32	¥.2.240
Total.........				¥.27.720

e. Cast Iron Shop

Roofing	Japanese slate	1.500 sheets	¥.15	¥.22.500
Wall repairing	Cement	500 kgs	¥.280	¥.2.800
"	Sand	150"tubo"	¥.160	¥.2.400
Window	Plate glass	250 ft	¥.32	¥.8.000
Total.........				¥.35.700

f. Fence-repaing

Fence-repairing	Wood	3 "koku"	¥.1.500	¥.4.500
"	Veneer	2 "tubo"	¥.450	¥.900
Total...........				¥.5.400

Grand total.......... ¥.502.438.80

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 770016

(3) Details of Funds for Transportation of Materials:

Kind of Materials	Weight	No. of wagons	Unit cost	Cost	Checked by O.P.G.
Slate	7 tons 99 sheet	2	3,200. ¥.2.500	¥.5.000	
Wood	13 tons 2,144 kalon	1	¥.2.500	¥.10.000	
~~Sand~~ Gravel	~~31 tons~~	5	¥.3.000	¥.15.000	1,600
~~Cement~~	~~4 tons~~ 12 kg	1	¥.2.500	¥.2.500	
Galva.steel	3 tons 4 sheet	1	¥.2.500	¥.2.500	
Total.....				¥.35.000	1,600.-

½

(4) Miscellaneous Expenses..... ¥.23.905 / 2,336.-

(5) Attached Documents
Map of our plant.....1

(6) Percentage of Non-U Machines; 86 o/o

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Name of Structure	sq. m.	
office Bilding	343	205
Finishing Fabrication	679	800
Machinery shop	696	763
Dining hall	198	000
Casting shop	679	831
Reseach	108	900
Heat Treatment sh.	237	600
Special machinery.	635	151
Warehouse & Storage	173	250
Dormitory	219	999
Annealing Furnase	19	800
Dormitory	115	894
Bath	14	830
W.C. s	21	264
Total.	4,147	307





DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 770010

Futaba Machine Tool Co. Ltd.

Scale 1/500
Site 7.782 sq.m.
Bldgs. 4.109 sq.m.



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 3 January 1951

To : Eq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant;

Futaba Kikai K.K

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPO/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

YOSHIHIRO HORIGUCHI
Head of 1st Commerce
Industry Section

For Takaji Kono

Incl #2

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

Application for Maintenance Reparation Machines

Kind of work Machine Tools

Project No, Plant No. 32-101

Plant Name; Futaba Kikai K.K.

Plant Address; 34 Naka 2-chome Takaida Fuse-city

Description of work for which funds are requested;

Machines in our plant was inflicted by Jane Typhoon on buildings in which the Designated Reparations one located, are to be repaired.

Justification for request;

Machines which dameged much by the rain, areto be break up, and other machines which became rusty, are to be greesing.

Cost Estimate;

	Custodian	M.I.T. Bureau of MIt
Materials Cost	¥ 18,370.20	¥ 16,558.–
Labor Cost	¥ 32,912.00	¥ 18,240.–
Miscellaneous Cost	¥ 287.04	¥ 257.–
Total	¥ 51,569.24	¥ 35,055.–

Estimated by (custodian)

K Muniga dated 25 ~~Sept~~ Dec, 1950

Checked by (osaka Bureau of M.I.T.I.)

T. Kono dated 31 January 1951

Approved by Kinki Civil Affairs Region

______________ dated ______

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179818

BASE FOR COST ESTIMATE

1. Number of machines applied;

80 sets

2. Total No. of point of machines applied for;

	Number	Point
4 man hours	50	3,716
8 man hours	23	2,340
32 man hours	7	1,120

3. percentage of non- U machines; 86 o/o

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

1. Detail of wage

Kind of work	No. of Item		Point	Number of workers	Unit Cost	Total	Checked by O.A.G.
	13	3,356	Cleaner	26.8	480		
Surface cleaning	50	~~3.716~~	~~Engineer-man~~	~~12.4~~	~~Y450~~	~~Y5.580~~	12,864
	"	"	~~Miscellaneous-service~~	~~6.2~~	~~Y238~~	~~Y1.475~~60	
Partial	23	2.340	~~Engineer-man~~	~~16.6~~	~~Y450~~	~~Y7.020~~	
overhauling	"	"	~~Miscel. service~~	~~7.8~~	~~Y238~~	~~Y.1.856~~40	
	7	1.120	~~Engineer-man~~	~~29.8~~	~~Y450~~	~~Y13.410~~	
Overhauling	"	"	~~Miscell.service~~	~~15~~	~~Y.238~~	~~Y3.570~~	
			cleaner	11.2	480		5376
	Total:				¥ 32.918		18,240

2. Detail of material cost

Kind of work	Name of Material	Quantity	Unit Cost	Total	Checked by O.A.G.
Surface cleaning	Kerosene	53.5 37.16 litre	Y16.35	Y.607.57	874
	Machine oil	53.5	Y55.59	Y.2.065.72	2,974
	Grease	~~58.16~~ kgs	Y.114.08	Y.4.239.21	6,103
	Waste	~~53.74~~ kgs	Y.47.13	Y.1.751.35	2521
	Soap & etc.		Y.22.85	Y.849.11	1,222
~~Partial overhauling~~	~~Kerosene~~	~~23.4 litre~~	~~Y.16.35~~	~~Y. 382.59~~	
	~~Machine oil~~	~~"~~	~~Y.55.59~~	~~Y.1.300.80~~	
	~~Grease~~	~~23.4 kgs~~	~~Y.114.08~~	~~Y.2.669.47~~	
	~~Waste~~	~~35.1 kgs~~	~~Y.47.13~~	~~Y.1.102.89~~	
	~~Soap & etc.~~		~~Y.22.85~~	~~Y.534.69~~	
~~Overhauling~~ Partial overhauling	Kerosene	11.2 litre	Y.16.35	Y.183.12	183
	Machine oil	"	Y.55.59	Y.622.61	622
	Grease	11.2 kgs	Y.114.08	Y.1.277.69	1,277
	Waste	16.8 kgs	Y.47.13	Y.527.86	527
	Soap & etc.		Y.22.85	Y.255.92	255
	Total:			¥ 18.370.60	16,558 ~~14,240~~

3. Miscellaneous expenses

Kind of work	Kind of expenses	Quantity	Unit Cost	Total	Checked by O.A.G.
Surface cleaning	Catching	5,35 ~~3.716~~ point	Y350	Y.130.06	187
	Papers	3.716 " 53.5	Y 50	Y.18	26
~~Partial overhauling~~	~~Catching~~	~~2.340 point~~	~~Y350~~	~~Y.81.90~~	
	~~Papers~~	~~" "~~	~~Y 50~~	~~Y.11.70~~	
Overhauling Partial overhauling	Catching	1.120 point	Y350	Y.39.20	39
	Papers	" "	Y.50	Y.5.60	5
	Total:			¥ 287.04	257

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

M1-1e5(a)

Economics

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Building Repairs and Maintenance of Equipment, at Tanaka Spoke K.K., Sakai Kojo, 32-77

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section Commerce and Industry Department

1. Expenditure from reparations funds of ¥36,910 for building repairs and ¥72,912 for surface cleaning and greasing of 230 items of reparations equipment at subject plant, as recommended by your office in Inclosures 1 and 2, respectively, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

2 Incls:
Applications, Osaka Pref Gov't
dtd 29 Jan 51
1-Building repair
2-Maintenance

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-714

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Tanaka Spoke K.K. Sakai 32-77

Maintenance:-

Surface cleaning 230 items 15,040 points.

Labor:-

Surface cleaning	$\frac{15040}{200}$ = 75 men @ 480		36,000.
Materials	$\frac{15040}{100}$ = 150 @ 256-		38,400.
Misc. Exp.	150 @ 4-		600
			¥ 75,000

Recommend approval of Osaka Pref estimate of ¥ 72,912-

Repairs of Bldg.

Recommend approval of Osaka Pref. estimate of ¥ 36,910-.

Total amount recommended for approval

¥109,822

WHK

6 File 51

Mr. Frazee,

¥ 109,822 recommended for 32-77 as listed above.

JEH

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 29. Jun 1951.

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

1. Attached herewith is the subject application submitted by Tanaka Spoke K.K. Sakai Kojo

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

YOSHIHIKO MIZOZUMI
Head of 1st Commerce & Industry Section

Incl #7

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

Application for Maintenance Work

Kind of work Repairing of building and wall

Project Number: 32 Plant Number: 77

Plant Name : Tanaka Spoke K.K. Sakai Kojo

Plant Address : 200, Naka-2-cho, Hamadera, Ishizu-cho, Sakai-shi

Description of Work for which funds are requested:

1. Repairing of Leak in the Roof, wall and door of custodial building
2. Repairing of factory wall

Justification for request:

Jaine Typhoon crashed our building, so factory buildings and wall were damaged. Custody of Repairing Machines were hindered the above mentioned.

Cost estimate :	Custodian	O.P.G.
Material Cost	¥ 366,600	¥ 21,240
Labor Cost	¥ 182,720	¥ 10,056
Transportation Cost	¥ 16,000	¥ 800
Miscellaneous Expenses	¥ -	¥ 4,814
Total.....	¥565,320	¥ 36,910

Estimated by (custodian) Toshikazu Tanaka

T. Tanaka dated Nov. 30/50

Checked by (O.P.G.)

[illegible] dated

Approved by Kinki Civil Affairs Region

dated

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

1/ [illegible]

(1) Details of Wages Required: 1. Custodial factory

Kind of Repairing		No. of Work	Unit Cost	Total	%	O.P.G.
Roofs	90 tubo Roofs	~~50~~ 12	~~663~~ ¥513	¥28,150	100	6.156
	Sundry Labourer	~~50~~ 12	~~238~~ 325	11,900		
~~Miscellaneous~~	~~Carpenter~~	~~50~~	~~513~~	~~25,650~~		3.900
	~~Tinner~~	~~50~~	~~538~~	~~26,900~~		
	Grand Total			92,600		¥ 10.056

2. Factory Wall (78%)

Kind of Repairing	Length	No. of Work	Unit Cost	Total	O.P.G.
Repairing of Wall			¥513		
Carpenter	1,000m.	120		61,560	
Sundry Labourer		120	238	28,560	
	Grand Total			90,120	

(2) Details of Material Cost:

1, Custodial factory (100%)

Kind of Repairing	tsubo	Name of Material	Quantity	Unit	Total	O.P.G.
Roof	45 tubo (new slate)	Slate	~~200 tsubo~~ 1350 sheets	~~¥900~~ ¥15.-	~~¥180,000~~	¥20.250
~~Miscellaneous~~	199	~~Galvanized Steel Sheets~~	~~50 sheets~~	~~380~~	~~19,000~~	
			~~200 kgs.~~	280	56,000	
	45 tubo (old slate)	Cement nail	18 kg.	¥55.-		¥ 990
		Grand Total			¥255,000	¥21.240

2. Factory Wall (78%)

Kind of Repairing	Length	Name of Material	Quantity	Unit	Total	O.P.G.
Repairing of Wall	1,000m.	Cryptomeria square timber	20koku	1,560	31,200	
		Cryptomeria board	30koku	2,400	72,000	
		Cement	1,500kgs.	280	8,400	
		Total			111,600	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

(3) Details of Funds for Transportation of Materials:

1. Custodial factory(100%)

Name of Material	Quantity	Length	No. of Wagons	Unit	Total	O.P.G.
Slate	~~200tsubo~~ 45 tabo					
~~Galvanized~~		~~5,000m.~~	~~3~~ 4	~~¥2,000~~ ¥3.200	¥6,000	¥800
~~Steel Sheets~~	~~50 sheets~~					
~~Cement~~	~~200 kgs.~~					
nail	28Kg					

Total ¥6,000 ¥800.

2. Factory Wall (78%)

Name of Material	Quantity	Length	No. of Wagons	Unit	Total	O.P.G.
~~Cryptomeria square timber~~	~~20koku~~	~~5,000m.~~	~~5~~	~~¥2,000~~	~~¥10,000~~	
~~Cryptomeria board~~	~~30koku~~					
~~Cement~~	~~1,500kgs.~~					

Total ¥10,000

miscellaneous Expenses ¥4.814.—

Tanaka Spoke K.K. Sakai Kojo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 29. Jun 1951

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

1. Attached herewith is the subject application submitted by

Tanaka Spoke K.K. Sakai Kojo

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

[signature]
YOSHIHIKO [illegible]
Head of 1st Commerce & Industry Section

Incl #2

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Application for Maintenance Work

Kind of work Surface Maintenance Work

Project Number: 32 Plant Number: 77

Plant Name: Tanaka Spoke K.K. Sakai Kojo

Plant Address: 200, Naka-2-cho, Hamadera, Ishizu-cho, Sakai-shi

Description of Work for which funds are required:

Surface maintenance work of Repairing Machines

Justification for request:

Jaine Typhoon crashed our building, Repairing Machines were damaged by rain or sand.

Cost estimate:

	Custodian	O.P.G.
Materials Cost	¥ 38,928	¥ 36.312
Labor Cost	¥36,288	¥ 36.000
Transportation Cost	¥ --	¥ /
Miscellaneous Expenses	¥ 600	¥ 600
Total..................	¥ 75,816	¥ 172.912

Estimated by (custodian)

Toshikazu Tanaka

T. Tanaka dated Nov. 30 /50

Checked by (O.P.G.) [signature] dated Jan. 29. 1951.

Approved by Kinki Civil Affairs Region

_______________ Dated _______________

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

BASE FOR COST ESTIMATE

1. Number of the machines applied for:

~~239~~ 230 sets

2. Total No. of Point of machines applied for:

	Number	Point
4 man hours:	~~239~~ 230	~~15,120~~ 15.040
8 man hours:	-	-
32 man hours:	-	-

3. Percentage of Non-U machines: 78%

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 750016

(1) Number of Machines:

Kind of Machines	Name of Machine	Number	Point	Type Number	Point	Just. for Requ
Surface Maintenance Work	Lathe	157		10,760		
	Drilling	40				
	Milling	8		1,220		
	Shaper	14		810		
	Gear Cutting	5		1,400		
	~~Motor~~	~~7~~		500		
	Grinder	5		~~65~~		
	~~Compressor~~	~~1~~		210		
	Hammer	1		~~10~~		
	~~Marking~~	~~1~~		100		
				~~40~~		
	Grand Total	~~280~~ 230		~~15,120~~ 15,040		

(2) Details of Wages Required:

Kind of Repairing	Number of Work	Unit Cost	Total
Surface Maintenance Work	~~76.6~~ 75	480	~~¥36,288~~ 36,000

(3) Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total	O.P.G.
Surface Maintenance Work	Washing Oil	150 litre	¥16.35	¥2,453	2,452
	Machine Oil	150 "	55.59	8,339	8.338
	Grease	150 ~~160~~ kgs.	114.08	18,253	17.112
	Rag	150 ~~500~~ kgs.	47.13	9,426	8.068
	Soap and Other	~~20~~	22.85	~~478~~ 457	342
	Total			¥38,928	36,312

(4) Details of Funds for Transportation of Materials: ---

(5) Miscellaneous Expenses:

Kind of Repairing	Quality	Quantity	UnitCost	Total	O.P.G.
Surface Maintenance Work	Technical Leading Cost	150	¥3.50	¥525	
	Paper	150	¥50	75	
	Total			¥600	600

(5) Percentage of Non-U machines: 78%

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

MI-1es(a)

JEH/at

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Building and Fence Repairs and Maintenance of Equipment, Taihei Kogyo K.K., Kishiwada Plant, 32-02

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section of Commerce and Industry Dept.

1. Expenditure from reparations funds of ¥169,810 for building repairs, ¥24,529 for fence repairs, and ¥122,600 for the surface cleaning and greasing of 209 items of reparations equipment at subject plant, as recommended by your office in Inclosures 1, 2, and 3, respectively, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

STERLIN C. MOORE
Major Infantry
Deputy Chief

3 Incls:
Applications, Osaka Pref
1-Building repair
2-Fence repair
3-Maintenance

0-713

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 770010

Taihei Kogyo, Kishiwada 32-2.

Maintenance

Surface cleaning 209 items 24,520 feet.

Labor.	$\frac{24520}{200}$ = 123. men @ 480.		59,040
Material	$\frac{24520}{100}$ = 245 @ 256		62,720.
Misc Exp.	245 @ 4 -		980
			¥122,740

Recommend approval Osaka Pref Estimate ¥ 122,600

Repair Fence.

Recommend approval Osaka Pref Estimate of ¥ 24,529 -

Bldg Repair Recommend approval Osaka Pref estimate ¥169,810

Total recommended for approval ¥ 316,939 -

WHM

¥ 316,939 6 Feb 51

Mr. Frazee, ~~¥ 147,129~~ recommended for 32-02

JEH

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 770016

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date :

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

Incl #1

For

YOSHIHIKO MOROZUMI
Head of 1st Commerce &
Industry Section
Takaji Kono

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

Application for Maintenance Work

Kind of work   Repair of Building of the Reparation Plant

Project Number: Plant Number 32 - 2

Plant Name : Taihei Kogyo K.K. Kishiwada Kojo

Plant Address : 707 Shimono-cho, Kishiwada-shi

Description of work for which funds are requested:

Repair of the roofs, the rain-pipes, the windows and the electric wires.

Justification of request:

The many parts of the roofs, the rain-pipes, the windows and the electric wires of the buildings in which the reparations equipments are being located, habe been damaged due to the last Jane Typhoon, and the said damaged parts must be repaired promptly because of keeping those designated reparations items in good conditions.

Cost estimate:

	Custodian	O. P. G.
Materials Cost	¥ 385,080	¥ 128.800 ✓
Labor Cost	¥ 90,124	¥ 32,381 ✓
Transportation Cost	¥ 16,525	¥ 1.600 ✓
Miscellaneous Expenses	¥ 73,700	¥ 7029 ✓
Total	¥ 565,429	¥ 169.810 ✓

Estimated by (Custodian) C Nakanishi dated 27. November

Checked by (O.P.G.) Takagi Kosa dated ____________

Approved by Kinki Civil Affairs Region

____________ dated ____________

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

(1) Details of wages required

Kind of Repairing	Number of work		Unit cost	Total	Checked by O.P.G.
Roof-tile	Roofer	~~46~~ 20	563	25,898	11.260
228 tsubo	Sundry labourer	~~46~~ 20	325	14,950	6.500
Ridge-tile	Roofer	12	563	6,756	
120 ken	Sundry labourer	12	325	3,900	
Rain pipe	Tinmen	15	538	8,070	8070
150 ken	Sundry labourer	15	325	4,875	4875
Renewing of		2	325		650
window glass	Sundry labourer	75	325	24,375	
750 squar-feet	Carpenter	2	513		1,026
Renewing of shingle 24 pcs	Sundry labourer	4	325	1,300	
		Total:		90,124	32.381

(2) Details of materials cost

Kind of Repairing	Name of Material	Quantity	Unit Cost	Total	Checked by OPG
Roof-tile 228 tsubo	Tile	~~10,944~~ 200 pcs	~~15~~ 380	164,160	76.000
	Soil	20 carts	500	10,000	
	Wire	9 kan	250	2,250	
	Straw	228 kan	30	6,840	
Ridge-tile 120 ken	Tile	2,880 pcs	15	43,200	
	Soil	2 carts	500	1,000	
	Wire	5 kan	250	1,250	
	Straw	20 kan	30	600	
Rain pipe 150 ken	Galvanized steel sheet	~~150~~ 120 sheet	380	57,000	45600
	Solder	17 kgs	240	4,080	
Renewing of window glass 750 squar-feet	Glass	~~10 bops~~ 3 koku	~~2,870~~ 2400	28,700	7200
Renewing of shingle 24 pcs	Pine	22 koku	3,000	66,000	
		Total:		385,080	128.800

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

Taihei Kogyo. Kishiwada 32-2.
Repairs.
Fence: 80 ken = 480 linear ft.

Barbed wire fence
480 ft @ 25 = ¥12,000 not sufficient.

Recommends approval based on 2 strand barbed wire fence —

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

(3) Details of fund for transportation of materials

Name of Material		Weight	Number of Wagon		Unit cost	Total	Estinated by O.P.G.
Tile	13,824	26 ton	Truck	3 days	2,250	6,750	
Soil		22 ton	Cart	11 days	850	9,350	
Straw		248 kan	Cart	half day 0.5	850	425	
				Total:		16,525	1600

(4) Miscellaneous expenses

1. Repair of electric wires.
2. Transportations on the working spot and clearance works.
3. Setting up and removal of scaffoldings.

(5) Attached documents

(a) Brief Diagram.

(b) Map up our plant.

all Total 15%

7.029

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018





rain leak from roof tile breakage

rain leak, from ridge tile breakage

sash-window damage

roof-board damage

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018



Plane figure



Cross section drawing

rain leak, from ridge tile breakage

rain leak, from rain-pipe breakage

roof-board damage

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date :

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, File 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

For Umajiro Fukuto

YOSHIHIKO MOROZUMI
Head of 1st Commerce &
Industry Section

Incl #2

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Application for Maintenance Work

Kind of Work Repair of the fence

Project Number: Plant Number: 32 - 2

Plant Name: Taihei Kogyo K.K., Kishiwada Kojo

Plant Address: 707 Shimono-cho, Kishiwada-shi

Description of work for which funds are requested:

Repair of the fence.

Justification of requested:

Having produced great difficulty in maintenance of the designated machines owing to the damage of the wall surrounding plant due to the last Jane Typhoon, we must repair it in order to shut off reparated area from the outside of it at once.

Cost estimate

	Custodian	O.P.G.
Materials cost	¥ 48,420	¥ ~~27,325~~ 14,260
Labour cost	¥ 8,784	¥ 5,490
Transportation cost	¥ 1,600	¥ 1,600
Miscellaneous expenses	¥ 8,821	¥ ~~5,463~~ 3,199
Total:	¥ 67,625	¥ ~~41,849~~ 24,529

Estimated by (Custodian) C. Nakanishi dated

Checked by (O.P.G.) FOR umajiro yokota dated

Approved by Kinki Civil Affairs Region dated

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175818

(1) Details of wages required

Kind of repairing	Number of work	Unit cost	Total	Checked by O.P.G.
Fence ~~60~~ 50 Ken	Carpenter ~~8~~ 5	¥ 513	¥ 4,104	2,565
	Sundry labourer (A) ~~8~~ 5	¥ 325	¥ 2,600	1,625
	" (B) ~~8~~ 5	¥ 260	¥ 2,080	1,300
	Total:		¥ ~~8,784~~ 5,490	

(2) Details of material cost

Kind of Repairing	Name of materials	Quantity	Unit Cost	Total	Checked by O.P.G.
Fence ~~60~~ 50 Ken	Cryptomeria board	~~11.5~~ 7 koku	¥ 2,400	¥ 27,600	~~6,800~~ 7,200
	Cross-bars supporting pillars	~~6.5~~ 4 koku	¥ 1,560	¥ 10,140	~~6,240~~ 3,120
	Supports	~~6~~ 3 koku	¥ 1,560	¥ 9,360	~~8,460~~ 3,120
	Nails	~~24~~ 15 Kgs.	¥ 55	¥ 1,320	~~825~~ 825
	Total:			¥ ~~48,420~~ ~~28,325~~ 14,260	

(3) Details of funds for transportation of materials:

Name of material	Weight	Number of wagons	Unit cost	Total	Checked by O.P.G.
Wood		Half a day	3,200	1,600	1,600

(4) Misellaneous expenses: 36415-15%

¥ 8,821 ~~1,462~~ 3,199

(5) Attached documents:

(a) A map of our plant 1

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Taihei Kogyo K.K. Kishiwada Kojo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date :

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant:

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

Incl #3

For

YOSHIHIKO MOROZUMI
Head of 1st Commerce &
Industry Section
Takaji Kono

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175818

Application for Maintenance Work

Kind of Work: Maintenance of Reparations Machine

Project Number: Plant Number: 32 - 2

Plant Name: Taihei Kogyo K.K., Kishiwada Kojo

Plant Address: 707 Shimono-cho, Kishiwada-shi

Description of work for which funds are requested:

Surface cleaning 209

Justification for request:

These designated machines having been made rusty and muddy by the damage of the roofs and other parts of the Buildings resulting from the last Jane Typhoon, we are to clear these machines that we may keep them in good condition.

(they have not been mended since July 1949)

Cost Estimate:

	Custodian	O. P. G.
Materials cost	¥ 62.771	¥ 62.771
Labor cost	¥ 58.848	¥ 58.848
Transportation cost	¥	¥
Miscellaneous expenses	¥ 981	¥ 981
Total:	¥ 122.600	¥ 122.600

Estimated by (Custodian) C. Nakanishi dated 27 November

Checked by (O.P.G.) Takaji Kono dated

Approved by Kinki Civil Affairs Region dated

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179818

(1) Details of labor cost:

Description	No. of Machine	Point	Worker's Name	No.	Unit	Price	Checked O.P.G.
Surface cleaning	209	24,520	Carer	122.6	¥ 480	58,848	58,848

(2) Details of material cost:

Surface cleaning and oiling

Name of material	Quantity	Unit	Price	Checked O.P.G.
Cleaning oil	245.2 liter	¥ 16.35	¥ 4,009	4,009
Machine oil	245.2 liter	¥ 55.59	¥13,631	13,631
Greace	245.2 kg.	¥114.08	¥27,972	27,972
Waste	367.7 kg.	¥ 31.42	¥11,556	11,565
Soap etc.		¥ 22.85	¥ 5,603	5,603
Total:			¥ 62,771	

(3) Details miscellaneous expenses:

Surface cleaning and oiling ¥ 19,224 981

(4) Percentage of non-U machine

100 %

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

M1-le5(a)

Economics

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Building and Fence Repairs, Nishibayashi Seiko K.K., Main Plant, 32-118

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section of Commerce and Industry Department

1. Expenditure from reparations funds of ¥118,040 for building and fence repairs at subject plant, as recommended by your office in Inclosure 1, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

1 Incl:
Application, Osaka Pref Gov't. dtd 31 Jan 51

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-712

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 179018

p. #32-118 (Prec Bg) Nisihayashi Seiko KK, 12 Dec 50
(Insp C/S, Incl 33)

(1) Plant is in operation as an integrated facility, using 67 of the 208 inventoried items. Maintenance is good on all items in use; however, some of the machines in dead storage will require new maintenance because of typhoon damage.

(2) The company submitted an estimate of ¥462,519 needed for repairs to buildings and regreasing of damaged machines. The undersigned is of the opinion that, as the plant is in operation as an integrated facility, the expense of the needed repairs should be borne by the company. Inclosure 34 is plant layout and copy of application of typhoon damages.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 75018

Subj: Showa Kosakusho K.K.

35-08

Thru:

TO:

1. Refer to the inclosed application from subject plant requesting reparations funds for ~~building repairs~~. repair of buildings housing reparations equipment.

2. Expenditure of ¥447,733 from reparations funds,

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

Nishibayashi Seiko 32-118.

Repairs to Bldgs. % operating? 31%.

Recommend approval if plant is operating 47%

as claimed ¥ 118,040 –

WWM

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 3 January 1951

To : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant: Nishihayashi Seiko K.K.

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

For YOSHIHIKO HOROZUMI
Head of 1st Commerce
Industry Section

Takaji Kono

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

Application for Maintenance Work

Kind of work Repairing of reparation plant

Project Number: Plant Number 32 - 118

Plant Name: Nishiobayashi Seiko K.K. Honsha Plant

Plant Address: 740 Deto, Nagayoshimura, Nakakawachigun, Osaka-fu.

Description of work for which funds are requested:

1st workshop

Replacement of slate	12 tsubo	36 sheets
Repairing of window glass	350 square shaku	

2nd workshop

Replacement of slate	9 tsubo	27 sheets
Repairing of window glass	270 square shaku	

3rd workshop

Replacement of slate	5 tsubo	15 sheets
Repairing of window glass	120 square shaku	

4th workshop

Replacement of slate	12 tsubo	36 sheets
Repairing of window glass	350 square shaku	

6th workshop

Replacement of slate	6 tsubo	18 sheets
Repairing of window glass	170 square shaku	

8th workshop

Replacement of slate	7 tsubo	21 sheets
Repairing of window glass	200 square shaku	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

18th Workshop

Replacement of slate	3 tsubo	9 sheets
Repairing of window glass	80 square shaku	

Fence

Repairing of fence	190 ken

Justification for request:

The buildings in which the reparations machines now under custody were severely damaged by the typhoon " Jane " this September 3, the roofs, windows and fences were crushed, and the reparations machines were rusted by the leakage of rains.
Such being the situation, it is urgent necessary to repair the damaged buildings, for perfect keeping and custody of the reparations machines.

Cost estimate:

(1). 1st Workshop
roof 12tsubo
window 350 square shaku

	Custodian	C. P. G.
Materials Cost	¥ 17,400.00	¥
Labor Cost	¥ 30,103.00	¥
Transportation Cost	¥ 1,000.00	¥
Miscellaneous Expenses	¥ 8,000.00	¥
Total	¥ 56,503.00	¥

(2). 2nd Workshop
roof 9 tsubo
window 250 square shaku

	Custodian	C. P. G.
Materials Cost	¥ 12,750.00	¥
Labor Cost	¥ 17,196.00	¥
Transportation Cost	¥ 900.00	¥
Miscellaneous Expenses	¥ 8,000.00	¥
Total	¥ 38,846.00	¥

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775010

I 041

(3). <u>3rd Workshop</u>
roof 5 tsubo
window 120 square shaku

	Custodian	C. P. G.
Materials Cost	¥ 5,630.00	¥
Labor Cost	¥ 10,660.00	¥
Transportation Cost	¥ 420.00	¥
Miscellaneous Expenses	¥ 3,200.00	¥
Total	¥ 19,910.00	¥

(4). <u>4th Workshop</u>
roof 12 tsubo
window 360 square shaku

	Custodian	C. P. G.
Materials Cost	¥ 17,400.00	¥
Labor Cost	¥ 25,236.00	¥
Transportation Cost	¥ 1,000.00	¥
Miscellaneous Expenses	¥ 8,000.00	¥
Total	¥ 51,636.00	¥

(5). <u>5th Workshop</u>
roof 6 tsubo
window 170 square shaku

	Custodian	C. P. G.
Materials Cost	¥ 8,530.00	¥
Labor Cost	¥ 9,654.00	¥
Transportation Cost	¥ 550.00	¥
Miscellaneous Expenses	¥ 4,500.00	¥
Total	¥ 23,234.00	¥

(6). <u>6th Workshop</u>
roof 7 tsubo
window 200 square shaku

	Custodian	C. P. G.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 779818

Materials Cost	¥ 1[illegible],[illegible]50.00	¥
Labor Cost	¥ 7,557.00	¥
Transportation Cost	¥ 480.00	¥
Miscellaneous Expenses	¥ 3,8[illegible]0.00	¥
Total	¥ 21,[illegible]37.00	¥

(7). 10th Workshop
roof Mitsubo
window 80 square shaku

	Custodian	O. P. G.
Materials Cost	¥ 4,170.00	¥
Labor Cost	¥ 3,243.00	¥
Transportation Cost	¥ 450.00	¥
Miscellaneous Expenses	¥ 3,500.00	¥
Total	¥ 11,363.00	¥

(8). Fence
190 ken

	Custodian	O. P. G.
Materials Cost	¥ 182,190.00	¥
Labor Cost	¥ 57,990.00	¥
Transportation Cost	¥ 10,000.00	¥
Miscellaneous Expenses	¥ 9,000.00	¥
Total	¥ 239,990.00	¥
GrandmTotal	¥ 462,519.00	¥

	Custodian	O PG
Cost estimate		
materials cost	238,080.—	76,814.—
labor cost	161,839.—	24,926.—
Transportation cost	14,800.—	3,200.—
miscellaneous expenses	48,000.—	14,000.—
total	462,519.—	~~117,940.—~~ 118,040.—

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175018

Estimated by (Custodian)

Shoji Nishi dated 5 Dec 1950

Checked by (O. P. G.)

Takaji Kono dated 31 January 1951

Approved by Kinki Civil Affairs Region

_____ dated _____

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

(1). Details of Wages Required:

Kind of Repairing	Number of Work		Unit Cost	Total	Checked by C. P. G.
(a). 1st Workshop					
Roof 12 tsubo	Roofer	23	¥563.00	¥ 12,949.00	563,—
3 tsubo		1			
Lighting windows	Carpenter	18 1	¥513.00	¥ 9,234.00	513,—
Windows & Doors Boarding	Tinsmith	15	¥528.00	¥ 7,920.00	650,—
350 Square shaku	Sundry labourer	2	325,00		
12 tsubo	Total			¥ 30,103.00	1,726,—
(b). 2nd Workshop					
Roof 9 tsubo	Roofer	12	¥563.00	¥ 6,756.00	
Lighting windows	Carpenter	18	¥513.00	¥ 4,104.00	
Windows & Doors	Tinsmith	12	¥528.00	¥ 6,336.00	
250 square shaku					
	Total			¥ 17,196.00	
(c). 3rd Workshop					
Roof 5 tsubo	Roofer	5	¥563.00	¥ 2,815.00	
Boarding 10 tsubo	Carpenter	1	513		513,—
	Sundry labourer	1	325		325,—
Lighting windows	Carpenter	5	¥513.00	¥ 2,565.00	
Doors & Eaves	Tinsmith	10	¥528.00	¥ 5,280.00	
120 square shaku					
	Total			¥ 10,660.00	838,—
(d). 4th Workshop					
Roof 12 tsubo	Roofer	18	¥563.00	¥ 10,134.00	
Boarding 6 tsubo	Carpenter	1	513,—		513,—
Lighting windows	Carpenter	14	¥513.00	¥ 7,182.00	
Doors & Eaves	Tinsmith	15	¥528.00	¥ 7,920.00	
350 Square shaku					
	Total			¥ 25,236.00	513,—
(e). 6th Workshop					
Roof 6 tsubo	Roofer	6	¥563.00	¥ 3,378.00	
Lighting windows	Carpenter	4	¥513.00	¥ 2,052.00	
Doors & Eaves	Tinsmith	8	¥528.00	¥ 4,224.00	
170 square shaku					
	Total			¥ 9,654.00	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

(f). 8th Workshop

Roof 7 tsubo	Roofer ~~6~~ 1	¥563.00	¥ 3,378.00	563,–
	Sundry labourer 1	325,–		325,–
~~Lighting windows,~~	~~Carpenter 3~~	~~¥513.00~~	~~¥ 1,539.00~~	
~~doors & eaves~~	~~Tinsmith 5~~	~~¥528.00~~	~~¥ 2,640.00~~	
200 square shaku				
	Total	....	¥ 7,557.00	888,–

(g). 16th Workshop

~~Roof 3 tsubo~~	~~Roofer 3~~	~~¥563.00~~	~~¥ 1,689.00~~
~~Lighting windows,~~	~~Carpenter 2~~	~~¥513.00~~	~~¥ 1,026.00~~
~~doors & eaves~~	~~Tinsmith 1~~	~~¥528.00~~	~~¥ 528.00~~
~~80 square shaku~~			
	~~Total~~	....	~~¥ 3,243.00~~

(h). Fence

190 Ken	Carpenter	~~50~~ 38	¥513.00	¥ 25,650.00	19,494,–
	~~Earthworkman~~	~~60~~	~~¥420.00~~	~~¥ 25,200.00~~	
	Labourer	~~30~~ 38	¥238.00	¥ 7,140.00	+ 12,350.–
					31,844
					× 0.63
	Total	....		¥ 57,990.00	20,061
	Grand Total	....		¥ 161,639.00	~~23,026~~
					24,026,–

(2). Details of Material Cost:

Kind of Repairing	Name of Materials	Quantity	Unit Cost	Total	Checked by C. P. G.
(a). 1st Workshop					
Roof ~~12~~ 3 tsubo	Slate	~~36~~ 8 sheets	~~¥250.00~~ 400,–	¥ 9,000.00	3,200.00
Boarding 12 tsubo	Cryptmeria board	1.728 koku	2400,–		4,128.00
Lighting windows, doors & eaves 350 square shaku	Glass	350 square shaku	¥ 24.00	¥ 8,400.00	
	Total	....		¥ 17,400.00	7,328,–
(b). 2nd Workshop					
~~Roof 9 tsubo~~	~~Slate~~	~~27 sheets~~	~~¥250.00~~	~~¥ 6,750.00~~	
~~Lighting windows, doors & eaves 250 square shaku~~	~~Glass~~	~~250 square shaku~~	~~¥ 24.00~~	~~¥ 6,000.00~~	
	Total	....		¥ 12,750.00	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

(c). 3rd Workshop

Roof 5 tsubo	Slate	15 sheets	¥250.00	¥3,750.00		
Boarding 6 tsubo	Cryptomeria board	~~6 tsubo~~ 1.44 koku	2,400.—			
Lighting windows, doors & eaves 120 square shaku	Glass	120 square shaku	¥ 24.00	¥ 1,880.00		3,456.—
		Total.....		¥ 5,630.00		3456.—

(d). 4th Workshop

Roof 12 tsubo	Slate	36 sheets	¥250.00	¥ 9,000.00		
Boarding 6 tsubo	Cryptomeria board	0.86 koku	2400.—		2064.—	
Lighting windows, doors & eaves 350 square shaku	Glass	350 square	¥ 24.00	¥ 8,400.00		
		Total		¥ 17,400.00		2,064.—

(e). 6th Workshop

~~Roof 6 tsubo~~	~~Slate~~	~~18 sheets~~	~~¥250.00~~	~~¥ 4,500.00~~		
~~Lighting windows, doors & eaves 170 square shaku~~	~~Glass~~	~~170 square shaku~~	~~¥ 24.00~~	~~¥ 4,080.00~~		
		Total.....		¥ 8,580.00		

(f). 8th Workshop

Roof 7 tsubo	Galvanized steel sheet Slate	21 sheets	380 ¥250.00	¥ 5,250.00		7,980.—
Lighting windows, doors & eaves 200 square shaku	Glass	200 square shaku	¥ 24.00	¥ 4,800.00		
		Total		¥ 10,050.00		7980.—

(g). 18th Workshop

~~Roof 3 tsubo~~	~~Slate~~	~~9 sheets~~	~~¥250.00~~	~~¥ 2,250.00~~		
~~Lighting windows, doors & eaves 80 square shaku~~	~~Glass~~	~~80 square shaku~~	~~¥ 24.00~~	~~¥ 1,920.00~~		
		Total		¥ 4,170.00		

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 175013

(h). Fence
190 ken

Wood	55 koku (20,2)	¥ 2,400.00 (1,500.—)	¥ 132,000.00	30,300.—
Wooden board	15 koku (22,68)	¥ 1,500.00 (2,400.—)	¥ 22,500.00	54,432.—
Nail	2[illegible] kan (57 kg)	¥ 328.00 (55.—)	¥ 7,600.00	3,135.—
Total			¥ 162,100.00	87,867 ×63 55,986
Grand Total			¥ 238,080.00	76,814.00

(3). Details of Funds for Transportation of Materials:

Name of Materials	Weight	Number of Wagons	Unit Cost	Total	Checked by C. P. G.
Slate	8 pcs	3	¥ 1,600.00	¥ 4,800.00	
Glass					
galvanized steel sheet	21 pcs	truck 1	3200.—		
Wood	43.28 koku	5	¥ 2,000.00	¥ 10,000.00	
Nail	57 kg				
Total				¥ 14,800.00	3200.—

(4). Miscellaneous Expenses:

¥ 4,800.00 14,000.—

(5). Attached Document:

(a). Map of our plant 1

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

32-118 Nishibayashi Seiko K.K.



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

MI-/e 5(a) Economics

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JWH/at

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Maintenance of Equipment at Nobuhara Seisakusho, Main Plant, 32-94

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section of Commerce and Industry Department

1. Expenditure from reparations funds of ¥111,862 for the maintenance of 83 items of reparations equipment at subject plant, as recommended by your office in Inclosure 1, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

1 Incl:
Application, Osaka Pref Gov't.

STERLIN C. MOORE
Major Infantry
Deputy Chief

a 711

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775018

6 Feb 51

Mr. Frazee, Bldg. rep. & conc. has already been approved. Our recommend. for maintenance is ¥ 111,862.00 for Plant 32-94. JEA

Nobuhara Seisakusho 32-94

Maintenance

Labor	Overhauling	2655/25 = 106.2 men		
	Partial "	4440/100 = 44.4 "		
	Surface cleaning	4230/200 = 21.2		
		171.8 men @ 480		82,460
Materials		11,325/100 = 113.25 @ 256		28,992
Misc. Exp		11,325/100 = 113.25 @ 4.		453
				111,905

Approve as per Osaka Pref. estimate of ¥ 111,862 —

WAM

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date :

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant: Nobuhara Seisakusho Honsya Kojo

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE:

for ~~YOSHIHIKO MOROZUMI~~ [signature]
Head of 1st Commerce & Industry Section

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

No, 1.

APPLICATION FOR MAINTENANCE WORK

Kind of Work. Care of Reparation Machines.

Project Number; Plant Number; 32-94.

Plant Name; Nobuhara Seisakusho Honsya Kojo.

Plant Address; No, 67 3-chome Daininhonmachi Oyodo-Ku, Osaka Shi.

Discription of work for which funds are requested;

Overhauling	15	Point.	2,655
Partly Overhauling	33	Point.	4,440
Working Surface Cleaning	35	Point.	4,230
			11,325

Justification for request;

A severe damage was caused on all buildings of factory by the violent typhoon visited the Kinki district on September 3, 1950. specially the reparation items under custody at our plant were so badly damaged by the water flooded into the plant and also by rain water leaked through the damaged roof that no longer proper maintenance be kept on unless the proper but urgent repairs of the buildings and Cares of the reparation items be applied on respectively.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

No, 2.

Cost Estimate;

	Custodian	Bureau of ~~M.I.T.I.~~ O.P.G
Materials Cost.	¥ 39,050.00	¥ ~~31,636~~ 28,970.- ✓
Labour Cost.	¥ 82,440.00	¥ 82,440.- ✓
Transportation Cost.	¥ 0	¥
Miscellaneous Expenses.	¥ 452.00	¥ 452.- ✓
Total........	¥ 121,942.00	¥ ~~114,527~~ 111,862.-

Estimated by (Custodian)

Kentaro Nobuharce Dated 15. Oct 1950

Checked by (~~Osaka Bureau of M.I.T.I.~~ O.P.G)

Umajiro. yakata Dated 13. Nov. 1950

Approved by Kinki Civil Affairs Region

_______________ Dated _______________

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

No, 3.

BACE FOR COST ESTIMATE

1. Number of the Machines applied for;

Number 83 (Water invasion 2,5 ft above floor)

2. Total of point of Machines applied for;

4 Man Hours;	35	4,230.
8 Man Hours;	33	4,440.
32 Man Hours;	15	2,655.

3. Percentage of Non-U Machines.

100 °/°

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

2. Details of labor cost;

Description.	No. of machine.	Point.	Worker's Name.	Worker's No.	Unit.	Price.	Checked OPC.
Surface cleaning.	35	4.230	Carer.	21.15	¥480.	10152	10.152
Partial overhauling.	33	4.440	do.	444	480	21.312	21312
Perfect overhauling.	15	2655	do.	1062	480	50.976	50.976
Total.							

3. Details of material cost: 82440

a). Surface cleaning and oiling.

Name of material.	Quantity.		Unit.	Price.	Checked by OPG
Cleaning oil.	42.3	liter.	¥16.35	¥ 691.00	691
Machine oil.	42.3	liter.	55.59	2351.00	2,351
Grease,	42.3	Kg.	114.08	4825.50	4825
Waste.	63.4	Kg.	47.13 ~~31.42~~	2988.00	1,993
Soap, etc.	42.3		22.85	966.50	966
Total.				¥ 11,822.60	10,826

b). Partial overhauling.

Name of material.	Quantity.		Unit.	Price.	by OPG
Cleaning oil.	444	liter.	¥16.35	725.90	725
Machine oil.	44.4	liter.	55.59	2467.70	2467
Grease.	44.4	Kg.	114.08	5065.10	5065
Waste.	66.6	Kg.	47.13 ~~31.42~~	3.13880	2092
Soap, etc.	444		22.85	1.01450	1014
Total.				¥ 12412.00	11.363

c) Perfect overhauling.

Cleaning oil.	53	liter	16.35	866.50	433
Machine oil.	53	liter	55.59	2945.70	1472
Grease.	53	Kg.	114.08	6046.20	3023
Waste.	39.7	Kg.	47.13 ~~31.42~~	3746.80	1,248
Soap, etc.	53		22.85	1211.00	605
Total.				¥ 14,816.00	6,781

Grand total of material cost: ¥ 39,050.60 28,970

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

4. Details of miscellaneous expenses:

Suface cleaning and oiling:	¥ 169.10	169.10
Partial overhauling:	¥ 177.60	177.60
Perfect overhauling:	¥ 105.90	105.90
Total.	¥ 452.60	452

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775016

MI-1esta)

HEADQUARTERS
KINKI CIVIL AFFAIRS REGION
APO 15

JEH/at

EC 600.3

10 February 1951

SUBJECT: Expenditure of Funds for Building and Fence Repairs and Maintenance of Equipment, Osaka Aluminum Seisakusho, Sakai Plant, 32-16

THRU : Kinki Liaison and Coordination Office

TO : Governor
Osaka Prefecture
Attn: Chief, No. 1 Section of Commerce and Industry Dept.

1. Expenditure from reparations funds of ¥214,794 for building and fence repairs and ¥12,856 for the surface cleaning and greasing of 45 items of reparations equipment at subject plant, as recommended by your office in Inclosures 1 and 2, respectively, is approved.

2. It is requested that this headquarters be notified when the work is completed.

FOR THE CHIEF:

2 Incls:
Applications, Osaka Pref.
dtd 30 Jan 51
1-Building repair
2-Maintenance

STERLIN C. MOORE
Major Infantry
Deputy Chief

0-710

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Osaka Aluminium Seisakusho 32-16.

Maintenance

Surface cleaning 45 items 2,574 points

Labor:

Surface cleaning $\frac{2574}{200}$ = 13 @ 480 ¥6240.

Materials $\frac{2574}{100}$ = 26 @ 256. 6656.

Misc Exps. 26 @ 4 104

¥13,020

Recommend approval of Osaka Pref. estimate of ¥12,856

Bldg. Repairs. 45% Non-operating.

Repair Shop #3 (100% idle)

Clear debris from 3 collapsed bldgs.

Wood fence to be repaired. Gov't fund to be made available for 10% of the cost as dead storage area is about 10% of the entire ground area.

(Plant is operating 55%.)

Recommend approval of Osaka Pref. estimate of ¥214,794

Total recommended for approval ¥227,650

WHM

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. [illegible]

OSAKA PREFECTURAL GOVERNMENT
THE FIRST COMMERCE AND
INDUSTRY SECTION

Date: 30. Jan. 1951.

TO : Hq Kinki Civil Affairs Region
ATTN: Economic Division

THRU : Kinki Liaison & Coordination Office

SUBJECT: Application for Approval of Repair Work of Reparations Plant: K.K. Osaka Aluminum Seisakusho Sakai Kojo

1. Attached herewith is the subject application submitted by

2. I certify that this application has been investigated by this office, and that investigation has revealed that the application is valid under the provisions of memorandum from the Civil Property Custodian for the Japanese Government Reparations Agency, file 387.6 (2 Jun 50) CPC/EX, subject: "Expenditure of Funds for Maintenance, Centralization of Machines, and Repair of Buildings in Reparations Plants, dated 11 September 1950; that all of the work requested is necessary to prevent damage to, deterioration and/or theft of reparations equipment; that the funds requested approximate the minimum amount necessary to accomplish the work; and that materials to be purchased are not available from reparations stocks.

3. Forwarded for your approval.

FOR THE GOVERNOR OF OSAKA PREFECTURE;

Incl #1

Y. Morozumi.
YOSHIHIKO MOROZUMI
Head of 1st Commerce &
Industry Section

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

Application for Maintenance Work

Kind of work Repairing and Replacement

Project Number: Plant Number: 32-16

Plant Name : K.K. Osaka Aluminum Seisakusho Sakai Kojo

Plant Address : 26, Shimoda-cho Sakai-shi

Description of work for which funds are requested:

A. Repairing the roof.......slate (1,110 sheets)
B. Replacement of rain pipes...... 186 Ken
C. Repairing of wooden walls...... 611 Ken
D. Arrangement of collapsed shops...... 420 man hours

Justification for request:

The shop in which the Reparation machines (215 sets) are stored was damaged and the wooden walls of the plant and 3 shops were collapsed by the typhoon (Sep. 3, 1950),so we are urgently in need of replacing and repairing those to maintain the reparation machines.

Cost estimate:

	Custodian	O.P.G.
Material Cost	¥ 762,480.00	¥ 138,930
Labor Cost	¥ ~~171,600~~ 194,280.00	¥ ~~44,700~~ 41,450
Transportation Cost	¥ 16,000.00	¥ 6,400
Miscellaneous Expenses	¥142,512.00	¥ ~~28,502~~ 28,014
Total..........	¥~~1,092,592~~ 1,115,272.00	¥ ~~214,794~~ ~~218,532~~ 214,794 ✓

Estimated by (Custodian)

M. Osada dated Nov. 30,1950

Checked by (O.P. G.)

L. J. Mosgrove dated 30. Jan. 1951

Approved by Kinki Civil Affairs Region

______________________ dated ____________

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. ______

No. 1

(1) Details of Wages Required:

A. Ware House (No.3)

Kind of work	Area	Worker	Quantity	Unit cost	Total	Non-U%	Check
Roofing	~~370~~ 111 tsubo	Roffer	~~20~~ 11 ✓	¥563.- 538 ✓	¥11,260.-	100 %	5,918 ✓
Foot-bridge		~~Carpenter~~ Tobi	10	¥431.-	¥ 4,310.-	100 %	4310 ✓
Sundry work		Sundry Labourer	~~10~~ 35 25	¥~~238~~ 325 .-	¥ ~~2,380~~ 11,375 .-	100 %	~~11,375~~ 8125 ✓
Rain-pipe	~~186~~ 120 ken	Rain-piper	~~30~~ 12	¥538.-	¥16,140.-	100 %	6456 ✓
window	2.5 tsubo	carpenter	2.5	513	1282		1,282 ✓
Total					¥ ~~34,090~~ 44,367 .-		~~29,347~~ 26,100 ✓

B. Wooden walls: (Percentage of Non-U..... 45 %)
Percentage of non operation area 10%

Kind of work	Number (walls)	Worker	Number (workers)	Unit cost	Total	Check
Wooden walls	611 ken	~~Carpenter~~ Earth Worker	~~50~~ 61	¥513.- 488	¥ 25,650.- 29,768	29,768 ✓
		Sundry Labourer	~~50~~ 61	¥~~238~~ 325 .-	¥ ~~11,900~~ 19,825 .-	19,825 ✓
Total					¥ ~~37,550~~ 49,593 .-	49,593
					10%	4,959

C. Arrangement of Collapsed Shops:

Kind of work	Area	Worker	Number	Unit cost	Total	Check
Arrangement	427.43 (70) tsubo	Sundry Labourer	~~420~~ 32	¥238.- 325	¥ 99,960.-	10,400 ✓
Total					¥ 99,960.-	10,400

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO.

No. 2

(2) Details of Material Cost:

A. Ware house (No.3)

Kind of work	Area	Name of Material	Quantity	Unit cost	Total	Non-U%	Check
Roofing	~~370~~ 111 tsubo	Galvanized Steel sheets	~~1,110~~ 255 sheets	¥380.-	¥421,800.-	100%	96,900 ✓
"	~~370~~ tsubo	Steel Nails	14 ~~16~~ kan	¥~~380~~ 300.-	¥ 6,080.-	100%	4,200 ✓
"	~~150~~ tsubo	Wooden Sheet	18 koku	¥2,400.-	¥43,200.-	100%	—
Rainpipe	~~186~~ 120 ken	Galvanized Steel sheets	~~288~~ 60 sheets	¥380.-	¥109,440.-	100%	22,800 ✓
Window		Wooden Sheets	2.7 ~~4~~ koku	¥2,400.-	¥ 9,600.-	100%	6,400 ✓
Foot-bridge Scaffold		Wooden Logs	100 pics.	¥6.-x 7 days	¥ 4,200.-		4200 ✓
Total					¥594,320.-		134,580 ✓

B. Wooden Walls

Kind of work	Length	Name of material	Quantity	Unit cost	Total	Check
Repairing	611 ken	Wood (~~Square~~ Logs)	~~100~~ 43 koku	¥~~1560~~ 900.-	¥156,000.-	38,700 ✓
		Steel Nails	16 ~~32~~ kan	¥ ~~380~~ 300.-	¥ 12,160.-	4,800 ✓
Total					¥ 168,160.-	43,500 ✓ 10% 4350

Note: We use the collapsed wooden sheets for repairing the walls. ✓

(3) Details of Funds for Transportation of Materials:

Name of material	Weight	Number of Wagons	Unit cost	Total	Check
Galvanized Steel Sheets	~~4~~ 1.5 tons	1 } 2 trucks	¥3,200.-	¥ 3,200.-	6400 ✓
Wooden Sheets	~~122~~ 45 koku	4 (Running Number 10)	¥3200.-	¥12,800.-	
Total				¥ 16,000.-	6400

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 170010

No. 3

(4) Details of Miscellaneous Expenses:

Kind of work	Amount	Details	Check
Roofing	¥ 72,831.-	Expenses for	16,532
Foot-bridge	¥ 12,76.50		1,276
Sundry Works	¥ 357.-	Directing the works,	
		Communications,	~~906~~
Rain-pipe	¥ 18,837.-	Mailing,	1,218
		Heating,	4,388
Wooden walls	¥ 32,776.50	Writing,	
		Drawing,	1,876
Arrangement	¥ 14,994.-	and Others.	1,560
Window	¥ 1,440.-		1,164
Total	¥142,512.-		~~28,502~~ 28,014