

GHQ/SCAP Records(RG 331)
Description of contents



- (1) Box no. 2724
- (2) Folder title/number : (18)
Reparations Installations, Vacant Floor Spaces
in - Tokyo-To

(3) Date : ?

(4) Subject :

Classification	Type of record
9212, 9230	c, r

(5) Item description and comment :
Tokyo

(6) Reproduction : Yes No

(7) Film no.

Sheet no.

About 6,300 tsuto available

Tokyo 2nd Military Arsenal, Oji Plant

- a. Code No. 39-52
- b. The Nearest Railway Station : Oji Station
- c. Distance to the Station : About 600 meter
- d. List of Buildings : as following

Bldg. No.	Floor Space (Sq.Ft.)	Structure	No. of Story	Floor	Height Beam-Floor (Ft.)	Loading Equip.	Estimated Cost for Repair
7	3,098	Ferro-Concrete	1	Concrete	16.5	None	¥ 32,000
14	24,912	Brick	2	"	18	"	33,880
15	11,448	Ferro-Concrete	1	"	21	"	1,500
16	14,976	Brick	2	"	15	"	43,000
17	360	Ferro-Concrete	1	"	9	"	3,200
18	21,430	"	2	"	10.5	"	61,000
19	468	Wooden	1	Earth	6	"	Unavailable
20	150	"	1	Concrete	9	"	"
21	11,880	Ferro-Concrete	2	"	10.5	"	37,000
22	2,736	"	3	"	7.5	"	500
24	4,104	"	1	"	15	"	500
25	13,063	Brick	3	"	18	"	500
26	10,022	"	4	"	18	"	30,000
27	3,528	Wooden	1	"	9	"	7,000

Bldg. No.	Floor Space (Sq. Ft.)	Structure	No. of Story	Floor	Height Beam-Floor (Ft.)	Loading Equip.	Estimated Cost for Repair
28	13,860	Ferro-Concrete	2	Concrete	7.5	None	¥ 14,000
31	7,848	Iron Frame	1	"	15	"	36,000
32	2,919	"	4	"	5.1	"	15,000
33	5,652	Ferro-Concrete	1	"	18	"	22,000
34	1,476	Iron-Frame	1	"	12	"	11,600
35	756	"	1	"	12	"	1,000
36	7,164	"	1	Earth	15	"	Unavailable
37	5,866	Wooden	1	"	13.5	"	2,000
41	5,544	"	1	"	12	"	Unavailable
48	2,412	Iron-Frame	1	"	15	"	Unavailable
49	252	Wooden	1	"	6	"	Unavailable
51	5,940	"	1	"	15	"	20,000
52	72	"	Concrete	Concrete	6	"	Unavailable
54	1,152	Wooden	1	"	9	"	Unavailable
55	11,340	Ferro-Concrete	1	"	25.5	"	20,000
58	216	Wooden	1	"	6	"	1,500
59	1,476	Iron Frame	1	"	10.5	"	22,000
60	7,596	Ferro-Concrete	1	"	25.5	"	62,500


Bldg. No.	Floor Space (Sq. Ft.)	Structure	No. of Story	Floor	Height Beam-Floor (Ft.)	Loading Equip.	Estimated Cost for Repair
61	13,572	Iron Frame	4	Concrete	10.5	None	¥ 92,700
62	14,976	Ferro-Concrete	3	"	12	"	123,000
63	2,376	Brick	1	"	13.5	"	29,000
66	144	Wooden	1	Earth	7.5	"	Unavailable
67	103	"	1	"	7.5	"	Unavailable
68	2,304	"	1	Concrete	12	"	Unavailable
69	2,520	"	1	"	12	"	700
70	2,268	"	1	"	10.5	"	13,400
72	2,988	Ferro-Concrete	1	"	15	"	38,000
73	1,044	Iron-Frame	1	"	18	"	45,000
74	540	Wooden	1	Earth	6	"	500
75	216	"	1	"	6	"	500
101	720	Wooden	1	Concrete	10.5	"	26,200
35 Ridges							¥1,151,600

Other reparations plants in Tokyo Area, there is no storage space for Reparations machinery.

旧東二陸軍造兵廠 王子工場 配置図

S = 1/2500

解放前可地王境
 水橋
 鉄道



註: 建家番号中
 I... 元造兵廠番号
 (I)... M.G.(軍政部)番号
 ①... 評價新番号

Unoccupied Building