

## Meeting report n° 4

### Attendance

<b>Name</b>	<b>Function</b>
Michiel Eecker	Teamleader
Jisca Boogaerts	Secretaresse
Arnout Dejans	
Arnout Van Tricht	
Rik Dendal	
Gertjan Geelen	

### Absent

<b>Name</b>	<b>Reason</b>
/	/

### Agenda

- Parts (order)
- Gears, wheels
- Matlab

### Agenda discussion

- Parts (order)

We made a list of the parts we need to order.  
Transmitter, receiver; wheels; gears

- Gears, wheels

We decided to make the wheels off Plexiglas.

When we are designing our gears we need to take into account that the wheel is the last gear and that the best gear ratio is different for a different radius of the wheel.

- Matlab

After the seminary we calculated the best gear ratio with matlab.



## Tasks:

Everybody take a look at the calculating of the gear ratio by hand.

## Future Meeting:

Tuesday 12/03 12u00