









# AIRCRAFT ACTION REPORT

**CONFIDENTIAL**  
RESTRICTED  
(Reclassify when filled out)

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

REPORT No. **VC-35 - 104**

**XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only):**

(a) Target(s) and Location(s) **1. Yontan Airfield**  
**2. Kadana Airfield** (FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK) (b) Time Over Target (s) **0630-0900 (I)** (Zone)

(c) Clouds Over Target **Solid at 2000' - Stratus 5/10 at 1000'**  
(BASE IN FEET, TYPE AND TENTHS OF COVER)

(d) Visibility of Target **Clear** (CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (e) Visibility **10** (MILES)

(f) Bombing Tactics: Type **Glide** (LEVEL, GLIDE OR DIVE) Sight Used **Gun** **Mk VIII** (TYPE)

Bombs Dropped per Run **1 and 2** (NUMBER) Spacing **50** (FEET) Altitude of Bomb Release **1500** (FEET)

(g) Number of Enemy Aircraft Hit on Ground: Destroyed \_\_\_\_\_ Probably Destroyed \_\_\_\_\_ Damaged \_\_\_\_\_

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO A/C ATTACKING (k) SQUADRON	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
1 AA Positions Yontan Airfield		4 TBM-3 VC-35	2 x 500# Bombs 6 x 5" HE Rockets	All in Area	Not Observed
2 AA Positions Kadana Airfield		4 TBM-3 VC-35	6 x 500# Bombs 20 x 5" HE Rockets	All in Area	Not Observed
3			550 x .50 cal		
4					
5					
6					
7					
8					

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

(p) Were Photographs Taken? **YES** Photographs of Damage, When Taken, Should Be Attached By Staple.







# AIRCRAFT ACTION REPORT

**CONFIDENTIAL**  
(Reclassify when filled out)

REPORT No. **VC-85 - 104**

**XIII. MATERIAL DATA.** (Comment freely on performance or suitability, following check list at left. Use additional sheets if necessary).

**ARMAMENT**

- Guns, Gunsights
- Turrets
- Ammunition
- Bombs, Torpedoes
- Bomb Sights
- Bomb Releases

**COMMUNICATIONS**

- Radio, Radar
- Homing Devices
- Visual Signals
- Codes, Ciphers

**RECOGNITION**

- IFF
- Signals
- Battle Lights
- Procedures

**PROTECTION**

- Armor, Points and Angles of Fire Needing Further Protection
- Leak Proofing

**EMERGENCY EQUIPMENT**

- Parachutes
- Life Belts, Life Rafts
- Safety Belts
- Emergency Kits
- Rations, First Aid

**NAVIGATIONAL EQUIPMENT**

- Compasses
- Driftsights
- Octants
- Automatic Pilots
- Charts
- Field Lighting

**INSTRUMENTS**

- Flight
- Power Plant

**OXYGEN SYSTEM**

**CAMOUFLAGE AND DECEPTION DEVICES**

**STRUCTURE**

- Airframe
- Control Surfaces
- Control System
- Dive Flaps
- Landing Gear
- Heating System
- Flight Characteristics At Various Loadings

**POWER PLANT**

- Engines
- Engine Accessories
- Propellers
- Lubricating System
- Starters
- Exhaust Dampers

**HYDRAULIC SYSTEM**

**ELECTRICAL SYSTEM**

- Auxiliary Plant
- Lights

**FUEL SYSTEM**

**FLIGHT CLOTHING**

**MAINTENANCE**

**BASE FACILITIES**

- Plane Servicing Equipment
- Personnel Facilities

REPORT PREPARED BY:

APPROVED BY:

**W. H. KEARNS, Lieut., USNR ACIO**

**FRED C. HERRIMAN, Lt.Cdr., USN, C.O.**

**31 March 1945**

SIGNATURE

RANK AND DUTY

SIGNATURE

RANK AND DUTY

DATE

**One TBM-3 developed radio transmitter trouble, due to weak tube.**

**One TBM-3 had a faulty electrical bomb release, but the manual release functioned satisfactorily.**

**One bomb failed to release at all and the pilot landed aboard with it.\*\***

**\* The pilot tried to release bombs electrically on "safe".**

**Pilot was given instruction in proper use of bomb release mechanism.**

**\*\* Due to shackle being of improper size. When plane went into dive, bomb bay synchronization was thrown out of adjustment due to excessive motion of shackle.**

**FORWARDED: G. A. T. WASHBURN,  
Captain, U. S. Navy,  
Commanding Officer,  
U.S.S. LUNGA POINT (CVE-94).**