

T.S

COPY. GLASGOW REPORT No. 68168

Lloyd's Register of Shipping.



Port

GLASGOW,

29th February, 1944

This is to Certify that I have

Surveyed the S.S. "MINIQUAN", 4605 tons gross of Antwerp as she lay afloat at Queens Dock and in Meadowside and Elderslie Dry Docks, Glasgow on 16th January, 1944 and subsequent dates, on account of damage stated to have been sustained through vessel encountering heavy weather during voyage from U.K. to Canada between 19th and 21st December, 1943

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I will Recommended that she be continued as at present classed in the Register Book, viz. +LOCAL shelter deck with fresh record of survey B,44 subject to a shell plate in 5th strake below sheer (s.s) in way of A.P. bulkhead being renewed and repairs to A.P. bulkhead (p.s) in way of horizontal stiffeners being carried out (and cement box being removed) also 5 lengths of cable (s.s) being retested at first opportunity, and middle line partition bulkhead in lower D.T. being dealt with at Owners' convenience, also indented plating (p. & s.) being dealt with

being fit to carry dry and perishable cargoes.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."