

LEGEND

RWY 03L DEPARTURES:

MAICA ONE DEPARTURE: Maintain RWY HDG climb to 4000FT, at 3NM MAR turn left HDG 291° intercept and follow RDL-355 MAR continue climb to 5000FT or follow ATC instructions.

MAUROA ONE DEPARTURE: Maintain RWY HDG climb to 3000FT, at 3 NM MAR turn right HDG 111° intercept and follow RDL-089 MAR. continue climb to 7000FT or follow ATC instructions.

PADOS ONE DEPARTURE: Maintain RWY HDG climb to 3000FT, at 3NM MAR turn right HDG 141° intercept and follow RDL-113 MAR, continue climb to 5000FT or follow ATC instructions.

OJEDA ONE DEPARTURE: Maintain RWY HDG climb to 3000FT, at 3NM MAR turn right HDG 206° intercept and follow RDL-172 MAR, continue climb to 5000FT or follow ATC.

BOBAT ONE DEPARTURE: Maintain RWY HDG climb to 3000FT, at 3NM MAR turn right HDG 236° intercept and follow RDL-197 MAR continue climb to 4000FT or follow ATC instructions.

GAVIS ONE DEPARTURE: Maintain RWY HDG climb initial to 3000FT, AT 3NM turn right direct to MAR/ VOR, to cross RDL-090 MAR continue climb to 5000FT or upper over MAR/VOR intercept and follow RDL-289° MAR direct to cross GAVIS with 9000FT or upper.