

Inventory No.	Name of Equipment	Status
30-4- 4976	Working Table	E. X.
4977	"	"
4978	"	"
4979	"	"
4980	"	"
4981	"	"
4982	"	"
4983	"	"
4984	"	"
4985	"	"
4986	"	"
4987	"	"
4988	"	"
4989	"	"
4990	"	"
4991	"	"
4992	"	"
4993	"	"
4994	"	"
4995	"	"
4996	"	"
4997	"	"
4998	"	"
4999	"	"
5000	"	"

Inventory No.	Name of Equipment	Status
30-4- 5001	Working Table	E. X.
5002	"	"
5003	"	"
5004	"	"
5005	"	"
5006	"	"
5007	"	"
5008	"	"
5009	"	"
5010	"	"
5011	"	"
5012	"	"
5013	"	"
5014	"	"
5015	"	"
5016	"	"
5017	"	"
5018	"	"
5019	"	"
5020	"	"
5021	"	"
5022	"	"
5023	"	"
5024	"	"
5025	"	"

Inventory No.	Name of Equipment	Status
30-4- 5026	Working Table	E. X.
5027	"	"
5028	"	"
5029	"	"
5030	"	"
5031	"	"
5032	"	"
5033	"	"
5034	"	"
5035	"	"
5036	"	"
5037	"	"
5038	"	"
5039	"	"
5040	"	"
5041	"	"
5042	"	"
5043	"	"
5044	"	"
5045	"	"
5046	"	"
5047	"	"
5048	"	"
5049	"	"
5050	"	"

Inventory No.	Name of Equipment	Status
30-4- 5051	Working Table	E. X.
5052	"	"
5053	"	"
5054	"	"
5055	"	"
5056	"	"
5057	"	"
5058	"	"
5059	"	"
5060	"	"
5061	"	"
5062	"	"
5063	"	"
5064	"	"
5065	"	"
5066	"	"
5067	"	"
5068	"	"
5069	"	"
5070	"	"
5071	"	"
5072	"	"
5073	"	"
5074	"	"
5075	"	"

Inventory No.	Name of Equipment	Status
30-4- 5076	Working Table	E. X.
5077	"	"
5078	"	"
5079	"	"
5080	"	"
5081	"	"
5082	"	"
5083	"	"
5084	"	"
5085	"	"
5086	"	"
5087	"	"
5088	"	"
5089	"	"
5090	"	"
5091	"	"
5092	"	"
5093	"	"
5094	"	"
5095	"	"
5096	"	"
5097	"	"
5098	"	"
5099	"	"
5100	"	"

Inventory No.	Name of Equipment	Status
30-4- 5101	Working Table	E. X.
5102	"	"
5103	"	"
5104	"	"
5105	"	"
5106	"	"
5107	"	"
5108	"	"
5109	"	"
5110	"	"
5111	"	"
5112	"	"
5113	"	"
5114	"	"
5115	"	"
5116	"	"
5117	"	"
5118	"	"
5119	"	"
5120	"	"
5121	"	"
5122	"	"
5123	"	"
5124	"	"
5125	"	"

Inventory No.	Name of Equipment	Status
30-4- 5126	Working Table	E. X.
5127	"	"
5128	"	"
5129	"	"
5130	"	"
5131	"	"
5132	"	"
5133	"	"
5134	"	"
5135	"	"
5136	"	"
5137	"	"
5138	"	"
5139	"	"
5140	"	"
5141	"	"
5142	"	"
5143	"	"
5144	"	"
5145	"	"
5146	"	"
5147	"	"
5148	"	"
5149	"	"
5150	"	"

Inventory No.	Name of Equipment	Status
30-4- 5151	Working Table	E. X.
5152	"	"
5153	"	"
5154	"	"
5155	"	"
5156	"	"
5157	"	"
5158	"	"
5159	"	"
5160	"	"
5161	"	"
5162	"	"
5163	"	"
5164	"	"
5165	"	"
5166	"	"
5167	"	"
5168	"	"
5169	"	"
5170	"	"
5171	"	"
5172	"	"
5173	"	"
5174	"	"
5175	"	"

Inventory No.	Name of Equipment	Status
30-4- 5176	Working Table	E. X.
5177	"	"
5178	"	"
5179	"	"
5180	"	"
5181	"	"
5182	"	"
5183	"	"
5184	"	"
5185	"	"
5186	"	"
5187	"	"
5188	"	"
5189	"	"
5190	"	"
5191	"	"
5192	"	"
5193	"	"
5194	"	"
5195	"	"
5196	"	"
5197	"	"
5198	"	"
5199	"	"
5200	"	"

Inventory No.	Name of Equipment	Status
30-4- 5201	Working Table	E. X.
5202	"	"
5203	"	"
5204	"	"
5205	"	"
5206	"	"
5207	"	"
5208	"	"
5209	"	"
5210	"	"
5211	"	"
5212	"	"
5213	"	"
5214	"	"
5215	"	"
5216	"	"
5217	"	"
5218	"	"
5219	"	"
5220	"	"
5221	"	"
5222	Transformer	D. S.
5223	"	D. S.

SUPPLY

Item No.	Name of Equipment	Quantity	Status
1-210	Grinding Wheels	5068	D. S.
211-502	Cutters	171,102	"
503-520	Drills	8,316	"
521-532	Bits	22,020	"
533-618	Grinding Wheels	3,847	"
619-628	Files	4,100	"
629-634	Grinding Wheels	68	"
635	Bits	500	"
636, 637	Files	800	"
638-668	Cutters	6,382	"
669-687	Reamers	1,896	S.
688	Reamers	56	D. S.
689-734	Reamers	8,105	S.
735-740	Cutters	2,337	D. S.
741-761	Drills	3,941	"
762	Reamers	35	S.
763	Reamers	139	D. S.
764	Reamers	107	S.
765-796	Cutters	4,142	D. S.
797, 798	Cutters	74	S.
799	Cutters	86	D. S.
800	Cutters	21	S.
801-803	Cutters	113	D. S.
804, 805	Cutters	138	S.
806-822	Cutters	14,618	D. S.

Item No.	Name of Equipment	Quantity	Status
823,824	Cutters	95	S.
825	Cutters	300	D. S.
826,827	Cutters	937	S.
828-834	Cutters	6,313	D. S.
835	Cutters	200	S.
836	Cutters	76	D. S.
837-840	Reamers	692	D. S.
841-850	Cutters	4,012	"
851-871	Bits	6,308	"
872-891	Taps	7,127	S.
892-896	Dies	909	"
897	Rings	1,478	D. S.
898-902	Cutters	96	"
903-907	Cutters	216	S.
908-911	End Mills	203	D. S.
912,913	Cutters	1,320	"
914	Reamers	360	S.
915	Cutters	130	S.
916,917	Reamers	107	S.
918,919	Cutters	199	D. S.
920	Reamers	340	S.
921	Bits	520	D. S.
922	Drills	30	S.
923-927	Taps	2,873	S.
928-932	Bits	287	D. S.

Item No.	Name of Equipment	Quantity	Status
933	Taps	4,540	S.
934-936	Dies	1,106	S.
937-944	Holdes	573	D. S.
945-947	Sockets	166	"
948	Holdes For Cutter	109	"
949-953	Arbores	467	"
954,955	Draw-in Bolt, Rods	95	"
956	Holdes For Cutters	2,864	"
957,958	Chucks For Milling M.	283	"
959	Correts For Drill	13	"
960-969	Tools For Holdes	1,813	"
970	Bits	22	"
971	Chucks-For-Cutter	382	"
972	Reamers	21	S.
973	Cutters	111	D. S.
974	Broache	10	S.
975	Dogs For Lathe	70	D. S.
976-978	Collas For Milling M.	1,217	"
979	Centers	1,860	"