

Material of shell plates 5 Thickness 1/32 Range of tensile strength 20/32 Are the shell plates welded  
rip. of riveting: cir. seams double long. seams treble butt Diameter of rivet holes in long. seams 1 1/16  
88.1

PROBITATE, WIVENHOE.  
ES. WIVENHOE. I.

The Shipyard,  
Wivenhoe, Essex.  
LATE OF THAMES STREET, GREENWICH.

13<sup>th</sup> August 1918


Mr Carey.

Enclosed is the completion form for  
trawler "William Soy", which requires to be endorsed  
by Mr Nicholas, regarding the boiler and auxiliary  
machinery. This has not been built under my supervision.  
If signature of the other Surveyors is required, I  
am not able to state.

I saw Mr. Stoddart at Wivenhoe, & handed to  
him a rough statement, of alterations in my daily visits,  
I am getting a copy done for you, at the same time  
I enclose for Mr. Nicholas & Blackie.

Kind regards  
A. B. Farmineer

In the event of Mr. Stoddart not being in  
+ you want to get in touch with me to-morrow  
at Wickes Sta. Ipswich.



© 2019

Lloyd's Register  
Foundation

W437-0097  
W437-0011

" donkey "