

```
<Qucs Schematic 0.0.16>
<Properties>
  <View=182,246,1157,944,0.742564,0,0>
  <Grid=10,10,1>
  <DataSet=adder4.dat>
  <DataDisplay=adder4.dpl>
  <OpenDisplay=1>
  <Script=adder4.m>
  <RunScript=0>
  <showFrame=0>
  <FrameText0=Title>
  <FrameText1=Drawn By:>
  <FrameText2=Date:>
  <FrameText3=Revision:>
</Properties>
<Symbol>
</Symbol>
<Components>
  <pad4bit Y1 1 300 360 -78 -60 0 3 "3" 0>
  <pad4bit Y2 1 980 350 -78 -60 0 3 "4" 0>
  <DigiSource S1 1 1000 850 -35 16 0 0 "1" 1 "low" 0 "1ns; 1ns" 0 "1 V" 0>
  <.Digi Digi1 1 620 310 0 63 0 0 "TruthTable" 1 "10 ns" 0 "Verilog" 0>
  <Sub FA1 1 500 690 -26 108 0 0 "/home/young/Work/fa.sch" 0>
  <Sub FA3 1 720 690 -26 108 0 0 "/home/young/Work/fa.sch" 0>
  <Sub FA4 1 940 690 -26 108 0 0 "/home/young/Work/fa.sch" 0>
  <Sub FA 1 280 690 -26 108 0 0 "/home/young/Work/fa.sch" 0>
</Components>
<Wires>
  <330 400 330 440 "" 0 0 0 "">
  <330 440 900 440 "" 0 0 0 "">
  <900 440 900 590 "" 0 0 0 "">
  <900 590 960 590 "A0" 950 560 15 "">
  <310 400 310 470 "" 0 0 0 "">
  <310 470 740 470 "" 0 0 0 "">
  <740 470 740 590 "A1" 770 530 94 "">
  <290 400 290 490 "" 0 0 0 "">
  <290 490 520 490 "" 0 0 0 "">
  <520 490 520 590 "A2" 550 520 57 "">
  <510 590 520 590 "" 0 0 0 "">
  <950 390 950 510 "" 0 0 0 "">
  <360 510 950 510 "" 0 0 0 "">
  <360 510 360 590 "B3" 390 530 48 "">
  <350 590 360 590 "" 0 0 0 "">
  <970 390 970 540 "" 0 0 0 "">
  <580 540 970 540 "" 0 0 0 "">
  <580 540 580 590 "B2" 610 550 42 "">
  <990 390 990 560 "" 0 0 0 "">
  <800 560 990 560 "" 0 0 0 "">
  <800 560 800 590 "" 0 0 0 "">
  <1020 390 1020 590 "B0" 1050 550 186 "">
  <1010 390 1020 390 "" 0 0 0 "">
  <850 690 890 690 "" 0 0 0 "">
  <630 690 670 690 "" 0 0 0 "">
  <400 690 410 690 "" 0 0 0 "">
  <270 400 270 590 "A3" 300 500 133 "">
  <270 590 300 590 "" 0 0 0 "">
  <1070 690 1070 850 "" 0 0 0 "">
  <1000 850 1070 850 "" 0 0 0 "">
  <450 690 470 690 "" 0 0 0 "">
  <670 690 680 690 "" 0 0 0 "">
  <410 690 450 690 "" 0 0 0 "">
  <1070 690 1070 690 "CI" 1100 660 0 "">
  <800 590 800 590 "B1" 830 560 0 "">
  <550 790 550 790 "S2" 580 760 0 "">
  <770 790 770 790 "S1" 800 760 0 "">
  <990 790 990 790 "S0" 1020 760 0 "">
  <330 790 330 790 "S3" 360 760 0 "">
```

```
<230 690 230 690 "C0" 260 660 0 ">  
</Wires>  
<Diagrams>  
</Diagrams>  
<Paintings>  
</Paintings>
```