

ANNUAL SURVEYS.

28055

No. 14 Survey held at London Date 24th Jan^y to 2nd Feb^y 1864
 on the Barque "Mathilde Octavio" Master Ouellet
 Tonnage 411 Built at Quebec When built 1866 (5 Mo.)
 By whom built Lachuel Owners E. Michon
 Port belonging to Quebec Destined Voyage "Le Havannah"
 If Surveyed Afloat or in Dry Dock Farber's Dry Dock and West India Dock.

28055
 1864

Last Survey, No. 742 Port of Quebec Classed 7. A. 1.
5.66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 15. 2 K</u>
Keelstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen.
Bottom sighted brightened to the 11 ft. Watermark, and painted with three coats of American Patent paint - Rebolted the Figure-head, and overhauled the caulking of the Buttocks. - She is in good and efficient condition, and fit, in our opinion, to remain as classed.

Committee's Minute 5th February 1864
 Character assigned 7 A 1 M.D.
J. Williamson

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____


Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Keelstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
 Character assigned _____



LOU 651 - 0423