

J-X-44

20 November 1945

J-Report-44

ANARITSU ELECTRIC COMPANY (90.17-2101) 35°52'N - 139°38'E

Plan Photo: 201

Team: PIC-J

Photos: PIC-J-16:3

Plant made telephone and wireless equipment and employed 4,000 workers (including part time). Was fire bombed on 15/16 May - 20% destroyed and 50% production loss. Cave storage being constructed nearby.

*Photo taken for Camouflage & underground - Claffer*

J-X-44

20 November 1945

J-Report-44

ANARITSU ELECTRIC COMPANY (90.17-2101) 35°52'N - 139°38'E

Plan Photo: 201

Team: PIC-J

Photos: PIC-J-16:3

Plant made telephone and wireless equipment and employed 4,000 workers (including part time). Was fire bombed on 15/16 May - 20% destroyed and 50% production loss. Cave storage being constructed nearby.

*Photo taken for camouflage & underground - Claffer*