

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 208 ✓ Weight: 2,580kg ✓ Width: 0.9 m ✓

Position Code No. 27-1 Cubage: 2.6 m³ ✓ Height: 1.3 m ✓

Machine Inventory No. : 2.254 ✓ Length: 2.2 m ✓ Set No.: _____
2.244

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
13	SURFACE PLATE
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
<i>Kawashima Shigeo</i>	
FOREMAN:	
<i>Sramutis Tituo</i>	
Name of Packer	

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 209 ✓ Weight: 2,295kg Width: 0.9 m ✓
 Position Code No. 27-1 Cubage: 2.4 m³ Height: 1.0 m ✓
 Machine Inventory No. : 2,245 ✓ 2,268 ✓ Length: 2.7 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p>✓ 16</p> <p><i>OK</i></p>	<p>SURFACE PLATE</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY: <i>Kawashima Shigeo</i></p> <p>FOREMAN: <i>Hiromitsu Tetsuo</i> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 210 ✓ Weight: 1,780Kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 1.2 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No.: 27-1-2249 ✓ Length: 1.1 m ✓ Set No.: 27-1/2 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p>7</p> <p><i>OK</i></p>	<p>SURFACE PLATE</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 211 ✓ Weight: 1,540Kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 0.9 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No.: 27-1-2249 ✓ Length: 1.1 m ✓ Set No.: 27-2/2 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

✓ 6

SURFACE PLATE

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 212 Weight: 1,200 kg Width: 1.2 m ✓
 Position Code No. 27-1 Cubage: 1.5 m³ Height: 0.3 m ✓
 Machine Inventory No. : Below Length: 1.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
29	2,270, 2,255, 2,255 2,253, 2,271, 2,257 2,266, 2,255, 2,262	SURFACE PLATE

CONDITION OF ITEM:
 Satisfactory

INSPECTED BY: Kawashima Rigea

FOREMAN: Hiramida Etsuo
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 213 ✓ Weight: 3,400k ✓ Width: 1.0 m ✓
 Position Code No. 27-i Cubage: 3.1 m³ Height: 1.1 m ✓
 Machine Inventory No. : 2,240 / 2,241 Length: 2.8 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
25	SURFACE PLATE

CONDITION OF ITEM:
 Satisfactory

INSPECTED BY: Washington Page

FOREMAN: Sramitib Tituo
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 214 ✓ Weight: 3,830kg ✓ Width: 1.3 m ✓
 Position Code No. 27-1 Cubage 3.3 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : 2,242 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
✓ 37 OK ✓	SURFACE PLATE
CONDITION OF ITEM: Satisfactory	
INSPECTED BY: <i>Ramona Stige's</i>	
FOREMAN: <i>Sirami's Tito</i> Name of Packer	

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 215 ✓ Weight: 2,430kg ✓ Width: 1.3 m ✓
 Position Code No. 27-1 Cubage: 2.8 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 2,246 Length: 2.4 m ✓ Set No.: _____
 Type of Package: CRATES DESTINATION: MANILA

Quantity	Item
33 ✓	SURFACE PLATE
<p>OK /</p>	<p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY: <i>Yoshihisa</i></p> <p>FOREMAN: <i>Shimizu Tetsuo</i> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 216 ✓ Weight 2,170Kg Width: 1.3m ✓
 Position Code No. _____ Cubage 2.0m³ ✓ Height: 1.0m ✓
 Machine Inventory No.: Below Length: 1.5m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
4	27-1-2247 ✓	SURFACE PLATE
7	2248 ✓	
35	2251 ✓	
5	2258 ✓	
6	2259 ✓	
2	2260 ✓	
1	2261 ✓	
1	2264 ✓	
3	2272 ✓	

OK

CONDITION OF ITEM:

1 Surface Plate broken.

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 217 Weight: 950kg Width: 1.0 m
 Position Code No. _____ Cubage: 1.2 m³ Height: 0.8 m
 Machine Inventory No. : See below Length: 1.5 m Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
	Machine Inventory No.
	27-1-1671 ✓
	1672 ✓
	1673 ✓
	1674 ✓
	1675 ✓
	1677 ✓
	1678 ✓
7	MACHINE VICES
1	4795 ✓ BIT HOLDER
	CONDITION OF ITEM:
	Machine Inventory No. 27-1-4795 (2) Bit holder fitting screws missing
	INSPECTED BY:
	FOREMAN: _____ Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 218 ✓ Weight: 536kg Width: 0.8 m ✓
 Position Code No. _____ Cubage: 0.4 m³ Height: 0.4 m ✓
 Machine Inventory No.: See below Length: 1.4 m ✓ Set No.: 23
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
3	Machine Inventory No. 27-1-4680 ✓ 4681 ✓ 4682 ✓ CIRCULAR TABLE for Milling
OK	CONDITION OF ITEM: Machine Inventory No. 27-1-4680 Handles Missing Worm gear change lever Broken Circular table locker " 4682 Handle Missing Handle shaft Broken
	GONDITION OF ITEM: INSPECTED BY: FOREMAN: _____ Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 219 ✓ Weight: 197kg ✓ Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.3 m³ ✓ Height: 0.5 m ✓
 Machine Inventory No. : 27-1-4683 ✓ 4712 ✓ Length: 0.9 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>2</p> <p style="font-size: 2em; margin-top: 100px;">OK ✓</p>	<p>DIVIDING HEAD</p> <p style="margin-top: 100px;">CONDITION OF ITEM: Machine Inventory No. 27-1-4712 Handle for turning Missing Handle for dividing Broken 4683 Dividing & turning handles missing</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 221 ✓ Weight: 366kg Width: 1.0 m ✓
 Position Code No. _____ Cubage: 0.7 m³ Height: 0.6 m ✓
 Machine Inventory No.: ²⁷⁻¹⁻4716-4725 ✓ Length: 1.2 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
10	CHUCKS

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 222 ✓ Weight: 795kg Width: 1.2 m ✓

Position Code No. _____ Cubage: 1.3 m³ Height: 0.9 m ✓

Machine Inventory No.: ²⁷⁻¹⁻4696-4773 Length: 1.2m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
25	<p data-bbox="931 1580 1470 1771">H696-H706 H760-H773</p> <p data-bbox="627 1755 774 1803">CHUCKS</p> <p data-bbox="1097 1819 1489 2074"><i>Check</i></p> <p data-bbox="254 2010 480 2250"><i>OK</i></p> <p data-bbox="676 2394 1097 2505">CONDITION OF ITEM: Satisfactory</p> <p data-bbox="676 2617 980 2665">INSPECTED BY:</p> <p data-bbox="950 2777 1607 2872">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 223 ✓ Weight: 800kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 0.9 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No.: See below Length: 1.3 m ✓ Set No.: _____
 Type of Package: CR. CRATE DESTINATION: MANILA

Quantity	Item
	Machine Inventory No.
	27-1-4709 ✓
	4710 ✓
	4711 ✓
	4785 ✓
	4786 ✓
	4787 ✓
	4788 ✓
	4789 ✓
10	4790 ✓
10	4791 ✓
	MACHINE VICES
	 CONDITION OF ITEM: Satisfactory
	 INSPECTED BY:
	 FOREMAN: _____ Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 224 ✓ Weight: 328 kg ✓ Width: 0.8 m ✓

Position Code No. _____ Cubage: 0.5 m³ ✓ Height: 0.5 m ✓

Machine Inventory No. : 27-1-4774-4779 ✓ Length: 1.3 m ✓ Set No.: _____

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
6	FACE PLATE

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 225 ✓ Weight: 840kg ✓ Width: 0.9 m ✓

Position Code No. _____ Cubage: 0.8 m³ ✓ Height: 0.8 m ✓

Machine Inventory No. : See below Length: 1.1 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

6	Machine Inventory No.
	27-1-4707 ✓
	4780 ✓
	4781 ✓
	4782 ✓
	4783 ✓
	4784 ✓ FACE PLATES

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 226 ✓ Weight: 2,400kg Width: 2.1 m ✓
 Position Code No. _____ Cubage: 6.0 m³ Height: 0.9 m ✓
 Machine Inventory No. 27-1-9909-10092 ✓ Length: 3.2 m ✓ Set No.: _____
 Type of Package: OPEN GRATE DESTINATION: MANILA

Quantity	Item																					
184	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <p>Machine Inventory No.</p> <table style="margin-left: 40px;"> <tr> <td>9938</td> <td>Frame</td> <td>Broken.</td> </tr> <tr> <td>9939</td> <td>"</td> <td>"</td> </tr> <tr> <td>9950</td> <td>Handle</td> <td>"</td> </tr> <tr> <td>9972</td> <td>Frame</td> <td>"</td> </tr> <tr> <td>10069</td> <td>"</td> <td>"</td> </tr> <tr> <td>10039</td> <td>"</td> <td>"</td> </tr> <tr> <td>10036</td> <td>"</td> <td>"</td> </tr> </table> <p style="margin-left: 40px;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">INSPECTED BY:</p> <p style="margin-left: 100px;">FOREMAN: _____</p> <p style="margin-left: 120px;">Name of Packer</p>	9938	Frame	Broken.	9939	"	"	9950	Handle	"	9972	Frame	"	10069	"	"	10039	"	"	10036	"	"
9938	Frame	Broken.																				
9939	"	"																				
9950	Handle	"																				
9972	Frame	"																				
10069	"	"																				
10039	"	"																				
10036	"	"																				

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 228 ✓ Weight: 2700kg Width: 2.2 m ✓
 Position Code No. _____ Cubage: 6.8 ¹³ Height: 1.0 m ✓
 Machine Inventory No. : 10395-10693 ²⁷⁻¹ Length: 3.1 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>299</p> <p><i>OK</i></p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <p>(5) Molding boxes partly broken</p> <p>(7) Handles broken</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 230 ✓ Weight: 1,000kg ✓ Width: 1.3 m ✓
 Position Code No. 27-1-10828-11003 ✓ Cubage: 1.8 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. 27-1-10828-11003 ✓ Length: 1.5 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANIA

Quantity	Item
<p>176</p> <p><i>OK</i></p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM: Machine Inventory No. 27-1-10844 10907 10867 10934 10869 10937 10877 10981 10886</p> <p>Frame Partly broken</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 232 ✓ Weight: 600kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 1.4 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-11063-11127 ✓ Length: 1.6 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item																		
65	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <table border="0"> <tr> <td>Machine Inventory No.</td> <td>Frame</td> <td>Partly broken</td> </tr> <tr> <td>27-1-11073</td> <td>"</td> <td>"</td> </tr> <tr> <td>11074</td> <td>"</td> <td>"</td> </tr> <tr> <td>11086</td> <td>(1) Handle</td> <td>Broken</td> </tr> <tr> <td>11118</td> <td>" "</td> <td>"</td> </tr> <tr> <td>11064</td> <td>" "</td> <td>"</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	Machine Inventory No.	Frame	Partly broken	27-1-11073	"	"	11074	"	"	11086	(1) Handle	Broken	11118	" "	"	11064	" "	"
Machine Inventory No.	Frame	Partly broken																	
27-1-11073	"	"																	
11074	"	"																	
11086	(1) Handle	Broken																	
11118	" "	"																	
11064	" "	"																	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 233 ✓ Weight: 2000kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 5.1 m³ Height: 1.3 m ✓
 Machine Inventory No. : 11128²⁷-11187 ✓ Length: 2.6m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>60</p> <p><i>OK</i></p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM: (3) Molding boxes partly broken</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 236 ✓ Weight: 1,650kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : 27-1-11247-11410 ✓ Length: 2.6 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>164</p> <p style="font-size: 2em; font-weight: bold; margin-top: 50px;">OK</p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <p>Machine Inventory No. Frame Partly broken 27-1-11339</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 237 ✓ Weight: 1,500kg Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.7 m³ Height: 1.0 m ✓
 Machine Inventory No.: 11411-11551 ✓ Length: 2.6 m ✓ Set No.: _____
 Type of Package: OPEN GRATE DESTINATION: MANILA

Quantity	Item
<p>141</p> <p><i>OK</i></p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 238 ✓ Weight: 1,550kg Width: 1.8 m ✓
Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.0 m ✓
Machine Inventory No. : 27-1-11552-11692 ✓ Length: 2.6 m ✓ Set No.: _____
Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>141</p> <p>OK ✓</p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <p>Machine Inventory No. 27-1-11609 Frame Partly broken 11665 " " "</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 239 ✓ Weight: 2050kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 4.2 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. 27-1-11693-11817 ✓ Length: 2.8 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>125</p> <p><i>OK</i></p>	<p>MOLDING BOXES</p> <p>CONDITION OF ITEM:</p> <p>(3) Molding boxes handle broken</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 240 ✓ Weight: 240 Kg ✓ Width: 0.8 m ✓
 Position Code No. _____ Cubage: 0.6 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No.: See below Length: 1.0 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p>	<p>Machine Inventory No. 27-1- ✓ 11818 thru 11838 ✓ MOLDING BOX</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 241 ✓ Weight: 445kg ✓ Width: 2.5 m ✓
 Position Code No. _____ Cubage: 5.6 m³ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-11952 ✓ Length: 1.5 m ✓ Set No.: _____
 Type of Package: SEMI OPEN CRATE DESTINATION: MANILA

Quantity	Item
1	OIL TANK

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 242 ✓ Weight: 540kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 1.0 m³ Height: 0.8 m ✓
 Machine Inventory No. : 27-1-11839-11903 ✓ Length: 1.3 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
65	MOLDING BOXES
	CONDITION OF ITEM:
	Machine Inventory No. 27-1-11837 Body partly broken 11865, 11873) 11885, 11888) (4) Knobs Broken 11897 (1) Knob Partly Broken
	CONDITION OF ITEM:
	INSPECTED BY:
	FOREMAN: _____ Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 243 ✓ Weight: 273kg ✓ Width: 0.8 m ✓

Position Code No. _____ Cubage: 0.6 m³ Height: 0.8 m ✓

Machine Inventory No. : 27-1-2044 Length: 1.0 m ✓ Set No.: _____

Type of Package: BOX DESTINATION: MANLALUNG

Quantity	Item
----------	------

1	MOTOR INDUCTION
---	-----------------

OT

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 244 ✓ Weight: 1550kg Width: 1.6 m ✓
 Position Code No. _____ Cubage: 6.0 m³ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-105-R20 Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE⁴³ DESTINATION: MANILA

Quantity	Item
<p>1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">CENTRIFUGAL SEPARATOR</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM:</p> <p style="text-align: center;">Leg Broken</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____</p> <p style="text-align: center;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 245 ✓ Weight: 120kg ✓ Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.4 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. :27-1-103-R33 ✓ Length: 0.7 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">TRANSFORMER</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM:</p> <p style="text-align: center;">Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____</p> <p style="text-align: center; margin-top: 5px;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 246 Weight: 1980kg Width: 1.1 m
 Position Code No: _____ Cubage: 3.6 m³ Height: 1.1 m
 Machine Inventory No. : _____ See below Length: 3.0 m Set No.: 28-1/31
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item No.	Item
268	1-6	SLOG HAMMERS, assorted
378	7-19	SPANNERS, assorted
22	20-21	WRENCHES, assorted
90	22-24	DIE HANDLES
390	25-28	TAP HANDLES
691	29	HAND VICES
37	30	"C" CLAMPS
50	31	SMALL JACKS
68	32	TONGS
16	33	FLATTERS
746	34	CENTER PUNCHES
1	35	TORCH LAMP
7	37	WIRE DRAW VICES
399	38	DRIVERS
3	39	DRILL CUTTERS
19	40	HAND BELLOWS
8	49	BRICK TROWELS
11	50	PAINTER'S TROWELS
54	51	FOUNDRY TROWELS
60	53	CARPENTOR'S HAND DRILLS
6	54	CARPENTOR'S MARKING PLANERS

CONDITION OF ITEM:
 Item No.
 1-3,6 Handles Missing
 5 In bad condition
 20 (9) Chain missing

CONDITION OF ITEM:
 55-56 PAINTERS BRUSHES
 2 57 OIL SYRINGES

INSPECTED BY: *Kawashima Seigeo*

FOREMAN: *Hiromitsu Tetsuo*
 Name of Packer

(addition)
 238

73-76

CUTTING BIT (addition)

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 247 ✓ Weight: 779Kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 3.6 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. See below Length: 2.0 m ✓ Set No.: 28-2/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	
	Item No.	
49	41 ✓	OIL STONES
552	42 ✓	" "
97	43 ✓	" "
72	44 ✓	" "
80	45 ✓	" "
106	46 ✓	" "
1970	47 ✓	FILE HANDLES
4826	48 ✓	FILE BRUSHES

OK

CONDITION OF ITEM:

Item No. OIL STONES Satisfactory
 41-46
 48 FILE BRUSHES 310 pcs. In bad condition

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 248 ✓ Weight: 2,970kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.7 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No.: See below Length: 2.4 m ✓ Set No.: 28-3/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item No.	Item
	59 ✓	CUTTING BITS
	60 ✓	" "
	61 ✓	" "
	62 ✓	" "
	63 ✓	" "
	64 ✓	BIT-TIPS
	65 ✓	CUTTING BITS
	66 ✓	" "
	67 ✓	" "
	68 ✓	" "
	69 ✓	" "
752		
280		
747		
641		
60		
379		
6,242		
111		
467		
449		
125		

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 249 ✓ Weight: 2,900kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.7 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No.: See below Length: 2.4 m ✓ Set No.: 28-4/31 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
	Item No.
81	70 ✓
38	71 ✓
2812	72 ✓
37	73 ✓
81	74 ✓
2669	75 ✓
34	76 ✓
42	78 ✓
153	79 ✓
	CUTTING BITS
	" "
	" "
	" "
	" "
	" "
	" "
	" "

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 250 ✓ Weight: 2,600kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.7 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : Item 77 ✓ Length: 2.4 m ✓ Set No.: 28-5/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1641	CUTTING BITS

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 251 ✓ Weight: 3,000kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.7 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : See below Length: 2.4 m ✓ Set No.: 28-6/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
	Item No.
3	80 ✓ BIT SHANKS
16	81 ✓ " "
2	82 ✓ " "
1,815	83 ✓ " "
67	84 ✓ " "
526	86 ✓ " "
94	87 ✓ " "
229	88 ✓ " "
1	89 ✓ " "
26	90 ✓ " "
729	91 ✓ " "
1,734	92 ✓ " "
6	95 ✓ " "
51	96 ✓ " "
14	97 ✓ " "
97	98 ✓ SCREW CUTTING BIT
	CONDITION OF ITEM:
	Satisfactory
	INSPECTED BY:
	FOREMAN: _____
	Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 252 ✓ Weight: 264kg ✓ Width: 0.4 m ✓
 Position Code No. _____ Cubage: 0.1 m³ ✓ Height: 0.3 m ✓
 Machine Inventory No.: Item 85 ✓ Length: 0.8 m ✓ Set No. 2877/31 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>534</p> <p><i>OK</i></p>	<p>BIT MATERIAL</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 253 ✓ Weight: 1,830Kg Width: 1.0 m ✓
 Position Code No. _____ Cubage: 1.4 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : See below Length: 1.7 m ✓ Set No. 28-8/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
350	Item No. 93 ✓ BIT SHANKS
932	Item No. 94 ✓ BIT SHANKS
<div style="font-size: 2em; font-family: cursive;">OK</div>	<p>CONDITION OF ITEM:</p> <p style="text-align: center;">Satisfactory</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____</p> <p style="text-align: right;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 254 Weight: 2690kg Width: 1.2 m
 Position Code No. _____ Cubage: 2.3 m³ Height: 0.9 m
 Machine Inventory No. : See below Length: 2.1 m Set No.: 28-9/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	
	Item No.	
12148	99-123	TWIST DRILLS
1890	124-133	HAND REAMERS
42	134-138	MACHINE REAMERS
59	139-142	HAND REAMERS
197	73-77	CUTTING BIT (addition)

CONDITION OF ITEM:
 Satisfactory

INSPECTED BY: *Kawabino Shigeo*

FOREMAN: *Niimata Tetsuo*
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 255 Weight: 2650kg Width: 1.2 m
 Position Code No. _____ Cubage: 2.5 m³ Height 0.9 m
 Machine Inventory No. : See below Length: 2.3 m Set No.: 28-10/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
12639 1515	Item No. 143-156 157-176 177, 179, 184-185, 188-189 191, 193, 195, 199-222
3733 707	273-287, 289-295, 297-300 301-313, 316-320 223-235, 237-239, 243 245-266, 268-272, 322-340
7 sets & 757	342, 344-356, 358-360 374-392 361-363, 365-366
16	368-370, 373 CUTTERS, assorted GEAR HOBS
152	75-76 CUTTING BIT (addition)
	CONDITION OF ITEM: satisfactory
	INSPECTED BY: <i>Kawashima Shigeo</i>
	FOREMAN: <i>Hiramitsu Tatsuo</i> Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 256 ✓ Weight: 1600kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 1.2 m ✓ Height: 0.7 m ✓
 Machine Inventory No. : See below Length: 1.7 m ✓ Set No.: 28-11/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
	Item No.
525	394-396 ✓ FILES, flat
319	397-399 ✓ FILES, half-round
2168	400-402 ✓ FILES, square
1845	403-405 ✓ FILES, round
829	406-408 ✓ FILES, three-cornered
112	409 ✓ FILES, small, flat
5	410 ✓ FILES, small half-round
11	411 ✓ FILES, small square
54	412 ✓ FILES, small, round
24	413 ✓ FILES, small, ellipse
12	414 ✓ FILES, small, three-cornered
7	415 ✓ FILES, small, flat lanky-head & one side flat
47	416-417 ✓ FILES, assorted size
3	418 ✓ FILES, flat for wood
7	419 ✓ FILES, half round for wood
7	420 ✓ FILES, flat for lead
34	421 ✓ FILES, half round for lead
	CONDITION OF ITEM:
	Satisfactory
	INSPECTED BY:
	FOREMAN: _____
	Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 257 ✓ Weight: 1,860Kg Width: 1.4 m ✓
 Position Code No. _____ Cubage: 4.0 m³ Height: 0.9 m ✓
 Machine Inventory No. : See below Length: 3.2 m Set No.: 28-12/31 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item	
	Item No.	
1061	422 ✓	GRINDING WHEELS
1044	423 ✓	" "
281	424 ✓	" "
79	425 ✓	" "
446	426 ✓	" "
103	427 ✓	" "
330	428 ✓	" "

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 258 Weight: 2020kg Width: 1.6 m
 Position Code No. _____ Cubage: 4.0 m³ Height: 1.0 m
 Machine Inventory No. : Item 429 Length: 2.5 m Set No.: 28-13/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item									
464	GRINDING WHEELS									
420	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Item No.</td> <td style="width: 40%;">CUTTING BIT</td> <td style="width: 45%;">(addition)</td> </tr> <tr> <td style="text-align: center;">65</td> <td></td> <td style="text-align: center;">"</td> </tr> <tr> <td style="text-align: center;">92</td> <td>75-76</td> <td style="text-align: center;">"</td> </tr> </table>	Item No.	CUTTING BIT	(addition)	65		"	92	75-76	"
Item No.	CUTTING BIT	(addition)								
65		"								
92	75-76	"								
CONDITION OF ITEM: Satisfactory										
INSPECTED BY: <i>Kawachiima Shigeo</i>										
FOREMAN: <i>Saramita Tetsuo</i> Name of Packer										

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 258 ✓ Weight: 1850kg ✓ Width: 1.6 m ✓
 Position Code No. _____ Cubage: 4.0 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : ^{Item} 429 ✓ Length: 2.5 m ✓ Set No.: 28-13/313 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>464</p> <p><u>OK</u></p>	<p>GRINDING WHEELS</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____</p> <p>Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 259 ✓ Weight: 1100kg ✓ Width: 1.4 m ✓
 Position Code No. _____ Cubage: 2.9 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : See below Length: 2.1 m ✓ Set No.: 28-14/31
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item		
	Item No.		
20	430 ✓	GRINDING	WHEELS
22	432 ✓	" "	" "
19	435 ✓	" "	" "
29	436 ✓	" "	" "
366	437 ✓	" "	" "

Re work

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 260 Weight: 980kg Width: 1.1 m
 Position Code No: _____ Cubage: 2.0 m³ Height: 1.0 m
 Machine Inventory No.: Item 443 Length: 1.8 m Set No.: 28-15/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
879	CUTTING WHEELS
200	Item No. 23 DIES HANDLE (addition)

CONDITION OF ITEM:

(40) pcs. Partly broken

INSPECTED BY: Kawashima Shigeo

FOREMAN: Suzumoto Tetsuo
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 261 ✓ Weight: 1550kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 2.6 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : Item 431 ✓ Length: 2.0 m ✓ Set No.: 28-16/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
207	GRINDING WHEELS

OK ✓

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 262 Weight: 1730kg Width: 1.3 m
 Position Code No. _____ Cubage: 3.3 m³ Height: 1.1 m
 Machine Inventory No.: Item 431 Length: 2.3 m Set No.: 28-17/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
207	GRINDING WHEELS
146	Item No. 73-77 CUTTING BIT (addition)

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Kawashima Shigeo

Maramba Tetsuo

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 263 Weight: 2320kg Width: 1.8 m
 Position Code No. _____ Cubage: 5.0 m³ Height: 0.9 m
 Machine Inventory No.: Item 433 Length: 3.1 m Set No.: 29-18/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
207	GRINDING WHEELS
	Item No.
13	6 Wooden hammer (addition)
4	18 Set wrench (")
10	29 Hand vice (")
400	32 Tong (")
50	38 Screw driver (")
50	449 Hand chisel (")
60m	480 Cotton belt (")
3	486 "V" belt (")
24	551 Gas welding burner (")
	CONDITION OF ITEM:
	Satisfactory <i>Kawachino Shigeo</i>
	INSPECTED BY: <i>Sirami...</i>
	FOREMAN: _____
	Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 264 Weight: 1090kg Width: 1.3 m

Position Code No. _____ Cubage: 2.6 m³ Height: 1.0 m

Machine Inventory No. : 438-442 Length: 2.0 m Set No.: 28-19/31

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
	Item No.
54	434 GRINDING WHEELS
2	438 " "
76	439 " "
120	440 " "
145	441 " "
2413	442 " "
24	425 Grinding wheel (addition)
93	426 " "
19	427 " "
4	431 " "
1	432 " "
1	435 " "
18	441 " "

CONDITION OF ITEM:

434 (1)pc. Partly broken
 439 (2)pcs. " "
 440 (2)pcs. " "
 441 (3)pcs. " "

INSPECTED BY:

Ramon S. Pigea

FOREMAN:

Miriam T. Tavares
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 265 Weight: 1150Kg Width: 1.2 m
 Position Code No. _____ Cubage: 3.3 m³ Height: 1.3 m
 Machine Inventory No.: See below Length: 2.1 m Set No. 28-20/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item No.	Item
173	444-447	SCREW CHAISERS
360	448-451	CHISELS
2261	452-454	LETTER PUNCHES
668	455-	SCRAPERS
3	456	PIPE CUTTERS
5	458	SEALING PUNCHES
6	459	BOLT CLIPPERS
25	460	CENTER DRILL
1536 & 32.6m	462, 467-476 479-482 484-487	BELT, assorted
1916	488	BELT LACKING
75	77	CUTTING BITS (Addition)
1	561	BALL BEARING

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 266 ✓ Weight: 400kg Width: 0.8 m ✓
 Position Code No. _____ Cubage: 1.0 m³ ✓ Height: 0.4 m ✓
 Machine Inventory No. : See below Length: 3.2 m ✓ Set No.: 28-21/31 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
	<p style="text-align: center;">Item No.</p>
74	<p style="text-align: center;">489 ✓ SCALES</p>
38	<p style="text-align: center;">✓ 495-497 ✓ STRAIGHT EDGES</p>
<p style="font-size: 2em; font-weight: bold;">OK</p>	<p>CONDITION OF ITEM: Satisfactory</p>
	<p>INSPECTED BY:</p>
	<p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 267 ✓ Weight: 950kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 2.3 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : See below Length: 2.1 m ✓ Set No.: 28-22/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	CONDITION OF ITEM:
	Item No.	
680	491 ✓ OUTSIDE CALIPERS	
1044	492 ✓ INSIDE CALIPERS	
27	493 ✓ COMPUSSES	
16	494 ✓ SPRING COMPUSSES	
74	✓ 498-501 SQUARES	
24	521 ✓	
	-522 ✓ RULE STANDS (7) pcs.	Broken
63	523 ✓	
	-528 ✓ SURFACE GAUGES (40) pcs.	"

OK

~~CONDITION OF ITEM:~~

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 268 ✓ Weight: 350kg ✓ Width: 1.1 m ✓
 Position Code No. _____ Cubage: 1.1 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No.: See below Length: 1.3 m ✓ Set No.: 28-23/31 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item No.	Item
405	✓ 490 ✓	SCRIBORS
2	457 ✓	GRINDING WHEELS (Diamont)
8	461 ✓	DIAMOND TOOLS
8	✓ 503-504 ✓	CALIPERS
11	505 ✓	INSIDE MICROMETERS
4	✓ 506 ✓	GAUGES
1441	✓ 508-514 ✓	GAUGES (ASSORTED)
1	✓ 515 ✓	GAUGES STAND
17	✓ 516-519 ✓	GAUGES (ASSORTED)
1	530 ✓	PHYROMETER
1	532 ✓	TACHEOMETER
1	534 ✓	GEAR TOOTH CALIPER
3	535 ✓	PROTRACTORS
2	536 ✓	LEVELS Sq. type
1	537 ✓	CLINOMETER
4	539 ✓	MICROMETER STANDS
39	548-549 ✓	TORCHES
76	550-551 ✓	BURNERS (NOZZLE)
1	552 ✓	REDUCING VALVE
2	553 ✓	ELECTRIC WELDER POLES
215	561 ✓	BALL BEARINGS

CONDITION OF ITEM:
 Item No. (5) Calipers out of order
 508 (1) Lense missing
 530 (1) Thermocouple missing (Useless)

INSPECTED BY:

FOREMAN: _____
 Name of Packer

OK ✓

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 269 ✓ Weight: 1,720kg ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 2.4 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : See below Length: 1.7 m ✓ Set No. 28-24/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
	Item No.
36	540 ✓ V BLOCK
38	541 ✓ SQUARE BLOCKS
1	543 ✓ V BLOCK
1	547 ✓ SQUARE BLOCK

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 270 ✓ Weight: 2,220kg Width: 1.0 m ✓
 Position Code No. 27-1 ✓ Cubage: 3.5 m³ Height: 1.5 m ✓
 Machine Inventory No. : Below Length: 2.4 m ✓ Set No.: 28-25/31
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item																								
2	5,232 5,285	FACE PLATE																								
5	5,316-5,320	CIRCULAR TABLE																								
20	5,288, 5,357, 5,376, 5,380 5,385, 5,404, 5,453, 5,450 5,348, 5,349, 5,395-5,396 5,427-5,432	LATHES CHUCK																								
<p>CONDITION OF ITEM:</p> <table border="0"> <tr> <td>Machine Inventory No.</td> <td>5,453</td> <td>Missing parts:</td> </tr> <tr> <td></td> <td>5,427</td> <td>Jaw 1</td> </tr> <tr> <td></td> <td>5,376</td> <td>Jaw 2</td> </tr> <tr> <td></td> <td>5,432</td> <td>Jaw 1, Feed screw 1</td> </tr> <tr> <td></td> <td>5,396</td> <td>Feed screw 2</td> </tr> <tr> <td></td> <td>5,428</td> <td>Jaw 1, Feed screw 4</td> </tr> <tr> <td></td> <td>5,431</td> <td>Jaw 4 Feed screw 1</td> </tr> <tr> <td></td> <td></td> <td>Jaw 1 Feed screw 1</td> </tr> </table> <p>CONDITION OF ITEM:</p>			Machine Inventory No.	5,453	Missing parts:		5,427	Jaw 1		5,376	Jaw 2		5,432	Jaw 1, Feed screw 1		5,396	Feed screw 2		5,428	Jaw 1, Feed screw 4		5,431	Jaw 4 Feed screw 1			Jaw 1 Feed screw 1
Machine Inventory No.	5,453	Missing parts:																								
	5,427	Jaw 1																								
	5,376	Jaw 2																								
	5,432	Jaw 1, Feed screw 1																								
	5,396	Feed screw 2																								
	5,428	Jaw 1, Feed screw 4																								
	5,431	Jaw 4 Feed screw 1																								
		Jaw 1 Feed screw 1																								

OK

INSPECTED BY: *Kawashima Shigeo*

FOREMAN: *Siramoto Tetsuo*
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 271 Weight: 1,620Kg Width: 1.2 m
 Position Code No. _____ Cubage: 2.0 m³ Height: 0.8 m
 Machine Inventory No.: See below Length: 2.1 m Set No.: 28-26/31
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
13	27-1-5456 ✓ 5464 ✓ 5478-5479 ✓	
11	✓ 5519-5525 ✓ 5535-5536 ✓	DIE HEADS
	✓ 5551-5553 ✓ 5581-5587 ✓ 5604 ✓	DRILL CHUCKS
	✓ 5709-5743 ✓ 5866-5882 ✓ 5934-5938 ✓	
135	✓ 5984-5994 ✓ 6153-6198 ✓ 6309-6314 ✓	
	✓ 6332-6333 ✓ 6370-6380 ✓ 6411-6412 ✓	DRILL SOCKETS
223	✓ 7297 ✓ 7345-7359 ✓ 7553-7606 ✓	
63	✓ 7904-7966 ✓ 8360-8449 ✓	CENTER, Lathe
68	✓ 8821-8883 ✓	DRESSOR HANDLES
10	✓ 9217-9284 ✓	BIT HOLDERS
	✓ 9442-9448 ✓ 9471-9473 ✓	MILLING ARBORS
	✓ 9489 9562-9569 ✓ 9507-9511 ✓	
30	✓ 9652 9620-9630 ✓	
	✓ 9483 ✓ 9530-9532 ✓	ANGLE PLATES
	✓ 6641-6645 ✓ 6675-6680 ✓ 6726-6736 ✓	
	✓ 6789-6798 ✓ 6830-6833 ✓ 6852-6853 ✓	
	✓ 6895-6906 ✓ 6964-6974 ✓ 7030-7040 ✓	
111	✓ 7089-7096 ✓ 7135-7141 ✓ 7177-7184 ✓	LATHE DOGS
	✓ 7214-7218 ✓ 7263-7273 ✓	
	CONDITION OF ITEM:	
	Machine Inventory No.	
	CONDITION OF ITEM:	
	27-1-5455	Handle, Chaser binding metal Missing
	5436	Handle "
	6831 6903 6900	Binding screws "
	7030 7036	" Bent
	INSPECTED BY:	
	FOREMAN: _____	
	Name of Packer	

OT

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 272 ✓ Weight: 1,465kg ✓ Width: 1.0 m ✓
 Position Code No. 27-1 Cubage: 1.5 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No. Below Length: 2.1 m ✓ Set No.: 28-27/31 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
✓ 35	5,298, 6,622 6,521-6,529 6,589-6,592	6,455-6,458 6,562-6,566 6,610, 6,611 BIT HOLDERS

CONDITION OF ITEM:

Missing parts:
 Bit binding screw 35

INSPECTED BY:

[Handwritten Signature]

FOREMAN:

[Handwritten Signature]
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 273 ✓ Weight: 2,475Kg Width: 1.4m ✓
 Position Code No. _____ Cubage: 3.5m³ ✓ Height: 0.9m ✓
 Machine Inventory No.: Below Length: 2.8m ✓ Set No.: 28-28/31 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
21	27-1-5225 ✓ ✓ 9727-9744 ✓ ✓ 9661-9662 ✓	MACHINE VICE
2	✓ 5335-5336 ✓	DIVIDING HEAD
15	9669 ✓ ✓ 9823-9836 ✓	BENCH VICE

OK ✓

CONDITION OF ITEM:
Machine Inventory

No.	No.	No.	Item
9823	9829	9832) Handle missing
9826	9830	9834	
9828	9831	9835	
9824	9828	9835) Spindle part out of order
9825	9833	9836	
9824			Vice clamp missing
9825			Body broken
5535			Chuck missing
5536			Dividing handle broken
9727-9744			Handles missing

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 274 Weight: 470kg Width: 1.1 m
 Position Code No. _____ Cubage: 1.6 m³ Height: 0.6 m
 Machine Inventory No. : See below Length: 2.4 m Set No.: 28-29/31
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
	Item No.
20	562 GRAPHITE CRUCIBLES
1	563 GRAPHITE CRUCIBLES
20	568 Pressure gauge (addition)
CONDITION OF ITEM:	
	Item No.
	563 CRUCIBLE Broken
INSPECTED BY: <i>Kawashima Shigeo</i>	
FOREMAN: <i>Sumita T.</i>	
Name of Packer	

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 275 ✓ Weight: 450kg ✓ Width: 1.1 m ✓
 Position Code No. _____ Cubage: 1.6 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : Item 562 ✓ Length: 2.4 m ✓ Set No.: 28-30/31 ✓
 Type of Package: BCX DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center; margin-top: 200px;">21</p>	<p style="text-align: center;">GRAPHITE CRUCIBLES</p> <p style="text-align: center; margin-top: 150px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 50px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 50px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 276 ✓ Weight: 78kg ✓ Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.2 m³ ✓ Height: 0.4 m ✓
 Machine Inventory No.: See below Length: 0.9 m ✓ Set No.: 28-31/31
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
	Item No.
	PRESSURE GAUGE
1	564 ✓
4	565 ✓
5	566 ✓
13	567 ✓
16	568 ✓
2	569 ✓
	" "
	" "
	" "
	" "
	" "
	" "
	" "
	" "

OK /

CONDITION OF ITEM:

Item No.	Glass (1)	Broken
567		

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 277 Weight: 1915kg Width: 1.9 m
Position Code No. _____ Cubage: 9.7 m³ Height: 1.7 m
Machine Inventory No. : 27-1-1664 Length: 3.0 m Set No.: 29-1/3
Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	HOIST for Crane
1	GEARS w/accessories

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 278 ✓ Weight: 2747kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 7.5 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : 27-1-1664 ✓ Length: 8.3 m ✓ Set No.: 29-2/3 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p>OK</p>	<p>SUPPORT STRUCTURE (Travelling)</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 280 ✓ Weight: 1915kg ✓ Width: 1.9 m ✓
 Position Code No. _____ Cubage: 9.7 m³ ✓ Height: 1.7 m ✓
 Machine Inventory No. : 27-1-1665 ✓ Length: 3.0 m ✓ Set No.: 30-1/3 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	HOIST for Crane
1	GEARS w/accessories
1	BASE

OK

CONDITION OF ITEM:

Traveling wheel Partly cracked

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 281 Weight: 2747kg Width: 1.5 m
 Position Code No. _____ Cubage: 7.5 m³ Height: 0.6 m
 Machine Inventory No.: 27-1-1665 Length: 8.3 m Set No.: 30-2/3
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
1	<p>TRAVELING SUPPORT STRUCTURE</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 282 Weight: 540kg Width: 0.4 m

Position Code No. _____ Cubage: 1.2 m³ Height: 0.3 m

Machine Inventory No. : 27-1-1665 Length: 10.0 m Set No.: 30-3/3

Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>4 Sections</p> <p><i>OK</i></p>	<p>RAILES</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
Package No. 283 ✓ Weight: 1,770Kg Width: 2.1 m
Position Code No. _____ Cubage: 9.2 m³ ✓ Height: 1.1 m ✓
Machine Inventory No. : 27-1-2377 ✓ Length: 4.0 m ✓ Set No.: 31-1/13 ✓
Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

6

UPRIGHT COLUMNS

OK

CONDITION OF ITEM:

Satisfactory

(10) Rivets Missing

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 284 ✓ Weight: 1.770Kg Width: 2.1 m ✓
 Position Code No. _____ Cubage: 9.2 m³ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-2377 ✓ Length: 4.0 m Set No.: 31-2/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>6</p> <p><i>OK</i></p>	<p>UPRIGHT COLUMNS</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>(4) Rivets Missing</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____</p> <p>Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 286 ✓ Weight: 1,770kg ✓ Width: 2.1 m ✓

Position Code No. _____ Cubage: 9.2 m³ ✓ Height: 1.1 m ✓

Machine Inventory No. : 27-1-2377 Length: 4.0 m ✓ Set No.: 31-4/13 ✓

Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

OK ✓

6 UPRIGHT COLUMNS

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 287 ✓ Weight: 1,770kg ✓ Width: 2.1 m ✓

Position Code No. 27-1-2377 Cubage: 9.2 m³ ✓ Height: 1.1 m ✓

Machine Inventory No. : 27-1-2377 Length: 4.0 m ✓ Set No.: 31-5/13 ✓

Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

6

UPRIGHT COLUMNS

OK
/

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 288 ✓ Weight: 1,770kg ✓ Width: 2.1 m ✓
 Position Code No. _____ Cubage: 9.2 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-2377 ✓ Length: 4.0 m ✓ Set No.: 31-6/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
6	UP RIGHT COLUMNS
6	UPRIGHT COLUMNS
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 289 ✓ Weight: 1,770kg Width: 2.1 m ✓
 Position Code No. _____ Cubage: 9.2 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-2377 Length: 4.0 m ✓ Set No.: 31-7/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
6 ⁶	<p data-bbox="607 1643 1009 1739">UP RIGHT COLUMNS UPRIGHT COLUMNS</p> <p data-bbox="676 2394 1097 2505">CONDITION OF ITEM: <u>Satisfactory</u></p> <p data-bbox="686 2521 1342 2585">(36) Rivets Missing</p> <p data-bbox="676 2617 989 2681">INSPECTED BY:</p> <p data-bbox="940 2761 1617 2888">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 290 ✓ Weight: 1,770kg Width: 2.1 m ✓
 Position Code No. _____ Cubage: 9.2 m³ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-2377 Length: 4.0 m ✓ Set No.: 31-8/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

6	UP RIGHT COLUMNS
6	UPRIGHT COLUMNS

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 291 ✓ Weight: 4,772kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 12.7 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-2377 ✓ Length: 9.4 m ✓ Set No.: 31-9/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item								
<p>6</p> <p style="font-size: 2em; margin-left: 20px;">OK</p>	<p>HORIZONTAL GIRDERS</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 70%;">(19) Connecting plates</td> <td style="width: 30%;">Missing</td> </tr> <tr> <td>(286) Rivets</td> <td>"</td> </tr> <tr> <td>(126) Bolts</td> <td>"</td> </tr> <tr> <td>Girder</td> <td>Bent</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	(19) Connecting plates	Missing	(286) Rivets	"	(126) Bolts	"	Girder	Bent
(19) Connecting plates	Missing								
(286) Rivets	"								
(126) Bolts	"								
Girder	Bent								

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 292 ✓ Weight: 4,772kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 12.7 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-2377 Length: 9.4 m ✓ Set No.: 31-10/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>6</p> <p>OK</p>	<p>HORIZONTAL GIRDERS</p> <p>CONDITION OF ITEM:</p> <p>(15) Connecting plates Missing (256) Rivets " (54) Bolts Bent Girder</p> <p>CONDITION OF ITEM: Rating <u>Satisfactory</u></p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 293 ✓ Weight: 4.772Kg Width: 1.5 m ✓
 Position Code No. _____ Cubage: 12.7 m³ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-2377 Length: 9.4 m Set No.: 31-11/13 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item							
6	HORIZONTAL GIRDERS							
OK /	CONDITION OF ITEM:							
	<table> <tr> <td>(18) Connecting plates</td> <td>Missing</td> </tr> <tr> <td>(266) Rivets</td> <td>"</td> </tr> <tr> <td>(46) Bolts</td> <td>Bent</td> </tr> <tr> <td>Girder</td> <td>Bent</td> </tr> </table>	(18) Connecting plates	Missing	(266) Rivets	"	(46) Bolts	Bent	Girder
(18) Connecting plates	Missing							
(266) Rivets	"							
(46) Bolts	Bent							
Girder	Bent							
	CONDITION OF ITEM:							
	Satisfactory							
	INSPECTED BY:							
	FOREMAN: _____ Name of Packer							

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 294 Weight: 4,772kg Width: 1.5 m
 Position Code No. _____ Cubage: 12.7 m³ Height: 0.9 m
 Machine Inventory No. : 27-1-2377 Length: 9.4 m Set No.: 31-12/13
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

6	HORIZONTAL GIRDERS
---	--------------------

CONDITION OF ITEM:
 (25) Connecting plates Missing
 (261) Rivets " "
 (20) Bolts " "
 Girder Bent

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 295 Weight: 1,820kg Width: 0.8 m

Position Code No. _____ Cubage: 3.2 m Height: 0.4 m

Machine Inventory No. : 27-1-2377 Length: 9.9 m Set No.: 31-13/13

Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

14	RAILS ✓
----	---------

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 296 ✓ Weight: 5000kg ✓ Width: 1.4 m ✓
 Position Code No. _____ Cubage: 5.5 m³ ✓ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 2.6 m ✓ Set No. 16-3/11 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">CENTER PISTON for forming press</p> <p style="margin-top: 100px;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">(1 set) Connecting ring Missing</p> <p style="margin-top: 20px;">INSPECTED BY:</p> <p style="margin-top: 40px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 297 ✓ Weight: 8300kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 9.4 m³ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 3.7 m ✓ Set No.: 16-4/11 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center;">1</p>	<p style="text-align: center;">TOP SECTION for forming press</p> <p style="text-align: center;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 298 ✓ Weight: 8630kg ✓ Width: 1.7 m ✓
Position Code No. _____ Cubage: 8.2 m³ Height: 1.3 m ✓
Machine Inventory No. : 27-1-1413 ✓ Length: 3.7 m ✓ Set No.: 16-5/11 ✓
Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
1	<p>MID SECTION for forming press</p> <p>CONDITION OF ITEM:</p> <p>(4) Bushes Missing</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 299 ✓ Weight: 7600kg Width: 2.0 m ✓
 Position Code No. _____ Cubage: 8.1 m³ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 3.7 m ✓ Set No.: 16-6/11 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

<p>1</p> <p><i>O/K</i></p>	<p>BOTTOM SECTION for forming press</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>
----------------------------	---

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 301 Weight: 3050kg Width: 1.2 m
 Position Code No. _____ Cubage: 6.0 m³ Height: 1.2 m
 Machine Inventory No. : 27-1-1413 Length: 4.2 m Set No.: 16-8/11
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; opacity: 0.5; transform: rotate(-45deg); position: absolute; left: -100px; top: 50px;">OK</p>	<p style="text-align: center;">OPERATION OXES & ACCESSORIES for forming press</p> <p style="text-align: center;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 302 ✓ Weight: 3600kg Width: 1.9 m ✓
 Position Code No. _____ Cubage: 4.9 m³ Height: 1.0 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 2.6 m ✓ Set No.: 16-9/11 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; opacity: 0.5; transform: rotate(-45deg); position: absolute; left: -100px; top: 50px;">OK</p>	<p style="text-align: center;">PARTS for forming press</p> <p style="text-align: center; margin-top: 200px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 303 ✓ Weight: 8100kg ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 5.6 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 5.4 m ✓ Set No.: 16-10/11 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
4	COLUMNS for forming press

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 304 ✓ Weight: 12100kg Width: 2.3 m ✓
 Position Code No. _____ Cubage: 6.1 m³ Height: 0.7 m ✓
 Machine Inventory No. : 27-1-1413 ✓ Length: 3.8 m Set No.: 16-11/11 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

1	OPERATING TABLE for forming press
---	-----------------------------------

015

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 305 ✓ Weight: 3000kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : 27-1-12051-12064 ✓ Length: 2.6 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
14	DIVIDING HEADS. w/accessories)!
<p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	

OK

PROGRESS REPORT OF INTEGRATED FACILITIES

1. Report No. & 1
 2. Allocation No.: 3 - 49
 3. Period Ending: 31 August, 1949

4. Code symbol of plants being reported on: 27 - 1
 5. Dismantling, disassembly and packaging:
 a. Allocation Notice completion date: No date reported
 b. Present estimate completion date: 25 October, 1949.
 c. Work completed during report period:
 (1) Dismantling and disassembly: 12 %
 (2) Packaging: 0.6 %
 d. Work completed to date:
 (1) Dismantling and disassembly: 12 %
 (2) Packaging: 0.6 %

e. Packages completed during report period:
 f. Packages completed to date:

Number	Gross Wt. (metric tons)	Gross Vol. (meas. tons)
2	2.860	3.528
2	2.860	3.528

6. Remarks:

Kawashima Shigeo
 KAWASHIMA SHIGEO
 7 (Signature)
 Chief Custodian of KAWATAMA
 Custody Office.
 8 (Title)

9. Reviewed by:

W. J. ...
 10 (Signature)
Res. Asst. Eng'r
 11 (Title)

Incl.: 2 Packing Lists

Del 10 5