

N-X-15

N-Report-15

PALACE AIRFIELD
90.17-2791

Palace Airfield was operative.
Construction had begun on a runway, oriented approximately north and south.

One covered a/c shelter was under construction.

Planes were parked in the wooded area to the west of the field.

Four planes were found on the airfield. One training plane was wrecked and burned. One ZEKE and two trainers were probably operative at the close of the war.

The field was used as a collection point for electronics and ordnance equipment.

The surface of the airfield was sod and rolled earth. It was relatively rough. Equipment assembled included 15 mobile searchlight units, complete with sound locators, plotting boards and power supply; assorted radar equipment, and ammunition stores.

The defensive installations located on the airfield included one 8-gun battery of 120 mm 56 cal. AA guns, 12 unoccupied 75 mm AA positions, one fire control radar, and complete optical fire control equipment.

N-X-15

N-Report-15

PALACE AIRFIELD
90.17-2791

Palace Airfield was operative.
Construction had begun on a runway, oriented approximately north and south.

One covered a/c shelter was under construction.

Planes were parked in the wooded area to the west of the field.

Four planes were found on the airfield. One training plane was wrecked and burned. One ZEKE and two trainers were probably operative at the close of the war.

The field was used as a collection point for electronics and ordnance equipment.

The surface of the airfield was sod and rolled earth. It was relatively rough. Equipment assembled included 15 mobile searchlight units, complete with sound locators, plotting boards and power supply; assorted radar equipment, and ammunition stores.

The defensive installations located on the airfield included one 8-gun battery of 120 mm 56 cal. AA guns, 22 unoccupied 75 mm AA positions, one fire control radar, and complete optical fire control equipment.