

# ANNUAL SURVEYS.

28129

No. 272 Survey held at London. Date 5<sup>th</sup> March 1867.  
 on the Ship "Timour" Master Not appointed  
 Tonnage 1331 Built at New Brunswick When built 1865 (3 Mo.)  
 By whom built Hilyard Owners Rathbone Bros. -  
 Port belonging to Liverpool Destined Voyage Calcutta -  
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.

Last Survey, No. 19625 Port of Liverpool. Classed 7. A. 1.  
10/65

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4<sup>n</sup>o</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 15. 2 K.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1/4<sup>th</sup> M.</u> When put on <u>1865.</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen.  
*Bottom sighted and the Yellow metal sheathing patched. As far as could be seen with a quantity of Ballast in the hold, she appeared in good and efficient condition and fit, in my opinion, to remain classed: A. 1.*

Committee's Minute 12<sup>th</sup> March 1867 by J. Williams & Co.  
 Character assigned 7 A 1 M.D.  
Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
Certificate (if required)

