DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



4階及屋上

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

縮尺 1/1,800

北

500w.1

500w.1

100w.11

45

100w.3

100w.4

100w.3

100w.4

100w.2

地階

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

富士産業株式會社武藏

縮尺 1/1,800　　昭和23年11月現在

北



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

土武藏工場見取圖

1月現在



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

100w. 3.

100w 4.

100w. 2

No. 30.

100w. 10. No. 2.

100w. 3.

100w. 5. 3台

100w. 6.

No. 1.

No. 28.

No. 29. 1台

100w. 3. 5台

100w. 4.

100w. 2.

1,655台

100w. 5 2台

100w. 4.

3台 No. 27.

No. 26. 2台

100w. 7.

100w. 3

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-31
Plant Name Fuji Industrial Co., Ltd. Ogikubo Plant
(Fuji Precision Machinery Co., Ltd. Tokyo Plant)

a. Total number of items mentioned, machine tools and equipment. 1943 sets

Nakanishi Turbine Manufactory and another one plant 8 sets

b. Total point value of a. above. 117,416

Nakanishi Turbine Manufactory and another one plant 660

c. Total floor space of the plant. (Under custody)

12,840.64 tsubo
(excluding reparation released area)

Floor space housing reparation equipment

Other floor space 11,961.59 tsubo
879.05 "

d. Nature and value of equipment.

Nature

Our plant is suitable for manufacture of small engine and its auxiliary parts and have heat treating shop, metal sheet working shop, forging shop and painting shop.

Foreign made machine tool 177 sets

Future life about 6 years

Characteristics

So we have many machine tools with high precision, so we can manufacture jigs, cutting tools and gauges.

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

Number 31

Disposition See the attached figure

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 89-31
Plant Name Fuji Industrial Co., Ltd. Ogikubo Plant
(Fuji Precision Machinery Co., Tokyo Plant)

Condition	Plant site area	24,786.485 tsubo (excluding released area 3389,515 tsubo)
	Floor space housing reparation equip.	11,961.59 tsubo
Construction	Steel-frame bldg	10,277,072 tsubo
	Ferro-concrete bldg	971.270 "
	Wooden bldg	713.248 "
		11,961.59 tsubo

f. Size and characteristics of plant area nature of protective inclosure:

Wall Ferro-concrete wall

No place where any thief enters into.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard:

None

h. Undesirable social condition:

None

i. Number of guard posts and required number of relief guards:

No. of guard posts 3

No. of guards 10

Place in which post exists	No. of guard		No. of shift	Total
Guard post at 1st front gate	always	2	2	4
Guard post at 2nd front gate	always	1	2	2
Guard post at east gate	always	2	2	4
				10

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-31
Plant Name Fuji Industrial Co., Ltd. Ogikubo Plant
(Fuji Precision Machinery Co., Ltd. Tokyo Plant)

j. Percentage of idle machinery:

Percentage in number	65 %
Percentage in point value	58 %

k. Plant layout showing disposition of buildings, reparations storage, and guard posts:

See the attached figure of plant layout.

Haruo Miiyama
Occupant of Ogikubo Plant,
Fuji Industrial Co., Ltd.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

LAYOUT OF INSTALLATION

Fuji Industrial Co. Ltd., Ogikubo Plant

No. 88, Shuku-machi

Suginami-ku, Tokyo

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

LAYOUT OF INSTALLATION

Fuji Industrial Co. Ltd., Ogikubo Plant

No. 88, Shuku-machi

Suginami-ku, Tokyo

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-32 Plant Name, Tanashi Plant, Fuji Industrial Co., Ltd.

Date, July 20, 1950

a, Total number of items mentioned, machine tools and equipment. 62

b, Total point value of a. above. 2,144

c, Total floor space of the plant. (Under custody) 889 Tsubo

Floor space of the containing reparations property 854.5 "
Others 34.5 "

d, Nature & value of equipment. Engine testing
Estimated average age.11

e, Number, disposition, construction and condition of buildings, housing reparations equipment.

Building No.	Name of building	Structure	Space (Tsubo)
2	Shop for testing engine	Concrete	169
3	"	"	169
4	"	2 Storeyed, Concrete	208
5	"	Concrete	156
6	Pump House	Wooden	9
7	"	"	7.5
	Sub-station	Steel Structure	1136
		Total	854.5

f, Size and characteristics of plant area nature of protective inclosure 1 area 2,049 Tsubo

g, Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. None

h, Undesirrable social condition. None

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-32 Plant Name , Tanashi Plant, Fuji Industrial Co., Ltd.

Date, July 20, 1950

---

i, Number of guard posts and required number of relief guards.

Total guards are 6 men, 1 man three shifts, assistant 1 man, 4men were approved by Japanese Government,added to 2men are working here as plant responsibility.

j, Percentage of idle machinery. 100 %

k, Plant layout showing disposition of building, reparations storage and guards post.

Please refer to the attached layout.

EIBEI KATANO
Occupant of Tanashi Plant,
Fuji Industrial Co., Ltd.

39-32

Lay-out of Tanashi plant

Fuji Industrial Co., Ltd



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Date 18 July 1950

Subject: Report of investigation directed by Kanto Civil Affairs Region concerning member of guard

TO: Kanto Civil Affaird Region

From: Mizuho Industrial Co., Ltd. Tanashi Plant
Plant No.: 39-34

---

a) Total number of items mentioned machine tools and equipment: 1,111
(and other evaluated machine and equipment :2630
machine and equipment on movement and use: None

b) Total point of value of above: 61,648

c) Total floor space of the plant
(Under custody)
Floor space of building housing reparation machine: 6830 tsubo
Other floor space of buildings : 6930 tsubo

d) Nature and value of equipment

Our company's machines and equipments has been manufacturing over 500 per month such as casting of light alloy cover of aircraft, clank, cylinder head, rear cover reducing apparatus, and forging of connection rod and rocker and kelmet bearings, untill the termination of war.

Among above machines the foreign made machine are keller, forging swedger, press, turret and other 42.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

The rate of purchasing year of above each machines is 20 percent of 1939 and 80 percent of 1941 and 1944 and have average future life from 10 to 15 years

e. Number disposition, construction and condition of buildings, housing reparations equipment:

there are 28 roofs (floor space 13770 tsubp) in all site of plant 62,515 tsubo
As for disposition and condition of buildings, to be refered the annexed sheet.

Construction of buildings

Blg.No.	Name of blg.	Floor space		structure
No.1	Foundry shop	3134	tsubo	steel concrete slate roof partly upstairs
No.2	Machine shop	1208	"	steel concrete slate roof
No.3	Forging shop	1008	"	" "
No.4	Housing shop of idle machine	2440	"	" "
No.6	Casting shop	3697	"	" " (release under application)
No.10	Compressor Room	175	"	steel concrete slate roof
No.11	Laboratory shop	161	"	" tile roof
No.12	"	332	"	wood structure " upstairs
No.13	Casting shop	118	"	steel concrete slate roof
No.14	Ware house	400	"	wood structure tile roof partly upstair
No.15	Office	384	"	" " upstair
No.23	Ware house	82	"	" "
No.24	Prior dinning room	300	"	" "

Each buildings of No.9, 16, 17, 18, 19, 20, 21, 25, 31, 32, 33, 34, 35, 36 is under 50 tsubo
The above buildings is inside of concrete fence and less fear of catching fire.

f. Size and characteristies of plant area nature of protective inclosure

Our plant has the site of 62515 tsubo and is enclosed with the fence of 2 or 3 meter height

g. Existence of firms, institution or installations adjacent to the plant which constitute a fire hazard

there are two or three houses at 20 meters distance in front of main gate and on the east of the plant
Fuji Industrial Co., Ltd. Tanashi Plant is situated on the north of the plant at 40 meters distance and have scarcely fire hazard.

h. Undesirable social condition

No.

i. No.of guard house and No. of auxiliary guard required

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant Code Number: 39-3A Mizuho Ind. Co.,Ltd.

	Guard room	No.of guard	Relief guard	Total
A.	Post	3	1	4
b.	Post	3	0	3
c.	Total	6	1	7

Remark: The site of 62,515 tsubo

j. Rate of idle machines.

Percentage of number of idle machines 77%
point value of idle machine 74%

k. Layout of disposition of buildings housing reparations machine and guard houses.

Refere to annexed plant layout.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

MIZUHO INDUSTRIAL CO LTD

TANASHI PLANT

3011 Takashimachi Kitatamagun T



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

NDUSTRIAL CO LTD

ASHI PLANT

shimachi Kitakanagawa Tokyo to



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Date: 20 July 1950.

Plant No. 39 - 35. Plant Name: Nippon Nainenki K.K. Kamata Plant.

a. Total number of items mentioned, machine tools and equipment: 84
20 inventoried machine tools were transferred for use to Samukawa Plant of Nippon Nainenki Seizo K.K.(our second company) Kanagawa prefecture.

b. Total point value of a. above: 1,959
Transferred machinery point value: 1,151.5

c. Total floor space of the plant (under custody)
Reparation items stored: 740 tsubo
Other designated space: 3,630 tsubo
4370

d. Nature and value of equipment.
3 integrated facilities - substation, heat treatment shop (mostly gas furnace) and boiler room. Others are miscellaneous machine tools and testing machines. (mostly recondition required)
Future life of those above are in average as follows:

Substation:	19 years.
Heat treatment shop	23 years.
Boiler room	13 years.
Miscelleanous machinery	12 years.

No foreign machinery contained.

e. Number, disposition, contruction and condition of buildings, housing reparation equipment.

Total number of building	17.
Lot of plant	5,535 tsubo.
Space of ground floor	3,188 tsubo.
Reinforced concrete building	2,208 tsubo.
Angle frame slate roofing building	189 tsubo.
Wooden slate roofing building (in poor condition)	791 tsubo.

Neither fire nor theft hazard adjacent the plant.

f. Size and characteristic of plant area nature of protective inclosure.
Plant lot is only one.
The lot is enclosed by concrete wall except the north-west side showed in red line on the outlay about 146 yards are wire-netting and zinc fence --- No theft hazard.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. --- None.

h. Undesirable social condition. --- None.

- P. T. O. -

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-35

h. Undersirable social condition : Nons

i. Number of guards posts and required number of relief guards.

Location of guard post	Number of regular guards
A post	3
B post	2
Total	5

j. Percentage of idle machinery: 100 %

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013


House
House
House

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Layout of Nippon Nainenki K.K. Kamata Plant

Plant Code no 39-35

177 Furuichi-machi Ohta-ku Tokyo

Building No	Name of Building	Remarks
1	Machine Shop	(a)(c) & (d): Reparations machine Tools & Equipments stored (b) substation Other place is occupied by Toyota motor Co.
2	office	occupied by Toyota motor Co.
3	Testing Room	Reparations Equipment Stored
4	Heat Treatment Shop	Reparations equipment stored (a): Furnace & Distributing Panel. (b): Transformer
5	Boiler Room	occupied by Toyota motor Co.
6	Ware house	Ditto
7	Kutchen	Ditto
8	Dormiterg	Ditto
9	Testing Room	not utilized
10	Warehouse	Reparations Equipment stored
11	Oil Storage	Occupied by Toyota motor Co.
12	Warehouse	
13	Warehouse	Reparations Supplies stored
14	Guard Room	
15	Time Recarding Room	
16	Guard Room	occupied by Toyota motor Co.
17	Ware house	

Note ▨ This make shows the Reparation Equipment stored

[A] This make shows Reservis

Permission date of occupant (Toyota motor Co.) 15 Jan 1947.

End

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 36 Plant Name Adachi Plant, Nippon Kinzoku Sangyo K.K.

a. Total number of items mentioned, machine tools and equipment. 445

b. Total point value of a above. 21.305

c. Total floor space of the plant. (Under custody) 588 Tsubo

(1) of buildings, housing reparations equipment. 588 Tsubo

(2) of other building. 0

d. Nature & Value of equipment. The equipment are adapted for making parts of bicycle or other machinery, and in them 7 pieces are foreign-made, excellent machines, and the average future life of all equipment is 15 years.

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

(1) number 6

(2) disposition 2 buildings-220.5 Tsubo are placed in A area-250 Tsubo, 3 building-217,5 Tsubo are placed in B area-500 Tsubo and 1 building-150 Tsubo are placed in C area-150 Tsubo.

(3) Construction 4 buildings-397.5 Tsubo are wooden, zinc-roofed, 1 building-150 Tsubo is wooden, slate-roofed and 1 building -40.5 Tsubo is steel-frame, slate-roofed.

(4) Condition They are safe from a fire or a theft

f. Size and characteristics of plant area, nature of protective inclosure.

(1) Size 900 Tsubo

(2) Characteristics divided into 3 area

(3) inclosure Wooden and safe from all hazard

g. Existence of firms, institution or installation adjacent to the plant which constitute a fire hazard.
Such a firm or a plant exist not in the neighbourhood.

h. Undesirable social condition. it exist not, because the plant is incolsed by agricultural lands and farm-houses.

i. Number of guard posts and required number of relief guards.

(1) posts 1

(2) guards Always 2, 3 shifts, relief 1

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 36 Plant Name Adachi Plant, Nippon Kinzoku Sangyo K.K.

j. Percentage of idle machinery

(1) for number 61.6 %

(2) for point value 65.2 %

k. Plant layout showing disposition of buildings, reparation storage, and guard posts. Attached paper

Attached Paper

LAY OUT

Plant No. 39 – 36

Plant Name Adachi plant, Nippon Kinzoku Sangyo K. K.

Location No. 2200 Higashi-shimane-cho, Adachi-ku, Tokyo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Date: 14 June 1950

Plant No. 39-37 Plant Name: Nippon Kentetsu Kogyo K.K.
Nakagawa Plant

---

a. Total number of items mentioned, machine tools and equipment. 248 sets

b. Total point values of a. above. 11,151.5

c. Total floor space of the plant.
(Under custody)

Floor space equipped with designated reparations machinery and equipment.
3,065.75 tsubo.
Other floor space designated.
284.06 tsubo.

d. Nature and value of equipment.

Sheet metal works are recommendable, as being equipped with all sorts of pressing and bending machinery.
Average future life of machinery is 15 years.

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

Number of buildings : 14
Floor space : 3,065.75 tsubo
Construction : slate roofing,
steel concreted,
or wooden.
Buildings are located in the ground area: 12,351.81 tsubo.

f. Size and characteristics of plant area, nature of protective inclosure.

Ground area: 12,351.81 tsubo.
(Not separate)
Barrier: Wooden pole, slate applying.
162 ken.
Wooden pole, zincified steel sheet. 83 ken
Wooden pole, board applying.
31 ken
Iron pole, board applying.
207 ken
Wooden pole, with barbed wire.
162 ken
No person can ~~not~~ enter into the area without information.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-37 Plant Name: Nippon Kentetsu Kogyo K. K.
Nakagawa Plant

---

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. None

h. Undesirable social condition. None

i. Number of guard posts and required number of relief guards.

Guards post: 2
No. of guards: 14
3 shifts each 4 persons
Chief 1
Assistant 1

j. Percentage of idle machinery.

(1) $\frac{148 \text{ sets (No. of idle machinery)}}{248 \text{ sets (Total No. of machinery)}}$

= 59.7 %

(2) $\frac{4,746.5 \text{ (Point value of idle mach.)}}{11,151.5 \text{ (Total point value)}}$

= 42.7 %

k. Plant layout showing disposition of buildings, reparations storage, and guards posts. As per attached.

NIPPON KENTETSU KOGYO K.K.
NAKAGAWA PLANT

Yonekichi Ishimori

YONEKICHI ISHIMORI

Plant Custodian

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Nippon Kentetsu Kogyo K.K.

Nakagawa Plant

GROUND AREA :- ~~[illegible]~~ M² 12,234.21 Tsubo

BUILDING AREA :- ~~25,835~~ M² 3,349.21 Tsubo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 38 Plant Name: Nippon Kentetsu Co., Ltd. Tokyo Plant Horikiri Branch. (Former Name: Nippon Kentetsu Kogyo Co., Ltd.)

---

a. Total number of items mentioned machine tools and equipment 85

b. Total point value of a. above. 5,113

c. Total floor space of the plant. (under custody) Floor area containing reparation items. 384.25 tsubo
Others 21.25 "

d. Nature and value of equipment. General machine tools.

e. Number, disposition, construction and condition of buildings, housing reparations equipment. Cf. layout.
Number 3 houses
Disposition Ground area 537.75 tsubo
Construction 3 houses..... Wooden built, slate roofing, 1 story.
Condition Car is needed.

f. Size and characteristics of plant area nature of protective inclosure.
Size ..... 537.75 tsubo
Fence is imperfect.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. None

h. Undesirable social condition. There are many the workless.

i. Number of guard posts and required number of relief guards. Post.....1 Guards....3 persons
Remark. 1 guard is living in the plant

j. Percentage of idle machinery. 81 %

k. Plant layout showing disposition of buildings, reparations storage, and guard posts.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

公差		符	年月日	改訂記事
仕上				
熱処理				



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

改訂記事	實施	捺印

監督官		尺度	1/240	工事番號	

日本建鐵工業

製圖	年月日		
出圖			
寫圖	年月日		

整理番號		番號	

符	名稱	圖番	寸度	材質	規格	數	重量

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

工事番號	日本建鐵工業株式會社			
教育・建物評教委	製圖	年月日		工作課長
	出圖			
番號	寫圖	年月日		檢圖

番	寸度	材質	規格	數	重量		記事

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

面積計算

A	108.7×96.0/2	4953.60		
B	108.7×96.0/2	939.00		
C	108.7×193.7/2	9899.36		
D	91×180.0/2	8190.00		
E	181.6×96.0/2	7795.80		
F	165.7×96.0/2	7948.80		
G	180.0×28.6/2	2574.00		
H	180.0×48.0/2	4320.00		
I	180.0×36.0/2	3240.00		
J	180.0×18.0/2	1620.00		
K	180.0×15.0/2	1350.00		
L		10125.00		
床版面積		47629.96㎡	1323.054	47653.944
梁側面積（Cantilever部）		15363.00㎡	426.750	15381.300
地覆面積		7056.00㎡	196.000	7272.000

工場 ¥37,750

24,000

13,750

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 38 Plant Name: Nippon Kentetsu Co., Ltd. Tokyo Plant
(Former Name: Nippon Kentetsu Kogyo Co., Ltd.)

---

a. Total number of items mentioned, machine tools and equipment. 488

b. Total point value of a. above. 30,511

c. Total floor space of the plant.
(Under custody) Floor area containing
reparation items 2,444.24 tsubo
Others 855.87 "

d. Nature & value of equipment. General machine tools(particularly adapted to metal forming.)

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

Number - 12 houses
Disposition
- cf. Layout.
Construction
- 3 houses ....Steel skelton built, slate roofing, 1 story.
- 2 houses ...Concrete built, 1 story.
- 3 houses ....Wooden built,zinc roofing, 1 story.
- 4 houses ....Wooden built, slate roofing, 1 story.
Condition
- Being near down town, cars for fire and burglary are necessary.

f. Size and characteristics of plant area nature of protective inclosure. - 5,991.57 tsubo
Divided in three blocks by the roads.
Some part of the fence is imperfect.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard.
No serious danger

h. Undesirable social condition; Neighbourhood is very confused down-town.

i. Number of guard posts and required number of relief guards. 3 Posts 12 persons
Relief guard 1 person

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

j. Percentage of idle machinery. 71 %

1. Plant layout showing disposition of buildings, reparations storage, and guard posts. Cf. attached layout.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

NIPPON KENTETSU K.K.

日本建鐵株式會社

寺院境内

安内図

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

TETSU K.K. TOKYO PLANT

株式會社東京第一工場平面圖

縮尺六百分之一



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 38 Plant Name: Nippon Kentetsu Co., Ltd. Tokyo Plant.
Omori Branch.
(Former Name: Nippon Kentetsu Kogyo Co., Ltd.)

---

a. Total number of items mentioned machine tools and equipment 58

b. Total point value of a. above. 3,002

c. Total floor space of the plant (under custody)

Floor area containing reparation items 114.50 tsubo
Others 11.67 "

d. Nature & value of equipment. Precision machine tools (Instrument)

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

Number ..... 4 houses cf. layout.
Disposition ..... ground area 252 tsubo
Construction ..... 2 houses..Wooden built, tile roofing, 1 story
1 house..Wooden built, tule roofing, 2 story.
Condition ..... Free from fire and burglary.

f. Size and characteristics of plant area nature of protective inclosure.....

Size ..... 252 tsubo
No dangers as it exist in residential quarters.
Fence is perfect.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. None

h. Undesirable social condition. None

i. Number of guard posts and required number of relief guards. Posts ....1 Guards .....3 persons
Relief guard ..... none

j. Percentage of idle machinery. 67 %

K. Plant layout showing disposition of buildings, reparations storage, and guard posts.

cf. layout.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

CORRECTION

THIS DOCUMENT

HAS BEEN REPHOTOGRAPHED

TO ASSURE LEGIBILITY

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

		符	年月日	改訂記事	實施
公差					
仕上					
熱處理					

二階



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

改訂記事	實施	捺印

監督官		尺度	1/10	工事番號	

日本建鐵工業

廣東工場大亜分工場平面図及機械配置		製圖	22年7月22日
		出圖	
整理番號		番號		寫圖	年月日

符	名稱	圖番	寸度	材質	規格	數	重量

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

事
號

日本建鐵工業株式會社

	製圖	年 月 日		工作課長	
	出圖				
號	寫圖	年 月 日		撿圖	

	寸度	材質	規格	數	重量		事記

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



A	(74.5×37)÷2	2746.5	1373.25	38.146	
B	(111.0×61.5)÷2	6826.5	3413.25	94.813	
C	(129.0×54.5)÷2	7030.5	2515.25	69.868	
D	(65.5×55.0)÷2	3602.5	1801.25	50.034	
床面積	(一階) 2383.3145 ft²	(二階) 2312.171 ft²			延面積計 7564.938 ft²

1280.587 ft²
1660.020 ft²
2794.737 ft²

2,532.661

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

木通隊主計 7564.938 ft²

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Date: July 20, 1950.

Subject: Report on number of guards in reparations plant.

To : Kanto Civil Affairs Region.

Name of plant:(Code No.39-40) Riken Kinzoku K.K.
Tokyo-Chuzosho.

Address : 30 Tokumaru-Honmachi,
Itabashi-ku, Tokyo-to.

Designation: Aircraft

Name of occupant: S. Sato

a. Total number of items mentioned,
machine tools and equipment. 42

b. Total point value of a, above. 1340.

c. Total floor space of the plant.
(under custody) 720.23 (Tsubo)

Floor space housing mentioned
machine tools. (234.5 Tsubo)

The others. (485.73 ")

d. Nature & value of equipment.

Most of them are used for production of non-ferrous alloys casting and machinery.

Valve of equipment are worthless by airraid damage.

e. Number, disposition, construction and condition of buildings, housing reparations equipment.

Number of buildings 14

Area of ground disposed 5,500 Tsubo

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

39-40 Riken Kinzoku K.K. Tokyo-Chuzosho

Construction

Built of wood and	tile-roofing	150.49	Tsubo
"	slate-roofing	131.25	"
"	iron-plate-roofing	268.5	"
"	wood-roofing	85	"

Condition ordinary condition

f. Size and characteristics of plant area nature of protective inclosure.

Size of area	5,500 Tsubo
Number of location	1
Nature of protective inclosure:	Board fence

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard. None.

h. Undesirable social condition. None.

i. Number of guard posts and required number of relief guards.

Guard posts	1
Guards	1
Relief guards	0

j. Percentage of idle machinery.

Percentage on No. of machine	59.5%
Percentage on point value	54.5%

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

k. Plant layout showing disposition of buildings, reparations storage, and guard posts.

Look the attached paper.

Signature T. Sato

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

LAYOUT PLAN



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

PLAN OF INSTALLATION (SCALE 1/600

NAME OF PLANT.

CODE NO.

SITE SPACE.

FLOOR SPACE.



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

(SCALE 1/600)

ME OF PLANT. RIKEN KINZOKU K.K. TOKYO TSUZOSHO

DE NO. 39-40

TE SPACE. 5500 (tsubo)

OOR SPACE. 7;0.23 (tsubo)

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39 - 41

Shinko Kikai Kogyo Co.

a. Total number of item mentioned, machine tools and equipment: 159

b. Total point value of a above: 10,840 ten

c. Total floor space of the plant under custody: 304.50 tsubo
Others: 297.25 tsubo

d. Nature of equipment: production of aircraft
Age of equipment in years: manufactured in 1940 - 1944

e. Number of buildings: 15

Floor space under custody: 304.50 tsubo
Floor space of wooden houses: 587.01 tsubo
Fire-proof building: 14.75 tsubo

f. Size of plant area: 1,400 tsubo
(due to the picture)

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard.: none

h. Undesirable social condition:
Many workless peoples lives adjacent to the plant.

i. Number of guard post: 1
Required number of guard: ~~5~~ 3
Number of relief guard: 1

j. Percentage of idle machinery: ~~na~~ %
Percentage of point value: 91 %

k. Due to the picture.

20枚

Lay out Plant.

Plant Code No. 39 – 41

SHINKO KIKAI KŌGYŌ K.K.



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

PLANT NO : 39 - 43

PLANT NAME: Showa Hikoki Kogyo K.K.
(Showa Aircraft Industry Co., Ltd.
Tokyo Plant)

DATE : 20 July 1950

A. Total number of items mentioned, machines tools and equipment
   a. Inventorized by T.M.G.T. 1063
   b. Evaluated by S.C.A.P. 1864
   c. Dispersed machines at Tohoku Dock Co., Ltd. Fukushima Factory
      Total --- 8 39-43-612, 613, 614, 615, 616, 617, 618, 619

B. Total point value of a Above
   a. 51,595 (Tokyo Plant)
   b. Unknown (Dispersed machines at Tohoku Dock Co., Ltd.)

C. Total floor space of the plant.
   a. Building of reparations equipment

BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS	BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS
23	237.0		171	202.0	
61	43.95		185	3,775.05	
96	95.82		187	591.90	
103	200.0		189	361.19	
106	200.0		191	361.19	
107	200.00		193	403.76	
110	82.1		205	96.0	
121	28.0		207	194.01	
151	7,687.82		209	166.0	
153	87.75		211	59.40	
155	38.5		231	265.23	
159	48.0		243	12.0	
161	45.26		245	10.0	
			Total 26	15491.93	

   b. Other

BLDG. NO.	FLOOR SPACE (TSUBO	REMARKS	BLDG. NO.	FLOOR SPACE (TSUBO	REMARKS
1	51.4		51	13.6	
3	68.09		53	13.6	
5	68.09		102	5.1	
7	24.7		103	200.0	
9	1,406.5		105	200.0	
11	314.0		109	152.5	
15	91.2		110	82.1	
21	104.0		111	8.0	
23	207.0		123	72.0	
25	200.0		124	242.7	
27	200.0		136	31.3	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS	BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS
137	1.5		179	5.0	
138	90.0		180	18.0	
139	393.5		181	8.8	
140	25.5		183	49.0	
141	30.0		191	361.0	
143	52.0		217	21.3	
145	201.4		223	97.0	
146	385.0		240	1.5	
148	73.0		241	92.0	
149	200.0		249	63.5	
157	105.0		250	2.0	
167	30.0				
173	43.2		TOTAL	6,105.0s	

D. Nature & Value of equipment

a. Nature of equipment

Repaire of Vehicles & Press working
(During war manufactured air plane, except engine)

b. Total numbers of Foreign made machines
(Superiority)
30 es

c. Future life (mean value)
13 years

E. Number, disposition, constructions and condition of buildings, housing reparations equipment

a. Number 24

b. Disposition

1. Ground 290,000 tsubo
2. Floor space 24 buildings, 15,469.93 tsubo

BLDG. NO.	FLOOR SPACE (TSUBO)	CONSTRUCTION
23	237.6	Wooden, Tile-roof
61	43.95	"
96	95.82	"
103	200.0	Wooden, Slate-roof
106	200.0	"
107	200.0	"
110	82.1	Wooden, Tile-roof, Two-storied house
121	28.9	Wooden, Slate-roof
151	7,687.82	Concreat, Slate-roof
153	87.75	Wooden, Slate-roof
155	38.5	Concreat, Slate-roof
159	48.0	Wooden, Slate-roof
161	45.26	"
171	202.0	Wooden, Tile-roof
185	3,775.05	Concreat, Wooden, Slate & Tile-roof
187	591.90	Wooden, Slate-roof
189	361.19	Wooden, Slate-roof
191	361.19	"

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

BLDG. NO.	FLOOR SPACE (TSUBO)	CONSTRUCTION
193	403.76	Wooden, Tile-roof
205	96.0	Wooden, Slate roof
207	194.01	Concreat, Slate roof
209	166.0	Slate-roof Concreat
211	59.40	Wooden, Slate-roof
231	265.23	Concreat, Slate-roof
TOTAL	15,469.93	

F. Size and characteristics of plant area nature of protective inclosure.
   a. Ground 290,000 tsubo
      Other, Air field 300,000 tsubo
   b. Concreat and Barbed wire-entanglements.
   c. Place the possibility of robbery or intrusion.
      None

G. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard.
   None

H. Undesirable social condition
   None

I. Number of guard posts and required number of relief guards.
   Under the custody of the Occupation Forces.

J. Percentage of idl machinery
   a. $\frac{521}{1063}$ =0.49 49% (Machines)
   b. $\frac{34664}{51505}$=0.67 67% (Index)

K. Plant layout showing disposition of buildings, reparations storage, and guard posts
   Attached sheets.

S. Kuboi S. Kuboi

Occupant of Showa Hikoki Kogyo K.K.
(Showa Aircraft Industry Co., Ltd.
Tokyo Plant)

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

PLANT NO. : 39 - 43

PLANT NAME : Showa Hikoki Kogyo K.K. Ogami Kojyo
(Showa Aircraft Industry Co., Ltd.
Ogami Factory)

A. Total number of items mentioned, machine tools and equipment
   a. Inventorized by T.M.G.T. 5
   b. Evaluated by S.C.A.P. 46

B. Total point value of a above.
   90 (machines)

C. Total floor space of the plant
   a. Buildings of reparation equipment

BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS
1st Factory 4	26.0	
" 5	40.0	
" 6	121.0	
" 10	6.0	
TOTAL 4	193.0	

   b. Other

BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS
1st Factory 1	41.75	
" 2	12.0	
" 3	10.25	
" 7	24.15	
" 8	20.0	
" 9	19.0	
" 11	24.0	
" 12	1.5	
" 13	4.0	
" 14	1.5	
" 15	2.0	
" 16	6.0	
2nd Factory 1	61.0	
" 2	1.5	
" 3	96.0	
" 4	2.0	
" 5	2.0	
TOTAL 17	348.65	

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

D. Nature & Value of equipment
   a. Nature of equipment
      Wood working
   b. Value of equipment
      Number of foreign made machine (superiority)
      None
      Future life (mean value)
      13 years

E. Number, disposition, construction and condition of buildings, housing reparations equipment
   a. Number 4 Buildings
   b. Disposition
      1. Ground 2,370.57 tsubo
      2. Floor space 193.0 tsubo (4 Buidlings)

BLDG. NO.	FLOOR SPACE (TSUBO)	CONSTRUCTION	REMARKS
4	26.0	Wooden, Tile-roof	
5	40.0	Wooden, roof of cryptomeria-bark	
6	121.0	Wooden, Tile & Tin-roof	
10	6.0	Wooden, Tine & Cryptomeria-bark	
TOTAL 4	193.0		

F. Size and characteristics of plant area nature of protective inclosure
   a. Ground 2,370.57 tsubo
   b. 1st factory: Board-fence
      2nd factory: Barbed-wire
   c. Place the possiblity of robbery or intrusion
      Very good

G. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard.
   None

H. Undesirable social condition
   None

I. Number of guard posts and required number of relief guards.
   a. Number of guard box 1
   b. Number of guard 6
      Ordinaly --- 2 men, 3 shift

J. Percentage of idle machinery
   a. $\frac{0}{5} = 0$ 0% (machines)
   b. $\frac{0}{90} = 0$ 0% (index)

K. Plant layout showing disposition of buildings, reparation storage, and guard posts.

S.Kuboi S. Kuboi
Occupant of Showa Hikoki Kogyo K.K.
Ogami Kojyo
(Showa Aircraft Industry Co. Ltd.)

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

N

SHŌWA HIKŌKI KŌGYŌ K.K ŌGA
Showa Aircraft Industry Co, Ltd Ōga

SKETCH



REM

Bldg No	Ite
1	offic
2	Ware-H
3	Ware-H
4	Ware-H
5	Saw M
6	Machin
7	Printing
8	Ware-H
9	Ware-H
10	Tool Ro
11	Drying R
12	Resting
13	Bicycl
14	Guard
15	Lavato
16	OiL St
Total	
2nd	Facto
1	office
2	ware-
3	Assemble
4	Ware-H
5	Lavator
Total	

Ground

REMARRS:

▭ CONTAING REPARATION

▭ GUARD BOX

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

09

KŌGYŌ K.K ŌGAMI KŌJYŌ
Industry Co. Ltd Ōgami plant)

SKETCH



REMARKS

Bldg No	Item	Area (tsubo)	Remarks
1	office	41.75	Fiast Floor 34.25
2	Ware-House	12.0	Second Floor 7.5
3	Ware-House	10.25	
4	Ware-House	26.0	
5	Saw Mill	40.0	
6	Machine Shop	121.0	
7	printing shop	24.15	
8	Ware-House	20.0	
9	Ware-House	19.0	
10	Tool Room	6.0	
11	Drying Room	24.0	
12	Resting Room	1.5	
13	Bicycle Yard	4.0	
14	Guard Box	1.5	
15	Lavatory	2.0	
16	oil Storage	6.0	
Total		359.15	
2nd	Factory		
1	office	81.0	
2	Ware-House	1.5	
3	Assemble & Printing Shop	96.0	
4	Ware-House	2.0	
5	Lavatory	2.0	
Total		182.5	

Ground 2370.57 tsubo

ARRS:
- CONTAING REPARATION EQUIPMENT
- GUARD BOX

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

PLANT NO : 39 - 44

PLANT NAME: Showa Hikoki Kogyo K.K. Ozaku Kojyo
(Showa Aircraft Industry Co., Ltd.)

A. Total number of items mentioned, machine tools and equipment
   a. Inventorized by T.N.G.T. 78
   b. Evaluated by S.C.A.P. 33

B. Total point value of a above
   5,755 ------ (Machines ------ 78ea)

C. Total floor space of the plant
   a. Buildings of reparation equipment

BLDG. NO.	FLOOR SPACE (TSUBO)	REMARKS
11	152.0	
14	152.0	
TOTAL 2	304.0	

   b. Other
   Bldg. NO. 19 5.0

D. Nature & Value of equipment
   a. Nature of equipment
      Lathe working
   b. Value of equipment
      Number of foreign made machines (supeaiority)
      2 ea
      Future life (mean value)
      13 years.

E. Number, disposition, construction and condition of buildings, housing reparation equipment.

BLDG. NO.	FLOOR SPACE (TSUBO)	CONSTRUCTION	REMARKS
11	152.0	Wooden, Tin-plate-roof	
14	152.0	"	
19	5.0	Wooden, roof of cryotomeria-bark	
TOTAL 3	309.0		

F. Size and characteristice of plant area nature of protective inclosure.
   a. Ground about 800(tsubo)
   b. None inclosure
   c. Plase the possiblity of robbery or intrusion
      No good.

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

G. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard
None

H. Undesirable social condition.
None

I. Number of guard posts and required number of relief guards.
a. Number of guard box 1
b. Number of guard 4 (Containing 1 Relief)
Ordinary —— 1 man, 3 shift

J. Percentage of idle machinery
a. $\frac{78}{78} = 1$ 100% (machines)

b. $\frac{5755}{5755} = 1$ 100% (index)

K. Plant layout showing disposition of buildings, reparation storage, and guard posts.
Attached sheet

S. Kuboi S. Kuboi
Occupant of Showa Hikoki Kogyo K.K.
Ozaku Kojyo
(Showa Aircraft Industry Co., Ltd.
Ozaku Plant)

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

SHŌWA HIKŌKI KŌGYŌ K.K OZA
(Showa Aircraft Industry Co., Ltd Oz



REMARKS

BLDG No	Item	Area (tsubo)	Remarks
11	Ware-House	152.	
14	Ware-House	152.	
19	Guard Box	5	
Total		309.	

Ground about 800 tsubo

REMARKS: ▭ Containg Reparation Equipment
▭ Guard Box

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

KI KŌGYŌ K.K OZAKU KŌJYŌ
t Industry Co., Ltd Ozaku plant)



on Equipment

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

T.H. No. 45

SUBJECT: Number of Guard for Reparation Plant (After 16 June '50)

TO : Kanto Civil Affair Region

THRU : Tokyo-to Liaison Office

FROM : Tachikawa Hikoki K.K. Code No. 39-45,
No. 100, 1-chome, Takamatsu-cho, Tachikawa-shi, Tokyo-to.

DATE : 15 June 1950

a & b. Total number of Machines, tools, equipments and Total point value:

	Number	Point value
Total number of items mentioned	1911	104,330
Total number of items now in custody	1054	67,671
Total number of items now out of custody	857	36,659

Total number of items now under use of the Occupation Forces.

"AU" by US Army Feamcom	745	
"AU" by US Tachikawa Air Force Base	3	
"AU" by US Yokota Air Force Base	4	33,424
"AU" by HQS 8th Army	54	
"AU" by GHQ Engineer Section	3	
"AU" by Tachibi Kogyo K.K.	48	3,235

c. Total floor space of the Plant:

Building containing Idle machines - Bldg. X93, 317th Area (Old Former Japanese Veterinary Supply Area) ... 1932 tsubo

Others..... Under custody of Occupation Forces

d. Nature & value of equipment:

Use of equipment ..... For Aircraft
Number of equipment made in foreign counties 706
Durability ..... 10 years

e. Number, disposition, construction and condition of buildings, housing reparation equipment.

(1) Number ... 1
(2) Disposition ... 317th Area
(3) Construction & Condition...
Wood building
Floor space 1932 tsubo
One-storied house
Zinc roofing

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

(Cont'd)

f. Size and characteristics of plant area nature of protective inclosure:

As the Plant is under custody of the Occupation Forces, the description is omitted.

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard:

Description is omitted here, becuse the plant is under custody of the Occupation Forces.

h. Undesirable social condition:

Description is omitted here, because the plant is under custody of the Occupation Forces.

i. Number of guard posts and required number of relief guards:

No guard is placed by the company around the Bldg. X93 in the 317th Area, because the Occupation Forces are placing guards. But, 3 men are used for custody.

j. Percentage of Idle Machinery:

Percentage from the view point of point value $\frac{1363}{1911}$ 96%

Percentage from the view point of point value $\frac{101,095}{104,330}$ 97%

Notes: The above mentioned percentage is calculated, considering the machineries under custody of the Occupation Forces Idle. This is being understood by the Japanese Government.

k. Plant layout showing disposition of buildings, reparations storage, and guard posts.

See attached map.

Name of Occupant: T. Murai

TAKEO MURAI
Tachikawa Hikoki K.K.
Tachikawa Kojo

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

MAP OF TACHIKAWA HIKOKI K.K. Code No. 39-45 (FEAMCOM AFB.)

立川飛行機株式會社工場區域概要圖

Notes:

— Reparation Area

Old Reparation Machinery Warehouse

A.U. Machinery Ware-Factory

Reparation Machinery Warehouse

Guard Box



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 30-48 Plant Name: Yokogawa Electric Works, Ltd. Koganei Plant

a. Total number of items mentioned, machine tools and equipment.

390 (83 transfered to main plant at Kichijoji)

b. Total point value of a. above.

20,552 (4,000 points)

c. Total floor space of the plant. (Under custody)

520 Tsubo (Take in machines 479 Tsubo, Others 41 Tsubo)

d. Nature & value of equipment.

1. What is make by machine equipment? Magneto
2. Is there any excellent foreign machines? None
3. Durable years? 18 years

e. Number disposition, construction and condition of buildings, housing reparations equipment.

1. Number : 9
2. Area : 1052 Tsubo
3. Buildings: 320 Tsubo

1. Brick house	2	Tsubo
2. Steel concrete	75	"
3. Wooden house	443	"
	520	Tsubo

f. Size and characteristics of plant area nature of protective inclosure.

1. Size : 1052 Tsubo
2. Characteristics: This area is exist on keio Univ. Technical Section
3. An encloser: Wire netting

g. Existence of firms, institutions or installations adjacent to the plant which constitute a fire hazard.

For fear of fire hazard because f.2. above and there is 50 rooms apartment house about 20 M distance.

h. Undesirable social condition.

None

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

Plant No. 39-48 Plant Name: Yokogawa Electric Works, Ltd. Koganei Plant

i. Number of guard posts and required number of relief guard

Location of guard	Regular No. of guard	Relief No. of guard	Remarks
1. One post	3	2	We need one guard more because f.2 and g. above.

j. Percentage of idle machinery.

100 %

k. Plant layout showing disposition of buildings, reparations storage, and guard posts.

It is on annexed paper.

Signature Ichiro Hanitoh
Occupent

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

工場配



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

工場配置図 (Arrangement of Plant.)

株式会社横河電機製作

Yokogawa Electric Wo



DECLASSIFIED E.O. 12065 SECTION 3-402/NNDG NO. 775013

株式会社横河電機製作所小金井工場

Yokogawa Electric Works, Ltd Koganei Plant.