









# AIRCRAFT ACTION REPORT

RESTRICTED  
(Reclassify when filled out)

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

REPORT No. 89

## XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only).

(a) Target(s) and Location(s) Installation Southern Okinawa (b) Time Over Target(s) 1000-1050 (17)  
(FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK) (Zone)

(c) Clouds Over Target 2000 .5 Cumulus  
(BASE IN FEET, TYPE AND TENTHS OF COVER)

(d) Visibility of Target Clear (e) Visibility 10 miles  
(CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (MILES)

(f) Bombing Tactics: Type \_\_\_\_\_ Bomb Sight Used \_\_\_\_\_  
(LEVEL, GLIDE OR DIVE) (TYPE)

Bombs Dropped per Run \_\_\_\_\_ Spacing \_\_\_\_\_ Altitude of Bomb Release \_\_\_\_\_  
(NUMBER) (FEET) (FEET)

(g) Number of Enemy Aircraft Hit on Ground: Destroyed \_\_\_\_\_ Probably Destroyed \_\_\_\_\_ Damaged \_\_\_\_\_

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO. A/C ATTACKING	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
		(k) SQUADRON			
1 Lookout posts	2	1 FM-2 VC-88	300 rds .50 cal	strafed	slight
2 Caves		1 FM-2 VC-88	600 rds. .50 cal	strafed	slight
3 Buildings		1 FM-2 VC-88	600 rds .50 cal	strafed	slight
4					
5					
6					
7					
8					

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

- 1 Lookout posts in target areas 7957 S and 7359 L strafed and hit but extent of damage unknown.
- 2 Caves, one in target area 7255S, apparently used by small boats and one in 755b L believed to be a gun position, were strafed and hit but extent of damage unknown.
- 3 Two buildings strafed in target area 7258 H, I, but extent of damage not definitely ascertained. Believed slight to serious.

CONFIDENTIAL

(p) Were Photographs Taken? NO Photographs of Damage, When Taken, Should Be Attached By Staple.







# AIRCRAFT ACTION REPORT

RESTRICTED  
(Reclassify when  
filled out)

REPORT No. 39

**XIII. MATERIAL DATA.** (Comment freely on performance or suitability, following check list at left.  
Use additional sheets if necessary).

## ARMAMENT

Guns, Gunsights  
Turrets  
Ammunition  
Bombs, Torpedoes  
Bomb Sights  
Bomb Releases

No comment.

## COMMUNICATIONS

Radio, Radar  
Homing Devices  
Visual Signals  
Codes, Ciphers

## RECOGNITION

IFF  
Signals  
Battle Lights  
Procedures

## PROTECTION

Armor; Points and Angles  
of Fire Needing Further  
Protection  
Leak Proofing

## EMERGENCY EQUIPMENT

Parachutes  
Life Belts, Life Rafts  
Safety Belts  
Emergency Kits  
Rations, First Aid

## NAVIGATIONAL EQUIPMENT

Compasses  
Driftsights  
Octants  
Automatic Pilots  
Charts  
Field Lighting

## INSTRUMENTS

Flight  
Power Plant

## OXYGEN SYSTEM

## CAMOUFLAGE AND DECEPTION DEVICES

## STRUCTURE

Airframe  
Control Surfaces  
Control System  
Dive Flaps  
Landing Gear  
Heating System  
Flight Characteristics  
At Various Loadings

## POWER PLANT

Engines  
Engine Accessories  
Propellers  
Lubricating System  
Starters  
Exhaust Dampers

## HYDRAULIC SYSTEM

## ELECTRICAL SYSTEM

Auxiliary Plant  
Lights

## FUEL SYSTEM

## FLIGHT CLOTHING

## MAINTENANCE

## BASE FACILITIES

Plane Servicing Equipment  
Personnel Facilities

REPORT PREPARED BY:

APPROVED BY:

CONFIDENTIAL

H. P. SCHWAB, Lt. USNR, ACIO  
SIGNATURE RANK AND DUTY

E. L. KROPP, Lt. USNR, Commanding  
SIGNATURE RANK AND DUTY

9 April 1945  
DATE