

ANNUAL SURVEYS.

27959

No. 250 Survey held at London Date 13th December 1866
 on the Ship "Oruak" Master J. English
 Tonnage 738 Built at Narwich When built 1865 (6. Mo.)
 By whom built Vause Owners J. Morrison
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Messrs Sigsbee Dry Dock

Dec 13 1866
 J. English

Last Survey, No. 1279 Port of Yarmouth Classed 10. A. 1
8/65

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Two</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 15. 2 K</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Said to be sufficient</u>
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>put on</u> When put on <u>1865</u>	
General Observations and Opinion,	<u>extensively patched</u> Caulking of Bottom, Deck, and Waterways	<u>Good where seen</u>

The Bottom sighted and the Yellow Metal sheathing extensively patched. She is now in good and efficient condition, and fit, in my opinion, to remain classed; A. 1.

Committee's Minute 21st December 1866
 Character assigned 10 A 1 M.S.
J. Williamson
 Certificate (if required)


No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways _____	

Committee's Minute _____ 18____
 Character assigned _____



LON 651-0344