

ANNUAL SURVEYS.

6469

(Received at London Office, Rec'd 20th Mar. 1884.)

No. 6469 Survey held at Glasgow Date, first Survey 1 Mar. Last Survey 5 Mar. 18 84
 No. in on the Iron S.S. "Hercules" Master A. Gesinger
 Reg. Book. 26 Tonnage Net 1272 Built at Port Glasgow When built 1880 Month 12
 Gross 1341 By whom built R. Duncan & Co. Owners C. S. Caird
 Under Dk. 1204 Port belonging to Greenock Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Henderson's dry dock
 (State Name of Dock.)

Last Survey, No. 8352 Port of Grek Classed 100A.1. Years assigned. Character in Register Book.
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides Plating Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 General Observations, Opinion as to Class, &c.

The bottom of the vessel cleaned and re-coated.
Cargo in hold at time of survey.
This vessel is now in good and efficient condition and is eligible
in my opinion to remain as classed.

Committee's Minute FRIDAY 21 MARCH 1884 18
 Character assigned T.M. 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 6469 Survey held at Glasgow Date, first Survey 1 Mar. Last Survey 3 Mar. 18 84
 No. in on the Iron S.S. "Sindbad" Master Page
 Reg. Book. 32 in Suppl. Tonnage Net 606 Built at Newcastle When built 1883 Month 6
 Gross 961 By whom built Campbell Owners J. G. Sharp
 Under Dk. 723 Port belonging to Newcastle Destined Voyage Santander
 If Surveyed Afloat or in Dry Dock Kelvinhaugh slip
 (State Name of Dock.)

Last Survey, No. 16992 Port of RWC Classed 100A.1. Years assigned. Character in Register Book.
 Present Condition of the Decks Not end. Treenails Rivets good
 Waterways " Breasthooks and Stems Not end.
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides Plating Ceiling "
 Wales good Rudder good
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good
 (If a Steam Ship, state if a Report is also sent on the Machinery.)

General Observations, Opinion as to Class, &c. This vessel having grounded on Bilbao bar recently, the
bottom has now been carefully examined and found in a satisfactory condition.
A length of bilge keel on the port side being broken and bent, about 67 feet of the bulk plate
has now been renewed. The bottom has also been cleaned and re-coated.
This vessel is now in good and efficient condition and is eligible in my opinion
to remain as classed.

Committee's Minute FRIDAY 21 MARCH 1884 18
 Character assigned T.M. 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

