ANNUAL SURVEYS.

Survey held at Sondon Pride of England Master France Tonnage 1338 Built at 2 nebec When built 1860 Potter Mo Owners By whom built Durning Port belonging to Thankow Destined Voyage If Surveyed Afloat or in Dry Dock Last Survey, No. 26685 Port of Landon The present Condition of the where seen Good Windlass and Capstan Good Where seen Good is Treenails____ Pumps Waterways_ Breasthooks and Stemson Comings_ Transoms, Pointers, and Crutches Masts, Yards, &c. Upper Deck Beams & Fastenings Timbers of the Frame Lower Deck Beams & Fastenings Keelsons _ Planksheers Anchors No. of & B. 15,2 K Clamps and Shelfs Sheerstrakes Cables Ceiling_ 9 6 9 Topsides_ Rudder Hawsers and Warps___ Wales Copper F N When put on 1865 Standing & Running Rigging _____ Plank (Bottom) and Counter Caulking of Bottom, Deck, and Waterways Where selve Good General Observations and Opinion, Is now in good and efficient condition and in my opinion fet to remain as classed. Committee's Minute 29 1 January 18by Character assigned Certificate (if required) No. Date Survey held at on the When built Built at Tonnage ___ Owners __ By whom built ___ Destined Voyage Port belonging to ____ If Surveyed Afloat or in Dry Dock Classed Last Survey, No. Port of The present Condition of the Windlass and Capstan Decks Pumps__ Waterways _ Breasthooks and Stemson Comings Transoms, Pointers, and Crutches Upper Deck Beams & Fastenings Masts, Yards, &c. Timbers of the Frame Lower Deck Beams & Fastenings Keelsons Planksheers Anchors No. of Clamps and Shelfs _ Sheerstrakes Cables Topsides Hawsers and Warps Rudder Wales Plank (Bottom) and Counter _ When put on _ Standing & Running Rigging General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Committee's Minute Character assigned