

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 109 ✓ Weight: 1070kgs ✓ Width: 1.2 m ✓

Position Code No. _____ Cubage: 4.8 m³ ✓ Height: 0.7 m ✓

Machine Inventory No. : 27-4-2309 ✓ Length: 5.7 m ✓ Set No.: 7-10/11 ✓

Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p>48 pcs.</p> <p><i>OK</i></p>	<p>PIPES for Diesel Engine</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY: <i>Wicki. Fukuda</i></p> <p>FOREMAN: <i>Taka. Wainosuke</i> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 110 ✓ Weight: 350kgs Width: 1.1 m ✓

Position Code No. _____ Cubage: 1.2 m³ Height: 0.9 m ✓

Machine Inventory No. : 27-4-2309 ✓ Length: 1.2 m ✓ Set No.: 7-11/11 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
1	RHEOSTAT for Diesel Engine
4	OIL SWITCH GEARS for Diesel Engine
<p>CONDITION OF ITEM:</p> <p>Rheostat, 4 Oil Switches: Broken</p>	
<p>CONDITION OF ITEM:</p>	
<p>INSPECTED BY: <u>Koichi Fukuda</u></p>	
<p>FOREMAN: <u>Takao Wainosuke</u> Name of Packer</p>	

Re-Check

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 111 ✓ Weight: 1720 ^{kgs} Width: 1.2 m ✓
 Position Code No. _____ Cubage: 2.2 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : 27-4-
3898-3302 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
5	R.R. POINTS

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

Koichi Furuda

Takao Dainosuke

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 112 ✓ Weight: 1070 kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 4.8 m³ ✓ Height: 1.7 m ✓
 Machine Inventory No.: See Below Length: 2.8 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	Condition of Item
	Inventory No.	
1	27-4-2459 ✓ TRANSFORMER, 85 K.V.A.	Gauge, Stop valve: Missing
1	27-4-2460 ✓ TRANSFORMER, 85 K.V.A.	Gauge, Valve handle: Missing
1	27-4-2461 ✓ TRANSFORMER, 85 K.V.A.	Gauge, Valve Handle: Missing

OK ✓

CONDITION OF ITEM: _____

INSPECTED BY:

Koichi Furudate

FOREMAN:

Takao Dainosuke

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 113 ✓ Weight: 295kgs ✓ Width: 0.7 m ✓

Position Code No. _____ Cubage: 0.5 m³ Height: 0.5 m ✓

Machine Inventory No. : 27-4-431 ✓ Length: 1.4 m ✓ Set No. B-1/4 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>1</p> <p>OK /</p>	<p>SPOT WELDER</p> <p>CONDITION OF ITEM:</p> <p>Exchange Weitch, Adjuster of Air Pressure Pressure: Broken Pipes, Hose: Missing</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u>Koichi Fukuda</u></p> <p>FOREMAN: <u>Takao Bainosuke</u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 115 Weight: 1350 kgs Width: 0.9 m

Position Code No. _____ Cubage: 1.4 m³ Height: 1.6 m

Machine Inventory No. : 27-4-481 Length: 1.0 m Set No.: 8-3/4

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	STEP-UP TRANSFORMER for Spot Welder

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Takao Banno
Takao Banno

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 116 ✓ Weight: 230kgs ✓ Width: 0.8 m ✓
 Position Code No. _____ Cubage: 1.1 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No.: 27-4-431 ✓ Length: 2.0 m ✓ Set No.: 8-4/4 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
1	<p>CONTROL PANELL, for Spot Welder</p> <p>CONDITION OF ITEM: Broken</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u>Koichi Furudate</u> <u>Takao Bainsuke</u> FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 117 ✓ Weight: 730kgs ✓ Width: 0.9 m ✓

Position Code No. _____ Cubage: 2.4 m³ ✓ Height: 1.9 m ✓

Machine Inventory No. : 27-4-436 ✓ Length: 1.4 m ✓ Set No.: _____

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	SPOT WELDER

OK

CONDITION OF ITEM:

Rubber hose: Missing

INSPECTED BY:

Koichi Furudas.

FOREMAN:

Takas Sunosuke

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 118 ✓ Weight: 330kgs ✓ Width: 0.9 m ✓

Position Code No. _____ Cubage: 0.9 m³ Height: 0.7 m ✓

Machine Inventory No.: 27-4-435 ✓ Length: 1.4 m ✓ Set No.: _____

Type of Package: BOX DESTINATION: MANILANG

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">SPOT WELDER</p> <p style="margin-top: 100px;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">Joint Point, Gum hose, Door, Rheostat, Foot Lever: Missing</p> <p style="margin-top: 50px;">CONDITION OF ITEM</p> <p style="margin-top: 50px;">INSPECTED BY: <u>Koichi Furuda</u></p> <p style="margin-left: 100px;"><u>Takao Dainosuke</u></p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓

Package No. 119 ✓ Weight: 3600kgs Width: 1.6 m ✓

Position Code No. _____ Cubage: 5.8 m³ Height: 1.9 m ✓

Machine Inventory No. : 27-4-444 ✓ Length: 1.9 m ✓ Set No.: 9-1/2 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
----------	------

1 ELECTRIC FURNACE

B. Lopez

CONDITION OF ITEM:

A Part of Casing, Terminal: Broken

~~CONDITION OF ITEM:~~

INSPECTED BY:

Koichi Furudate

Takao Dainosuke

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 120 ✓ Weight: 460kgs ✓ Width: 1.0 m ✓

Position Code No. _____ Cubage: 1.5 m³ ✓ Height: 0.8 m ✓

Machine Inventory No. : 27-4-444 ✓ Length: 1.9 m ✓ Set No.: 9-2/2 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item				
<p>1</p> <p><i>mark original hand with care</i></p> <p><i>OK</i></p>	<p>CONTROL PANEL, for Electric Furnace</p> <p>CONDITION OF ITEM:</p> <table data-bbox="686 1883 1528 1995"> <tr> <td>Source Exchange Handle:</td> <td>Missing</td> </tr> <tr> <td>Marble Pannel:</td> <td>Broken</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u><i>Koichi Fukuda</i></u></p> <p><u><i>Takao Dainosuke</i></u></p> <p>FOREMAN: _____ Name of Packer</p>	Source Exchange Handle:	Missing	Marble Pannel:	Broken
Source Exchange Handle:	Missing				
Marble Pannel:	Broken				

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 121 ✓ Weight: 295kgs Width: 0.7 m ✓

Position Code No. _____ Cubage: 0.5 m³ Height: 0.5m ✓

Machine Inventory No. : 27-4-438 ✓ Length: 1.4 m ✓ Set No. 10-1/4 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
----------	------

1 SPOT WELDER

09

CONDITION OF ITEM:

Cooling Device, Connecting Switches: Broken
Stop Welding Lower Metal: Missing

~~CONDITION OF ITEM:~~

INSPECTED BY:

Koichi Furudate

FOREMAN: Takao Dainosuke
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 122 ✓ Weight: 320kgs ✓ Width: 0.8 m ✓
 Position Code No. _____ Cubage: 1.2 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : 27-4-438 ✓ Length: 1.9 m ✓ Set No.: 10-2/4 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
----------	------

OK

1

CONJUNCTION BOX for Spot Welder

CONDITION OF ITEM:

Broken

INSPECTED BY:

Koichi. Furudas.

FOREMAN:

Takao Dainosuke

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 123 ✓ Weight: 230kgs ✓ Width: 0.8 m ✓

Position Code No. _____ Cubage: 1.1 m³ ✓ Height: 0.7 m ✓

Machine Inventory No. : 27-4-438 ✓ Length: 2.0 m ✓ Set No.: 10-3/4 ✓

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>✓ 1 015</p>	<p>CONTROL PANEL, for Spot Welder</p> <p>CONDITION OF ITEM:</p> <p>Broken</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <i>Koichi Fukuda</i> <i>Takao Dainosuke</i></p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 126 ✓ Weight: 700kgs Width: 0.9 m ✓
 Position Code No. _____ Cubage: 2.0 m³ Height: 1.7 m ✓
 Machine Inventory No. : 27-4-448 ✓ Length: 1.3 m ✓ Set No.: 11-2/2 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	CONTROL PANEL for Furnace

OK

CONDITION OF ITEM:

Meter: Broken
 Cover: Missing

INSPECTED BY:

Koichi Furudas

Takao Dainosuke

FOREMAN:

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 128 ✓ Weight: 2020kgs Width: 1.1 m ✓

Position Code No. _____ Cubage: 2.3 m³ ✓ Height: 1.3 m ✓

Machine Inventory No. : 27-4-2231 ✓ Length: 1.6 m ✓ Set No.: 12-2/3 ✓

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

✓ 1

OK

MOTOR, 100 H.P., for Compressor

CONDITION

CONDITION OF ITEM:

Satisfactory

~~CONDITION OF ITEM:~~

INSPECTED BY: Koichi Furudate

FOREMAN: Takao Dainosuke

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 129 Weight: 610kgs Width: 0.9 m

Position Code No. _____ Cubage: 2.0 m³ Height: 0.7 m

Machine Inventory No.: 27-4-2231 Length: 3.1 m Set No.: 12-3/3

Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">3</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">COOLING PIPES for Compressor</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY: <u>Takashi Sudo</u> <u>Takashi Sudo</u></p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓

Package No. 130 ✓ Weight: 1103kgs Width: 1.1 m ✓

Position Code No. _____ Cubage: 3.5 m³ ✓ Height: 1.6 m ✓

Machine Inventory No.: 27-4-3970 ✓
3971 ✓ Length: 2.0 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	
		Condition of Item
1 ✓	MANUAL PRESS	Satisfactory
1 ✓	MANUAL PRESS	"
	CONDITION OF ITEM:	
	INSPECTED BY:	<i>Koichi Furudas.</i>
	FOREMAN:	<i>Kantake Masamitsu</i>
	Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 131 ✓ Weight: 1080 kgs Width: 1.5 m ✓

Position Code No. _____ Cubage: 3.6 m³ Height: 1.4 m ✓

Machine Inventory No. : 27-4-3972 ✓
27-4-3973 ✓ Length: 1.7 m ✓ Set No.: _____

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>2</p> <p><i>OK</i></p>	<p>MANUAL SHEARS</p> <p>CONDITION OF ITEM: <u>Satisfactory</u></p> <p>INSPECTED BY: <u>Koichi Furuda</u></p> <p>FOREMAN: <u>Kantake Masamitsu</u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓

Package No. 132 ✓ Weight 452 kgs ✓ Width: 0.8 m ✓

Position Code No. _____ Cubage: 1.0 m³ ✓ Height: 0.9 m ✓

Machine Inventory No. : 27-4-3987 ✓ 3988 ✓ Length: 1.4 m ✓ Set No.: _____

Type of Package: BOX DESTINATION: MANILA

Quantity	Item	Condition of Item
----------	------	-------------------

1

MANUAL PRESS ✓

Satisfactory

1

MANUAL PRESS ✓

Satisfactory

OK

CONDITION OF ITEM:

INSPECTED BY: Koichi Fukuda

FOREMAN: Kantake Masamitsu
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 133 ✓ Weight: 1791kgs Width: 1.5 m ✓

Position Code No. _____ Cubage: 6.2 m³ Height: 1.8 m ✓

Machine Inventory No. : See Below Length: 2.3 m ✓ Set No.: _____

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item									
	<table border="0" style="width: 100%;"> <tr> <td style="width: 20%;"></td> <td style="width: 40%;">Inventory No</td> <td style="width: 40%;">Condition of Item</td> </tr> <tr> <td style="text-align: center;">1</td> <td>27-4-3969 ✓ MANUAL BENDING</td> <td>Chain: Missing</td> </tr> <tr> <td style="text-align: center;">1</td> <td>" 3978 ✓ SHEARING</td> <td>2 Springs: Missing Foot step: Broken</td> </tr> </table>		Inventory No	Condition of Item	1	27-4-3969 ✓ MANUAL BENDING	Chain: Missing	1	" 3978 ✓ SHEARING	2 Springs: Missing Foot step: Broken
	Inventory No	Condition of Item								
1	27-4-3969 ✓ MANUAL BENDING	Chain: Missing								
1	" 3978 ✓ SHEARING	2 Springs: Missing Foot step: Broken								

OK

~~CONDITION OF ITEM~~

INSPECTED BY:

Koichi Fukuda

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 134 ✓ Weight: 3097kgs Width: 1.8 m ✓
 Position Code No. _____ Cubage: 9.1 m³ Height: 2.2 m ✓
 Machine Inventory No. : See Below Length: 2.3 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item		Condition of Item
	Inventory No.		
1	27-4-3979 ✓	METAL ROLLER	Satisfactory
1	" " 3982 ✓	METAL ROLLER	"
1	" " 3980 ✓	METAL ROLLER	"
1	" " 4006 ✓	METAL ROLLER	"

Blocking on top.

~~CONDITION OF ITEM:~~

INSPECTED BY:

Koichi Kusuda

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 135 ✓ Weight: 1941 kgs ✓ Width: 1.5 m ✓

Position Code No. _____ Cubage: 5.6 m³ ✓ Height: 1.7 m ✓

Machine Inventory No. : 27-4-3977 ✓ ²⁷⁻⁴⁻³⁹⁸¹ ✓ Length: 2.2 m ✓ Set No.: _____

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">2</p> <p style="font-size: 2em; margin-left: 10px;">011</p>	<p style="text-align: center;">SHEARING MACHINES</p> <p style="text-align: center; margin-top: 200px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 50px;">INSPECTED BY: <u>Koichi Fukuda</u></p> <p style="text-align: center; margin-top: 20px;">FOREMAN: <u>Kantake Masamitsu</u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 136 ✓ Weight: 687kgs ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 3.5 m³ Height: 1.4 m ✓
 Machine Inventory No. : 27-4-3986 ✓ Length: 2.1 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i></p>	<p>BLOWER W/Motor</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>CONDITION OF ITEM.</p> <p>INSPECTED BY: <i>Koichi Susuda</i></p> <p>FOREMAN: <i>Kantake Masamitsu</i> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 137 ✓ Weight: 535kgs ✓ Width: 0.9 m ✓

Position Code No. _____ Cubage: 1.7 m³ ✓ Height: 1.6 m ✓

Machine Inventory No.: 27-4-4048 ✓ Length: 1.2 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>TOOL GRINDER</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u>Koichi Furudate</u></p> <p>FOREMAN: <u>Kentake Masamitsu</u> Name of Packer</p>

OK ✓

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 138 ✓ Weight 1950kgs ✓ Width: 1.1 m ✓
 Position Code No. _____ Cubage: 6.1 m³ Height: 1.9 m ✓
 Machine Inventory No. : 27-4-3993 ✓ Length: 2.9 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	BENDING MACHINE

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

Koichi Furudate

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 140 ✓ Weight 1556kgs ✓ Width: 1.7 m ✓

Position Code No. _____ Cubage: 8.3 m³ Height: 1.8 m ✓

Machine Inventory No.: See Below Length: 2.7 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item		
	Inventory No		Condition of Item
1	37-4-4016 ✓	BENDING MACHINE	Satisfactory
1	" 5677 ✓	METAL SHEAR	"

OK

CONDITION OF ITEM:

INSPECTED BY:

Koichi Fukuda

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 141 ✓ Weight: 1950 kgs ✓ Width: 1.3 m ✓

Position Code No. _____ Cubage: 5.5 m³ ✓ Height: 1.5 m ✓

Machine Inventory No. : 27-4-589 ✓ 27-4-590 ✓ Length: 2.8 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p>	<p style="text-align: center;">2 ELECTRIC FURNACES</p> <p style="text-align: center;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center;">INSPECTED BY: <u>Koichi Furudas.</u></p> <p style="text-align: center;">FOREMAN: <u>Kantake Masamitsu</u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 142 ✓ Weight: 1780kgs ✓ Width: 1.2 m ✓

Position Code No. _____ Cubage: 3.4 m³ ✓ Height: 2.0 m ✓

Machine Inventory No.: 27-4-2201 ✓ Length: 1.4 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OIT</p>	<p style="text-align: center;">TRANSFORMER, 200 K.V.A.</p> <p style="margin-top: 100px;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">Gauge: Broken</p> <p style="margin-top: 20px;">INSPECTED BY: <u>Keichi Fukuda</u></p> <p style="margin-left: 40px;"><u>Takao Dainosuke</u></p> <p style="margin-left: 40px;">FOREMAN: _____</p> <p style="margin-left: 80px;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 143 Weight: 200kgs Width: 0.7 m

Position Code No. _____ Cubage: 0.3 m³ Height: 0.5 m

Machine Inventory No. : 27-4-4026 Length: 0.9 m Set No.: _____

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
----------	------

2 RIVET TIGHTNERS

CONDITION OF ITEM:
Satisfactory

CONDITION OF ITEM:

INSPECTED BY: *Roicel Tubudesan*

FOREMAN: *Kantake Masamitsu*
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 5-42

Package No. 144 ✓ Weight: 450kgs Width: 0.8 m ✓

Position Code No. _____ Cubage: 1.2 m³ Height: 0.9 m ✓

Machine Inventory No. : 27-4-2500 ✓ Length: 1.6 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1 ✓	WATER PUMP, w/MOTOR
-----	---------------------

OK

CONDITION OF ITEM:

Satisfactory

CONDITION OF ITEM: -

INSPECTED BY:

Koichi Fukuda

FOREMAN:

Kantake Masamitsu
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 145 ✓ Weight: 1883 kgs ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 5.5 m³ ✓ Height: 1.5 m ✓
 Machine Inventory No. : 27-4-637 ✓ 27-4-639 ✓ Length: 2.8 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item	Condition of Item
1 ✓	ELECTRIC FURNACE	Satisfactory
1 ✓	-do-	-do-

OK
Block

~~CONDITION OF ITEM:~~

INSPECTED BY: *Kiichi Furusada*

FOREMAN: *Kantake Masamitsu*
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 146 ✓ Weight: 2870kgs ✓ Width: 1.6 m ✓

Position Code No. _____ Cubage: 6.0 m³ ✓ Height: 2.1 m ✓

Machine Inventory No. : 27-4-2299 ✓ Length: 1.8 m ✓ Set No.: 13-1/2 ✓

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

<p>1</p>	<p>AIR COMPRESSOR W/M</p>
----------	---------------------------

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Koichi Furudas.

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 147 ✓ Weight: 1245kgs ✓ Width: 1.1 m ✓

Position Code No. _____ Cubage: 2.6 m³ ✓ Height: 1.3 m ✓

Machine Inventory No. : 27-4-2299 ✓ Length: 1.8 m ✓ Set No.: 13-2/2 ✓

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i></p>	<p>MOTOR 100 H.P. for Compressor</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY: <u><i>Koichi Furuda</i></u></p> <p>FOREMAN: <u><i>Kantake Masamitsu</i></u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 148 ✓ Weight: 820kgs ✓ Width: 1.2 m ✓

Position Code No. _____ Cubage: 2.5 m³ ✓ Height: 1.6 m ✓

Machine Inventory No. : 27-4-627 ✓ Length: 1.3 m ✓ Set No.: _____

Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i></p>	<p>EDGE BENDER</p> <p>CONDITION OF ITEM:</p> <p>Motor and Belt: Missing</p> <p>INSPECTED BY: <i>Koichi Fukuda</i></p> <p>FOREMAN: <i>Kantake Masamitsu</i> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 149 ✓ Weight: 1042kgs ✓ Width: 1.0 m ✓

Position Code No. _____ Cubage: 2.1 m³ Height: 1.0 m ✓

Machine Inventory No. : 27-4-2507 ✓ Length: 2.1 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1

1 CYLINDER GAS ENGINE

*Shaft
Blocky*

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Koichi Fukuda

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 150 ✓ Weight: 1678 kgs Width: 1.4 m ✓
 Position Code No. _____ Cubage: 4.3 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : See Below Length: 3.1 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item	Condition of Item
1	Inventory No. <u>27-4-3544</u> ✓ HOIST	Wire, Motor, Travelling chain gear and Shaft, Travelling motion gear: Missing Switch: Broken
1	<u>27-4-3545</u> ✓ HOIST	Satisfactory
1	<u>27-4-3546</u> ✓ HOIST	Motor, Travelling chain gear, Travelling motion gear: Missing Switch: Broken

OK

~~CONDITION OF ITEM:~~

INSPECTED BY: Yoichi Fukuda
 FOREMAN: Kantake Masamitsu
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 151 ✓ Weight: 2855kgs ✓ Width: 1.6 m ✓
 Position Code No. _____ Cubage: 6.4 m³ ✓ Height: 2.1 m ✓
 Machine Inventory No. : 27-4-2302 ✓ Length: 1.9 m ✓ Set No.: 14-1/2 ✓
 Type of Package: GRATE . DESTINATION: MANILA

Quantity	Item
1	COMPRESSOR

OK ✓

CONDITION OF ITEM:

Oil Pipe: Missing

INSPECTED BY: Koichi Fukuda

FOREMAN: Kami-ke Masamu
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 154 ✓ Weight: 800kgs ✓ Width: 0.9 m ✓

Position Code No. _____ Cubage: 1.1 m³ Height: 0.9 m ✓

Machine Inventory No. : 27-4-2303 ✓ Length: 1.3 m ✓ Set No.: 15-2/2 ✓

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1	MOTOR 50 H.P. for Compressor
---	------------------------------

OK
Block

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Koichi Furudas.

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
Package No. 155 Weight: 699kgs Width: 1.4 m
Position Code No. _____ Cubage: 2.2m³ Height: 1.0 m
Machine Inventory No. : 27-4-7819 Length: 1.6 m Set No.: _____
Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1 HOIST

OK

CONDITION OF ITEM:

wire, hook, switch cover, pole: Missing

~~CONDITION OF ITEM:~~

INSPECTED BY:

Koichi Furudas.

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 156 ✓ Weight: 770kgs ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 2.0 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : 27-4-3633 ✓ Length: 1.7 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item	Condition of Item
1	HOIST	Satisfactory
48m	COPPER WIRE	"
48m	" "	"
48m	" "	"
2	TURN BUCKLES	"
7	FITTING METALS	"
2	INSULATORS	"

~~CONDITION OF ITEM:~~

INSPECTED BY:

Keichi Furudate

FOREMAN:

Kawasaki Masato

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 157 ✓ Weight: 11400 kg Width: 2.5 m ✓
 Position Code No. _____ Cubage: 49.4 m³ Height: 2.5 m ✓
 Machine Inventory No. : 27-4-2145 ✓ Length: 7.9 m ✓ Set No.: 16-1/2 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i> <i>Good</i></p>	<p>BOILER</p> <p>CONDITION OF ITEM: 2 Water gauges: Missing</p> <p>INSPECTED BY: <u><i>Loick ...</i></u></p> <p>FOREMAN: <u><i>Kantaro Masamitsu</i></u> Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 158 Weight: 384 kgs Width: 0.6 m
 Position Code No. _____ Cubage: 0.7 m³ Height: 0.6 m
 Machine Inventory No.: 27-4-2145 Length: 2.0 m Set No.: 16-2/2
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item	Condition of Item
1	CONTROL VALVE	Lever : Missing
2	AIR INLETS	Cover: Missing
2	AIR REGULATORS	Steel Plate: Missing
1	MAIN VALVE	Handle: Missing
30	FIRE GRATES	Satisfactory
1	STOP VALVE	Handle: Missing
Total: 37		

OK

CONDITION OF ITEM:

INSPECTED BY:

Koichi Tsujidas

FOREMAN:

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 159 ✓ Weight: 11400 kg Width: 2.5 m ✓
 Position Code No. _____ Cubage: 49.4 m³ Height: 2.5 m ✓
 Machine Inventory No. : 27-4-2144 ✓ Length: 7.9 m ✓ Set No.: 17-1/2 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-left: 20px;">OK</p>	<p style="text-align: center;">BOILER</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">2 Water Gauges, Man hole, Cover: Missing</p> <p style="text-align: center;"><u>CONDITION OF ITEM:</u></p> <p style="margin-left: 40px;">INSPECTED BY: <u>Yoichi Furuda</u></p> <p style="margin-left: 40px;">FOREMAN: <u>Kantake Masamitsu</u></p> <p style="margin-left: 40px;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 160 ✓ Weight: 426kgs ✓ Width: 0.7 m ✓
 Position Code No. _____ Cubage: 0.8 m³ Height: 0.6 m ✓
 Machine Inventory No. : 27-4-2144 ✓ Length: 2.0 m ✓ Set No. 17-2/2 ✓
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item	Condition of Item
<u>OK</u> 1	SAFETY VALVE	Mass Balance: Missing
1	MAIN VALVE	Handle: Missing
1	CONTROL VALVE	Satisfactory
2	AIR INLETS	Cover: Missing
2	AIR REGULATORS	Steel Plate: Missing
30	FIRE GRATES	Satisfactory
1	STOP VALVES	Handle: Missing
Total	38	

~~CONDITION OF ITEM:~~

INSPECTED BY:

Koichi Furudate

FOREMAN

Kantake Masamitsu

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 161 ✓ Weight: 67 kg Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.2 m³ Height: 0.4 m ✓
 Machine Inventory No.: See Below Length: 0.9 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item	Condition of Item
	Inventory No	Condition of Item
1	27-4-8151 ✓	ELECTRIC Pencil Satisfactory
1	" 8724 ✓	AMMETER A.C. Portable "
1	" 8736 ✓	" " " "
1	" 8758 ✓	VOLT METER A.C. "
1	" 8762 ✓	" " " "
1	" 8765 ✓	" " " "
1	" 8764 ✓	" " " "
1	" 8769 ✓	" " D.C. "
1	" 8782 ✓	WATT METER "
1	" 9004 ✓	PLANI METER "
Total	10	

OK

~~CONDITION OF ITEM:~~

INSPECTED BY: Koichi Furudate

FOREMAN: Kantake Masamitsu
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 162 ✓ Weight: 3410kgs ✓ Width: 1.6m ✓
 Position Code No. _____ Cubage: 4.9m³ ✓ Height: 1.6m ✓
 Machine Inventory No. : 27-4-921 ✓ Length: 1.9m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

*Tighten
Loose
Parts*

27-4-921 TRANSMISSION BOX
 27-4-922 "

CONDITION OF ITEM:

27-4-921 Gear and accessories missing
 27-4-922 Gear and accessories missing

INSPECTED BY:

Taburo Masuda

FOREMAN:

Misaki Higaki

Name of Packer

Sima Co, Ltd,

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3042
 Package No. 163 ✓ Weight: 6730kgs ✓ Width: 1.8m ✓
 Position Code No. _____ Cubage: 10.4m³ ✓ Height: 2.5m ✓
 Machine Inventory No. : 27-4-1116A Length: 2.3m ✓ Set No.: 18-1/3 ✓
 Type of Package: ~~SKID BASE~~ CRATE DESTINATION: MANILA

Quantity	Item
1	<p>ELECTRIC FURNACE</p> <p>CONDITION OF ITEM:</p> <p>Main Circuit Wire, Upper Door Guide Rail, Upper Door Balance Weights and Their Accessories (Wire, Chain Wheel, Chain etc.) missing.</p> <p>INSPECTED BY:</p> <p><i>Taboro. Masud</i></p> <p>FOREMAN <i>Nisasi. Higaki</i></p> <p>Name of Packer</p> <p><i>Sima Co, Ltd.</i></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42

Package No. 1634 ✓ Weight: 170kgs ✓ Width: 0.6m ✓

Position Code No. _____ Cubage: 0.6m³ ✓ Height: 1.1m ✓

Machine Inventory No. : 27-4-1116C Length: 0.9m ✓ Set No.: 18-²/₃ ✓

Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
----------	------

1	TRANSFORMER FOR FURNACE
---	-------------------------

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: Fabun O. Plasud ✓

FOREMAN: Hisashi Haraji
Name of Packer
Sima Co., Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 165 ✓ Weight: 730kgs ✓ Width: 1.4m ✓
 Position Code No. _____ Cubage: 4.7m³ ✓ Height: 1.6m ✓
 Machine Inventory No. : 27-4-1116 ✓ Length: 2.1m ✓ Set No.: 18-3/3 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1	SWITCH BOARD FOR FURNACE
---	--------------------------

CONDITION OF ITEM:

Volt Meter and Ammeter Circuit, Handle missing.

INSPECTED BY:

Taburo. Masud

FOREMAN:

Nisasi. Higaki
Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 166 ✓ Weight: 3370kgs ✓ Width: 1.6m ✓
 Position Code No. _____ Cubage: 4.8m³ ✓ Height: 1.5m ✓
 Machine Inventory No.: 27-4-1086 ✓ 27-4-1088 ✓ Length: 2.0m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	27-4-1086 POWER TRANSMISSION
1	27-4-1088 "

OK

CONDITION OF ITEM:

27-4-1086: Satisfactory
 27-4-1088: Switch Cover, Button Switch and Wire to Magnetic Switch missing.

INSPECTED BY: Taboro. Masuo

FOREMAN: Hisasi. Higashi
 Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 167 ✓ Weight: 6280kgs Width: 1.6m ✓
 Position Code No. _____ Cubage: 11.1m³ ✓ Height: 2.4m ✓
 Machine Inventory No. : 27-4-1098 ✓ Length: 2.9m ✓ Set No.: _____
 Type of Package: CRATT DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center; margin-top: 100px;">1</p>	<p style="text-align: center;">MILLING MACHINE</p> <p style="margin-top: 100px;">CONDITION OF ITEM: 4 V Belts, Switch Box Cover, 2 Inspection Hole Covers, Cutting Oil pipings missing.</p> <p style="margin-top: 20px;">INSPECTED BY: <i>Faburo Plasud</i></p> <p style="margin-top: 10px;">FOREMAN: <i>Hisasi Higaki</i> Name of Packer <i>Sima Co, Ltd.</i></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 168 ✓ Weight: 3090kgs ✓ Width: 1.2m ✓
 Position Code No. _____ Cubage: 4.6m³ ✓ Height: 1.9m ✓
 Machine Inventory No. : 27-4-1132 ✓ Length: 2.0m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	SHAPER AND SLOTTOR
	<p>CONDITION OF ITEM: Magnetic Switch, Angular Vice, Handle Lever for Ram Stoke Adjusting missing.</p>
	<p>INSPECTED BY: <i>Fabun S. Pando</i></p>
	<p>FOREMAN: <i>Nisasi Higaki</i> Name of Packer <i>Sima Co, Ltd.</i></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 169 ✓ Weight: 400kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 1.4m³ ✓ Height: 1.2m ✓
 Machine Inventory No.: 27-4-1062 ✓ Length: 1.5m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
----------	------

OK

1	POLISHING AND BUFFING MACHINE
---	-------------------------------

CONDITION OF ITEM:

Spindle Nut and Washer, Bearing
3 Retainer Screw Bolt missing.

INSPECTED BY:

Faburo. Planas

FOREMAN:

Hisasi Higashi
Name of Packer

Sima Co., Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 170 ✓ Weight: 2280kgs ✓ Width: 1.8m ✓
 Position Code No. _____ Cubage: 15.9m ✓ Height: 2.6m ✓
 Machine Inventory No. : 27-4-2416 ✓ Length: 3.4m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

OK

1

DIESEL ENGINE

CONDITION OF ITEM:

Fuel Tank, Rocker Arm Oil Pan, Performance
 Guide Book missing.

INSPECTED BY:

Faburo. P. Masud

FOREMAN:

Nisasi. Magay

Name of Packer

Simon Lopez

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 171 ✓ Weight: 9530kgs ✓ Width: 1.8m ✓
 Position Code No. _____ Cubage: 18.1m³ ✓ Height: 1.9m ✓
 Machine Inventory No. : 27-4-1060 Length: 5.3m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center;">1</p>	<p style="text-align: center;">LATEX</p> <p>CONDITION OF ITEM: Face plate, Change Gears, Tail stock Center, Motor, Oil Pump Driving Belt, Motor Belt, Switch Gears, Change Gear Table, Handle Knob, Cutting Oil Pipings, Motor Belt Cover, Work Guide Attached to Carriage missing.</p> <p>INSPECTED BY: <i>Eaburo. Masud</i></p> <p>FOREMAN: <i>Nisasi. Nagaki</i> Name of Packer <i>Sima Co, Ltd.</i></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 172 ✓ Weight: 1330kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 1.8m³ ✓ Height: 1.6m ✓
 Machine Inventory No.: 27-4-1,128 ✓ Length: 1.4m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>GRINDING MACHINE</p> <p>Block under motor</p> <p>Tighten lower parts.</p> <p>Cover plate</p> <p>Tighten or repair to floor</p> <p>CONDITION OF ITEM: Motor, pulley, Belt Electric Lead Wire, Switch Missing.</p> <p>INSPECTED BY: <u>Taburo P. Masud</u></p> <p>FOREMAN: <u>Nisasi Higaki</u> Name of Packer <u>Sima Co., Ltd.</u></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 173 ✓ Weight: 2040kgs ✓ Width: 1.1m ✓
 Position Code No. _____ Cubage: 4.4m³ ✓ Height: 2.1m ✓
 Machine Inventory No.: 27-4-1,299 Length: 1.9m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>MILLING MACHINE</p> <p>CONDITION OF ITEM: Magnetic Switch Box, Vee Belt Cover, 2 Over Head Slide Stays, Cutting Oil Feeding Gum Pipe, A Set of Arbour Nut and Washer, 5 Handle gripes, 2 Oil Filter of Beds, Machine vice missing</p> <p>INSPECTED BY: <u>Takuro. Masuda</u></p> <p>FOREMAN: <u>Hisasi Higaki</u> Name of Packer <u>Sima Co, Ltd.</u></p>

*fair
 Assames
 many items
 one in
 condition
 where they
 may be
 damaged.*

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 174 ✓ Weight: 170kgs ✓ Width: 0.8m ✓
 Position Code No: _____ Cubage: 0.7m³ ✓ Height: 0.6m ✓
 Machine Inventory No. : 27-4-1335 ✓ Length: 1.5m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
<p>1</p> <p>OK ✓</p>	<p>HARDNESS TESTER</p> <p>CONDITION OF ITEM:</p> <p>Counter Weight, Precise Accessories missing</p> <p>INSPECTED BY: <u>Faburo. P. Ramos</u></p> <p>FOREMAN: <u>Blisa. ...</u></p> <p>Name of Packer <u>Sima Co., Ltd.</u></p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 175 ✓ Weight: 1584 kgs ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 3.4 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No.: 27-4-1188 Length: 2.2 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1	27-4-1180 ✓ A.C. INDUCTION MOTOR
1	27-4-1188 ✓ "

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: T. Taburo. Plano
 Name of Packer: W. Higaki

Sima Co. Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 176 ✓ Weight: 810kgs Width: 0.9m ✓
 Position Code No. _____ Cubage: 1.7m³ Height: 1.0m ✓
 Machine Inventory No. : 27-4-1154 Length: 1.8m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	✓ 27-4-1154 A.C. INDUCTION MOTOR
1	✓ 27-4-1155 "

OK

CONDITION OF ITEM:
 Satisfactory

INSPECTED BY: Taburo. Masud

FOREMAN: Nisasi. Higaki
 Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 177 ✓ Weight: 1514kgs ✓ Width: 1.7m ✓
 Position Code No. _____ Cubage: 5.1m³ ✓ Height: 1.0m ✓
 Machine Inventory No. : 27-4-3837 Length: 3.0m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1 ✓	27-4-3837 HOIST
1 ✓	27-4-3840 "

OK

CONDITION OF ITEM:

27-4-3837: Switch Gears, Hoisting Wire and Hook, Collector Shoes missing, Oil Piping damaged.
 27-4-3840: Hoisting Wire, Switch Cover and Bar, Guide Wheel and its Shaft, Collector Shoe missing.

INSPECTED BY:

Takuro Masuda
FOREMAN: *Hisasi Higaki*
 Name of Packer
Sima Co, Ltd.

Mr. CV

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 178 ✓ Weight: 341kgs ✓ Width: 0.9m ✓
 Position Code No. _____ Cubage: 0.8m³ ✓ Height: 0.6m ✓
 Machine Inventory No. : Below Length: 1.4m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-1170 ✓	A.C. INDUCTION MOTOR
1	27-4-1171 ✓	"
1	27-4-1174 ✓	"
1	27-4-1168 ✓	"

*Check
Hold
down
balls*

CONDITION OF ITEM:
 Satisfactory *Faburo Plasud*

INSPECTED BY:
Hisasi Higashi

FOREMAN:
 Name of Packer
Sima Co., Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 179 ✓ Weight: 341kgs ✓ Width: 1.0m ✓
 Position Code No. _____ Cubage: 1.0m³ ✓ Height: 0.7m ✓
 Machine Inventory No. : _____ Below Length: 1.4m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-1172 ✓	A.C. INDUCTION MOTOR
1	27-4-1173 ✓	"
1	27-4-1175 ✓	"
1	27-4-1176 ✓	"

OK
/

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Faburo. Masud

FOREMAN:

Hisasi Higaki

Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 180 ✓ Weight: 172kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 0.5m³ ✓ Height: 0.6m ✓
 Machine Inventory No. : 27-4-1177 ✓ Length: 1.0m ✓ Set No: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
1	27-4-1177 ✓ A.C. INDUCTION MOTOR
1	27-4-1178 ✓ "

OK ✓

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Taburo. Masud

FOREMAN:

Hisasi Higaki

Name of Packer

Suma Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 181 Weight: 477kgs Width: 1.0m
 Position Code No. _____ Cubage: 1.1m³ Height: 0.6m
 Machine Inventory No. : Below Length: 1.0m Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
1	27-4-1179 A.G. INDUCTION MOTOR
1	27-4-1182 "
1	27-4-1156 "
1	27-4-1185 "
1	27-4-1150 "
1	27-4-1196 "

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Faburo. Masuo

FOREMAN:

Nisasi. Higaki

Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 182 ✓ Weight: 578kgs ✓ Width: 1.0m ✓
 Position Code No. _____ Cubage: 1.1m³ ✓ Height: 0.7m ✓
 Machine Inventory No.: Below Length: 1.6m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-3641 ✓	A.C. INDUCTION MOTOR
1	27-4-3642 ✓	"
1	27-4-3643 ✓	"
1	27-4-3644 ✓	"

OIT

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: *Taburo. Plasid*
Hisasi. Higaki

FOREMAN: _____
 Name of Packer
Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 183 ✓ Weight: 366kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 0.6m³ ✓ Height: 0.5m ✓
 Machine Inventory No.: Below Length: 1.6m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-3647 ✓	A.C. INDUCTION MOTOR
1	27-4-3649 ✓	"
1	27-4-3652 ✓	"
1	27-4-3653 ✓	"
1	27-4-3654 ✓	"
1	27-4-3655 ✓	"

*Check
hold
down
Bolts.*

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Faburo. Plasud

FOREMAN:

Hisasi Higaki

Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 184 ✓ Weight: 211kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 0.6m³ ✓ Height: 0.5m ✓
 Machine Inventory No. : Below Length: 1.4m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
1	27-4-3656 ✓ A.C. INDUCTION MOTOR
1	27-4-3659 ✓ "
1	27-4-3664 ✓ "
1	27-4-3665 ✓ "
1	27-4-3666 ✓ "
<p>CONDITION OF ITEM: Satisfactory</p>	
<p>INSPECTED BY: <i>Faburo Plasud</i></p>	
<p>FOREMAN: <i>Misaki Higaki</i> Name of Packer <i>Sima Co, Ltd.</i></p>	

Check bolts.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 185 ✓ Weight: 286kg ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 0.6m³ ✓ Height: 0.5m ✓
 Machine Inventory No.: Below Length: 1.6m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-3667 ✓	A.C. INDUCTION MOTOR
1	27-4-3668 ✓	"
1	27-4-3670 ✓	"
1	27-4-3671 ✓	"
1	27-4-3672 ✓	"
1	27-4-3674 ✓	"

No. nuts or bolts.

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Taburo. P. Casio
Hisasi. Higashi

FOREMAN:

Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 186 ✓ Weight: 229kgs ✓ Width: 0.7m ✓
 Position Code No. _____ Cubage: 0.5m³ ✓ Height: 0.5m ✓
 Machine Inventory No. : Below Length: 1.5m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Inventory No.	Item
1	27-4-3680 ✓	A.C. INDUCTION MOTOR
1	27-4-3682 ✓	"
1	27-4-3683 ✓	"
1	27-4-3684 ✓	"
1	27-4-3685 ✓	"
1	27-4-3689 ✓	"

Check Bolts.

CONDITION OF ITEM:
Satisfactory

Taluro Masud

INSPECTED BY:

FOREMAN: *Nisasi Negaki*
Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 187 Weight: 200kgs Width: 1.0m
 Position Code No. _____ Cubage: 0.8m³ Height: 0.7m
 Machine Inventory No. : Below Length: 1.2m Set No.: _____
 Type of Package: _____ WOODEN BOX DESTINATION: MANILA

Quantity	Inv. No.	Item
1	27-4-2421	A.C. INDUCTION MOTOR
1	27-4-2423	"

CONDITION OF ITEM:
 Satisfactory

INSPECTED BY: *Taburo. Masud*

FOREMAN: *Nisasi. Higaki*
 Name of Packer
Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-42 ✓
 Package No. 188 ✓ Weight: 372 kgs ✓ Width: 0.8m ✓
 Position Code No. _____ Cubage: 1.4m³ ✓ Height: 0.9m ✓
 Machine Inventory No.: 27-4-3836 ✓ Length: 2.0m ✓ Set No.: _____
 Type of Package: WOODEN BOX DESTINATION: MANILA

Quantity	Item
1	27-4-2342 PUMP
1	27-4-3836 SPEED CHANGER

OK
 Balts need tightening

CONDITION OF ITEM:

27-4-2342: Satisfactory
 27-4-4846: "

INSPECTED BY:

Taburo. Masud

FOREMAN:

Hisasi Higaki
 Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42
 Package No. 189 ✓ Weight: 810kgs ✓ Width: 1.0m ✓
 Position Code No. _____ Cubage: 2.9m³ ✓ Height: 1.6m ✓
 Machine Inventory No. : 27-4-2333 ✓ Length: 1.8m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

<p>1</p>	<p>AIR COMPRESSOR</p>
----------	-----------------------

OK

CONDITION OF ITEM:

Motor with V Pulley, Belt, High pressure Hose,
 Pip(partially) missing

INSPECTED BY:

Faburo. Plas...

FOREMAN:

Hisasi Higaki

Name of Packer

Sima Co, Ltd.

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42 ✓
 Package No. 100 ✓ Weight: 158 kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 0.7 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No. : See Below Length: 1.0 m ✓ Set No.: _____
 Type of Package: Box ✓ DESTINATION: Manila ✓

Quantity	Item
1. ✓	Inventory No. 27-4-1818 Projection tester Condition of Item: Missing part are as follows: Projective lens of camera missing
1. ✓	Inventory No. 27-4-1819 Current tester

OK

CONDITION OF ITEM:

INSPECTED BY: Mingru Minami
Tomoo Kunihiro

FOREMAN: KUNIHIRO TOMOO
Name of Packer

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42
 Package No. 191 Weight: 118 kg Width: 0.7 m
 Position Code No. _____ Cubage 0.4 m³ Height: 0.7 m
 Machine Inventory No.: See Below Length: 0.8 m Set No.: _____
 Type of Package: Box DESTINATION: Manila

Quantity	Inventory No	Item	Condition of Item
1	27-4-4665	Ammeter	
1	27-4-4684	Platinum Crucible	
1	27-4-4701	Aneroid Barometer, Cover Glass & Hand Broken	
1	27-4-4707	Microscope, Objective Missing(4), Case Broken	
1	27-4-4709	Microscope	
1	27-4-4794	Kohlrash Bridge	
1	27-4-4795	" "	
1	27-4-4796	" "	
1	27-4-4814	Thermo-Electric ...	Thermo-couple Missing
1	27-4-4815	Pyrometer ...	Thermo-couple Missing
1	27-4-4816	Ammeter	
1	27-4-4821	Voltmeter	
1	27-4-4749	Stop Watch	
1	27-4-4750	Tachometer	
1	27-4-4747	Hardness Tester	
1	27-4-4711	ScalesAll Weight Missing, Body Broken
1	27-4-4712	ScalesAll Weight Missing, Body Broken
1	27-4-4713	"All Weight Missing, Body Broken
1	27-4-4714	"All Weight Missing, Body Broken
1	27-4-4721	Balance	

CONDITION OF ITEM:

INSPECTED BY:

Minoru Minami

FOREMAN: KUNIHIRO TOMOS

Name of Packer

Tomoo Kunihiro

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42
 Package No. 192 ✓ Weight: 149 kg ✓ Width: 0.7 m ✓
 Position Code No. _____ Cubage: 0.4 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : See Below Length: 1.0 m ✓ Set No.: _____
 Type of Package: Box ✓ DESTINATION: Manila ✓

Quantity	Item
1	Inventory No. 27-4-4746 Sieve Mesh
1	" " 27-4-4776 Rheostat
1	" " 27-4-4777 Transformer Rheostat
1	" " 27-4-4786 Transformer
1	" " 27-4-4787 Transformer
1	" " 27-4-4788 Transformer
1	" " 27-4-4792 Transformer
1	" " 27-4-4793 Transformer

CONDITION OF ITEM:

INSPECTED BY: Minoru Minami
 FOREMAN: Tomoo Kunihiro
 Name of Packer: KUNIHIRO TOMOO

PACKING LIST

Recipient Nation: Phillippines Allocation Number: 3 - 42
 Package No. 193 ✓ Weight: 90 kg ✓ Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.4 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : See Below Length: 1.2 m ✓ Set No.: _____
 Type of Package: BOX ✓ DESTINATION: MANILA ✓

Quantity	Item
1.	Inventory No. 27-4-1813 portable grinder Condition of Item: Missing part are as follows: Grinding stone are missing
20	Item No. 2 Calipers

CONDITION OF ITEM:

INSPECTED BY: Minoru Minami

FOREMAN: Tomoo Kunihiro
 Name of Packer

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42
 Package No. 194 Weight: 77 kg ✓ Width: 0.6 m ✓
 Position Code No. _____ Cubage: 0.3 m³ Height: 0.6 m ✓
 Machine Inventory No.: See Below Length: 0.7 m ✓ Set No.: _____
 Type of Package: Box DESTINATION: Manila

Quantity	Item	
1	Item No. 5	Diamond Drill Point
1	" " 32	Dial Gauge
1	" " 33	Pitch Gauge
3	" " 35	Thickness Gauges
2	" " 42	Calipers
35	" " 45	Levels

CONDITION OF ITEM:

INSPECTED BY: Minoru Minami

FOREMAN: James Kunihiro
 KUNIHIRO TOMOO
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-42 ✓
 Package No. 195 ✓ Weight: 3190 ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 7.9 m ✓ Height: 2.1 m ✓
 Machine Inventory No.: See Below Length: 2.1 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	Inventory No. <u>27-4-1738</u> ✓ CASTING MACHINE CONDITION OF ITEM: Gum pipes, gauge missing
1	Inventory No. <u>27-4-1776</u> ✓ CASTING MACHINE CONDITION OF ITEM: Measuring operation missing
<p>CONDITION OF ITEM:</p>	
<p>INSPECTED BY: <u>Minoru Minami</u></p> <p>FOREMAN: <u>Tomoo Kunihiro</u> KUNIHIRO TOMOO Name of Packer</p>	

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3 - 42 ✓
 Package No. 196 ✓ Weight: 2530 kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 7.4 m³ ✓ Height: 2.3 m ✓
 Machine Inventory No. : 27-4-1734 ✓ Length: 1.9 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p data-bbox="578 1851 950 1899">CASTING MACHINE</p> <p data-bbox="656 2346 1078 2394">CONDITION OF ITEM:</p> <p data-bbox="695 2409 1274 2505">Gauge , gum pipes missing Handle broken</p> <p data-bbox="656 2569 960 2617">INSPECTED BY: <i>Minoru Minami</i></p> <p data-bbox="931 2729 1470 2777">FOREMAN: <i>Tomoo Kunihira</i> Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42 ✓
 Package No. 197 ✓ Weight: 1026 kg Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.5 m³ Height: 1.2 m ✓
 Machine Inventory No. See Below Length: 1.4 m ✓ Set No.: _____
 Type of Package: Grate DESTINATION: Manila

Quantity	Item
1	Inventory No. 27-4-1790 ✓ Brinell type Hardness tester CONDITION OF ITEM: Pressure guage Missing
1	Inventory No. 27-4-1794 ✓ Brinell type Hardness tester CONDITION OF ITEM: Pressure guage Missing
1	Inventory No. 27-4-1795 ✓ Brinell type Hardness tester CONDITION OF ITEM: Pressure guage Missing
1	Inventory No. 27-4-1796 ✓ Brinell type Hardness tester CONDITION OF ITEM: Pressure guage Missing
	CONDITION OF ITEM:
	INSPECTED BY: <i>Minoru Minami</i>
	FOREMAN: <i>James Kunihiro</i> KUNIHIRO TOMOO
	Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 363-42

Package No. 198 ✓ Weight: 2820 kg Width: 1.6 m ✓

Position Code No. _____ Cubage: 6.0 m³ Height: 2.1 m ✓

Machine Inventory No. : 27-4-2228 ✓ Length: 1.8 m ✓ Set No. 19-1/3 ✓

Type of Package: GRATE DESTINATION: KEELUNG

Quantity	Item
----------	------

1 COMPRESSOR

*Pitch
OK*

CONDITION OF ITEM:

Gauge, Pipes missing

INSPECTED BY: *Minoru Minami*

FOREMAN: *Tom Kunihiro*
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3 - 42 ✓
 Package No. 199 ✓ Weight: 1700 kg Width: 1.2 m ✓
 Position Code No. _____ Cubage: 3.2 m³ Height: 1.4 m ✓
 Machine Inventory No. : 27-4-2228 ✓ Length: 1.9 m ✓ Set No.: 19-2/3 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
----------	------

1	MOTOR for compressor
---	----------------------

515

CONDITION OF ITEM:

Satisfactory

Minoru Minami

INSPECTED BY:

Tomoo Kunihiro

FOREMAN: KUNIHIRO TOMOO

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3 - 42 ✓
 Package No. 201 ✓ Weight: 1057 kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 3.5 m³ Height: 1.9 m ✓
 Machine Inventory No. : 27-4-1826 ✓ Length: 1.4 m ✓ Set No.: 20-1/2 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>ELECTRICAL FURNACE</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY: <i>Minoru Minami</i></p> <p>FOREMAN: <i>Kunihiro Tomoo</i> Name of Packer</p>

PACKING LIST

Recipient Nation: philippines Allocation Number: 3 - 42
Package No. 203 ✓ Weight: 3880 kg Width: 2.0 m ✓
Position Code No. Cubage: 9.2 m³ ✓ Height: 2.2 m ✓
Machine Inventory No. : 27-4-1834 Length: 2.1 m ✓ Set No.: 21-1/2 ✓
Type of Package: Crate DESTINATION: Manila ✓

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK ✓</p>	<p>✓ 1 Electrical Furnace</p> <p style="text-align: center; margin-top: 200px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY: <i>Minoru Minami</i></p> <p style="text-align: center; margin-top: 20px;">FOREMAN: <i>Tomoo Kunihiro</i> Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42 ✓
 Package No. 204 ✓ Weight: 750 kg Width: 1.2 m ✓
 Position Code No. _____ Cubage: 2.4 m³ Height: 1.1 m ✓
 Machine Inventory No. : 27-4-1834 ✓ Length: 1.8 m ✓ Set No.: 21-2/2 ✓
 Type of Package: Grate DESTINATION: Manila

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK ✓</p> <p style="text-align: center; margin-top: 100px;">1</p>	<p>Control panel for electrical furnace</p> <p>CONDITION OF ITEM: Ammeter, Voltmeter, Thermometer Missing Switch Broken</p> <p style="margin-top: 100px;">CONDITION OF ITEM:</p> <p style="margin-top: 20px;">INSPECTED BY: <i>Minoru Minami</i></p> <p style="margin-top: 20px;">FOREMAN: <i>Kunihiro Tomoo</i> Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42
 Package No. 205 ✓ Weight: 8320 kg ✓ Width: 2.0 m ✓
 Position Code No. _____ Cubage: 14.9 m³ ✓ Height: 2.4 m ✓
 Machine Inventory No. : 27-4-1820 ✓ Length: 3.1 m ✓ Set No.: 22-2/2 ✓
 Type of Package: Grate DESTINATION: Manila

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p>	<p style="margin-left: 40px;">1 Electrical furnace</p> <p style="margin-left: 100px;">CONDITION OF ITEM:</p> <p style="margin-left: 120px;">Satisfactory</p> <p style="margin-left: 100px;">INSPECTED BY: <i>Minoru Minami</i></p> <p style="margin-left: 120px;">FOREMAN: <i>Tomoo Kashihiro</i> Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42 ✓

Package No. 206 ✓ Weight: 861 kg ✓ Width: 1.6 m ✓

Position Code No. _____ Cubage: 2.3 m3 ✓ Height: 1.1 m ✓

Machine Inventory No.: 27-4-1820 ✓ Length: 1.3 m ✓ Set No.: 22-2/2 ✓

Type of Package: Crate DESTINATION: Manila

Quantity	Item
----------	------

1 Control panel for electrical furnace

CONDITION OF ITEM:
Ammeter, Voltmeter, Switch handle Broken

OK

CONDITION OF ITEM:

INSPECTED BY: *Minoru Minami*

Tomoo Kunihiro
FOREMAN: KUNIHIRO TOMOO
Name of Packer

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42
 Package No. 207 ✓ Weight: 3880 ^{kg} Width: 2.0 m ✓
 Position Code No. _____ Cubage: 9.2 m³ Height: 2.2 m ✓
 Machine Inventory No. : 27-4-1824 ✓ Length: 2.1 m ✓ Set No.: 23-1/2 ✓
 Type of Package: Grate ✓ DESTINATION: Manila

Quantity	Item
✓ 1	<p>Electric Furnace</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY: <i>Miyoru Minami</i> <i>Tomoo Kunihiro</i> FOREMAN: KUNIHIRO TOMOO Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3 - 42 ✓
 Package No. 208 ✓ Weight: 750 kg Width: 1.2 m ✓
 Position Code No. _____ Cubage: 2.4 m3 Height: 1.1 m ✓
 Machine Inventory No.: 27-4-1824 ✓ Length: 1.8 m ✓ Set No.: 23-2/2 ✓
 Type of Package: Grate DESTINATION: Manila

Quantity	Item
<p>OK ✓</p>	<p>1 Control panel for electrical furnace</p> <p>CONDITION OF ITEM: Cover of switch Broken</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u>Minoru Minami</u></p> <p><u>Tomoo Kunishiro</u> FOREIGNER <u>KUNISHIRO TOMOO</u> Name of Packer</p>