

AIRCRAFT ACTION REPORT

RESTRICTED
(Reclassify when filled out)

CONFIDENTIAL

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

REPORT No. 5

XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only).

(a) Target(s) and Location(s) Urdaneta, Luzon (b) Time Over Target(s) 1500-1730 Z (Zone)
(FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK)

(c) Clouds Over Target None
(BASE IN FEET, TYPE AND TENTHS OF COVER)

(d) Visibility of Target Clear (e) Visibility Unlimited
(CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (MILES)

(f) Bombing Tactics: Type Slide Bomb Sight Used None
(LEVEL, GLIDE OR DIVE) (TYPE)

Bombs Dropped per Run 500s 1 Spacing 60-70 Altitude of Bomb Release 2000-3000
100s 2 (NUMBER) (FEET) (FEET)

R.P.: 2 each run, 60-70° glide, 1000-1500 yards alt range.

(g) Number of Enemy Aircraft Hit on Ground: Destroyed _____ Probably Destroyed _____ Damaged _____

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO. A/C ATTACKING (k) SQUADRON	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO. HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
1 Buildings in area ground main intersection of town.	Radius of area 75 ft.	4 70-94	10x100 lb. G.P., 15 F.P., 1500x.50 cal.	All in area	3/4 of buildings destroyed, 1 damaged
2 Schoolhouse north of plaza.	50 feet square	3 70-94	4x500, 4x100, 8 F.P.	1 F.P.	Slight
3 U-shaped building east of plaza.	175 ft. x 75 ft.	2 70-94	2x500 1500x.50 cal.	1x500	Serious
4 Trenches & bligs. south of plaza.	Area 300 ft. square.	2 70-94	2x500, 6x100 1000x .50 cal.	All in area.	Bldg. partially destroyed. Other damage not observed.
5					
6					
7					
8					

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

- (1) Area bombing. 3/4 of buildings in area burning or in rubble; 1 damaged from strafing runs.
- (2) Schoolhouse wall holed by rocket. Other damage not observed.
- (3) Bomb fell within building court crumbling one wall.
- (4) Part of building destroyed. Damage to trench works not observed.

None of value

(p) Were Photographs Taken? _____ Photographs of Damage, When Taken, Should Be Attached By Staple.

AIRCRAFT ACTION REPORT

CONFIDENTIAL

RESTRICTED
(Reclassify when
filled out)

REPORT No. 5

XIII. MATERIAL DATA. (Comment freely on performance or suitability, following check list at left.
Use additional sheets if necessary).

No comment

ARMAMENT

- Guns, Gunsights
- Turrets
- Ammunition
- Bombs, Torpedoes
- Bomb Sights
- Bomb Releases

COMMUNICATIONS

- Radio, Radar
- Homing Devices
- Visual Signals
- Codes, Ciphers

RECOGNITION

- IFF
- Signals
- Battle Lights
- Procedures

PROTECTION

- Armor; Points and Angles
of Fire Needing Further
Protection
- Leak Proofing

EMERGENCY EQUIPMENT

- Parachutes
- Life Belts, Life Rafts
- Safety Belts
- Emergency Kits
- Rations, First Aid

NAVIGATIONAL EQUIPMENT

- Compasses
- Driftsights
- Octants
- Automatic Pilots
- Charts
- Field Lighting

INSTRUMENTS

- Flight
- Power Plant

OXYGEN SYSTEM

**CAMOUFLAGE AND
DECEPTION DEVICES**

STRUCTURE

- Airframe
- Control Surfaces
- Control System
- Dive Flaps
- Landing Gear
- Heating System
- Flight Characteristics
At Various Loadings

POWER PLANT

- Engines
- Engine Accessories
- Propellers
- Lubricating System
- Starters
- Exhaust Dampers

HYDRAULIC SYSTEM

ELECTRICAL SYSTEM

- Auxiliary Plant
- Lights

FUEL SYSTEM

FLIGHT CLOTHING

MAINTENANCE

BASE FACILITIES

- Plane Servicing Equipment
- Personnel Facilities

REPORT PREPARED BY:

Grant W. MILLNER, Lt.(A), USNR.

SIGNATURE

AOI Officer.

RANK AND DUTY

APPROVED BY:

J. F. PATTERSON, LtCdr.,(A1), USNR.

SIGNATURE

RANK AND DUTY

Commanding Officer.

1/12/45

DATE