

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 108 ✓ Weight: 6,850kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2238 ✓ 2239 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p>2</p> <p>OK ✓</p>	<p>SURFACE PLATES</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 109 ✓ Weight: 6,850kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2235 ✓ 2233 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
2	<p data-bbox="588 1611 901 1675">SURFACE PLATE</p> <p data-bbox="656 2346 1078 2473">CONDITION OF ITEM: Satisfactory</p> <p data-bbox="666 2569 970 2633">INSPECTED BY:</p> <p data-bbox="931 2729 1597 2824">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 110 ✓ Weight: 6,850kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2230 ✓ 2231 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

OK
✓

2

SURFACE PLATE

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 111 ✓ Weight 6,850kg ✓ Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2228 ✓ 2229 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION MANILA

Quantity	Item
2	SURFACE PLATE
OK /	
	CONDITION OF ITEM:
	Satisfactory
	INSPECTED BY:
	FOREMAN: _____ Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 112 ✓ Weight: 6,850kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2226 ✓ 2227 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">01</p> <p style="text-align: center;">2</p>	<p style="text-align: center;">SURFACE PLATES</p> <p style="text-align: center;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 113 ✓ Weight: 6,850kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 4.7 m³ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-2222 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
2	SURFACE PLATES
2	SURFACE PLATES

0 ↑
 /

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 114 ✓ Weight: 7660kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 14.8 m³ Height: 2.8 m ✓
 Machine Inventory No. 27-1-1413 ✓ Length: 3.1 m ✓ Set No.: 16-1/21 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	HIGH PRESSURE WATER PUMP
1	ACCESSORIES
CONDITION OF ITEM: (1) Lubricant pipe Missing (1) Exhaust-pipe for safety valve Missing	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 115 Weight: 453kg Width: 0.6 m
 Position Code No. _____ Cubage: 1.1 m³ Height: 1.3 m
 Machine Inventory No. : 27-1-1413 Length: 1.4 m Set No.: 16-2/21
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>2</p> <p style="font-size: 2em; margin-top: 100px;"><u>OK</u></p>	<p>DIS CONNECTING SWITCHES, INSULATOR & CABLE</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 116 ✓ Weight: 8142kg ✓ Width: 2.0 m ✓
 Position Code No. _____ Cubage: 10.9 m³ ✓ Height: 2.1 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 2.6 m ✓ Set No.: 17-1/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	COMPRESSOR HEAD
1	BASE for Motor
2	CONNECTING RING

OK

CONDITION OF ITEM:

Condition of this machine is mentioned at Packing list P.K.G. No. 118.

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 117 ✓ Weight: 4044kg ✓ Width: 1.5 m ✓
 Position Code No. _____ Cubage: 5.3 m³ ✓ Height: 1.6 m ✓
 Machine Inventory No.: 27-1-1634 ✓ Length: 2.2 m ✓ Set No.: 17-2/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	COMPRESSOR HEAD
4	LARGE VALVES
2	SMALL VALVES
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

015

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 118 ✓ Weight: 4,870kg Width: 1.5 m ✓
 Position Code No. _____ Cubage: 8.7 m³ Height: 1.7 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 3.4 m ✓ Set No.: 17-3/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">COMPRESSOR BODY</p> <p style="margin-top: 100px;">CONDITION OF ITEM: Condition of this machine is mentioned at Packing list P.K.G. No. 119.</p> <p style="margin-top: 20px;">INSPECTED BY:</p> <p style="margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 119 ✓ Weight: 4870kg Width: 1.4 m ✓
 Position Code No. _____ Cubage: 7.6 m³ Height: 1.6 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 3.4 m ✓ Set No.: 17-4/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item																
<p>1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">COMPRESSOR BODY</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 80%;">Lubricator pump (1)</td> <td style="text-align: right;">Missing</td> </tr> <tr> <td>Oil indicator (4)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Air filter (1)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Pressure gauge for receiver (1)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Nipple & pipe for receiver (1 set)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Stud bolt for frame (18)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Stud bolt for cylinder (8)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Regurator</td> <td style="text-align: right;">Repair needed</td> </tr> </table> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>	Lubricator pump (1)	Missing	Oil indicator (4)	"	Air filter (1)	"	Pressure gauge for receiver (1)	"	Nipple & pipe for receiver (1 set)	"	Stud bolt for frame (18)	"	Stud bolt for cylinder (8)	"	Regurator	Repair needed
Lubricator pump (1)	Missing																
Oil indicator (4)	"																
Air filter (1)	"																
Pressure gauge for receiver (1)	"																
Nipple & pipe for receiver (1 set)	"																
Stud bolt for frame (18)	"																
Stud bolt for cylinder (8)	"																
Regurator	Repair needed																

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 120 Weight: 2688kg Width: 1.3 m
 Position Code No. _____ Cubage: 12.0 m³ Height: 2.0 m
 Machine Inventory No. : 27-1-1634 Length: 4.6 m Set No.: 17-5/16
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1

O/K

TANK for Air Compressor

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 122 ✓ Weight: 6690kg ✓ Width: 3.1 m ✓
 Position Code No. _____ Cubage: 9.8 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 3.5 m ✓ Set No.: 17-7/16 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">ONE HALF MOTOR</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM: (198) pcs. Belt & nuts Missing</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 123 ✓ Weight: 1582kg Width: 1.4 m ✓
 Position Code No. _____ Cubage: 2.2 m³ Height: 1.0 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 1.6 m ✓ Set No.: 17-8/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p data-bbox="196 2010 490 2394">OK</p> <p data-bbox="401 1739 441 1803">2</p>	<p data-bbox="627 1739 1019 1803">MOTOR GENERATORS</p> <p data-bbox="676 2362 1087 2409">CONDITION OF ITEM:</p> <p data-bbox="686 2457 970 2505">Satisfactory</p> <p data-bbox="676 2585 970 2633">INSPECTED BY:</p> <p data-bbox="940 2729 1607 2824">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 124 ✓ Weight: 6760kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 22.2 m³ Height: 1.6 m ✓
 Machine Inventory No.: 27-1-1634 Length: 7.7 m ✓ Set No.: 17-9/16 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
90	SMALL PIPES

OK

CONDITION OF ITEM:

(198 sets) Bolt & Nuts Missing

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 125 ✓ Weight: 1119kg ✓ Width: 2.4 m ✓
 Position Code No. _____ Cubage: 5.5 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 3.8 m ✓ Set No.: 17-10/16 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
----------	------

4
OK

LARGE PIPES

CONDITION OF ITEM:

(80 sets) Bolts & Nuts Missing

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 126 ✓ Weight: 2500kg Width: 1.9 m ✓
 Position Code No. _____ Cubage: 19.9 m³ Height: 1.9 m ✓
 Machine Inventory No. : 27-1-1634 ✓ Length: 5.5 m ✓ Set No.: 17-11/16 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p>1 1</p> <p><u>OK</u></p>	<p>TANK for air Compressor</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 127 ✓ Weight: 2500kg ✓ Width: 1.9 m ✓
 Position Code No. _____ Cubage: 19.9 m³ Height: 1.9 m ✓
 Machine Inventory No.: 27-1-1634 Length: 5.5 m ✓ Set No.: 17-12/16 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK ✓</p>	<p style="text-align: center;">TANK</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 130 ✓ Weight: 1,600kg ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 6.9 m³ ✓ Height: 2.8 m ✓
 Machine Inventory No. 27-1-1634 ✓ Length: 1.9 m ✓ Set No.: 17-15/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item												
<p>1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p>SWITCH BOX w/Oil circuit Breaker</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 70%;">Handle for field rheostat (1)</td> <td style="width: 30%;">Missing</td> </tr> <tr> <td>Field Switch (1)</td> <td>Broken</td> </tr> <tr> <td>Watt-hourmeter (1)</td> <td>Missing</td> </tr> <tr> <td>Multicontact relay (3)</td> <td>"</td> </tr> <tr> <td>Relay (5)</td> <td>"</td> </tr> <tr> <td>Fuse for signal lamp (8)</td> <td>"</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	Handle for field rheostat (1)	Missing	Field Switch (1)	Broken	Watt-hourmeter (1)	Missing	Multicontact relay (3)	"	Relay (5)	"	Fuse for signal lamp (8)	"
Handle for field rheostat (1)	Missing												
Field Switch (1)	Broken												
Watt-hourmeter (1)	Missing												
Multicontact relay (3)	"												
Relay (5)	"												
Fuse for signal lamp (8)	"												

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 131 ✓ Weight: 1,580kg ✓ Width: 1.3 m ✓
 Position Code No. _____ Cubage: 6.9 m³ ✓ Height: 2.8 m ✓
 Machine Inventory No. :27-1-1634 ✓ Length: 1.9 m ✓ Set No.: 17-16/16 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1 SWITCH BOX w/Oil circuit Breaker

0 ↑

CONDITION OF ITEM:

Watt hour meter (1)	Broken
Relay (5)	"
Multicontact relay (1)	"
Multicontact (2)	Missing
Signal lamp (4)	"

~~CONDITION OF ITEM:~~

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 132 ✓ Weight: 7806kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 15.7 m³ Height: 2.8 m ✓
 Machine Inventory No.: 27-1-1498 ✓ Length: 3.3 m ✓ Set No.: 18-1/12 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	HIGH PRESSURE WATER PUMP
1	SWITCH BOX
1	ACCESSORIES

OK

CONDITION OF ITEM:

- (1) Switch Missing
- (4) Lubricant pipe fitting bolts Missing
- (2) Glass pipes of Water-gauge "

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 133 ✓ Weight: 18378kg Width: 1.8 m ✓
 Position Code No. _____ Cubage: 18.5 m³ Height: 2.7 m ✓
 Machine Inventory No. : 27-1-1498 ✓ Length: 3.8 m ✓ Set No.: 18-2/12 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	TOP SECTION of Forming Press.
1	CENTER PISTON
2	HOISTING RAMS.
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 134 ✓ Weight: 8202kg Width: 1.6 m ✓
 Position Code No. _____ Cubage: 8.5 m³ ✓ Height: 1.4 m ✓
 Machine Inventory No. : 27-1-1498 ✓ Length: 3,8 m ✓ Set No.: 18-3/12 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center; margin-top: 100px;">1</p>	<p style="text-align: center; margin-top: 100px;">MID SECTION of Forming Press.</p> <p style="margin-top: 100px;">CONDITION OF ITEM:</p> <p style="margin-left: 40px;">Washer for guide bar Broken</p> <p style="margin-top: 20px;">INSPECTED BY:</p> <p style="margin-top: 40px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 135 Weight: 8265kg Width: 2.0 m

Position Code No. _____ Cubage: 8.4 m³ Height: 1.1 m

Machine Inventory No. : 27-1-1498 Length: 3.8 m Set No.: 18-4/12

Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-left: 10px;">015</p>	<p style="text-align: center;">BASE for Forming Press</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">Satisfactory</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 136 ✓ Weight: 11809kg Width: 2.2 m ✓
 Position Code No. _____ Cubage: 7.7 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 27-1-1498 ✓ Length: 3.9 m ✓ Set No.: 18-5/12 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
1	ANVIL for Forming Press
2	RAILES
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 137 ✓ Weight: 14780kg ✓ Width: 2.2m ✓
Position Code No. _____ Cubage: 15.2 m³ Height: 1.3 m ✓
Machine Inventory No. : 27-1-1498 ✓ Length: 5.3 m ✓ Set No.: 18-6/12 ✓
Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
4	COLUMNS for Forming Press
3	PIPES for Forming Press
4	SMALL AXLES for Forming Press
1	ACCESSORIES for Forming Press

OK

CONDITION OF ITEM:
Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 138 ✓ Weight: 2,770kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 4.4 m³ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-1498 ✓ Length: 2.8 m ✓ Set No.: 18-7/12 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	CENTER PISTON for farming press
1	REGURATOR (Control assembly)
7	VALVES

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 139 Weight: 1170kg Width: 1.5 m
 Position Code No. _____ Cubage: 6.5 m³ Height: 1.4 m
 Machine Inventory No. : 27-1-1498 Length: 3.1 m Set No.: 18-8/12
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

1	TANK
---	------

O/K

CONDITION OF ITEM:

(2) Glass-pipes for Water-gauge missing

INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 140 ✓ Weight: 9626kg Width: 2.1 m
 Position Code No. _____ Cubage: 15.4 m³ Height: 1.7 m ✓
 Machine Inventory No. : 27-1-1498 Length: 4.3 m ✓ Set No.: 18-9/12 ✓
 Type of Package: OPEN CRATE DESTINATION: MANILA

Quantity	Item
1	ACCESSORIES for Forming Press
15	PIPES
CONDITION OF ITEM:	
Satisfactory	
INSPECTED BY:	
FOREMAN: _____	
Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 141 Weight: 11159kg Width: 2.6 m
 Position Code No. _____ Cubage: 7.8 m³ Height: 1.0 m
 Machine Inventory No.: 27-1-1498 Length: 3.0 m Set No.: 18-10/12
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
1	ACCUMULATOR BASE
1	BINDING METAL
4	ROLLERS
CONDITION OF ITEM: Satisfactory Satis	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

ok

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 142 ✓ Weight: 9359kg Width: 1.3 m ✓
Position Code No. _____ Cubage: 9.7 m³ Height: 1.2 m ✓ 02 ✓
Machine Inventory No. : 27-1-1498 ✓ Length: 6.2 m ✓ Set No.: 18-11/12 ✓
Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
1	ACCUMULATOR PISTON
1	VALVE
6	SMALL AXLES
1	WEIGHT
2	JOINTS for Axle
1	PIPE
<p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____</p> <p style="text-align: right;">Name of Packer</p>	

OK

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49
 Package No. 143 ✓ Weight: 8659kg Width: 2.2 m ✓
 Position Code No. _____ Cubage: 30.0 m³ Height: 1.3 m ✓
 Machine Inventory No. : 27-1-1498 Length: 10.5 m Set No.: 18-12/12 ✓
 Type of Package: BUNDLE DESTINATION: MANILA

Quantity	Item
1	STRUCTURE for Accumulator
25	PIPES
CONDITION OF ITEM: Satisfactory	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

015

04

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 144 ✓ Weight: 6830kg Width: 1.7 m ✓
 Position Code No. _____ Cubage: 3.0 m³ Height: 0.8 m ✓
 Machine Inventory No. : 27-1-2296 ✓ 9866 ✓ Length: 2.2 m ✓ Set No.: _____
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
1	SURFACE PLATE
1	SWAGE BLOCK
<p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 146 ✓ Weight: 1,840kg Width: 1.0 m ✓
 Position Code No. _____ Cubage: 3.0 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-1641 Length: 2.7 m ✓ Set No. 19-1/2 ✓
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item																																													
1	AIR COMPRESSOR (BODY)																																													
	CONDITION OF ITEM:																																													
	<table border="0"> <tr> <td>Key for V pulley</td> <td>1</td> <td>Missing</td> <td>1</td> <td>Missing</td> </tr> <tr> <td>Lubricator</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>Pipe for lubricator</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>Auto Automatic adjusting valve</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>Pipe for automatic adjusting valve</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>Frame side cover</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>V pulley</td> <td>1</td> <td>"</td> <td>1</td> <td>"</td> </tr> <tr> <td>Safety valve, pressure gauge for receiver</td> <td>1</td> <td>Missing</td> <td>1</td> <td>Missing</td> </tr> <tr> <td>Oil draining pipe (1 set)</td> <td></td> <td>"</td> <td></td> <td>"</td> </tr> </table>	Key for V pulley	1	Missing	1	Missing	Lubricator	1	"	1	"	Pipe for lubricator	1	"	1	"	Auto Automatic adjusting valve	1	"	1	"	Pipe for automatic adjusting valve	1	"	1	"	Frame side cover	1	"	1	"	V pulley	1	"	1	"	Safety valve, pressure gauge for receiver	1	Missing	1	Missing	Oil draining pipe (1 set)		"		"
Key for V pulley	1	Missing	1	Missing																																										
Lubricator	1	"	1	"																																										
Pipe for lubricator	1	"	1	"																																										
Auto Automatic adjusting valve	1	"	1	"																																										
Pipe for automatic adjusting valve	1	"	1	"																																										
Frame side cover	1	"	1	"																																										
V pulley	1	"	1	"																																										
Safety valve, pressure gauge for receiver	1	Missing	1	Missing																																										
Oil draining pipe (1 set)		"		"																																										
	CONDITION OF ITEM:																																													
	INSPECTED BY:																																													
	FOREMAN: _____ Name of Packer																																													

OK

Cover

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 147 ✓ Weight: 640kg ✓ Width: 1.1 m ✓

Position Code No. _____ Cubage: 3.0 m³ ✓ Height: 1.2 m ✓

Machine Inventory No.: 27-1-1641 ✓ Length: 2.3 m ✓ Set No.: 19-2/2 ✓

Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

1	TANK for Air Compressor
---	-------------------------

O/K

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 148 ✓ Weight: 1,840Kg Width: 1.0 m ✓
 Position Code No. _____ Cubage: 3.0 m³ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-1640 ✓ Length: 2.7 m ✓ Set No.: 20-1/2 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item																				
<p>1</p> <p><i>OK</i></p>	<p>AIR COMPRESSOR</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%;">Key for belt pulley</td> <td style="text-align: right;">Missing</td> </tr> <tr> <td>Lubricator</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Automatic adjusting valve</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Suction & exhaust flange (2)</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Main bearing side cover</td> <td style="text-align: right;">"</td> </tr> <tr> <td>pulley binding bolt & nut</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Receiver safety valve</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Receiver pressure gauge</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Oil draining pipe</td> <td style="text-align: right;">"</td> </tr> <tr> <td>Stop valve</td> <td style="text-align: right;">"</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	Key for belt pulley	Missing	Lubricator	"	Automatic adjusting valve	"	Suction & exhaust flange (2)	"	Main bearing side cover	"	pulley binding bolt & nut	"	Receiver safety valve	"	Receiver pressure gauge	"	Oil draining pipe	"	Stop valve	"
Key for belt pulley	Missing																				
Lubricator	"																				
Automatic adjusting valve	"																				
Suction & exhaust flange (2)	"																				
Main bearing side cover	"																				
pulley binding bolt & nut	"																				
Receiver safety valve	"																				
Receiver pressure gauge	"																				
Oil draining pipe	"																				
Stop valve	"																				

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 149 ✓ Weight: 1245 kg Width: 1.6 m ✓
 Position Code No. _____ Cubage: 6.3 m³ ✓ Height: 1.7 m ✓
 Machine Inventory No. : 27-1-1640 ✓ Length: 2.3 m ✓ Set No.: 20-2/2
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center; margin-top: 100px;">I</p>	<p style="text-align: center;">TANK for Air Compressor</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 150 ✓ Weight: 3,280kg Width: 1.5 m ✓
 Position Code No. _____ Cubage: 7.7 m³ Height: 1.7 m ✓
 Machine Inventory No. : 27-1-218 ✓ Length: 3.0 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA, SHIP YARD.

Quantity	Item										
<p>1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p>TURRET LATHE W/Motor</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 60%;">Tool rest handle</td> <td>Broken</td> </tr> <tr> <td>Long feed control apparatus</td> <td>Missing</td> </tr> <tr> <td>Turret</td> <td>Broken</td> </tr> <tr> <td>Belton</td> <td>Missing</td> </tr> <tr> <td>Switch</td> <td>"</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	Tool rest handle	Broken	Long feed control apparatus	Missing	Turret	Broken	Belton	Missing	Switch	"
Tool rest handle	Broken										
Long feed control apparatus	Missing										
Turret	Broken										
Belton	Missing										
Switch	"										

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 151 ✓ Weight: 1950kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 4.3 m³ ✓ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-1221 ✓ Length: 2.4 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item				
<p>1</p> <p><i>OK</i></p>	<p>TURRET LATHE W/motor</p> <p>CONDITION OF ITEM:</p> <table data-bbox="686 2394 1528 2521"> <tr> <td>Turret, motor & switch</td> <td>Broken</td> </tr> <tr> <td>Change gear cover</td> <td>Missing</td> </tr> </table> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	Turret, motor & switch	Broken	Change gear cover	Missing
Turret, motor & switch	Broken				
Change gear cover	Missing				

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 152 Weight: 3,300Kg Width: 1.5 m
 Position Code No. _____ Cubage: 7.7 m³ Height: 1.7 m
 Machine Inventory No. : 27-1-116 Length: 3.0 m Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item												
1	<p>TURRET LATHE</p> <p>CONDITION OF ITEM:</p> <table style="margin-left: 40px;"> <tr> <td>Feed gear & bolt</td> <td>Missing</td> </tr> <tr> <td>Handles</td> <td>Broken</td> </tr> <tr> <td>Switch</td> <td>Missing</td> </tr> <tr> <td>Oil pump</td> <td>"</td> </tr> <tr> <td>Pipe</td> <td>"</td> </tr> <tr> <td>Turret</td> <td>Dismantled</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	Feed gear & bolt	Missing	Handles	Broken	Switch	Missing	Oil pump	"	Pipe	"	Turret	Dismantled
Feed gear & bolt	Missing												
Handles	Broken												
Switch	Missing												
Oil pump	"												
Pipe	"												
Turret	Dismantled												

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 153 ✓ Weight: 2130Kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.4 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : See below Length: 2.2 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p>	<p>Machine Inventory No. 27-1-2094 ✓ 2095 ✓ 2097 ✓</p> <p style="text-align: center;">HOISTS</p> <p>CONDITION OF ITEM: Machine Inventory No. 27-1-2094 Pulley(1), Trolley apparatus(1 set), Block wire(1), missing; Girder apparatus(1 set) broken. 2095 Trolley apparatus(1 set), missing; Hand operating apparatus(1 set), cover for magnet(1), Control apparatus(1 set) broken. 2097 Hand operating apparatus(1 set), Trolley apparatus(1 set) missing; Control apparatus(1 set), Magnetic brake(1 set), Gear brake(1 set) broken.</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 154 ✓ Weight: 2050Kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.5 m³ Height: 1.0 m ✓
 Machine Inventory No.: See below Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>3</p> <p><i>OK</i></p>	<p>Machine Inventory No. 27-1-2093 ✓ 2109 ✓ 2110 ✓</p> <p>HOISTS</p> <p>CONDITION OF ITEM:</p> <p>Machine Inventory No.</p> <p>27-1-2093 Chain for operating(1), End cover(1), Trolley apparatus(1 set), Oil cup(1) missing. Magnetic brake(1 set), Control apparatus (1 set) broken.</p> <p>2109 Trolley apparatus(1 set) missing. Chain wheel(1), controller(1) broken.</p> <p>2110 Trolley apparatus(1 set) missing. Chain wheel(1), controller cover broken.</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 155 ✓ Weight: 2,120 Kg Width: 1.8 m ✓
 Position Code No. _____ Cubage: 4.0 m³ Height: 1.0 m ✓
 Machine Inventory No.: See below Length: 2.2 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>3</p> <p style="font-size: 2em; margin-left: 20px;">OK</p>	<p>Machine Inventory No. 27-1-2096 ✓ 2098 ✓ 2111 ✓ HOISTS</p> <p>CONDITION OF ITEM: Machine Inventory No. 27-1-2096 Trolley apparatus(1 set), Hand operating apparatus(1 set), missing; Gear brake(1 set), Control apparatus(1 set) broken. 2098 Trolley apparatus(1 set). Oil cup(1) missing; Controller apparatus(1 set), Hand operating app apparatus(1 set), End cover(1), & Magnetic Brake(1) broken 2111 Trolley apparatus(1 set) missing; Control apparatus(1 set) Operating Chain Wheel (1), Magnetic brake (1) broken</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 156 ✓ Weight: 2,180Kg ✓ Width: 1.8 m ✓
 Position Code No. _____ Cubage: 5.0 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No.: See below Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="font-size: 2em; margin-left: 20px;">OK</p> <p style="text-align: center; margin-top: 100px;">3</p>	<p>Machine Inventory No. 27-1-2099 ✓ 2100 ✓ 2108 ✓</p> <p style="text-align: right;">HOISTS</p> <p>CONDITION OF ITEM:</p> <p>Machine Inventory No. 27-1-2099 Switch lever(1), Trolley apparatus(1 set) missing; Control apparatus(1 set), Grease cup(4) broken. 2100 Trolley apparatus(1 set), Oil cup(3), Switch lever(1), End cover(1) missing; Control apparatus(1 set) broken. 2108 Trolley apparatus(1 set) Oil cup(3) missing; Control apparatus(1 set) Oil cup(1) broken.</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation PHILIPPINES Allocation Number: 3-49
 Package No. 157 ✓ Weight: 2,390kg ✓ Width: 2.2 m ✓
 Position Code No. 27-1 Cubage: 5.0 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 2,107 ✓ 2,105 ✓ Length: 2.5 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

2

HOISTS

OK

CONDITION OF ITEM:

Missing parts: 2,107	2,105
Oil cup: 3	Trolley apparatus: 1 set
Oil gauge: 2	Controller cover: 1
Trolley apparatus: 1 set	Oil cup: 1
Broken parts: 2,107	2,105
Oil cup: 1	Oil cup: 4

CONDITION OF ITEM:

INSPECTED BY: *Kawashima Shigeo*

FOREMAN: *Mitugi Arase*
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 158 ✓ Weight: 2,380kg ✓ Width: 2.2 m ✓
 Position Code No. 27-1 Cubage: 5.0 m³ ✓ Height: 0.9 m ✓
 Machine Inventory No. : 2,092 ✓ 2,101 ✓ Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p>2</p> <p style="font-size: 2em; margin-left: 20px;">OK</p>	<p>HOIST</p> <p>CONDITION OF ITEM:</p> <p>2,092: Oil cup broken, Controller cover 2, Hanging trolley 1, Trolley apparatus 1 set missing</p> <p>2,101: Oil cup 3, Oil gauge 2, Trolley apparatus 1 set missing</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <u>Kawashima Shigeo</u></p> <p>FOREMAN: <u>Mitugi Arase</u> Name of Packer</p>

PACKING LIST

Recipient Nation PHILIPPINES Allocation Number 3-49
 Package No. 159 ✓ Weight 2,380kg ✓ Width: 2.2 m ✓
 Position Code No. 27-1 ✓ Cubage 5.0 m³ ✓ Height 0.9 m ✓
 Machine Inventory No. : 2,102 ✓ 2,103 ✓ Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION MANILA

Quantity	Item
2	HOISTS
	CONDITION OF ITEM:
	Machine Inventory No. 2,102 Oil cup (2), Oil gauge (2), Trolley apparatus (1 set) missing, Oil cup (2) broken.
	Machine Inventory No. 2,103 Oil cup (3), Oil Gauge (2), Trolley apparatus (1 set) missing, Oil cup (2) broken.
	CONDITION OF ITEM:
	INSPECTED BY: <i>William [Signature]</i>
	FOREMAN: <i>Mitugi Arase</i>
	Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 160 ✓ Weight: 2,380kg ✓ Width: 2.2 m ✓
 Position Code No. 27-1 Cubage: 5.3 m³ Height: 1.0 m ✓
 Machine Inventory No. : 2,105 ✓ Length: 2.4 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item												
<p>2 ✓</p> <p>OK</p>	<p>HOISTS</p> <p>CONDITION OF ITEM:</p> <table border="0"> <tr> <td>Missing parts: 2,106</td> <td>2,104</td> </tr> <tr> <td>Oil cup: 1</td> <td>Oil cups: 2</td> </tr> <tr> <td>Trolley apparatus: 1 set</td> <td>Gear: 1</td> </tr> <tr> <td>Broken parts: 2,104</td> <td>Trolley apparatus: 1 set</td> </tr> <tr> <td>Oil cup: 4</td> <td></td> </tr> <tr> <td>Gear: 1</td> <td></td> </tr> </table> <p><u>CONDITION OF ITEM:</u></p> <p>INSPECTED BY: <i>Kawashima Shigeo</i></p> <p>FOREMAN: <i>Mitsuji Arase</i> Name of Packer</p>	Missing parts: 2,106	2,104	Oil cup: 1	Oil cups: 2	Trolley apparatus: 1 set	Gear: 1	Broken parts: 2,104	Trolley apparatus: 1 set	Oil cup: 4		Gear: 1	
Missing parts: 2,106	2,104												
Oil cup: 1	Oil cups: 2												
Trolley apparatus: 1 set	Gear: 1												
Broken parts: 2,104	Trolley apparatus: 1 set												
Oil cup: 4													
Gear: 1													

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 161 ✓ Weight: 430kg Width: 1.1 m ✓
 Position Code No. _____ Cubage: 1.7 m³ Height: 0.8 m ✓
 Machine Inventory No.: See below Length: 1.9 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
1	Machine Inventory No. 27-1-1524 ✓ PNEUMATIC DRILL
4	2038 ✓ 2039 ✓ 2040 ✓ 1380 ✓ PUMP
CONDITION OF ITEM: Machine Inventory No. 27-1-1524 Table Missing 2039 Motor "	
INSPECTED BY:	
FOREMAN: _____ Name of Packer	

OK /

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 163 ✓ Weight: 3100kg Width: 1.4 m ✓

Position Code No. _____ Cubage: 5.1 m³ Height: 1.4 m ✓

Machine Inventory No. : 27-1-1536 Length: 2.6 m ✓ Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>ELECTRIC FURNACE W/STEP UP TRANSFORMER</p> <p>CONDITION OF ITEM: (1) Pilot lamp missing</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK
OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 164 ✓ Weight: 2330kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 3.6 m³ ✓ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-1540 ✓ Length: 2.5 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	STEP UP TRANSFORMER
1	ELECTRIC FURNACE

*Clear
over
ped.*

CONDITION OF ITEM:
 (2) Ammeters Missing
 (1) Lilot lamp "
 Transformer cover Partly broken
 Pole Broken
 INSPECTED BY:

FOREMAN: _____
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINS Allocation Number: 3-49
 Package No. 165 ✓ Weight: 1930kg ✓ Width: 1.2 m ✓
 Position Code No. _____ Cubage: 3.8 m³ ✓ Height: 1.6 m ✓
 Machine Inventory No. : 27-1-1533 ✓ Length: 2.0 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
1	ELECTRIC FUANACE
1	STEPUP TRANSFORMER
OK	CONDITION OF ITEM:
	(2) Electric Pole Missing
	(1) Pilot lamp "
	(1) Side cover Broken
	(1) Pilot lamp "
	(1) Voltmeter "
	CONDITION OF ITEM:
	INSPECTED BY:
	FOREMAN: _____ Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 166 Weight: 1750kg Width: 1.3 m
Position Code No. _____ Cubage: 3.7 m³ Height: 1.2 m
Machine Inventory No. : 27-1-1534 Length: 2.4 m Set No.: _____
Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	<p>ELECTRIC FURNACE W/ STEP UP TRANSFORMER</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 167 ✓ Weight: 726kg Width: 0.8 m ✓
 Position Code No. _____ Cubage: 1.3 m³ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-103-R1 ✓ Length: 1.1 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

1

GAUGE TESTOR

OK

CONDITION OF ITEM:

Piping In good condition

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 169 ✓ Weight: 950kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 2.0 m ³ ✓ Height: 1.5 m ✓
 Machine Inventory No. : 27-1-1556 ✓ Length: 1.5 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i></p>	<p>WELDER, ELECTRIC</p> <p>CONDITION OF ITEM:</p> <p>(1) D.C. Voltmeter Broken</p> <p>(1) D.C. Ammeter "</p> <p>(1) Cover of Directcurrent motor Broken</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 170 ✓ Weight: 970kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.9 m³ ✓ Height: 1.3 m ✓
 Machine Inventory No. : 27-1-1697 ✓ Length: 1.6 m ✓ Set No.: 21-1/2 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">RECTIFIER</p> <p style="margin-top: 200px;">CONDITION OF ITEM: Rectifier Partly broken Brush holder broken Knock cover "</p> <p style="margin-top: 20px;">INSPECTED BY:</p> <p style="margin-top: 50px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 171 Weight: 390kg Width: 0.8 m
Position Code No. _____ Cubage: 0.9 m³ Height: 0.6 m
Machine Inventory No. : 27-1-1697 Length: 1.9 m Set No.: 21-2/2
Type of Package: BOX DESTINATION: MANILA

Quantity	Item
8	RHEOSTATS

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 172 ✓ Weight: 1880kg ✓ Width: 1.1 m ✓
 Position Code No. _____ Cubage: 3.0 m³ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-1698 ✓ Length: 2.3 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item														
<p>1</p> <p style="font-size: 2em; margin-top: 100px;"><u>OK</u></p>	<p>RHEOSTAT W/Rectifier ✦ for generator</p> <p>CONDITION OF ITEM:</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%;">(1 set) Brush regulator</td> <td style="text-align: right;">Missing</td> </tr> <tr> <td>(11) Base fitting bolts</td> <td style="text-align: right;">"</td> </tr> <tr> <td>(4) Knock bolts</td> <td style="text-align: right;">"</td> </tr> <tr> <td>(1) Oil cup</td> <td style="text-align: right;">"</td> </tr> <tr> <td>(1) Rectifier fitting & cover</td> <td style="text-align: right;">Broken</td> </tr> <tr> <td>(1) Oil cup</td> <td style="text-align: right;">Broken</td> </tr> <tr> <td>Rheostat</td> <td style="text-align: right;">Satisfactory</td> </tr> </table> <p>CONDITION OF ITEM</p> <p>INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	(1 set) Brush regulator	Missing	(11) Base fitting bolts	"	(4) Knock bolts	"	(1) Oil cup	"	(1) Rectifier fitting & cover	Broken	(1) Oil cup	Broken	Rheostat	Satisfactory
(1 set) Brush regulator	Missing														
(11) Base fitting bolts	"														
(4) Knock bolts	"														
(1) Oil cup	"														
(1) Rectifier fitting & cover	Broken														
(1) Oil cup	Broken														
Rheostat	Satisfactory														

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 173 ✓ Weight: 615kg ✓ Width: 0.7 m ✓
 Position Code No. _____ Cubage: 1.0 m³ ✓ Height: 1.1 m ✓
 Machine Inventory No. : 27-1-1696 ✓ Length: 1.3 m ✓ Set No.: 22-1/2 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item														
<p>1</p>	<p style="text-align: center;">MOTOR GENERATOR</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 70%;">(1) Lead wire</td> <td style="width: 30%;">Broken</td> </tr> <tr> <td>(1) Terminal</td> <td style="text-align: center;">"</td> </tr> <tr> <td>(1) Carbon brush</td> <td style="text-align: center;">"</td> </tr> <tr> <td>(1) Brush holder</td> <td style="text-align: center;">"</td> </tr> <tr> <td>(1) Oil cup</td> <td style="text-align: center;">"</td> </tr> <tr> <td>Rheostat</td> <td style="text-align: center;">Out of order</td> </tr> <tr> <td>Switch board</td> <td style="text-align: center;">Missing</td> </tr> </table> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: right;">FOREMAN: _____ Name of Packer</p>	(1) Lead wire	Broken	(1) Terminal	"	(1) Carbon brush	"	(1) Brush holder	"	(1) Oil cup	"	Rheostat	Out of order	Switch board	Missing
(1) Lead wire	Broken														
(1) Terminal	"														
(1) Carbon brush	"														
(1) Brush holder	"														
(1) Oil cup	"														
Rheostat	Out of order														
Switch board	Missing														

OK ✓

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 174 ✓ Weight: 320kg ✓ Width: 1.0 m ✓
 Position Code No. _____ Cubage: 0.8 m³ ✓ Height: 0.8 m ✓
 Machine Inventory No.: 27-1-1696 ✓ Length: 1.0 m ✓ Set No.: 22-2/2 ✓
 Type of Package: BOX DESTINATION MANILA

Quantity	Item																				
4	<p style="text-align: center;">RHEOSTATS</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <table style="width: 100%; border-collapse: collapse;"> <tr><td style="width: 80%;">(1) Starter Handle</td><td style="text-align: right;">Missing</td></tr> <tr><td>(1) Indicating plate</td><td style="text-align: right;">"</td></tr> <tr><td>(1) Indicator</td><td style="text-align: right;">"</td></tr> <tr><td>(1) Cover</td><td style="text-align: right;">"</td></tr> <tr><td>(1) Handle & Contact brush</td><td style="text-align: right;">missing</td></tr> <tr><td>(1) Sliding contact</td><td style="text-align: right;">Missing</td></tr> <tr><td>(2) Terminals</td><td style="text-align: right;">"</td></tr> <tr><td>(1) Terminal board</td><td style="text-align: right;">Broken</td></tr> <tr><td>(2) Panels, stone</td><td style="text-align: right;">"</td></tr> <tr><td>(2) Terminal</td><td style="text-align: right;">"</td></tr> </table> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____ Name of Packer</p>	(1) Starter Handle	Missing	(1) Indicating plate	"	(1) Indicator	"	(1) Cover	"	(1) Handle & Contact brush	missing	(1) Sliding contact	Missing	(2) Terminals	"	(1) Terminal board	Broken	(2) Panels, stone	"	(2) Terminal	"
(1) Starter Handle	Missing																				
(1) Indicating plate	"																				
(1) Indicator	"																				
(1) Cover	"																				
(1) Handle & Contact brush	missing																				
(1) Sliding contact	Missing																				
(2) Terminals	"																				
(1) Terminal board	Broken																				
(2) Panels, stone	"																				
(2) Terminal	"																				

OK

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 175 ✓ Weight: 550kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 1.0 m³ ✓ Height: 1.0 m ✓
 Machine Inventory No. : 27-1-1552 ✓ Length: 1.1 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>1</p> <p><i>OK</i></p>	<p>ELECTRIC WELDER</p> <p>CONDITION OF ITEM:</p> <p>Switch & Handle Broken</p> <p>Voltage regulator "</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____</p> <p>Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 176 ✓ Weight: 845 kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 4.2 m³ Height: 2.0 m ✓
 Machine Inventory No.: 27-1-1528 ✓ Length: 1.6 m ✓ Set No.: _____
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">1</p> <p style="font-size: 2em; margin-top: 100px;">OK</p>	<p style="text-align: center;">BUTT WELDER</p> <p style="text-align: center; margin-top: 100px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 50px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 50px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
Package No. 177 ✓ Weight: 2,850kg ✓ Width: 1.4 m ✓
Position Code No. _____ Cubage: 6.4 m³ Height: 1.7 m ✓
Machine Inventory No. : 27-1-18 ✓ Length: 2.7 m ✓ Set No.: _____
Type of Package: GRATE DESTINATION: MANILA

Quantity	Item										
1	<p>LATHE w/motor</p> <p>CONDITION OF ITEM:</p> <table data-bbox="617 1867 1391 2090"> <tr><td>Lead screw</td><td>Broken</td></tr> <tr><td>Change speed lever</td><td>"</td></tr> <tr><td>Tool rest</td><td>Dismantled</td></tr> <tr><td>Chuck</td><td>Broken</td></tr> <tr><td>Tail stock clamping plate</td><td>missing</td></tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>	Lead screw	Broken	Change speed lever	"	Tool rest	Dismantled	Chuck	Broken	Tail stock clamping plate	missing
Lead screw	Broken										
Change speed lever	"										
Tool rest	Dismantled										
Chuck	Broken										
Tail stock clamping plate	missing										

OK ✓

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 179 ✓ Weight: 255kg ✓ Width: 0.9 m ✓
 Position Code No. _____ Cubage: 0.7 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No. : See below Length: 1.1 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
	Machine Inventory
	No.
	27-27-1-1560 ✓
	1561 ✓
	1567 ✓
4	1574 ✓ BENCH MICROMETER
	1564 ✓
2	1565 ✓ GAUGE TESTING MICROMETER
	CONDITION OF ITEM:
	Machine Inventory
	No.
	27-1-1560 Lightening apparatus, lense, handle missing
	1561 Lightening apparatus broken
	1564 Lightening apparatus lense missing
	1565 Electric bulb missing
	Lightening apparatus bad
	1567 Indicator glass broken
	Indication bad
	1574 Indicator glass broken
	CONDITION OF ITEM:
	Indication bad
	Center stock missing
	Feed change apparatus bad
	INSPECTED BY:
	FOREMAN: _____
	Name of Packer

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 180 Weight: 135Kg Width: 0.8 m
 Position Code No. _____ Cubage: 0.4 m³ Height: 0.6 m
 Machine Inventory No.: See below Length: 0.9 m Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item																					
	Machine Inventory No. 27-1-1575 ✓																					
3	1576 ✓ 1577 ✓ BENCH MICROMETERS																					
2	1581 ✓ 1584 ✓ HARDNESS TESTERS																					
	CONDITION OF ITEM: Machine Inventory No. 27-1-1575																					
	<table style="width: 100%; border: none;"> <tr> <td style="width: 30%;"></td> <td style="width: 40%;">Dial</td> <td style="width: 30%;">Broken</td> </tr> <tr> <td></td> <td>Dial adjusting rod</td> <td>Out of order</td> </tr> <tr> <td>1576</td> <td>Cord & Electric bulb</td> <td>Missing</td> </tr> <tr> <td>1577</td> <td>Cord & Electric bulb</td> <td>"</td> </tr> <tr> <td>1581</td> <td>Diamond</td> <td>"</td> </tr> <tr> <td></td> <td>Gauge</td> <td>Out of order</td> </tr> <tr> <td>1584</td> <td>Diamond</td> <td>Missing</td> </tr> </table>		Dial	Broken		Dial adjusting rod	Out of order	1576	Cord & Electric bulb	Missing	1577	Cord & Electric bulb	"	1581	Diamond	"		Gauge	Out of order	1584	Diamond	Missing
	Dial	Broken																				
	Dial adjusting rod	Out of order																				
1576	Cord & Electric bulb	Missing																				
1577	Cord & Electric bulb	"																				
1581	Diamond	"																				
	Gauge	Out of order																				
1584	Diamond	Missing																				
	CONDITION OF ITEM:																					
	INSPECTED BY:																					
	FOREMAN: _____ Name of Packer																					

ok

6

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-40
 Package No. 131 ✓ Weight: 2.290kg ✓ Width: 1.3 m ✓
 Position Code No. 27-1 Cubage: 3.3 ✓ Height: 0.5 m ✓
 Machine Inventory No. : 90-R 35 Length: 0.2 m ✓ Set No.: 23-215 ✓
 Type of Package: CRATE ✓ DESTINATION: MANILA ✓

Quantity	Item
50	<p>VIOSS.</p> <p>CONDITION OF ITEM:</p> <p>missing parts: Vise slip needle thrust metal spindle metal</p> <p>Bad parts: handle half nut</p> <p>broken parts: bag</p> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <i>Kawarhina Shyee</i></p> <p>FOREMAN: <i>Hiramito Tatau</i> Name of Packer</p>

PACKING LIST

Recipient Nation: Philippines Allocation Number: 3-49
 Package No. 182 ✓ Weight: 2,035kg Width: 1.3 m ✓
 Position Code No. 27-1 Cubage: 3.3 m³ Height: 0.8 m ✓
 Machine Inventory No.: 90-R 35 ✓ Length: 3.2 m ✓ Set No.: 23-2/6 ✓
 Type of Package: GRAT3 ✓ DESTINATION: MANILA ✓

Quantity	Item
50 ✓	VICERS.
	<u>CONDITION OF ITEM</u>
	Missing parts: Vice clamp 7 Handle 1 Half nut 1 Bad parts: Handle 5 spindle screw 5
	<u>CONDITION OF ITEM:</u>
	INSPECTED BY: <u>Kawashima Shigeo</u>
	FOREMAN: <u>Naramitsu Tetsuo</u> Name of Packer

017

170

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 153 ✓ Weight: 1,860 lbs ✓ Width: 1.5 m ✓
 Position Code No. 274 Cubage: 3.3 ✓ Height: 0.8 m ✓
 Machine Inventory No. : 90-N 35 Length: 3.2 m ✓ Set No.: 23-51 ✓
 Type of Package: CRATE ✓ DESTINATION: MANILA ✓

Quantity	Item																														
50 ✓	VICS.																														
	CONDITION OF ITEM:																														
	<table border="0"> <tr> <td>Missing parts:</td> <td>Half nut</td> <td>1</td> </tr> <tr> <td></td> <td>Vice clamp</td> <td>1</td> </tr> <tr> <td></td> <td>Handle</td> <td>1</td> </tr> <tr> <td></td> <td>Thrust metal</td> <td>1</td> </tr> <tr> <td></td> <td>Spindle metal pin</td> <td>1</td> </tr> <tr> <td>Bad parts:</td> <td>Spindle screw</td> <td>3</td> </tr> <tr> <td></td> <td>Spindle stopper</td> <td>1</td> </tr> <tr> <td></td> <td>Thrust metal</td> <td>1</td> </tr> <tr> <td></td> <td>Spindle metal pin</td> <td>1</td> </tr> <tr> <td></td> <td>Handle</td> <td>3</td> </tr> </table>	Missing parts:	Half nut	1		Vice clamp	1		Handle	1		Thrust metal	1		Spindle metal pin	1	Bad parts:	Spindle screw	3		Spindle stopper	1		Thrust metal	1		Spindle metal pin	1		Handle	3
Missing parts:	Half nut	1																													
	Vice clamp	1																													
	Handle	1																													
	Thrust metal	1																													
	Spindle metal pin	1																													
Bad parts:	Spindle screw	3																													
	Spindle stopper	1																													
	Thrust metal	1																													
	Spindle metal pin	1																													
	Handle	3																													
	CONDITION OF ITEM:																														
	INSPECTED BY: <u>Kawashima Shigeo</u>																														
	FOREMAN: <u>Niramitsu Tetsuo</u> Name of Packer																														

14

PACKING LIST

Recipient Nation: SPAIN Allocation Number: 3-49
 Package No. 204 ✓ Weight: 2.830kg ✓ Width: 2.3 ✓
 Position Code No. 22-2 Cubage: 3.3 ✓ Height: 0.8 ✓
 Machine Inventory No.: 90-4 55 ✓ Length: 3.0 ✓ Set No.: 23-4/5 ✓
 Type of Package: CRATE ✓ DESTINATION: MANILA ✓

Quantity	Item
----------	------

50 ✓

VIBRO.

CONDITION OF ITEM:

Missing parts:	Vibro clamp	1
	Three metal screw	1
	Half nut	1
	Handle	1
	Spindle stopper	1
	Spindle	1
Use parts:	Handle	1
	Spindle screw	1
	Sliding operation	1

CONDITION OF ITEM:

INSPECTED BY: Kawashima Shigeo

FOREMAN: Hiramides Titao
 Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 185 Weight: 1,370 kg Width: 1.1 m
 Position Code No. 27-1 Cubage: 20 m³ Height: 0.7 m
 Machine Inventory No. : 90-R 35 Length: 2.6 m Set No.: 23-5/6
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item												
50	<p>VICES.</p> <p>CONDITION OF ITEM:</p> <p>Missing parts of Vices:</p> <table data-bbox="1009 1867 1715 2090"> <tr> <td>Spindle supporter:</td> <td>3 Pcs.</td> </tr> <tr> <td>Vice clamp:</td> <td>3 Pcs.</td> </tr> <tr> <td>Thrust metal cover:</td> <td>1 Pc.</td> </tr> <tr> <td>Spindle supporter cover:</td> <td>2 Pcs.</td> </tr> <tr> <td>Spindle:</td> <td>1 Pc.</td> </tr> </table> <p>Bad parts of Vices:</p> <table data-bbox="1009 2090 1715 2154"> <tr> <td>Spindle serew:</td> <td>2 Pcs.</td> </tr> </table> <p>CONDITION OF ITEM:</p> <p>INSPECTED BY: <i>Kawashima Shigeo</i></p> <p><i>Hiramitsu Tatsuo</i></p> <p>FOREMAN: <u>HIRAMITSU TATSUO</u> Name of Packer</p>	Spindle supporter:	3 Pcs.	Vice clamp:	3 Pcs.	Thrust metal cover:	1 Pc.	Spindle supporter cover:	2 Pcs.	Spindle:	1 Pc.	Spindle serew:	2 Pcs.
Spindle supporter:	3 Pcs.												
Vice clamp:	3 Pcs.												
Thrust metal cover:	1 Pc.												
Spindle supporter cover:	2 Pcs.												
Spindle:	1 Pc.												
Spindle serew:	2 Pcs.												

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 186 Weight: 1,490Kg Width: 1.1 m
 Position Code No. 27-1 Cubage: 2.0m Height: 0.7m
 Machine Inventory No. : 90- R 35 Length: 2.6 m Set No.: 23-6/6
 Type of Package: GRATE DESTINATION: MANILA

Quantity	Item														
50	<p data-bbox="588 1596 715 1643">VICES</p> <p data-bbox="588 1819 1019 1867">CONDITION OF ITEMS</p> <p data-bbox="656 1899 1185 1947">Missing parts of VICES:</p> <table data-bbox="813 1947 1479 2186"> <tr><td>Vice clamp;</td><td>6 Pcs.</td></tr> <tr><td>Handle;</td><td>8 Pcs.</td></tr> <tr><td>Spindle;</td><td>4 Pcs.</td></tr> <tr><td>Spindle stopper;</td><td>2 Pcs.</td></tr> <tr><td>Half nut;</td><td>2 Pcs.</td></tr> <tr><td>Half nut pin;</td><td>1 pc.</td></tr> </table> <p data-bbox="637 2202 1078 2250">Bad parts of VICES:</p> <table data-bbox="813 2250 1479 2298"> <tr><td>Spindle;</td><td>5 Pcs.</td></tr> </table> <p data-bbox="637 2362 1048 2409">CONDITION OF ITEM:</p> <p data-bbox="637 2585 931 2633">INSPECTED BY: <i>Ramon L. ...</i></p> <p data-bbox="901 2665 1528 2793">FOREMAN: <i>Hiramitsu Tatsuo</i> <u>HIRAMITSU TATSUO</u> Name of Packer</p>	Vice clamp;	6 Pcs.	Handle;	8 Pcs.	Spindle;	4 Pcs.	Spindle stopper;	2 Pcs.	Half nut;	2 Pcs.	Half nut pin;	1 pc.	Spindle;	5 Pcs.
Vice clamp;	6 Pcs.														
Handle;	8 Pcs.														
Spindle;	4 Pcs.														
Spindle stopper;	2 Pcs.														
Half nut;	2 Pcs.														
Half nut pin;	1 pc.														
Spindle;	5 Pcs.														

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 187 ✓ Weight: 380Kg ✓ Width: 0.7 m ✓

Position Code No. _____ Cubage: 0.4 m³ ✓ Height: 0.5 m ✓

Machine Inventory No. : 27-1-90-R33 ✓ Length: 1.2 m ✓ Set No.: _____

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
----------	------

OR

14	MACHINE VICES
----	---------------

CONDITION OF ITEM:

(14) Handles Missing

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES ✓ Allocation Number: 3-49 ✓
 Package No. 188 ✓ Weight: 275 Kg ✓ Width: 0.5 m ✓
 Position Code No. _____ Cubage: 0.2 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : 27-1-90-R38 ✓ Length: 0.8 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
<p>7</p> <p><u>OK</u></p>	<p>MAGNETIC CHUCK</p> <p>CONDITION OF ITEM: Cord (7) Bad</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 190 ✓ Weight: 1,540kg. ✓ Width: 0.9 m ✓

Position Code No. 27-1 Cubage: 1.4 m³ ✓ Height: 0.7 m ✓

Machine Inventory No.: 90-R 40 Length: 2.2 m ✓ Set No. 24-2/2 ✓

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
----------	------

6

CIRCULAR TABLE

CONDITION OF ITEM:

Missing parts: Fitting bolt & nut 4

Broken parts: Handle knock pin 2

INSPECTED BY: *Kawashima Shigeo*

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 191 ✓ Weight: 200Kg Width: 0.8 m ✓
 Position Code No. _____ Cubage: 0.5 m³ Height: 0.6 m ✓
 Machine Inventory No.: See below Length: 1.1 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
2	Machine Inventory No. 27-1-1589 - 1590 ✓ PORTABLE GRINDERS
	1599 - 1600 ✓
	1601 - 1602 ✓
6	1611 - 1612 ✓ PORTABLE PNEUMATIC DRILLS
2	1616 - 1617 ✓ PORTABLE PNEUMATIC GRINDERS
	1626 - 1627 ✓
3	2032 ✓ PORTABLE ELECTRIC DRILLS
CONDITION OF ITEM:	
Machine Inventory No. 27-1-1626 Switch & Insulation Out of order	
	Carbon brush Missing
	1589 Insulation Inferior
	1627 Brush holder & chuck Missing
	Insulation Inferior
	1590 Switch & Insulation Out of order
	Carbon brush & Grinding cover Missing
	2032 Switch & Inferior Out of order
	Carbon brush Missing
	1617 Grinding cover "
	1616 Grinding cover & Air change valve Missing
CONDITION OF ITEM:	
	1600 Air change valve & handle "
	1602 Piston Broken
	Air change valve & handle Missing
INSPECTED BY:	
FOREMAN: _____	
Name of Packer	

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 192 ✓ Weight: 410kg ✓ Width: 0.7 m ✓
 Position Code No. _____ Cubage: 0.4 m³ Height: 0.5 m ✓
 Machine Inventory No. : 27-1-90-R16 ✓ R21 ✓ Length: 1.1 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
7	CHAIN BLOCKS
1	ELECTRIC GRINDER
<p>CONDITION OF ITEM:</p> <p>Machine Inventory No. 27-1-90-R16 (1) Chain Missing (1) Hoisting chain Missing 90-R21 Switch out of order Grinding wheel Broken Bearing out of order</p>	
<p>CONDITION OF ITEM:</p>	
<p>INSPECTED BY:</p>	
<p>FOREMAN: _____ Name of Packer</p>	

OK /

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 194 ✓ Weight: 815 kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 2.7 m³ Height: 1.2 m ✓
 Machine Inventory No. : 27-1-62-R1 Length: 1.7 m ✓ Set No.: 25-2/3 ✓
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
6	<p>LARGE SWITCH BOARDS</p> <p>CONDITION OF ITEM: (2) (24) fitting bolts seen Missing</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 195 Weight: 902kg Width: 1.1 m
 Position Code No. _____ Cubage: 3.5 Height: 1.2 m
 Machine Inventory No. : 27-1-62-R1 Length: 2.7m Set No.: 25-3/3
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
6	<p>MEDIUM SWITCH BOARDS</p> <p>CONDITION OF ITEM:</p> <p>(5) (10) Electric bulbs missing</p> <p>Inside wiring In bad condition</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 196 ✓ Weight: 214kg ✓ Width: 0.7 m ✓
 Position Code No. _____ Cubage: 0.4 m³ Height: 0.6 m ✓ 02
 Machine Inventory No. : 27-1-62-R2 ✓ Length: 1.0 m ✓ Set No.: _____
 Type of Package: BOX DESTINATION: MANILA

Quantity	Item
2	<p>OIL CIRCUIT BREAKERS</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

OK /

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 197 Weight: 235kg Width: 0.7 m

Position Code No. _____ Cubage: 0.6 m³ Height: 0.7 m

Machine Inventory No. : 27-1-62-R6 Length: 1.3 m Set No.: _____

Type of Package: BOX DESTINATION: MANILA

Quantity	Item
1	STARTER W/instrument

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49

Package No. 199 ✓ Weight: 2,020Kg Width: 1.3 m ✓

Position Code No. _____ Cubage: 1.2 m³ ✓ Height: 0.7 m ✓

Machine Inventory No. : 27-1-2250 ✓ Length: 1.3 m ✓ Set No.: 26-1/6 ✓

Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
----------	------

5
OK
✓

SURFACE PLATE

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

FOREMAN: _____
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 200 ✓ Weight: 2,200Kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 1.2 m³ Height: 0.7 m ✓
 Machine Inventory No. : 27-1-2250 ✓ Length: 1.3 m ✓ Set No.: 26-2/6 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p>5</p> <p>OK ✓</p>	<p>SURFACE PLATE</p> <p>CONDITION OF ITEM:</p> <p>Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 201 ✓ Weight: 1,740Kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 1.2 m³ ✓ Height: 0.7 m ✓
 Machine Inventory No. : 27-1-2250 ✓ Length: 1.3 m ✓ Set No. 26-3/6 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p>4</p> <p><u>OK</u></p>	<p>SURFACE PLATE</p> <p>CONDITION OF ITEM: Satisfactory</p> <p>INSPECTED BY:</p> <p>FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 202 ✓ Weight: 1,625Kg Width: 1.3 m ✓
 Position Code No. _____ Cubage: 1.0 m³ ✓ Height: 0.6 m ✓
 Machine Inventory No. : 27-1-2250 ✓ Length: 1.3 m ✓ Set No.: 26-4/6 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">4</p> <p style="font-size: 2em; margin-left: 10px;">211.</p>	<p style="text-align: center;">SURFACE PLATE</p> <p style="text-align: center; margin-top: 200px;">CONDITION OF ITEM: Satisfactory</p> <p style="text-align: center; margin-top: 20px;">INSPECTED BY:</p> <p style="text-align: center; margin-top: 20px;">FOREMAN: _____ Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49 ✓
 Package No. 204 ✓ Weight: 1,500Kg Width: 1.3 m
 Position Code No. _____ Cubage: 1.0 m³ Height: 0.6 m ✓
 Machine Inventory No. : 27-1-2250 ✓ Length: 1.3 m ✓ Set No.: 26-6/6 ✓
 Type of Package: SKID BASE DESTINATION: MANILA

Quantity	Item
<p style="text-align: center;">4</p> <p style="font-size: 2em; margin-left: 10px;">OK</p>	<p style="text-align: center;">SURFACE PLATE</p> <p style="text-align: center;">CONDITION OF ITEM:</p> <p style="text-align: center;">Satisfactory</p> <p style="text-align: center;">INSPECTED BY:</p> <p style="text-align: center;">FOREMAN: _____</p> <p style="text-align: center;">Name of Packer</p>

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 205 ✓ Weight: 3,420kg Width: 1.3 m ✓
 Position Code No. 27-1 Cubage: 3.7 m³ Height: 1.2 m ✓
 Machine Inventory No. : 2,243 Length: 2.4 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
✓ 10	SURFACE PLATE

OK

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Kawashima Shigeo

FOREMAN:

Siramiya Tetsuo

Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-49
 Package No. 207 ✓ Weight 2,100kg Width: 1.1 m ✓
 Position Code No. 27-1 Cubage: 2.2 m³ ✓ Height: 1.4 m ✓
 Machine Inventory No. : Below Length: 1.4 m ✓ Set No.: _____
 Type of Package: CRATE DESTINATION: MANILA

Quantity	Machine Inventory No.	Item
7	✓ 2,252, 2,253 2,267 ✓	SURFACE PLATE

CONDITION OF ITEM:

Satisfactory

INSPECTED BY:

Kawashima Seigo

FOREMAN:

Shirotsugu Tetsuo

Name of Packer