

AIRCRAFT ACTION REPORT

CONFIDENTIAL
RESTRICTED
(Reclassify when filled out)

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

REPORT No. 97 - 98

XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only).

- (a) Target(s) and Location(s) 3 large buildings in area 7573 (b) Time Over Target(s) 1250 (1) (Zone)
(FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK)
- (c) Clouds Over Target 3200 ft. - cumulus - 9/10ths
(BASE IN FEET, TYPE AND TENTHS OF COVER)
- (d) Visibility of Target Very Hazy (e) Visibility 3 - 5
(CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (MILES)
- (f) Bombing Tactics: Type Glide Bomb Sight Used Mk. 8 gunsight
(LEVEL, GLIDE OR DIVE) (TYPE)
- Bombs Dropped per Run Varied Spacing 30 - 50 Altitude of Bomb Release Slant range 800 - 1200 yds. 1000 - 2000 ft.
(NUMBER) (FEET) (FEET)
- (g) Number of Enemy Aircraft Hit on Ground: Destroyed None Probably Destroyed None Damaged None

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO A/C ATTACKING	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
		(k) SQUADRON			
1 <u>3 buildings in area 7573.</u>	<u>1 - 200 ft. long.</u>	<u>8 TBM-3</u> <u>VC-35</u>	<u>20 - 250 lb. G.P.</u> <u>12 - 100 lb. G.P.</u>	<u>Many</u>	<u>Serious</u>
2	<u>2 - 75 ft. long.</u>		<u>64 - 5"(HB) AR</u> <u>Strafe - 2100 rds.</u>		
3					
4					
5					
6					
7					
8					

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

1. The largest building in the group was most seriously damaged. Part of it was destroyed completely and the rest, hurt bad. The smaller buildings were likewise extensively damaged and some parts of them destroyed completely. The attached photographs taken during the bombing attack show the character of the buildings and the extent of the damage.

(p) Were Photographs Taken? Yes Photographs of Damage, When Taken, Should Be Attached By Staple.

XIII. MATERIAL DATA. (Comment freely on performance or suitability, following check list at left.
Use additional sheets if necessary).

ARMAMENT

Guns, Gunsights
Turrets
Ammunition
Bombs, Torpedoes
Bomb Sights
Bomb Releases

COMMUNICATIONS

Radio, Radar
Homing Devices
Visual Signals
Codes, Ciphers

RECOGNITION

IFF
Signals
Battle Lights
Procedures

PROTECTION

Armor; Points and Angles
of Fire Needing Further
Protection
Leak Proofing

EMERGENCY EQUIPMENT

Parachutes
Life Belts, Life Rafts
Safety Belts
Emergency Kits
Rations, First Aid

NAVIGATIONAL EQUIPMENT

Compasses
Driftsights
Octants
Automatic Pilots
Charts
Field Lighting

INSTRUMENTS

Flight
Power Plant

OXYGEN SYSTEM

**CAMOUFLAGE AND
DECEPTION DEVICES**

STRUCTURE

Airframe
Control Surfaces
Control System
Dive Flaps
Landing Gear
Heating System
Flight Characteristics
At Various Loadings

POWER PLANT

Engines
Engine Accessories
Propellers
Lubricating System
Starters
Exhaust Dampers

HYDRAULIC SYSTEM

ELECTRICAL SYSTEM

Auxiliary Plant
Lights

FUEL SYSTEM

FLIGHT CLOTHING

MAINTENANCE

BASE FACILITIES

Plane Servicing Equipment
Personnel Facilities

REPORT PREPARED BY:

APPROVED BY:

H. VERNON HNEY, Lt., USNR, A.C.I. Officer.

H. S. WOHLBY, Lieut., USNR.

5/7/48

SIGNATURE

RANK AND DUTY

SIGNATURE

RANK AND DUTY

DATE

Squadron Commander.