DECLASSIFIED E.O. 12065 SECTION 3 402, MDS 4.0

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 234 Weight: 2,060 Width: 4.82

Position Code No. Cubage: 32-32-5000 Height: 1.9

Machine Inventory No.: Length: Set No.: 92/2

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Motor (55 HP) for Blower".

CONTENTS OF ITEM:

Cap for Oil Gauge	1	Missing
Oil Well Cap for Bearing	1	Missing
Oil Gauge for Motor	1	Broken

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 233 Weight: 1,480 Width: 1.5

Position Code No. _____ Cubage: 5.4 Height: 1.9

Machine Inventory No.: 32-32-5000 Length: 1.9 Set No.: 9-½

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Blower", " Less Motor".

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: E. Urabami
Chief Custodia

FOREMAN: ASANUMA GUMI CO., LTD.
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 102, NARS NO.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 228 Weight: 50 Width: 0.9

Position Code No.: Cubage: 0.9 Height: 0.8

Machine Inventory No.: 32-32-1403 Length: 1.2 Set No.:

Type of Package: Nailed Wood Box Destination: MANILA

Quantity	Item
1	"Mercury Bulb." "Complete"

Condition of Item: Satisfactory

E, Urakami
Chief Custodian

INSPECTED BY: _____

FOREMAN: M. Komatsu
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINES

Allocation Number: 3-60

Package No.: 224

Weight: 1,500

Width: 1.1

Position Code No.:

Cubage: 2.8

Height: 1.1

Machine Inventory No.: 32-32-1559

Length: 2.3

Set No.:

Type of Package: Sheathed Crate

Destination: MANILA

Quantity	Item
1	"Pump with Motor, Switch Box." "Complete"

Condition of Item:

Oil Covers for Motor: 2 Missing

Side Cover & Screw: 1 Set Missing

Pressure Gauge: 1 Broken

Cooling Piping: 1 Broken

Valve for Cooling Piping: 1 Broken

Pouring Piping for Oil: 1 Broken

E. Urakami
Chief Custodian

INSPECTED BY:

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS No: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 223 Weight: 2,100 Width: 1.2

Position Code No.: _____ Cubage: 6.0 Height: 2.1

Machine Inventory No.: See Below Length: 2.4 Set No.: _____

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
6	"Welders, AC 10 KW." "Complete"
	Condition of Item:
	32-32-4280 Secondary Coil: 1 Set Missing Pilot Lamp: 1 Missing
	32-32-4282 Secondary Coil: 1 Set Missing Switch Handle: Broken Pilot Lamp for Secondary Coil: 1 Missing
	32-32-4283 Secondary Coil: 1 Set Missing Setting Metal for Secondary Coil: 1 Set Missing Pilot Lamp: 1 Missing
	32-32-4287 Secondary Coil: 1 Set Missing Setting Metal for Secondary Coil: 1 Set Missing Pilot Lamp: 1 Missing Switch Handle: Broken
	32-32-4289 Secondary Coil: 1 Set Missing Setting Metals for Secondary Coil: 2 Missing Change Handle: for Secondary Coil: 1 Missing Pilot Lamp: 1 Missing Adjusting Needle: 1 Missing
	32-32-4291 Secondary Coil 1 Set Missing Pilot Lamp 1 Missing

Machine Inventory No.
32-32-4280
32-32-4281
32-32-4283
32-32-4287
32-32-4289
32-32-4291

E, Urakami
Chief Custodian

INSPECTED BY: _____

FOREMAN: M. Kowatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO: [illegible]

PACKING LIST

Recipient Nation: ~~PHILIPPINES~~ Allocation Number: ~~3-60~~

Package No. 222 Weight: 840 Width: 0.9

Position Code No. _____ Cubage: 1.9 Height: 1.2

Machine Inventory No.: ~~32-32(C)-22~~ (2) (3) Length: 1.8 Set No.: _____

32-32(C)-22

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
2	"Transformers, 20 K.V.A.", "Complete". (2), (3).
1	"Transformer, 4 K.V.A.". "Complete". (32-32(C)-22)

CONDITION OF ITEM:

(2), (3)
Satisfactories
32-32(C)-22 "
Setting Bolts & Nuts for Cover 2 Missing

INSPECTED BY: E. Nirakami
Chief Custodian

FOREMAN: [illegible]
Name of Packer
A. Nakagawa

DECLASSIFIED Auth. NARA Date 3-30-77

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 221 Weight: 1,380 Width: 1.3

Position Code No. _____ Cubage: 4.2 Height: 1.9

Machine Inventory No.: 32-32(D)-217 Length: 1.7 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item		
1	"Milling Machine, Vertical, without Motor", "Complete".		
	Condition of Item:		
	Change Gears	6	Missing
	Socket	1	Missing
	Clamp Bolt for Arbor	1	Missing
	Oil Pump & Pipes	1 set	Missing
	Switch	1	Missing
	Cover for Change Gear	1	Missing
	Bolts for Every Kind	4	Missing
	Screw Type Bracket for Feed Table	1	Missing
	Stopper for Feed Apparatus	1	Missing
	Oilers	2	Missing
	Handle for Long Feed Table	1	Broken

~~CONDITION OF ITEM~~:

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd. 3/11
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1), AND 5 (B)(3)

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 220 Weight: 2,180 Width: 1.2

Position Code No. Cubage: 5.4 Height: 1.5

Machine Inventory No.: 32-32-4038 32-32-4040 Length: 3.0 Set No.:

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
2	"Motor Generator Sets, 7.5 K.W.", "Complete".

CONDITION OF ITEM: Satisfactorily

S. Urakami
Chief Custodian

INSPECTED BY: H. Nakagawa

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), AND NSC

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 219 Weight: 660 Width: 1.0

Position Code No. _____ Cubage: 1.7 Height: 1.1

Machine Inventory No.: 32-32-3201 Length: 1.5 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Motor, A.C. 20 K.W."; "Complete".

CONDITION OF ITEM:

Qty	
Pull	1 Missing
Bearing for Rotor Spendle	1 Missing
Fitting Nut for Lead Wire	1 Missing
Cover for Slip Ring	1 Missing
Brush Holder	Bending

INSPECTED BY: E. Nirakami Chief Custo

FOREMAN: Asaruma Gumi Co., Ltd.

Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation PHILIPPINES Allocation Number: 3-60

Package No. 218 Weight: 4,150 Width: 1.2

Position Code No. _____ Cubage: 3.0 Height: 1.2

Machine Inventory No. 32-32-3025 Length: 2.1 Set No.: _____

Type of Package Sheathed Crate DESTINATION MANILA

Quantity	Item
1	"Motor, A.C. 20 K.W.", " Complete"

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

A. Nakagawa

DECLASSIFIED E.O. 11652 SECTION 5 (E), AND/OR

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 217 Weight: 3,070 Width: 2.0

Position Code No. Cubage: 7.5 Height: 1.7

Machine Inventory No.: 32-32-3967 32-32-3969 Length: 2.2 Set No.:

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Motor, A.C. 50 HP"., "Complete". (32-32-3967)
1	"Motor, 35 HP", "Complete". (32-32-3969)
	/A.C.

CONDITION OF ITEM:

32-32-3967 :	Cap for Oil Gauge	1	Missing
32-32-3969 :	Cap of Oil Sump for Metal	1	Missing
	Bolt for Motor Cover	1	Missing

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 11652 SECTION 3 (E), NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 216 Weight: 1,180 Width: 1.4

Position Code No. _____ Cubage: 3.4 Height: 1.6

Machine Inventory No.: 32-32-3265 Length: 1.5 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	" Blower with Motor", " Complete"

CONDITION OF ITEM:

Setting Bolts for Motor:	2	Missing
Setting Taper Pins for Motor:	2	Missing
Setting Bolt for Blower Cover:	1	Missing

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: Asazuma Gumi Co., Ltd.
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1) NND 760050

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 214 Weight: 12,500 Width: 1.8

Position Code No. _____ Cubage: 18.5 Height: 1.8

Machine Inventory No.: 32-32-3769 Length: 5.7 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item		
1	"Lathe, Gap, 10 HP Motor Drive", "Complete".		
	Condition of Item:		
	Cover for V Belt Pulley	1	Missing
	Grip for Clutch Handle	1	Missing
	Oil Cups	3	Missing
	Set Bolts for [illegible] Switch	2	Missing
	Handle of Tool Post Screw	1	Missing
	Handles of Upper and Under Tool Post	2	Missing
	Setting Nut for Carriage	1	Missing
	Oil Pump & Pipes	1 set	Missing
	Head Stock	1	Broken
	Vertical Tool Post	1	Broken
	Bed		Broken
	Switch [illegible] Box	1	Broken
	Chuck	1	Broken
	Friction Clutch	1	Broken

CONDITION OF ITEM:

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 213 Weight: 6,430 Width: 1.8

Position Code No. _____ Cubage: 19.1 Height: 1.8

Machine Inventory No.: 32-32-4119 Length: 5.9 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item		
1	"Lathe, Gap, 10 HP Motor Drive", "Complete".		
	Condition of Item:		
	Change Lever for Head Stock	1 set	Missing
	Set Bolt for V Belting Cover	1	Missing
	Cover for Oil-Instil of Feed Gear Box	1	Missing
	Clutch Handle	1	Missing
	Set Bolt for Feed Rack	1	Missing
	Grip for Reverse Switch	1	Missing
	Upper Tool Post Handle	1	Missing
	Key for Upper Tool Post	1	Missing
	Set Bolt for Feed Rod Cover	1 set	Missing
	Oil Pump & Pipes	1 set	Broken
	Setting Part of Feed Rod	1	Broken
	Handle for Head Stock Change Lever	1	Broken

CONDITION OF ITEM: [illegible]

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: Asanuma Gumi Co., Ltd.

Name of Packer

A. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS No:

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 212 Weight: 3,020 Width: 1.4

Position Code No. 7-4 Cubage: 7.4 Height: 1.7

Machine Inventory No. 32-32(D)-231 Length: 3.1 Set No.:

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Lathe, Gap, without Motor", "Complete".

Rit CONDITION OF ITEM:

Rit Oil Pump	1	set	Missing
Handle for Tail Stock Spindle	1		Missing
Cover for Belting	1		Missing
Change Gear	1	set	Missing
Spindle for Tail Stock	1		Missing Broken
Cover for Tool Post Feeding Apparatus	1		Broken

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: Asano Gumi Co., Ltd.

Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12356 Section 3.4(b)

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 210 Weight: 3,030 Width: 1.3

Position Code No. _____ Cubage: 9.1 Height: 2.6

Machine Inventory No. : ~~32-32x(p)-213~~ Length: 2.7 ~~2.7~~ Set No.: _____

Type of Package: ~~sheathed ora te~~ DESTINATION: MANILA

Quantity	Item
1	"Voltage Regulator of Arc Welder ","Complete".
	Codition of Item:
	Motor 1 Missing

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: ~~Asanuma Gumi Co., Ltd.~~
Name of Packer

H. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO:

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 208 Weight: 1,590 Width: 1.3

Position Code No. _____ Cubage: 6.0 Height: 1.4

Machine Inventory No.: 32-32-5292 Length: 3.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete".

CONDITION OF ITEM:

Glass for Ammeter 1 Broken

INSPECTED BY E, Urakami
Chief Custodian

FOREMAN Sanuma Bumi Co., Ltd.
Name of Packer

H. Nakagawa

3/4

DECLASSIFIED E.O. 12065 SECTION 3 (E), NND 760

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 204 Weight: 2,170 Width: 1.3

Position Code No. _____ Cubage: 4.6 Height: 1.7

Machine Inventory No.: 32-32-1409 32-32-1410 Length: 1.8 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
2	"Motor Generator Set Welder 7.5 KW." "Complete"

CONDITION OF ITEM: Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 203 Weight: 6,800 Width: 1.8

Position Code No. _____ Cubage: 6.5 Height: 2.0

Machine Inventory No.: 32-32-5415 Length: 1.8 Set No.: 6,3/3

Type of Package: Open Type Crate DESTINATION: MANILA

Quantity	Item
1	"Anvil for Forging Hammer"

CONDITION OF ITEM:

Valve for Handle: 1 Missing
Connecting Pins for Valve: 2 Missing

INSPECTED BY E, Urakami
Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 202 Weight: 3,170 Width: 1.4

Position Code No. _____ Cubage: 5.1 Height: 1.3

Machine Inventory No.: 32-32-5415 Length: 2.8 Set No.: 6,2/3

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
	"Cylinder for Forging Hammer"

CONDITION OF ITEM:

Column: 1 Broken

INSPECTED BY: E, Urakami Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1) NND 963

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 201 Weight: 7,260 Width: 2.8

Position Code No. _____ Cubage: 20.2 Height: 2.0

Machine Inventory No.: 32-32-5415 Length: 3.6 Set No.: 6,1/3

Type of Package: Open Type Crate DESTINATION: MANILA

Quantity	Item
1	"Forging Hammer" "Less Cylinder" "Less Anvil"

CONDITION OF ITEM:

Frame for Guide: 1 Broken

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO: 1 1 0 2 2

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 200 Weight: 400 Width: 1.2

Position Code No. _____ Cubage: 3.5 Height: 0.9

Machine Inventory No.: 3-32-1973 Length: 2.6 Set No.: 3, 2/2

Type of Package: Nailed Wood Box DESTINATION: MANILA

Quantity	Item
1	"Separator, Dust for Sand Blast"

CONDITION OF ITEM: Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Konatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b)(1) NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 199 Weight: 430 Width: 1.1

Position Code No. Cubage: 2.6 Height: 3.9

Machine Inventory No. 32-32-1973 Length: 2.6 Set No.: 5, 1/2

Type of Package: Nailed Wood Box Destination: MANILA

Quantity	Item
1	"Cabinet, Sand Blast." "Lean Separator, Dust"

Condition of Item: Satisfactory

E, Urakami

INSPECTED BY: Chief Custodian

FOREMAN: M. Komatsu

Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), MAR NO.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 198 Weight: 460 Width: 0.9

Position Code No. _____ Cubage: 2.6 Height: 1.2

Machine Inventory No.: 32-32-(53) 32-32-(54) Length: 2.4 Set No.: _____

Type of Package: Nailed Wood Box DESTINATION: MANILA

Quantity	Item
1	"Switchboard" "Complete" 32-32-(53)
1	"Condenser" "Complete" 32-32-(54)

CONDITION OF ITEM:

32-32-(53) Resisters: 2 Missing
Cover for Resistor: 1 Broken

32-32-(54) Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS Date: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 194 Weight: 470 Width: 0.7

Position Code No.: Cubage: 1.6 Height: 1.0

32-32-1918

Machine Inventory No.: (14) Length: 2.3 Set No.:

Type of Package: Nailed Wood Box Destination: MANILA

Quantity	Item
1	"Switchboard Panel." "Complete"

Condition of Item:

Ammeter : 1 Broken

Voltmeter : 1 Broken

Pilot Lamps: 1 Set Missing

Lever for Switch 1 Missing

INSPECTED BY: E, Urakami Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 193 Weight: 1650 Width: 1.2

Position Code No. _____ Cubage: 3.4 Height: 1.1

Machine Inventory No. 32-32-5113 Length: 2.6 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Motor, AC 20 HP." "Complete."

CONDITION OF ITEM:
Bolts & nuts for coupling 6 set missing

INSPECTED BY: E. Urakami
C of C Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 192 Weight: 16,140 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No. 32-32-6379 Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

331

DECLASSIFIED E.O. 12065 SECTION 3 (E)(2) NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 191 Weight 15.220 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No. 32-32-6381 Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete"

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), MDR No.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 190 Weight: 14,650 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No.: ~~32-32-6401~~ _____ Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM: Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Aledo
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 189 Weight: 16,400 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No. 32-32-6404 Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 188 Weight: 16,400 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No.: 32-32-6377 Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 187 Weight: 16,080 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No.: 32-32-6378 Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), AND NSC

PACKING LIST

Recipient Nation: ~~PHILIPPINES~~ Allocation Number: ~~3-60~~

Package No. ~~186~~ Weight: ~~15,180~~ Width: ~~2.8~~

Position Code No. _____ Cubage: ~~9.8~~ Height: 0.7

Machine Inventory No.: ~~32-32-6407~~ Length: ~~5.0~~ Set No.: _____

Type of Package: ~~Crate~~ DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:

~~Set-bolts~~ 27 missing

INSPECTED BY: E Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: ~~PHILIPPINES~~ Allocation Number: 3-60

Package No. ~~185~~ Weight: 15,900 Width: 2.8

Position Code No. _____ Cubage: 9.8 Height: 0.7

Machine Inventory No.: ~~32-32-6408~~ Length: 5.0 Set No.: _____

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate" " "Completed"

CONDITION OF ITEM:

Set-bolts & nuts 22 sets missing
Rails for removing 2 sets missing

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 184 Weight: 15,800 Width: 2.8

Position Code No. 9.8 Cubage: Height: 0.7

Machine Inventory No.: 32-32-6409 Length: 5.0 Set No.:

Type of Package: Crate DESTINATION: MANILA

Quantity	Item
1	"Surface Plate." "Complete."

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
Chief Custo

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E) AND NSC MEMO

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: Ex 3-60

Package No.: 183 Weight: 2,300 Width: 1.7

Position Code No.: Cubage: 6.1 Height: 1.8

Machine Inventory No.: 32-32(D)-162 Length: 2.0 Set No.:

Type of Package: Sheathed crate Destination: MANILA

Quantity	Item		
1	"~~Exxxx xxxx xxxxxx~~" Gear Cutting Machine, "complete".		
	Condition of Item:		
	1. Change gear:	1 set	Missing
	2. Counter:	1 set	"
	3. Upper cover:	1	"
	4. Weight & Hanging Wire:	1 set	"
	5. Feed handles:	3	"
	6. Feed ratchet nuts:	2	"
	7. Weight adjusting arm:	1	Bending

E, Urakami
Chief Custodian

INSPECTED BY:

FOREMAN: H. Nakagawa
Asanuma Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), AND/OR

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 182 Weight: 1,860 Width: 1.2

Position Code No.: Cubage: 4.1 Height: 1.5

Machine Inventory No.: 32-32-3448 32-32-3566 Length: 2.3 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item		
1 2	"Motors, A.C. 30 HP", "complete".		
	Condition of Item:		
32-32-3448:	1. Brush holder:	1 set	Missing
	2. Fingers for Short circuit:	2	"
	3. Oil gauge:	1	Broken
32-32-3566:	1. Hanger for Motor:	1	Missing
	2. Cover for outlet of Lead wire:	1	"

E. Urakami
Chief Custodian

INSPECTED BY: 941
H. Nakagawa

FOREMAN: Asahi Kogyo Kaisha, Ltd.
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARA Date 6/24/2011

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 181 Weight: 1,800 Width: 1.7

Position Code No.: Cubage: 7.0 Height: 1.8

Machine Inventory No.: 32-32(D)-192 Length: 2.3 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item		
1	"~~XXXX XXXXXX~~ Milling Machine, without motor", "complete".		
	Condition of Item:		
	1. Counter:	1 set	Missing
	2. Oil cups:	5	"
	3. Cover for Reduction gear:	1	"
	4. Change gear & cover:	1 set	"
	5. Setting bolts for Feed lever bracket:	2	"
	6. Crank handles:	2	"
	7. Oil tank:	1	"
	8. Lubricating:	1 set	"
	9. Fittings for material to be cut:	1	"

E. Urakami
Chief Custodian

INSPECTED BY:

FOREMAN: A. Sangalang Ord. Co., U.S.A.
Name of Packer

G. K. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARA, [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 180 Weight: 2,750 Width: 1.3

Position Code No.: Cubage: 6.9 Height: 1.7

Machine Inventory No.: 32-32(D)-206 Length: 3.1 Set No.:

Type of Package: Sheathed crate Destination: MANILA

Quantity	Item		
1	"Lathe, gap, without motor", "Complete".		
	Condition of Item:		
	1. Oil pump & pipes:	1 set	Missing
	2. Claw for Friction clutch:	1	"
	3. Lever, trip for switch:	1	"
	4. Oil cups:	3	"
	5. Change gear:	1 set	"
	6. Saddle wipers & holders:	3	"
	7. Chip cover:	1	"
	8. Gear cover:	1	"
	9. Belt cover:	1	"
	10. Hinge of Head stock cover:	1	Broken
	11. Claw for Friction clutch:	Partly	"
	12. Cross feed handle:	1	Bending
	13. Bolts for Tool post:	3	Broken

E, Urakami
Chief Custodian

INSPECTED BY: T. Nakagawa

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E)/AMS No. [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 179 Weight: 2,070 Width: 1.3

Position Code No.: Cubage: 5.1 Height: 1.4

Machine Inventory No.: 32-32(D)-200 Length: 2.8 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item		
1	"Lathe, 440 x 700, without motor", "Complete".		
	Condition of Item:		
	1. Oil pump & pipes:	1 set	Missing
	2. Clutch operating device:	1 set	"
	3. Belt cover:	1	"
	4. Gear cover:	1	"
	5. Change gear:	1 set	"
	6. Lever grips:	4	"
	7. Oil cups:	6	"
	8. Shifter shoes for Back gear:	1	"
	9. Oil gauge:	1	"
	10. Crank handles for Tool post:	2	"
	11. Lever for Apron control:	1	"
	12. Nut for Back gear shifter spindle:	1	Bending
	13. Oil pan:	1	"

E. Urakami
Chief Custodian

INSPECTED BY: T. Nakagawa

FOREMAN: Asanuma Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E)(1)(2) NSC MEMO

PACKING LIST

Recipient Nation: PHILIPPINES **Allocation Number:** 3-60

Package No: 178 **Weight:** 2,980 **Width:** 1.5

Position Code No.: **Cubage:** 8.7 **Height:** 1.7

Machine Inventory No.: 32-32(D)-63 **Length:** 3.4 **Set No.:**

Type of Package: Sheathed Crate **Destination:** MANILA

Quantity	Item		
1	"Lathe, without motor", "complete".		
	Condition of Item:		
	1. Change gear:	1 set	Missing
	2. Lever for speed change gear:	3	"
	3. Tumbler handle grip for Feed gear box:	1	"
	4. Operating lever for Feed rod:	1	"
	5. Switch box cover:	1	"
	6. Adjusting bolt for under tool holder gib:	1	"
	7. Levers for Apron Feed:	2	"
	8. Clamp & lever for Tail stock spindle:	1 set	"
	9. Gear Cover:	1	"
	10. Lever grips:	4	Broken
	11. Oil gauge for Head stock	1	Broken
	12. Crank handle for Cross Feed:	1	Broken

E. Urakami
Chief Custodian

INSPECTED BY: _____

FOREMAN: H. Nakagawa
Name of Packer

Isaruma Gumi Co., Ltd.

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 177 Weight: 1,710 Width: 1.1

Position Code No.: Cubage: 4.3 Height: 1.5

Machine Inventory No.: 32-32(D)-264 Length: 2.6 Set No.:

Type of Package: Sheathed crate Destination: MANILA

Quantity	Item		
1	"Lathe, 440 x 500", "Complete".		
	Condition of Item:		
	1. Motor:	1	Missing
	2. Change gear:	1 set	"
	3. Adjusting bolts for Tail stock:	2	"
	4. Cooling device:	1 set	"
	5. Operating lever for Friction clutch:	1	"
	6. Oil pan:	1	Bending
	7. Tool post:	1	Missing

E. Urakami
Chief Custodian

INSPECTED BY: H. Nakagawa

FOREMAN: Kawasaki Dock Co., Ltd.
of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), MDC No. _____

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 176 Weight: 2,020 Width: 1.3

Position Code No. _____ Cubage: 6.2 Height: 1.6

Machine Inventory No.: 32-32(D)-84 Length: 3.0 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Lathe, 250 x 1800 without Motor", "Complete".

Condition of Item:

Cover for Head Stock Gear	1	Missing
Change Gears	1 set	Missing
Pulley & Belt Cover	1	Missing
Oil Cups	7	Missing
Piping for Oil Pump	1 set	Missing
Gear for oil Pump Conduction	1 set	Missing
Handle for Cross Slide	1	Missing
Glass for Oil Gauge	1	Missing
Lever for Longitudinal Feed Control	1	Missing
Grips for Friction Clutch	2	Missing
Hand Wheel for Longitudinal Feed	1	Missing
Bolt for Tail Stock Clamp	1	Missing
Lever for Tail Stock Spindle Clamp	1	Missing
Lever for Clutch Control		Broken
Oil Pan		Damaged

~~CONDITION OF ITEM~~:

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: ASANUMA (Jpn) Co., Ltd.
Name of Packer
A. Nakagawa

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 175 Weight: 910 Width: 1.0

Position Code No.: Cubage: 3.7 Height: 2.3

Machine Inventory No.: 32-32-2085 Length: 1.6 Set No.:

Type of Package: Sheathed crate Destination: MANILA

Quantity	Item
1	"Band saw, wood" without motor", "Complete".
	Condition of Item:
	Satisfactory

E. Urakami
Chief Custodian
INSPECTED BY:

H. Nakagawa

FOREMAN: Asamura Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b)(1) NND 947020 By [illegible] NARS, Date 12-16-98

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 174 Weight: 1,420 Width: 0.8

Position Code No.: Cubage: 5.6 Height: 1.9

Machine Inventory No.: See below Length: 3.7 Set No.:

Type of Package: Sheathed crate Destination: MANILA

Quantity	Item		
1	"Wood working saw with 1 HP motor", "Complete". 32-32(P)-20		
3	"Wood working saws", "Complete". 32-32(P)-21, 32-32(P)-22, 32-32(P)-23		
	Condition of Item:		
32-32(P)-20:	1. Motor base:	1	Missing
	2. Motor sieve:	1	"
	3. Spring & Wire for tighting of Saw teeth:	1 set	"
	4. Belt cover:	1	Broken
32-32(P)-21:	1. Motor:	1	Missing
	2. Motor sieve:	1	"
	3. Wire for tighting of Saw teeth:	1	"
32-32(P)-22:	1. Motor:	1	Missing
	2. Motor sieve	1	"
	3. Wires for tighting of Saw Teeth:	2	"
32-32(P)-23:	1. Motor:	1	Missing
	2. Motor Sieve:	1	"
	3. Wires for tighting of Saw teeth:	2	"
	4. Saw teeth fittings:	1 set	"

Machine Inventory No.
32-32(P)-20
32-32(P)-21
32-32(P)-22
32-32(P)-23

T. Nakami
Chief Custodian

INSPECTED BY: H. Nakagawa

FOREMAN: Asahuma Gumi Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1), AND 5

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 169 Weight: 2,550 Width: 1.5

Position Code No. ~~32-32-1120~~ Cubage: 5.1 Height: 1.8

Machine Inventory No: 32-32-871 Length: 1.9 Set No.: ____

Type of Package: Sheathed Crate DESTINATION MANILA

Quantity	Item
1	"Forging,Bolt" "Complete," 32-32-1120
1	"Speed Reducer,5 HP" "Complete" 32-32-871

CONDITION OF ITEM:

32-32-1120

Belt for motor	1 missing
Set-bolts for dice setting plate	2 missing
Set-pins for dice setting plate	6 missing
Connecting arrangement	3 missing
Roller	4 missing
Motor	1 missing
Pulley	1 missing
Bolts for liner	6 missing

32-32-871

Pulley	1 missing
Bolts for anchor	4 missing
Bolts for flange	6 missing

~~CONDITION OF ITEM:~~

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: M. Ueda
Name of Packer

10

DECLASSIFIED E.O. 12065 SECTION 3-402/NNBS NO: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No. 161 Weight 1,570 Width: 1.3

Position Code No. _____ Cubage: 2.7 Height: 1.5

Machine Inventory No.: 32-32-1918-2 Length: 1.4 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Melting Furnace," "Complete"

CONDITION OF ITEM:

Bumper Cover: 1 Missing

INSPECTED BY: E. Urakami
Chief Cust

FOREMAN: M. Komatsu
Name of Packer

351

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1) NND 760

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 160 Weight: 2,640 Width: 1.3

Position Code No.: Cubage: 8.3 Height: 2.9

Machine Inventory No.: See Below Length: 2.2 Set No.:

Type of Package: Sheathed Crate Destiantion: MANILA

Quantity	Item
1	"Oil Switch." "Complete" 32-32-1780
1	"Blower with Motor." "Complete" 32-32-5386
1	"Transformer, 25KVA." "Complete" (12)
1	"Motor, AC 2HP." "Complete" 32-32-5329

CONDITION OF ITEM:

32-32-1780	Wheel & Lever for Change Switch: each 1 Missing Apparatus for No Voltage Release: 1 Broken Glass for Pilot Lamp: 1 Broken Insulator 2 Broken
32-32-5386	Satisfactory
(12)	Satisfactory
32-32-5329	Satisfactory

Machine Inventory No.:
32-32-1780
32-32-5386
(12)
32-32-5329

E, Urakami
Chief Custodian

INSPECTED BY: _____

FOREMAN: M. Konatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 153 Weight: 3,000 Width: 2.0

Position Code No.: Cubage: 6.2 Height: 1.4

Machinn Inventory No.: 32-32-5489 Length: 2.2 Set No.: 3, 1/3

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
1	" Bending Roll 15 HP " " Less Stand & Roll "

Condition of Item:

Gear Cover: 1 Missing

Legs for stand : 3 Broken

E, Urakami
Chief Custodian

INSPECTED BY: _____

Foreman: M. Komatsu
Name of packer

DECLASSIFIED E.O. 11652 SECTION 5 (E)(2) AND (3)

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No: 148 Weight: 1,170 Width: 1.1

Position Code No: Cubage: 2.4 Height: 1.0

Machine Inventory No.: 32-32-1665 (149) (60) Length: 2.2 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
1	"Motor A.C. 15KW. with Reduction Gear" "Complete" 32-32-1665
1	"Hardness Tester," "Complete" (149)
1	"Vacuum Pump," "Complete" (60)

CONDITION OF ITEM:

32-32-1665	Pins for Coupling:	5	Missing
	Base:		Broken
(149)	Circular Plate:	1	Missing
(60)	Motor:	1	Missing

E. Urakami Chief Custodian

INSPECTED BY: _____

FOREMAN: M. Komatsu

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1)(D) NND 963225

PACKING LIST

Recipient Nation: ~~PHILIPPINES~~ Allocation Number: 3-60

Package No. 147 Weight: 700 Width: 0.8

Position Code No. _____ Cubage: 1.0 Height: 0.8

Machine Inventory No.: See Below Length: 1.6 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item	
1	"Motor, AC 20KW." "Complete"	32-32-1655
1	"Friction Tester" "Complete"	(133)
2	"Oil Switches" "Complete"	32-32-5582 32-32-5583
	CONDITION OF ITEM:	
	32-32-1655 (133) Satisfactory	
	Motor: 1 Missing	
	Connecting Gear Apparatus: 1 set Missing	
	Oil Cup: 1 Missing	
	Setting Bolts for Motor: 4 Missing	
	32-32-5582 Satisfactory	
	32-32-5583 Base Partly 1 Broken	
Machine Inventory No.:	32-32-1655, (133), 32-32-5582 32-32-5583,	
	CONDITION OF ITEM: E. Urakami Chief Custodian	
	INSPECTED BY:	
	FOREMAN: M. Komatsu	
	Name of Packer	

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES **Allocation Number:** 3-60

Package No.: 138 **Weight:** 950 **Width:** 1.3

Position Code No.: _____ **Cubage:** 2.C **Height:** 1.1

Machine Inventory No.: See Below **Length:** 1.4 **Set No.:** _____

Type of Package: Sheadthed Crate **Destination:** MANILA

Quantity	Item
4	" Motor, AC 1/4 ""Complete"(131),(135),(136),(137),
1	" Air Compressor with switch starter and motor"C 32-32-5841

Condition of Item:

(131) Satisfactory
(135) Satisfactory
(136) Setting Pins for Stator Cover: 2 Missing
Terminal Cover: 1 Missing
(137) Satisfactory
32-32-5841 Cooling Pipe: 1 Missing
Belt: 1 Missing
Terminal Cover for Motor: 1 Missing
Cover for Oil Pump: 1 Missing
Pilot Lamp for Magnet Switch: 1 Mis
Pipe for Air Tank: Broken
Safety Apparatus: Broken
Pressure Gauge for Air Tank: Broken

Machine Inventory No: (131),(135),(136),(137),32-32-5841

E. Urakami

INSPECTED BY: Chief Custodian

FOREMAN: M. Komatsu
NAME OF PACKER

DECLASSIFIED E.O. 11652 SECTION 3 (E)(1)(2) NSC MEMO

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 81 Weight: 12000kg Width: 2.4m

Position Code No.: Cubage: 8.6 cub.m Height: 0.7m

Machine Inventory No.: 32-32-6410 Length: 5.1m Set No.:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E. Urakami
INSPECTED BY: Chief Custodian

M. Ueda
FOREMAN: Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E)(2) AND NSC MEMO

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 80 Weight: 15.800 Width: 2.9

Position Code No. _____ Cubage: 10.4 Height: 0.7

Machine Inventory No.: 32-32-6411 Length: 5.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate" " Complete "

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: M, Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NND 968

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 79 Weight: 2,700 Width: 1.8

Position Code No. _____ Cubage: 2.2 Height: 0.4

Machine Inventory No.: 32-32-6413 Length: 3.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate " " Complete "

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: S. Murakami Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1)(D) By [illegible]

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No: 78 Weight: 2700kg Width: 1.7m

Position Code No: Cubage: 2.1 cub.m Height: 0.4m

Machine Inventory No: 32-32-6421 Length: 3.1 Set No:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE," "COMPLETE,"

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: M. Ueda

Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E) AND 5 (D)

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No: 77 Weight: 1800kg Width: 1.3m

Position Code No: _____ Cubage: 1.6 cub.m Height: 0.4m

Machine Inventory No: 32-32-6419 Length: 3.0m Set No: ___

Type of PackagE: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E, Urakami
Chief Custodian

INSPECTED BY: _____

FOREMAN: M Ueda 361

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(2) AND NND 963216

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 76 Weight: 3,800 Width: 1.4

Position Code No. _____ Cubage: 3.4 Height: 0.4

Machine Inventory No. : 32-32-6418 Length: 6.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate " " Complete "

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: M. Ueda

Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), AND NC

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 75 Weight: 2,250 Width: 1.3

Position Code No. _____ Cubage: 2.1 Height: 0.4

Machine Inventory No.: 32-32-6417 Length: 4.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate " " Complete "

CONDITION OF ITEM:

Satisfactory

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: M. Ueda

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402, NARS NO.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 74 Weight: 6,500 Width: 1.8

Position Code No. _____ Cubage: 4.6 Height: 0.5

Machine Inventory No.: 32-32-6370 Length: 5.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate " " Complete "

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urbani
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402, NARS NO.

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No: 73 Weight: 2250kg Width: 1.1m

Position Code NO: Cubage: 1.1 cub.m Height: 0.4m

Machine Inventory No: 32-32-6372 Length: 2.5m Set No:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E, Urakami
INSPECTED BY: Chief Custodian.

FOREMAN: M Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E) MAR 1995

PACKING LIST

Recipient Nation: Philippine Allocation Number: 3-60

Package No. 72 Weight; 1120kg Width; 1.2m

Position Code No: _____ Cubage : 1.0 cub.m Height; 0.4m

Machine Inventory No; 32-32-6374 Length: 2.1m Set No: _____

Type of Package; CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."
	CONDITION OF ITEM:
	Satisfactory

INSPECTED BY: E, Urakami Chief Custodian

FOREMAN: M. Ueda
Name of Foreman

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINE Allocation: Number: 2-60

PACKAGE No: 71 Weight: 2300kg Width: 1.3m

Position Code No: Cubage: 2.7 sub.m Height: 0.5m

Machine Inventory No: 32-72-6406 Length: 4.1m Set No:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE," "COMPLETE,"

CONDITION OF ITEM:

Satisfactory

E, Urakami
INSPECTED BY: Chief Custodian

FOREMAN: M Ueda
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NND 963

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No: 70. Weight: 3000kg Width: 1.5m

Position Code No: _____ Cubage: 5.0 cub.m Height: 0.5m

Machine Inventory No: 32-32-6416 Length: 6.6m Set No: _____

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E, Urakami
INSPECTED BY: Chief Custodian

FORMEN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 5 (E)(2)(B) NO. [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 68 Weight: 1,300 Width: 1.3

Position Code No. _____ Cubage: 1.1 Height: 0.4

Machine Inventory No. : 32-32-6424 Length: 2.2 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate" "Complete"

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
Chief Custodian

FOREMAN: M. Ueda
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), AND NN

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: F-60

Package No: 67 Weight: 6250kg Width: 1.8m

Position Code No: _____ Cubage: 4.7 cub.m Height: 0.8m

Machine Inventory No: 32-32-6415 Length: 5.2m Set No: _____

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:
Satisfactory

E. Urabami
Chief Custodian

INSPECTED BY: _____

M. Ueda
Foreman: _____
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E)(1) AND (2)

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No.: 66 Weight: 62.00kg Width: 1.8m

Position Code No.: Cubage: 4.6 cub.m Height: 0.5m

Machine Inventory No.: 32-32-6425 Length: 5.1m Set No.:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E, Urakami

INSPECTED BY: Chief Custodian

371

FOREMAN: M. Ueda

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E)(1)(D) NND 63

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 65 Weight: 6,500 Width: 1.8

Position Code No. _____ Cubage: 4.6 Height: 0.5

Machine Inventory No. : 32-32-6426 Length: 5.1 Set No.: _____

Type of Package: CRATE DESTINATION: MANILA

Quantity	Item
1	" Surface Plate" " Complete "

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: M, Ueda
Name of Packer

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No.: 64 Weight: 1500kg Width: 1.3m

Position Code No.: Cubage: 1.6 cub. m Height: 0.4m

Machine Inventory No.: 32-32-6422 Length: 3.1 m Set No.:

Type of Package: CRATE Destination: MANILA

Quantity	Item
1.	"SURFACE PLATE." "COMPLETE."

CONDITION OF ITEM:

Satisfactory

E. Urakami

INSPECTED BY: Chief Custodian

M. Ueda

FOREMAN:

Name of Packer

DECLASSIFIED E.O. 11652 SECTION 5 (B), AND 7

PACKING LIST

Recipient Nation: PHILIPPINE Allocation Number: 3-60

Package No. 63 Weight: 860 Width: 1.2

Position Code No. _____ Cubage: 3.3 Height: 1.2

Machine Inventory No. 32-32-1823 Length: 2.3 Set No: 3/3

Type of Package: Open Type Crate DESTINATION MANILA

Quantity	Item
1	"Air Resevoir, for Compressor, Complete,"

CONDITION OF ITEM:

Safety Valve for Air Resevoir: 1 set Missing

INSPECTED BY: E, Urakami
Chief Custodian

FOREMAN: M Komatsu
Name of Packer

AY 3-60

HEADQUARTERS
OSAKA CIVIL AFFAIRS TEAM
APO 25

RAS/lmp

11 October 1949

SUBJECT: Damage to Allocated Equipment

TO: General Headquarters
Supreme Commander for the Allied Powers
APO 500
ATTN: Civil Property Custodian

1. Attention invited to the inclosed communication from the Osaka Finance Office reporting loss of the shaft and pumping unit of a deep well pump, inventory number 32-32-3223, and damage to a switchboard, inventory number 32-32-5293, incurred in the course of dismantling and crating operations. Both items were allocated to the Phillipines by Allocation Notice 3-60 (pp 12 and 13, resp).

2. The shaft and pumping unit dropped to the bottom of the well in which the pump was installed while the contractor was attempting to remove it. The top of the shaft is 210 ft. below ground level. Repeated attempts to retrieve the shaft have been unsuccessful. The shaft can be retrieved, but the cost will be prohibitive and will be several times the value of the pump. The pump driving motor is intact and available. This headquarters has instructed the Osaka Finance Office to abandon efforts to retrieve the shaft pending further instructions.

3. The switchboard was damaged when the box in which it was crated dropped from a crane in the course of transposition. The marble switchboard plate was cracked in several places. It is beyond economical repair and is considered as scrap.

4. It is concluded from investigation that:

a. Dropping of the deep well pump shaft could have been avoided if the contractor had exercised better judgement in calculating risks involved in removing the shaft from the well, but is not attributed to actual negligence by the contractor.

b. The crate containing the switchboard was dropped due to a defective crane cable. The accident was beyond the control of the individuals moving the crate.

OSAKA M.G.
RES-COM-IND
FILE 1-5763

DECLASSIFIED E.O. 12065 Section 3 (E), NARS Date 7/24/78

Hq Osaka Civ Affrs Team, APO 25 — 11 October 1949
Subj: Damage to Allocated Equipment

5. Request this headquarters be informed as to disposition of above cited items, or further action desired.

FOR THE CHIEF:

2 Incls:
Reports of accidents
as above

FRED N. ALEXANDER
WOJG USA
Asst Adjutant

DECLASSIFIED E.O. 12065 SECTION 3 (b)(1) NND [illegible]

COPY

KINKI LIAISON & COORDINATION OFFICE T3/ts

Prefectural Building
OSAKA

KKLCO No. 869 ER 11 October 1949

TO : Chief,
Osaka Civil Affairs Team

SUBJECT: Report on Accidents During Packaging Operation,
Osaka Arsenal (32-32)

For your information.

S. Shima
Director

Incl: Letter from Osaka Finance Division
OFO No. 56 dated 29 September 1949.

OSAKA FINANCE OFFICE
(Osaka)

29 September 1949.

OFO No. 56

TO : Economics Division,
Osaka Civil Affairs Team

THROUGH: Kinki Liaison Office.

SUBJECT: Report on Accidents During Packaging Operation.

This Office hereby humbly submits to your headquarters the attached report on the accidents happened in regard to the items under the contract of Asanuma Gumi, Ltd. during the packaging operation.

FOR THE CHIEF

Incls: Report

for Y. Toyoda
Vice Chief

KK/ym/mk

KKLCO
Received: 5:00 AM PM
11/1/'49

Attached No. 1

Report on accidents Happened
During Packaging Operation

1. Recipient Nation and Allocation Notice Number:

   Philippines 3 - 60

2. Name of Contractor: Asamura Gumi, Ltd.

3. Schedule of Operation:

   From August 12 thru September 20.

4. Regarding to the Shaft for Deep-well Pump (See attached sketch No.1)

   (1) Inventory Number: 32 - 32 - 3223

   (2) Date Accidents Occurred: September 2.

   (3) Details of Accident:

The operation was started with the taking off of the pump at first, then tried to pull up the shaft but failed because the connecting coupling was fastened with rust. Therefore anchor bolt and coupling were taken away. At this moment the wire (3/4") fastened to prevent the shaft's falling into the well snapped and the shaft was fell into the 300-feet deep-well. The length of the shaft is approximately 90 feet.

DECLASSIFIED E.O. 11652 SECTION 5 (b), NARS Date

Attached No. 2

Switch Board

(1) Inventory Number: 32 - 32 - 5293

(2) Date Accidents Happened: September 25.

(3) Details of Accident:

This item was completely packaged and approved by the Philippines' representative and Mr. Welch on September 24. At the time of transportation with a ten-ton crane from the packaging spot to storage yard the wire rope (dia. 20 mm) was cut off and the package fell down to the ground from two meters above. Inspection of the package dropped revealed that the marble plate of the switch board was damaged at several points. This accident was immediately reported to Mr. Welch, field inspector.

This package is sheathed crate of 1610 kg. of weight. Packaging number is 209.

Just before the accident was happened the wire of the crane was in good condition and pulled up and transported a package of more than 6 tons.

DECLASSIFIED E.O. 11652 DEPT. OF STATE, STATE LETTER NO.

In regard to the above accidents this office instructed as follows.

1. In relation to the shaft for deep-well pump pulling up or compensation with substitute.

2. Pertaining to the switch board compensation with substitute.

DECLASSIFIED E.O. 12065 SECTION 3 (b), NND

File
Allocation Notice
3-60

HCK/ras/hck

HEADQUARTERS
OSAKA CIVIL AFFAIRS TEAM
APO 25

4 October 1949

SUBJECT: Transmittal of Progress Reports

TO: General Headquarters
Supreme Commander for the Allied Powers
APO 500
ATTN: Civil Property Custodian

1. Herewith transmitted are reports of progress, for the period 16 September thru 22 September, in the packaging and crating of Allocation Notices 1-68, 1-69, 2-60, 3-60, 3-61, 4-63 and 4-65, at the Osaka Arsenal 32-32.

2. The reports, prepared by the Osaka Finance Office, have been reviewed by this headquarters and found to be accurately reflective of the status of operations.

3. Packing lists for the 346 packages cited in the progress reports as having been completed in the reported period were previously transmitted to your headquarters as follows:

a. Packing lists for the 144 packages cited in the report for AN 1-68 (Incl No. 1), were forwarded under cover of letter, this headquarters, subject: "Transmittal of Packing Lists", 22 September 1949. Package numbers as follows: 17, 18, 19, 28, 30, 34, 38, 40, 41, 45, 47, 49, 54, 62, 70, 74, 77, 81, 83, 87, 89, 92 thru 144, 146 thru 157, 171 thru 203, 208 thru 216, 222, 223 and 224.

b. Packing lists for the 10 packages cited in the report for AN 2-60 (Incl No. 3), were delivered to the hand of Mr. John Laffin, CPC/Rep, on 17 September 1949. Package numbers as follows: 2 thru 6 and 11 thru 15.

c. Packing lists for the 84 packages cited in the report for AN 2-61 (Incl No. 4); for the 75 packages cited in the report for AN 3-60 (Incl No. 5); and for the 75 packages cited in the report for AN 4-63 (Incl No. 7), were forwarded under cover of letter, this headquarters, subject: "Transmittal of Packing Lists", 26 September 1949. Pertinent package numbers are as follows:

(1) AN 2-61: 1 thru 3, 6, 7, 15, 18, 19, 21, 28 thru 31, 34, 37 thru 54 and 56 thru 107.

(2) AN 3-60: 61, 62, 107 thru 137, 139 thru 146,

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDS NO: [illegible]

Hq Osaka Civil Affairs Team, APO 25 4 Oct 49
Subj: Transmittal of Progress Reports

149 thru 152, 154 thru 159, 162 thru 168, 170 thru 173, 195, 196, 197, 205, 206, 207, 225, 226, 227 and 229 thru 232.

(3) AN 4-63: 32, 47, 49, 53, 83 thru 91, 114 thru 119, 121, 124, 125, 129, 130, 131 and 177 thru 181.

FOR THE CHIEF:

FRED N. ALEXANDER
WOJG USA
Asst Adjutant

8 Incls:
As above (ea dup)

DECLASSIFIED E.O. 11652 SECTION 3 (E)(1) NND 760033

PROGRESS REPORT OF INTEGRATED FACILITIES

No. 3
Progress Report
Period ending 22 Sept

1. Report No: 3
2. Allocation No: 3 - 60
3. Period Ending: 22 Sept 49
4. Code symbol of plants being reported on: 32 - 32
5. Dismantling, Disassembly, and Packing:
   a. Allocation Notice completion date:
   b. Present estimates completion date: 20 Sept 49
   c. Work completed during report period:
      (1) Dismantling and disassembly: 2.3 %
      (2) Packing: 5 %
   d. Work completed to date:
      (1) Dismantling and disassembly: 56 %
      (2) Packing: 5.38 %

	Number	Gross Weight (metric tons)	Gross Volume (meas. tons)
e. Packages completed during report period:	75	151.917	312.76
f. Packages completed to date:	141	294.3845	636.63

6. Remarks: (1) Completion date for Plane and surface plate is 28 Feb 49
   (2) Packaging operation completed on all items other than the above. About 600 items being readied for inspection.
7. Signature E. Urakami
8. Title Chief Custodian
9. Reviewed by
10. Signature
11. Title

Pkg list already transmitted to SCAP

DECLASSIFIED E.O. 12065 SECTION 3 402/NARS No.: _____

----REPORT----

AN 3-60

Asanuma Gumi Co., Ltd.
13, Ishigatsuji-cho,
Tennoji-ku, Osaka.
28th Sept. 1949

To: Chief of the Reparation Section
Department of Finance
Osaka

Allocation No.: 3-60
Package No.: 209
Machine Inventory No.: 32-32-5293
Name of Machine: Transformer
Date of Inspected passed: 25th Sept. 1949

Weight: 1,610 KG
Size of Broken wire: 19 mm Dia.
Fact

While piling the crate that has been passed the inspecting we pulled up the above crate with the 10 Ton crane the wire has been broken and dropped the crate from 15 Ft. above the ground and damaged to the above item. We imediately contacted to the Japanese Government Inspector andewhen Mr. Welch, the Scap Inspector came, He told us to leave it alone until words from him.

We have loaded 8 Ton crate just before that and many crate during that day.

Signature: H. Nakazawa
Title : Supervisor
Organization: Asanuma Gumi Co., Ltd.
Date : 28th Sept, 1949

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS

---REPORT---

Asanuma Gumi Co., Ltd.
13, Ishigatsuji-cho,
Tennoji-ku, Osaka
9th Sept. 1949

To: Chief of the Reparation Section
Financial Department
Osaka

1. Machine Inventory No: 32-32-3223
2. Name of Item: Deep Well Pump Shaft
3. Date of Work Start: 30th Aug. 1949
4. Date of Shaft Dropped: 2nd Sept. 1949
5. Condition of the Work at that time:

We tied the wire from the beam to the center of the pump and hang the shaft to the both corner of the building. We have prepared to take the pump first and secondly the shaft liked removing the parts of the roof and above , but the coupling that connected the pump and shafthas been rusted and was unable the turn, so We loosen the anchor bolts and finally made it to turn. We slowly took the coupling off, the whole weight of the shaft went to the wire and suddenly the wire had broken at the both sides and the shaft dropped.
As We think that the expert has had difficulties in calculating the weight of the shaft and the pressure of the water inside. The Well exactly so by tooking at the weight from the list as 1 Ton which was given by the Reparation Office. We used the wire(Dia. 3/4") calculating 3, 4 times from the Government estimated weight.

6. Preparation of Pulling up Job:

Soon as the shaft dropped we removed the pump and the expert has calculated the deepness and the shaft of the end of the shaft, we found the following :

Deepness of the well: 308 ft.
Distanceto the shaft: 210 Ft.
Shape:

We have prepared the tools and machine.

7. Condition of Pulling up Job:

We have from 3rd Sept. to 8th Sept. to catch the end tried by the machine , but was in vain.
Again we called 3 expert from Nippon Underground Water Association and let them inspected the well butthey said it difficult job and they could not take that job, because it is 95 % useless job.

Signature: H. Nakagawa
Title : Supervisor
Organization: Asanuma Gumi Co., Ltd.
Date : 9th Sept. 1949

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

Section Detailed:



DECLASSIFIED E.O. 12065 SECTION 3 402, MDS MR

Attached packing list pertain to a sweetheart which was dropped & damaged on 24 Sept 49. Mr. Mendozona, Philippines engineer does not want the item shipped.

Japs will submit a report of damage, & be forwarded thru channels.

S.

DECLASSIFIED E.O. 12065 SECTION 3 402, MDS No. [illegible]

file
alloc not
3-60

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 209 Weight: 1,610 Width: 1.2

Position Code No. _____ Cubage: 5.5 Height: 1.4

Machine Inventory No.: 32-32-5293 Length: 3.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete"

Deleted

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami
H. Nakagawa
Asst. Chief Custodian

FOREMAN: [illegible] Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS NO.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 360

Package No. 209 Weight: 1,610 Width: 1.2

Position Code No. _____ Cubage: 5.5 Height: 1.4

Machine Inventory No.: 32-32-5293 Length: 5.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "[illegible]".

CONDITION OF ITEM: Satisfactory

INSPECTED BY: E. Urakami Chief Custodian
H. Nakagawa

FOREMAN: [illegible] Co., Ltd.
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: ~~3-60~~

Package No. 209 Weight: 1,610 Width: 1.2

Position Code No. _____ Cubage: 5.5 Height: 1.4

Machine Inventory No.: 32-32-5293 Length: 3.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete".

CONDITION OF ITEM:
Satisfactory E. Uriakami Chief Custodian

INSPECTED BY: H. Nakagawa

FOREMAN: ~~Asanuma Gumi Co., Ltd.~~
Name of Packer

DECLASSIFIED E.O. 11652 SECTION 3 (E), NARS Date 7/1/97

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 209 Weight: 1,610 Width: 1.2

Position Code No. _____ Cubage: 5.5 Height: 1.4

Machine Inventory No.: 32-32-5293 Length: 3.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete".

CONDITION OF ITEM:
Satisfactory

INSPECTED BY: E. Urakami Chief Custodian
for Nakagawa

FOREMAN: ~~Yamuna Gumi Co., Ltd.~~
Name of Packer

DECLASSIFIED E.O. 12065 SEC. 3.5, NSC MEMO 11/2/98, STATE DEPT. GUIDELINES

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 209 Weight: 1,610 Width: 1.2

Position Code No. _____ Cubage: 5.5 Height: 1.4

Machine Inventory No.: 32-32-5293 Length: 3.3 Set No.: _____

Type of Package: Sheathed Crate DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete".

CONDITION OF ITEM:
Satisfactory E. Urakami
Chief Custodian

INSPECTED BY:

FOREMAN: ~~Asano Kisen Co., Ltd.~~ Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS, DATE 7/

PACKING LIST

Recipient Nation: ~~PHILIPPINES~~ Allocation Number: ~~3-60~~

Package No. ~~209~~ Weight: ~~1,610~~ Width: ~~1.2~~

Position Code No. _____ Cubage: ~~5.5~~ Height: ~~1.4~~

Machine Inventory No.: ~~32-32-5293~~ Length: ~~3.3~~ Set No.: _____

Type of Package: ~~Sheathed Crate~~ DESTINATION: MANILA

Quantity	Item
1	"Switch Board", "Complete".

CONDITION OF ITEM:

~~Satisfactory~~ E. Urakami Chief Custodian

INSPECTED BY: H. Nakagawa

FOREMAN:

~~Aeronautical Supply Co., Ltd.~~
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

Progress report for the
period ending 22 Sept

75 pkg

1943

DECLASSIFIED E.O. 11652 SECTION 3 (E), MAR 10

Alloc. Not.
3-60

HEADQUARTERS
OSAKA CIVIL AFFAIRS TEAM
APO 25

HCK/ras/lmp

25 September 1949

SUBJECT: Transmittal of Packing Lists - Allocation Notices 1-68, 3-60 and 4-63

TO: General Headquarters, Supreme Commander for the Allied Powers
APO 500
ATTN: Civil Property Custodian

1. Herewith transmitted are packing lists regarding equipment crated in compliance with Allocation Notices 1-68, 3-60 and 4-63 at the Osaka Arsenal, Plant 32-32.

2. The packing lists, prepared by the Osaka Finance Division, have been reviewed by this headquarters and found to be correct.

3. Forwarded in compliance with 8j(2), Operational Directive 21 for 1948.

FOR THE CHIEF:

FRED N. ALEXANDER
WOJG USA
Asst Adjutant

3 Incls:
Packing lists - Allocation Notices 1-68,3-60 & 4-63 (ea trip)

OSAKA M.G
RES-COM-IND
FILE 0-263

DECLASSIFIED E.O. 11652 SECTION 3 (E) AND NND 63

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 61 Weight: 1,737 Width: 1.3

Position Code No.: Cubage: 3.7 Height: 1.9

Machine Inventory No.: 32-32-1823 Length: 1.5 Set No.: 1/3

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
1	" Air Compressor," " Complete "

Condition of Item:

Vee-Belt (D type) 4 Missing

INSPECTED BY: E. Uzkami Chief Custodian

FOREMAN: M. Komatsu Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 62 Weight: 420 Width: 1.1

Position Code No.: Cubage: 2.4 Height: 1.3

Machine Inventory No.: 32-32-1823 Length: 1.7 Set No.: 1, 2/3

Type of Package.: Sheathed Crate Destination: MANILA

Quantity	Item
1	" Motor, for Air Compressor" "Complete"

Condition of Item:

Satisfactory

INSPECTED BY: E, Urakami Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 132 Weight: 600 Width: 1.3

Position Code No.: Cubage: 1.7 Height: 0.8

Machine Inventory No.: See Below Length: 1.6 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
4	"Blowers, with Motor 2 1/2 HP." "Complete" Condition of Item: Satisfactory.

Machine Inventory Nos.

Machine Inventory No.

32-32-5836 (18-27)
32-32-5837 (18-28)
32-32-5838 (18-29)
32-32-5839 (18-30)

INSPECTED BY : E. Urakami Chief Custodian

FOREMAN: M. Komatsu
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3-402/NNDS NO: [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-00

Package No.: 133 Weight: 1,800 Width: 1.5

Position Code No.: Cubage: 3.8 Height: 1.6

Machine Inventory No.: 32-32-1555 Length: 1.6 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
1	" Motor,AC 25HP with 2 starters""Complete "

Condition of Item:

Setting Bolt for Cover: 1 Missing
Motor Base Partly: Broken
Pulley: 1 Missing
Driving Gear: Broken

INSPECTED BY: E. Urakami Chief Custodian

FOREMAN: M. Komatsu Name of Packer

DECLASSIFIED E.O. 11652 SECTION 5 (E)(2) NARS Date [illegible]

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 134 Weight 1,300 Width: 1.2

Position Code No.: Cubage: 3.2 Height: 1.4

Machine Inventory No. 32-32-5572 32-32-1860 Length: 1.9 Set No.

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
1	"Motor AC, 7.5 HP.," "Complete" (32-32-5572)
1	"Turbine Pump," "Complete" (32-32-1860)

Condition of Item:

32-32-5572 Satisfactory

32-32-1860 Motor: Missing

Pressure Gauges: 2 Missing

Coupling Pins: 8 Missing

E. Nakatani

INSPECTED BY Chief Custodian

M. Komatsu

FOREMAN
Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (b), NARS Date

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number 3-60

Package No. 135 Weight: 1,130 Width: 1.0

Position Code No.: Cubage: 1.9 Height: 1.2

Machine Inventory No.: 32-32-1427 Length: 1.6 Set No.:

Type of Package Sheathed Crate Distination: MANILA

Quantity	Item
1	"Motor, AC, 25 HP." "Complete"
	Condition of Item:
	Cover Handles: 2 Missing
	Brake wheel: Broken

INSPECTED BY: E. Urakami Chief Custodian

Foreman: M. Konatsu

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 (E), NARS DATE

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No. 136 Weight 1,000 Width: 1.1

Position Code No. Cubage: 1.3 Height: 0.9

Machine Inventory No. 32-32-1847 32-32-1848 Length: 1.3 Set No.

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item
2	"Motors, AC. 5 H.P." "Complete"

Condition of Item:

32-32-1847 Satisfactory

32-32-1848 Terminal Cover : 1 Missing

1 Bolt : 1 Missing

E. Urakami

INSPECTED BY : Chief Custodian

FOREMAN: M. Komatsu

Name of Packer

DECLASSIFIED E.O. 12065 SECTION 3 102, NARS NO.

PACKING LIST

Recipient Nation: PHILIPPINES Allocation Number: 3-60

Package No.: 137 Weight 1600 Width: 1.5

Position Code No. Cubage: 3.2 Height 1.5

Machine Inventory No. 32-32-5570, (147) Length: 1.4 Set No.:

Type of Package: Sheathed Crate Destination: MANILA

Quantity	Item		
1	"Motor, AC. 50 HP."	"Complete"	32-32-5570
1	"Optical Pyrometer"	"Complete"	(147)

Condition of Item:

32-32-5570 Slide Bolts: 2 Missing
Slide Adjusting Bolt: 1 Broken

(147) Lense: 1 Missing

INSPECTED BY: E, Urakami Chief Custodian

FOREMAN: M. Konishi
Name of Paker