





# AIRCRAFT ACTION REPORT

**Confidential**  
**RESTRICTED**  
(Reclassify when filled out)

(OMIT THIS SHEET IF NO ATTACK WAS MADE)

REPORT No. VC-84 #96

## XI. ATTACK ON ENEMY SHIPS OR GROUND OBJECTIVES (By Own Aircraft Listed in II Only).

- (a) Target(s) and Location(s) #See below (b) Time Over Target(s) 1000 I (Zone)  
(FOR SHIPS INCLUDE ALL IN AREA UNDER ATTACK)
- (c) Clouds Over Target 3500, strato cumulus, .9  
(BASE IN FEET, TYPE AND TENTHS OF COVER)
- (d) Visibility of Target Clear below ceiling obscured above (e) Visibility 15  
(CLEAR, HAZY, PARTIALLY OBSCURED BY CLOUDS, ETC.) (MILES)
- (f) Bombing Tactics: Type \_\_\_\_\_ Bomb Sight Used \_\_\_\_\_  
(LEVEL, GLIDE OR DIVE) (TYPE)
- ~~Bombs Dropped~~ Rockets per Run All Spacing \_\_\_\_\_ Altitude of Bomb Release \_\_\_\_\_  
(NUMBER) (FEET) (FEET)
- Slant range 1700 feet
- (g) Number of Enemy Aircraft Hit on Ground: Destroyed 0 Probably Destroyed 0 Damaged 0

(h) AIMING POINT	(i) DIMENSIONS OR TONNAGE	(j) NO. A/C ATTACKING	(l) BOMBS AND AMMUNITION EXPENDED, EACH AIMING POINT	(m) NO. HITS On Aiming Point	(n) DAMAGE (None, slight, serious, destroyed or sunk)
		(k) SQUADRON			
1 Target No. 1	200 x 400 yards	4 FM-2 VC-84	24 Rockets lik 1 body; lik 7 motor.	18	Unknown
2 Target No. 2	200 x 400 yards	2 FM-2 VC-84	8 Rockets as above	6	Unknown
3					
4					
5					
6					
7					
8					

(o) RESULTS: (For all hits claimed on ship targets and for land targets of special interest, draw diagram, top or side view or both, as appropriate, showing type and location of hits. For all targets give location and effect of hits, and identify by numbers above. Use additional sheets if necessary).

Specific results of the attacks could not be observed although rocket hits were made in the positions as indicated above. The targets were also strafed.

- # 1- Reported coast defense gun positions, outskirts of Naha, southeast of town, Okinawa Jima, 7570 Charlie Dog on local grid.
- 2- Revetted AA positions 200 yards east of R-S strip Naha Airfield, Okinawa Jima, 7169 Mike Roger on local grid.

(p) Were Photographs Taken? Yes Photographs of Damage, When Taken, Should Be Attached By Staple.  
Gun camera film showed no results.



# AIRCRAFT ACTION REPORT

~~Confidential~~  
RESTRICTED  
(Reclassify when filled out)

REPORT No. VC-84 #08

**XIII. MATERIAL DATA.** (Comment freely on performance or suitability, following check list at left. Use additional sheets if necessary).

**ARMAMENT**

- Guns, Gunsights
- Turrets
- Ammunition
- Bombs, Torpedoes
- Bomb Sights
- Bomb Releases

**COMMUNICATIONS**

- Radio, Radar
- Homing Devices
- Visual Signals
- Codes, Ciphers

**RECOGNITION**

- IFF
- Signals
- Battle Lights
- Procedures

**PROTECTION**

- Armor; Points and Angles of Fire Needing Further Protection
- Leak Proofing

**EMERGENCY EQUIPMENT**

- Parachutes
- Life Belts, Life Rafts
- Safety Belts
- Emergency Kits
- Rations, First Aid

**NAVIGATIONAL EQUIPMENT**

- Compasses
- Driftsights
- Octants
- Automatic Pilots
- Charts
- Field Lighting

**INSTRUMENTS**

- Flight
- Power Plant

**OXYGEN SYSTEM**

**CAMOUFLAGE AND DECEPTION DEVICES**

**STRUCTURE**

- Airframe
- Control Surfaces
- Control System
- Dive Flaps
- Landing Gear
- Heating System
- Flight Characteristics At Various Loadings

**POWER PLANT**

- Engines
- Engine Accessories
- Propellers
- Lubricating System
- Starters
- Exhaust Dampers

**HYDRAULIC SYSTEM**

**ELECTRICAL SYSTEM**

- Auxiliary Plant
- Lights

**FUEL SYSTEM**

**FLIGHT CLOTHING**

**MAINTENANCE**

**BASE FACILITIES**

- Plane Servicing Equipment
- Personnel Facilities

Communications difficulties were encountered but appeared due to crowded channels rather than radio failure. Equipment performance was normal.

REPORT PREPARED BY:

Robert C. FULFON, Jr., Lt., USNR

SIGNATURE Acting Officer, VC-84

RANK AND DUTY

APPROVED BY:

Douglas K. HENLISH, Lt., (A1), USNR

SIGNATURE Acting Commanding Officer, VC-84

RANK AND DUTY

4-6-65

DATE