

GHQ/SCAP Records (RG 331, National Archives and Records Service)

Description of contents

- (1) Box no. **2901**
- (2) Folder title/number: **(9)**
Reparation Selections
- (3) Date: **Sept. 1946 - July 1947**

(4) Subject:

Classification	Type of record
9230	e, 1, k

(5) Item description and comment:

Kyoto

(6) Reproduction: Yes No

(7) Film no. _____ Sheet no. _____

(Compiled by *National Diet Library*)

PLANT COVER SHEET:

(Notice: dates are when inventory was completed) (forwarded)
 not when forwarded

deleted
East Section Deleted

1. YOSHICHI KOGYO K.K. (22) (5 Sept. 46) ----- 4/4/46
- ~~2. HANEGAWA BOSEKI K.K., KYOTO KOJO (4) (17 Sept. 46) --- 17/9/46~~
3. NIKKOKU KOGYO K.K., KAMIRYO SEISAKUSHO (12) (23 Sept. 46) 25/9/46
4. " " " " KYOTO SEISAKUSHO (13) (26 Sept. 46) --- 28/9/46
5. SHIMAZU SEISAKUSHO K.K. SANJO WORKS (18) (30 Sept. 46) --- 30/9/46
6. " " " " SHIJO WORKS (19) (1 Oct. 46) --- 1/10/46
7. NIKKOKU KOGYO K.K., KAMIGYO SEISAKUSHO (12) (4 Oct. 46) --- 3/10/46
8. SHIMAZU SEISAKUSHO K.K., JUGO WORKS (17) (2 Oct. 46) --- 3/10/46
9. KURE NAVAL ARSENAL (TERAUCHI SEISAKUSHO) (47,c) (2 Oct. 46) -- 4/10/46
10. " " " " (47,b) (2 Oct. 46) --- 5/10/46
11. MITSUBISHI JUKOGYO K.K., KYOTO KIKI SEISAKUSHO,
 KATSURA KOJO (9) (8 Oct. 46) ----- 10/10/46
12. MITSUBISHI JUKOGYO K.K., KYOTO KIKI SEISAKUSHO,
 UZUMASA PLANT (10) (7 Oct. 46) ----- 10/10/46
13. OSAKA SEISAZOKI K.K., KAMECKA KOJO (16) (9 Oct. 46) --- 10/10/46
14. NAKAJIMA AIRCRAFT CO. (FUJI INDUSTRIAL CO.) KOIZUMI PLANT (9,A) (8 Oct. 46) --- 10/10/46
15. UJI POWDER FACTORY (23) (9 Oct. 46) ----- 10/10/46
16. KAWANISHI KONUKI K.K., FUKUCHIYAMA (CONCEALED) KOJO (5) (11 Oct. 46) 12/10/46
17. NIPPO SEIRO K.K., 1ST PLANT (14) (1 Oct. 46) --- 14/10/46
18. " " " " 2ND PLANT (15) (1 Oct. 46) --- 14/10/46
19. MAIZURU NAVAL YARD (PORT CONTROL: MACHINERY DEPT.) (29) (15 Oct. 46) 17/10/46
20. SHIMAZU SEISAKUSHO, TAKANO KOJO (31,E) (16 Oct. 46) --- 17/10/46
21. SHIMAZU SEISAKUSHO, TAKANO KOJO (31) (16 Oct. 46) --- 18/10/46
22. HASHIDATE SHIPBUILDING CO. (26, 0) (10 Oct. 46) --- 19/10/46
23. 3RD POWER PLANT (25) (11 Oct. 46) --- 19/10/46
24. SHIMAZU SEISAKUSHO, GOJO PLANT (41) (21 Oct. 46) --- 21/10/46
25. NIKKOKU KOGYO K.K., SONOBE SEISAKUSHO (32) (21 Oct. 46) --- 22/10/46
26. HELAN SANGYO K.K., KITANO PLANT (34) (23 Oct. 46) --- 23/10/46
27. KAWASAKI AIRCRAFT COMPANY, TARATSUKI PLANT (48) (30 Oct. 46) --- 1/11/46
- ~~28. KYOTO SEIKI KIKAI K.K. (KYOTO MACHINERY CO., Ltd.) (28) (1 Oct. 46)~~
29. YAMASHINA SEIROSHO, HIGASHINO FACTORY (42) (1 Nov. 46) 9/11/46 4/11/46
30. KOTOBURI KOGYO K.K., KYOTO JUJO FACTORY (36) (6 Nov. 46) --- 7/11/46
31. YAMASHINA SEIROSHO, HINOOKA FACTORY (43) (1 Nov. 46) --- 7/11/46
32. KOTOBURI KOGYO K.K., KYOTO MAIN FACTORY (37) (7 Nov. 46) --- 8/11/46
- ~~33. MAIZURU NAVAL YARD SANGYO KAISHA LTD. (24) (2 Aug. 46)~~
34. THIRTY FIRST NAVAL AIR DEPOT (26,A) (12 Nov. 46) --- 13/11/46
35. MIYAKO SANGYO K.K. (NIPPON SEIRI KOGYO K.K.) (39) (13 Nov. 46) --- 14/11/46
36. KYOTO ROSAKU KIKAI K.K., JUJO KOJO (44) (9 Nov. 46) --- 15/11/46
37. Tongo Sei Ki K.K. (30) 14 Nov. 46 --- 26/11/46
38. Former Maizuru Naval Arsenal (24) (23 Jan. 47) (10 Feb. 47)
39. Osaka Military Arsenal (132) (22 April 47) (25. Apr. 47)
40. Engine Experiment Dept of Former Maizuru Navy Yard. (29) (6 May 47) (10 May 47)

41. 3d Naval Explosives Arsenal (25) (25a) (25c) (25d) (25e)
- ~~42. Uji Powder Factory (23) See 44~~
43. Shimadzu Seisakusho, Danjo Kajo (18, 18a, 18b, 18c)
44. Uji Power Factory (23)
45. ① Former Naval 31st Aeroplane Repair Dept (22-26)
 ② Former Boiler Experiment Dept., Maizuru Naval Arsenal (22-29)
 ③ Former Naval 3rd Powder Plant (22-25 + 23-25(N))
46. ① Osaka Mil Arsenal, Sonobe Factory (22-132 (S))
 ② 2nd Tokyo Mil. Arsenal, Uji Powder Plant (22-23)
 ③ Maizuru Naval Arsenal (22-24)
47. ① Uji Powder Plant (22-23)
 ② Osaka Mil Arsenal (22-132 (S))
 ③ Maizuru Naval Arsenal (22-24)
48. ① Supplementing Inventory Sheets and Plant Cover Sheets
 ② Uji Plant (22-23)
 ③ Sonobe Branch of Osaka Mil Arsenal (22-132 (S))
49. The Institute of Bearing Research 22-28.
50. ① Uji Plant of 2nd Tokyo Mil Arsenal (22-23)
 ② Sonobe Branch of Osaka Mil Arsenal (22-132 (S))
51. Jikuuke Kenkyujo (Laboratory)
52. Plant cover sheets - ① 22-132 (d)
 ② 22-132 (f)
53. Plant Cover Sheet - Jikuuke Kenkyujo

775013KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)APC 713 (Kyoto, Honshu)
(LOCATION)PREFECTURAL AND PLANT
CODE NUMBER: 22-132(d)SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.
(Supplementary - OD 5/10)

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Osaka Military Arsenal's Dispersal Area
- b.) ADDRESS: Dispersed at: Kenchiku Gakka, Kyoto University
Yoshida-machi, Sakyo-ku Kyoto-City
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO _____
4. a.) SPOT CHECK COMPLETED ON: 29 Dec 1947
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 1
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 1
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK
 - b.) SELF POWERED No
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field Man)

①

KYOTO MILITARY GOVERNMENT I
(HEADQUARTERS OR SIMILAR UNIT)

ABO 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-132(f)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : (Supplementary - OD 5/10)
CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Osaka Military Arsenal's Dispersal Area
 b.) ADDRESS: Dispersal Area: Asahi Sangyo KK, 42 Goshonouchi-machi, Mibu, Nakagyo-ku, Kyoto City
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES X NO _____
4. a.) SEOT CHECK COMPLETED ON: 29 Dec 1947
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 3
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 3
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) Kansai Aiden KK
 - b.) SELF POWERED No
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
(Field Man)

775013

KYOTO MILITARY GOVERNMENT TEAM
APO 713 (Kyoto, Honshu)

ELC/RO/ct
27 Dec 1947

SUBJECT: Plant Cover Sheet and Inventory Sheets for Laboratory

TO : Supreme Commander for the Allied Powers, APO 500
Attn: Economic & Scientific Section

1. Enclosed is one (1) copy of plant cover sheet and inventory sheets of Jikunke Kenkyujo (Laboratory) inventoried in compliance to OD 5/12.

2. Forwarded in compliance to par. 7 OD 5/3, Hq Eighth Army, dtd 24 June 1946.

FOR THE COMMANDING OFFICER:

THOMAS R. HARBIN
1st Lt, Inf
Adjutant

- 2 Incls:
- 1 Plant Cover Sht (1cc)
 - 2 Inventory Sht (39 shts)

DEC 27 1947

51

Econ Div - File
MTF
8X
see
19

775013

*DT Econ Div File
MVA
Ecc*

KYOTO MILITARY GOVERNMENT TEAM
APO 713 (Kyoto, Honshu)

ELO/JI/ct
29 Dec 1947

OO: BA

SUBJECT: Supplementary Plant Cover Sheets

TO : Commanding General, Eighth Army, APO 943
Attn: Military Government Section

THRU : Channels

In compliance with par 7, OP 5/3, Hq Eighth Army, 24 June 1946,
forwarded herewith are supplementary plant cover sheets for the following
listed plants:

Uji Plant of 2d Tokyo Mil Arsenal (22-23)

Sonobe Branch of Osaka Mil Arsenal (22-132(a))

FOR THE COMMANDING OFFICER:

THOMAS R. HARBIN
1st Lt. Inf
Adjutant

2 Incls:
As indicated

DEC 31 1947

775013

~~File Copy~~
~~From Sec~~
~~At Sec~~

KYOTO MILITARY GOVERNMENT TEAM
(Headquarters, or similar Unit)

APC 713 (Kyoto, Honshu)
(Location)

Prefectural & Plant
Code Number; 22-132(S)

Date; 15 Nov 1947.

Subject: Plant Cover Sheet and Inventory Verification Report.

TO : Chief, Reparations Branch, Industrial Division, ESS,
GHQ, Tokyo, Japan.

In compliance with instructions, the following report is hereby rendered on the plant specified below;

1. a.) Name of Plant: Osaka Mil Arsenal, Sonobe Factory.
b.) Address: Sonobe-cho, Funai-gun, Kyoto Pref.

2. Principal Products of Plant:
a.) Pre-war: None
b.) During War: None
c.) Present: None

3. Physical Condition of Plant: _____
a.) Estical percent of damage to building by air raids or fire: None
b.) Is necessary preventive maintenance of equipment being done?
Yes: X
No : _____

4. a.) Spot-check completed on: 17 Nov 1947.
b.) Total number of items inventoried and marked: 290
c.) Total Number of Inventory Sheets forwarded herewith: 290

5. General Remarks: _____

46

Signed Gerald F. Davis SA
(Field Man)

775013File Copy
ECON. Div.
M. & H. Sec.KYOTO MILITARY GOVERNMENT TEAM
Headquarters, or similar UnitAPC 713 (Kyoto, Honshu)
(Location)Prefectural & Plant
Code Number: 22 - 23Date: 5 Nov 1947.

Subject: Plant Cover Sheet and Inventory Verification Report.

To : Chief, Reparations Branch, Industrial Division, ESS.
GHQ, Tokyo, Japan.

In compliance with instructions, the following report is hereby rendered on the plant specified:

1. a.) Name of Plant: 2nd Tokyo Mil. Arsenal, Uji Powder Plant.
b.) Address: Higashi Uji-machi, Uji-gun, Kyoto Pref.
2. Principal products of plant:
 - a.) Pre-war: Explosive
 - b.) During War: Explosive
 - c.) Present: Japan Drug Manufacturing Co., Ltd. --- Drugs
3. Physical Condition of Plant: _____
 - a.) Estimate percent of damage to building by air raids or fire: None
 - b.) Is necessary preventive maintenance of equipment being done?
Yes: X
No: _____
4. a.) Spot-check completed on: 21 Nov 47
b.) Total number of items inventoried and marked: 170
c.) Total number of Inventory Sheets forwarded herewith: 170
5. General Remarks: _____

Signed Serald P. Over Sgt.
(Field Man)

H6

775013

00

KYOTO MILITARY GOVERNMENT TEAM
(Headquarters or Similar Unit)

MAIZURU DETACHMENT APO 612 MAIZURU
(Location)

PREFECTURAL AND PLANT
CODE NUMBER..... 22-24

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT:
Supplementary - OD5/10

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS,
GHQ, Tokyo, Japan.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Maizuru Naval Arsenal
b.) ADDRESS: Amarube, Maizuru City, Kyoto Pref.
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Marine Engine, & Ship Building, and manufacturing
STEEL
 - b.) WARTIME: Ditto
 - c.) PRESENT: Repair of ships, salvaging ships, scrapping ships,
and manufacturing freight cars.
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE:
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES X NO 54
4. a.) SPOT CHECK COMPLETED ON: 20 November 47
b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 986
c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HERewith: 986
5. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b) 58
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED

Miguel J. ... Pfc
(FIELD MAN)

46

775013

KYOTO MILITARY GOVERNMENT TEAM
 (Headquarters or Similar Unit)
MAIZURU DETACHMENT APO 713 (Maizuru)
 (Location)

PREFECTURE AND PLANT CODE NUMBER
22-24 Kyoto Prefecture

SUBJECT: Plant Cover Sheet and Inventory Verification Report
 TO : Chief, Reparations, Branch, Industrial Division, ESS.GHQ,
 Tokyo, Japan.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Maizuru Naval Arsenal
 b.) ADDRESS: Awarabe, Maizuru City Kyoto Prefecture
2. PRINCIPAL PRODUCTS OR PLANT:
 a.) PRE-WAR: Marine Engine & Ship Building, and manufacturing arms
 b.) WARTIME: DITTO
 c.) PRESENT: Repair of ships, salvaging ships, scrapping ships.
3. PHYSICAL CONDITION OF PLANT:
 a.) ESTIMATE PER CENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: ONE PERCENT
 b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO
4. a.) SPOT CHECK COMPLETED ON: 20 November 47
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 4,400
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 4,400
5. ELECTRIC POWER SOURCE:
 a.) PURCHASED (PUBLIC UTILITIES) All except in emergency
 b.) SELF POWERED: In emergency
 If self powered give following data. HYDRO: THERMAL: 6
 DIESEL: CAPACITY OF PLANT: KILOWATTS: 3110 KW
6. GENERAL REMARKS:
 a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b)
 b.) OTHER PERTINENT INFORMATION: This items are transferred to 22-24 from ex 22-45 only

SIGNED:

Shigeo Takamura Pfc
 (FIELD MAN)

46

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

MAIZURU DETACHMENT APO 713 (Maizuru)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-26

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT: Supplementary-OD 5/10
TO : CHIEF REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Former Naval 31st Aeroplane Repair Depot.
b.) ADDRESS: Kunda-mura, Yosa-gun, Kyoto-pref.
2. PRINCIPAL PRODUCTS OF PLANT:
a.) PRE-WAR: None
b.) WARTIME: Naval Aircraft Repairing
c.) PRESENT: Salt, Press-work, & Welding-work, Woodenworking
3. PHYSICAL CONDITION OF PLANT:
a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: 5%
b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO
4. a.) SPOT CHECK COMPLETED ON: 10 Nov. 1947
b.) TOTAL NUMBER OF ITEMS INVENTORIES AND MARKED: 27
c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 27
5. GENERAL REMARKS: _____

SIGNED _____

(Field Man)

26493
45

22521

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)MAIZURU DETACHMENT APO 713 (Maizuru)
(LOCATION)PREFECTURAL AND PLANT
CODE NUMBER : 22-29

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT: Supplementary-OD 5/10
TO : CHIEF REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Former Boiler Experiment Dept. of Maizuru Naval Arsenal
b.) ADDRESS: Amarube-shimo, Maizuru City, Kyoto Pref.
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Research & Experiment of Steam Boilers for ships.
 - b.) WARTIME: Do.
 - c.) PRESENT: Nothing
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO
4. a.) SPOT CHECK COMPLETED ON: 10 Nov. 1947
b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 12
c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 12
5. GENERAL REMARKS: _____

SIGNED _____
(Field Man)

45

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

MAIZURU DETACHMENT APO 713 (Maizuru)

PREFECTURAL AND PLANT
 CODE NUMBER: 22-25 & 22-25 (N)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT: Supplementary-OD 5/10
 TO : CHIEF REPAIRATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Former Naval 3rd Powder Plant
 b.) ADDRESS: Asaku, Maizuru City, Kyoto Pref.
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Explosives
 - b.) WARTIME: Do.
 - c.) PRESENT: Nothing
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: 1%
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES X NO
4. a.) SPOT CHECK COMPLETED ON: 10 Nov. 1947
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 101
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 101
5. GENERAL REMARKS: _____

SIGNED _____
 (Field Man)

45

775013

File copy

KYOTO MILITARY GOVERNMENT I
(HEADQUARTERS OR SIMILAR UNIT)

APQ 713 (Kyoto, Honshu)
(LOCATION)

Corrected Copy
(9 Aug 1947)

PREFECTURAL AND PLANT
CODE NUMBER: 22-23

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Uji Factory of Second Tokyo Military Arsenal
 b.) ADDRESS: Higashi-uji-machi, Uji-gun, Kyoto-fu
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Explosives and smokeless powder
 - b.) WARTIME: Explosives and smokeless powder
 - c.) PRESENT: None
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO
4. a.) SPOT CHECK COMPLETED ON: 9 Oct 1946
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 2097
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 2097
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK
 - b.) SELF POWERED No
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 134
 - b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED J. J. To
(Field Man)

44

775013

HEADQUARTERS I CORPS
APO 301 (Kyoto, Honshu)

EHN/af

AG 004 - BA

7 JUL 1947

SUBJECT: Execution of Cover Sheets

TO : Commanding Officer
Kyoto Military Government Team
APO 713

Attached information sheets from ESS/RS, SCAP, refer to inventory sheets for which no plant cover sheets have been received by the Supreme Commander for the Allied Powers or by Headquarters Eighth Army. Plant cover sheets will be executed and forwarded to the Supreme Commander for the Allied Powers and Headquarters Eighth Army in accordance with current directives. In the case of dispersed machinery, a note as to the name and location of the parent plant will be included.

BY COMMAND OF MAJOR GENERAL WOODRUFF:

3 Incls:
Info sheets for
plants:
22-18(a)
22-18(b)
22-18(c)

Rufus Cooke
RUFUS COOKE
CWO, USA
Asst. Adjutant General.

53022

HEADQUARTERS I CORPS
APO 301 (Kyoto, Honshu)

EHN/af

AG 004 - BA

: 7 JUL 1947

SUBJECT: Execution of Cover Sheets

TO : Commanding Officer
Kyoto Military Government Team
APO 713

Attached information sheets from ESS/RS, SCAP, refer to inventory sheets for which no plant cover sheets have been received by the Supreme Commander for the Allied Powers or by Headquarters Eighth Army. Plant cover sheets will be executed and forwarded to the Supreme Commander for the Allied Powers and Headquarters Eighth Army in accordance with current directives. In the case of dispersed machinery, a note as to the name and location of the parent plant will be included.

BY COMMAND OF MAJOR GENERAL WOODRUFF:

3 Incls:
Info sheets for
plants:
22-18(a)
22-18(b)
22-18(c)

R A F E COOKE
CWO, USA
Asst. Adjutant General

775013**KYOTO MILITARY GOVERNMENT TEAM**
(HEADQUARTERS OR SIMILAR UNIT)**AFO 713 (Kyoto, Honshu)**
(LOCATION)PREFECTURAL AND PLANT
CODE NUMBER: 22-18

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Shimazu Seisakusho, KK, Sanjo Koje
- b.) ADDRESS: 18 Kawabara-cho, Nishinokyo, Nakagyo-ku, Kyoto-shi, Kyoto-fu
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Precision & Optical Measuring Instruments, X-Ray Apparatus, Reduction Gears, Spinning Nozzles & Pumps for Rayon
 - b.) WARTIME: Precision & Optical Measuring Instruments, Components for Aircraft Gun-sights
 - c.) PRESENT: X-Ray Apparatus, Reduction Gears, Precision & Optical Measuring Instruments
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO
4. a.) SPOT CHECK COMPLETED ON: 30 Sept 1946
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 1314
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 1314
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK
 - b.) SELF POWERED No
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 37
 - b.) OTHER PERTINENT INFORMATION: See reverse side

SIGNED _____

(Field Men)

In view of the fact that the eastern section of the plant has been exempted from reparations claim (reference: 9th Ind from GHQ, SCAP, AG 095 (10 July 46) ESS/IN, dtd 22 Oct 46, letter, Kyoto Mil Govt Team, AG 004, subject: Release of Shimazu Ind, Ltd, Sanjo Plant from Reparational list, dtd 10 July 1946) after the inventory is completed, machines 1 through 751 and 2047 through 2053 located in the eastern section have been deleted.

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APG 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-18(A)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: (Dispersal area) Shinazu Seisakusho, Shijo Kojo
- b.) ADDRESS: 3 Hanai-cho, Mibu, Nakagyo-ku, Kyoto-shi, Kyoto-fu
2. ~~PHYSICAL PRODUCTS OF PLANT:~~
 - a.) ~~NAME AND LOCATION OF PARENT PLANT:~~
 - b.) ~~NAME:~~ Shinazu Seisakusho, Sanjo Kojo (22-18)
 - c.) ~~ADDRESS:~~ 18 Kuwabara-cho, Nishinokyo, Nakagyo-ku, Kyoto-shi, Kyoto-fu
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO
4. a.) SPOT CHECK COMPLETED ON: 30 Sept 1946
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 211
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 211
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK
 - b.) SELF POWERED No
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field Men)

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APC 713 (Kyoto, Honshu)

(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-18(B)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: (Dispersal area) Shimazu Seisakusho, Gojo Kojo
- b.) ADDRESS: 11 Umazuka-cho, Sain, Ukyo-ku, Kyoto-shi, Kyoto-fu

2. ~~PRINCIPAL PRODUCTS OF PLANT:~~

~~Parent Plant:~~ Name and Location of Parent Plant: _____

~~Parent Plant:~~ Shimazu Seisakusho, Sanjo Kojo (22-18)

~~Parent Plant:~~ 18 Kuwabara-cho, Mishinokyo, Nakagyo-ku, Kyoto-shi, Kyoto-fu

3. PHYSICAL CONDITION OF PLANT:

- a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
- b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO _____

4. a.) SPOT CHECK COMPLETED ON: 30 Sept 1946

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 28

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 28

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK

b.) SELF POWERED No
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None

b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
(Field man)

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APC 713 (Kyoto, Honshu)

(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-18(c)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: (Dispersal area) Shimazu Seisakusho, Murasakino Kojo
b.) ADDRESS: 1 Nishigeshoda-cho, Murasakino, Hamigyo-ku, Kyoto-shi, Kyoto-fu

2. PRINCIPAL PRODUCTS OF PLANT:

~~XXXXXXXXXX~~ Name and Location of Parent Plant:

~~XXXXXXXXXX~~ Shimazu Seisakusho, Sanjo Kojo (22-18)

~~XXXXXXXXXX~~ 18 Kuwabara-cho, Nishinokyo, Nakagyo-ku, Kyoto-shi, Kyoto-fu

3. PHYSICAL CONDITION OF PLANT:

a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None

b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO

4. a.) SPOT CHECK COMPLETED ON: 30 Sept 1946

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 47

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HERewith: 47

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) Kansai Haiden KK

b.) SELF POWERED No
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILLOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None

b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field Man)

Plant Cover Sheet

BASIC: Ltr, Kyoto Mil Govt Team, subj: "Plant Cover Sheet", dtd 10 May 47.

AG 004 (Rep) - BA

1st Ind

EM/EM

Hq 1 Corps, APO 301, 15 MAY 1947.

TO: CO, Kyoto Mil Govt Team, APO 713

1. The Engine Experiment Department of the Maizuru Navy Yard is designated as a technical laboratory. Information is requested as to whether the 197 items have been inventoried and marked in compliance with section V, Operational Directive No. 5/5, Headquarters Eighth Army, dated 24 September 1946.

2. It is requested that the signature of the field man be obtained prior to submitting the inclosed plant cover sheets to higher headquarters.

BY COMMAND OF MAJOR GENERAL WOODRUFF:

M. S. TAYLOR
M. CR, A.S.D.
ASST. ADJ. GEN.

1 Incl:
n/c

775013

Rx 9
file copy

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APQ 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-25

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: UJI POWDER FACTORY
 b.) ADDRESS: Mitsashi-Uji-Machi, Uji-gun, Kyoto-fu
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Explosives and smokeless powder
 - b.) WARTIME: Explosives and smokeless powder
 - c.) PRESENT: None
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO _____
4. a.) SPOT CHECK COMPLETED ON: 9 Oct 1946
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 2054
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 2054
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) from Kansai Eaiden KK
 - b.) SELF POWERED None
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 134
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
(Field Man)

Should be deleted (g.s.)
see (44)

(42)

775013

BASIC: Ltr, Kyoto Mil Govt Team, subj: "Corrected Plant Cover Sheets",
dtd 23 May 47.

AG 004(Rep) - BA

1st Ind

EHN/mmn

Hq I Corps, APO 301, 29 May 1947

TO: CG, Eighth Army, APO 343

Corrected plant cover sheets for the Third Naval Explosives Arsenal (22-25) and its dispersed areas, are forwarded herewith for your information. It is requested that the previously submitted plant cover sheets be withdrawn and replaced by the attached copies.

FOR THE COMMANDING GENERAL:

/s/ O.H. Schmidt
/t/ O.H. SCHMIDT
Major, AGD
Asst Adj Gen

6 Incls:
1 copy each w/d

AG 004 (MG-Em)

2 Ind

Headquarters Eighth Army, APO 343

7 June 1947

TO: Commanding General, I Corps, APO 301

Corrected plant cover sheets will be executed and forwarded in accordance with current directives, showing the name and location of each dispersal area of the Third Naval Explosives Arsenal.

BY COMMAND OF LIEUTENANT GENERAL EICHELBERGER:

/s/ R. Schafer
/t/ R. SCHAFER
Lt. Col., Col
Asst Adj Gen.

6 Incls:
1 - w/d
2 - n/c
3 - "
4 - "
5 - "
6 - "

775013

BASIC: Ltr, Kyoto Mil Govt Team, 004 - BA, subj: "Corrected Plant Cover Sheets", dtd 23 May 47.

AG 004 - BA

3rd Ind

AH/yo

Hq I Corps, APO 301, 11 JUN 1947

TO: CO, Kyoto Mil Govt Team, APO 713

Transmitted for compliance with 2nd indorsement.

BY COMMAND OF MAJOR GENERAL WOODRUFF:

6 Incls:
n/c

O. H. SCHMIDT
MAJOR AGD
ASST. ADJ. GEN.

775013

File Copy

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APO 718

KYOTO

(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22 - 25

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: THIRD NAVAL EXPLOSIVES ARSENAL
- b.) ADDRESS: Misuru, Kyoto prefecture
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Explosives
 - b.) WARTIME: Explosives
 - c.) PRESENT: None
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO
4. a.) SPOT CHECK COMPLETED ON: 11 Oct 1946
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MAPKED: 854
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 854
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) All except in emergency
 - b.) SELF POWERED In emergency
If self powered give following data. HYDRO: 00 THERMAL: 00 DIESEL:
CAPACITY OF PLANT: 00 KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 20
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED [Signature]

(Field Men)

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APU 713 KYOTO

(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-25(A)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: THIRD NAVAL EXPLOSIVES ARSENAL
- b.) ADDRESS: Dispersed in Toyama prefecture (See reverse side for details)
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES _____ NO _____
4. a.) SPOT CHECK COMPLETED ON: _____
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MAPKED: 41
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 41
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) _____
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
(Field men)

Machines 1 through 30 are dispersed at:

Hokuriku Haiden, Toyama Branch
Toyama City, Toyama Prefecture

Machines 31 through 40 are dispersed at:

Toa Gosei, Fushiki Factory
Fushiki, Takaoka City, Toyama Prefecture

Machine 41 is dispersed at:

Daiken Mokuzai KK, Iba Factory
Iba-cho, Toyama Prefecture

775013

KYOTO MILITARY GOVERNMENT TEAM
 (HEADQUARTERS OR SIMILAR UNIT)

APO 713

KYOTO

(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22-25(B)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: THIRD NAVAL EXPLOSIVES ARSENAL
- b.) ADDRESS: Dispersed in Ishikawa prefecture (See reverse side for details)
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES _____ NO _____
4. a.) SPOT CHECK COMPLETED ON: _____
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MAPKED: 46
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 46
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) _____
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field Man)

Machine 1 is dispersed at:

Komatsu Seisakusho, Awazu Factory
Awazu-cho, Ishikawa Prefecture

Machines 2 through 46 are dispersed at:

Hokuriku Haiden, Daishoji Branch
Daishoji-cho, Ishikawa Prefecture

775013

KYOTO MILITARY GOVERNMENT TEAM
 (HEADQUARTERS OR SIMILAR UNIT)

APO 713

KYOTO

(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22-25(C)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: THIRD NAVAL EXPLOSIVES ARSENAL
- b.) ADDRESS: Dispersed in Fukui prefecture (See reverse side for details)
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES _____ NO _____
4. a.) SPOT CHECK COMPLETED ON: _____
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 20
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 20
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) _____
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field No.)

Should be deleted (2,9)

Machines 1 and 20 are dispersed at:

Daitetsu Kogyo Seisakusho
Akebono, Ono-cho, Ono-gun, Fukui Prefecture

Machine 2 is dispersed at:

Shikano Saw Mill
Saburi-mura, Ooi-gun, Fukui Prefecture

Machine 3 is dispersed at:

Kamakura Agricultural Association
Uchiura-mura, Ooi-gun, Fukui Prefecture

Machines 4 and 5 are dispersed at:

Village Office of Saburi-mura
Ooi-gun, Fukui Prefecture

Machines 6, 9, 12 through 18 are dispersed at:

Uchiura Agricultural Association (Yamanaka)
Uchiura-mura, Ooi-gun, Fukui Prefecture

Machine 7 is dispersed at:

Uchiura Agricultural Association (Kanno)
Uchiura-mura, Ooi-gun, Fukui Prefecture

Machine 8 is dispersed at:

Uchiura Agricultural Association (Uchiura)
Uchiura-mura, Ooi-gun, Fukui Prefecture

Machines 10 and 11 are dispersed at:

Village Office of Saburi-mura
Ooi-gun, Fukui Prefecture

Machine 19 is dispersed at:

Uchiura Agricultural Association (Nambae)
Uchiura-mura, Ooi-gun, Fukui Prefecture

775013

KYOTO MILITARY GOVERNMENT TEAM
 (HEADQUARTERS OR SIMILAR UNIT)

APO 713

KYOTO

(LOCATION)

PREFECTURAL AND PLANT
 CODE NUMBER: 22-25(D)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: THIRD NAVAL EXPLOSIVES ASSEMBLY
 Dispersed at Saji Agricultural Association (Saji-cho Nokai)
 b.) ADDRESS: Saji-cho, Hyogo Prefecture

2. PRINCIPAL PRODUCTS OF PLANT:

- a.) PRE-WAR: _____
- b.) WARTIME: _____
- c.) PRESENT: _____

3. PHYSICAL CONDITION OF PLANT:

- a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
- b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES _____ NO _____

4. a.) SPOT CHECK COMPLETED ON: _____

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 6

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 6

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) _____

b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) _____

b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
 (Field Men)

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APQ 715 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: **22-25(3)**

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: ~~THIRD NAVAL EXPLOSIVES ARSENAL~~
- b.) ADDRESS: ~~dispersed in Osaka prefecture (See reverse side for details)~~
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: _____
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES _____ NO _____
4. a.) SPOT CHECK COMPLETED ON: _____
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 3
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 3
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) _____
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____

(Field Men)

File

Kyoto Military Government Team (Maizuru)
(HEADQUARTERS OR SIMILAR UNIT)

Maizuru Detachment APO 713 (Maizuru)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-29

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Engine Experiment Dept of Former Maizuru Navy Yard.
b.) ADDRESS: Amarube, Maizuru City, Kyoto Prefecture

2. PRINCIPAL PRODUCTS OF PLANT:

- a.) PRE-WAR: Experiments and Research of Boilers of war-ships
b.) WARTIME: Do
c.) PRESENT: (Idle State)

3. PHYSICAL CONDITION OF PLANT:

- a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES X NO _____

4. a.) SPOT CHECK COMPLETED ON: 6 May 1947

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 197

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 197

5. ELECTRIC POWER SOURCE:

- a.) PURCHASED (PUBLIC UTILITIES) All
b.) SELF POWERED None
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None

b.) OTHER PERTINENT INFORMATION: _____

SIGNED _____
(Field Men)

775013

CORRECTED
COPY

KYOTO MILITARY GOVERNMENT TEAM

(HEADQUARTERS OR SIMILAR UNIT)

APD 713 (Kyoto, Honchu)

(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-132 (A)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL
 b.) ADDRESS: Dispersed at -- Shinomi Seisakusho, Kawabara-cho, Nishinokyo, Nakagyo-ku, Kyoto City

2. PRINCIPAL PRODUCTS OF PLANT:

- a.) PRE-WAR: _____
 b.) WARTIME: _____
 c.) PRESENT: _____

3. PHYSICAL CONDITION OF PLANT:

- a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES X NO _____

4. a.) SPOT CHECK COMPLETED ON: 23 April 1947

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 14

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 14

5. ELECTRIC POWER SOURCE:

- a.) PURCHASED (PUBLIC UTILITIES) _____
 b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

- a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 b.) OTHER PERTINENT INFORMATION: See reverse side

SIGNED J. J.
(Field Man)

Parentetical plant designation, (A), was furnished to OSMA MILITARY ARSENAL's machinery dispersed at Shimizu Seisakusho, Kusabara-cho, Minami-ku, Wakayama-ken, Kyoto City, Kyoto Prefecture.

CORRECTED
COPY

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

AFD #13 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22-102 (B)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL

b.) ADDRESS: Dispersed at -- Kashifaji Jukkocho, Kamitoba, Shinogyo-ku, Kyoto City, Kyoto Prefecture.

2. PRINCIPAL PRODUCTS OF PLANT:

a.) PRE-WAR: _____

b.) WARTIME: _____

c.) PRESENT: _____

3. PHYSICAL CONDITION OF PLANT:

a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None

b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES x NO _____

4. a.) SPOT CHECK COMPLETED ON: 17 April 1947

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 5

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HERewith: 5

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) _____

b.) SELF POWERED _____
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None

b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED [Signature]
(Field Man)

Parentetical plant designation, (D), was furnished to OSAKA MILITARY
ARSENAL's machinery dispersed at Kashifuji Tekkojo, Kamitoba, Shinogyo-ku,
Kyoto City, Kyoto Prefecture.

775013

CORRECTED
COPY

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APC 713 (Kyoto, Honshu)

(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: **22-132(0)**

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL
- b.) ADDRESS: Dispersed at -- Dai Nippon Zoki K.K., Ishibashi-cho, Umekoji, Shimogyo-ku, Kyoto City.
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAIN OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES x NO _____
4. a.) SPOT CHECK COMPLETED ON: 14 April 1947
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 5
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 5
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data, HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: See reverse side

SIGNED _____

(field man)

CORRECTED COPY

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

AFQ 713 (Kyoto, Honchu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: **22-133 (D)**

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: **OSAKA MILITARY ARSENAL**

b.) ADDRESS: **Dispersed at -- Kyoto Imperial University, Yoshida-nishi, Sakyo-ku, Kyoto City**

2. PRINCIPAL PRODUCTS OF PLANT:

a.) PRE-WAR: _____

b.) WARTIME: _____

c.) PRESENT: _____

3. PHYSICAL CONDITION OF PLANT:

a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: **None**

b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES **2** NO _____

4. a.) SPOT CHECK COMPLETED ON: **22 April 1947**

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: **2**

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: **2**

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) _____

b.) SELF POWERED _____
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) **None**

b.) OTHER PERTINENT INFORMATION: **See reverse side.**

SIGNED *[Signature]*
(Field Man)

775013

CORRECTED
COPY**KYOTO MILITARY GOVERNMENT TEAM**
(HEADQUARTERS OR SIMILAR UNIT)APD 713 (Kyoto, Honshu)

(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22-132 (B)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL
- b.) ADDRESS: Dispersed at -- Morita Seigokubo, Higashihana-machi, Fushimi-ku, Kyoto City
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES 2 NO _____
4. a.) SPOT CHECK COMPLETED ON: 17 April 1947
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 35
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 35
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 6
 - b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED _____

(Field Men)

Parentetical plant designation, (Z), was furnished to OSAKA MILITARY ARSENAL's machinery dispersed at Morita Seisakusho, Higashihara-machi, Fushimi-ku, Kyoto City, Kyoto Prefecture.

775013

CORRECTED
COPY**KYOTO MILITARY GOVERNMENT TEAM**
(HEADQUARTERS OR SIMILAR UNIT)**AFPO 713 (Kyoto, Honma)**
(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: ~~22-132(F)~~ 22-132(F)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL
- b.) ADDRESS: Dispersed at -- Asahi Sangyo K.K., 42 Goshonouchi-machi, Mibu, Nakagyo-ku, Kyoto City
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES X NO _____
4. a.) SPOT CHECK COMPLETED ON: 14 April 1947
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 2
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 2
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED

[Signature]
(Field Man)

775013

Parentesimal plant designation, (F), was furnished to OSAWA MILITARY
ARSENAL'S machinery dispersed at Awhi, Sangyo T.K., 43 Gomonouchi-machi
Min, Nakagyo-ku, Kyoto City, Kyoto Prefecture.

775013

CORRECTED
COPY

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

AP0 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-132(P)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: OSAKA MILITARY ARSENAL
- b.) ADDRESS: Dispersed at -- Umezu Seikosho, Umezu, Ukyo-ku, Kyoto City, Kyoto Prefecture.
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: _____
 - b.) WARTIME: _____
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO _____
4. a.) SPOT CHECK COMPLETED ON: 22 April 1947
- b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MAPKED: 8
- c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 8
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) _____
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED [Signature]
(Field Men)

Parentetical plant designation, (P), was furnished to OSAKA
MILITARY ARSENAL's machinery dispersed to Umezu Seikoshu,
Umezu, Ukyo-ku, Kyoto City, Kyoto Prefecture.

775013KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)APQ 713 (Kyoto, Honshu)
(LOCATION)PREFECTURAL AND PLANT
CODE NUMBER: 22-24

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: Former Maizuru Naval Arsenal
b.) ADDRESS: Amarube, Maizuru City, Kyoto Prefecture
2. PRINCIPAL PRODUCTS OF PLANT:
a.) PRE-WAR: Mine, parts of Machine-gun, parts of torpedoe & electric instruments.
b.) WARTIME: Same as above.
c.) PRESENT: Repairing of fright cars.
3. PHYSICAL CONDITION OF PLANT:
a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: 5% (fire)
b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES X NO _____
4. a.) SPOT CHECK COMPLETED ON: 23 Jan. 1947
b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 3,318
c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 3,318
5. ELECTRIC POWER SOURCE:
a.) PURCHASED (PUBLIC UTILITIES) 2,200 KW all
b.) SELF POWERED None
If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
b.) OTHER PERTINENT INFORMATION: _____
- SIGNED _____
(Field Man)

This dispersed machinery of this plant (22-24) has parenthetical code numbers as follows:

22-24 (A)	-1.....	125	Osaka Prefecture
22-24 (B)	-1.....	40	Hyogo "
22-24 (C)	-1.....	33	Tottori "
22-24 (D)	-1.....	21	Nara "
22-24 (E)	-1.....	24	Ishikawa "
22-24 (F)	-1.....	5	Shiga "
22-24 (G)	-1		Mie "
22-24 (H)	-1		Shimane "

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APC 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-48(K)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: KAWASAKI AIRCRAFT COMPANY, Takatsuki Plant
 b.) ADDRESS: Takatsuki, Osaka Prefecture
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: This information is not known at this Hq, since only the
 - b.) WARTIME: dispersed machines are involved in this inventory.
 - c.) PRESENT: _____
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: See 2.
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES x NO _____
4. a.) SPOT CHECK COMPLETED ON: 3 Dec. 1946
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MAPKED: 2
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 2
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) See 2.
 - b.) SELF POWERED _____
 If self powered give following data. HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: See reverse side.

SIGNED

[Signature]
(Field Man)

Parentetical letter (K) was furnished by this Hq to the dispersal area of these machines located at FOKUSEI KIKAI SEISARUSHO, Shijo-Omiya Nishi-iru, Nakagyo-ku, Kyoto City, in compliance with letter, Hq I Corps, dated 18 Oct. 1946, Subject: "Inventory of Dispersed Reparations Machines and Equipment", paragraph 3.

775013

files

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

NOV 22 1946

AMINO-CHO, KYOTO-FU
(LOCATION)

PREFECTURAL AND PLANT

CODE NUMBER: 22-30 (1-119)

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: TANGO SEIKI K.K.
 b.) ADDRESS: 256 Amino-cho Takano Gun, Kyoto-Fu
2. PRINCIPAL PRODUCTS OF PLANT:
 - a.) PRE-WAR: Silk Processing Plant
 - b.) WARTIME: Airoplane parts
 - c.) PRESENT: Foot lockers for Occupation Forces, farm tools and house utensils
3. PHYSICAL CONDITION OF PLANT:
 - a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: 0
 - b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
 YES NO
4. a.) SPOT CHECK COMPLETED ON: 14 November 1946
 b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 119 Incl EX
 c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 119 Incl EX
5. ELECTRIC POWER SOURCE:
 - a.) PURCHASED (PUBLIC UTILITIES) 130 KVA-3,300 V (Public Utilities)
 - b.) SELF POWERED _____
 If self powered give following data, HYDRO: _____ THERMAL: _____ DIESEL: _____
 CAPACITY OF PLANT: _____ KILOWATTS
6. GENERAL REMARKS:
 - a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None
 - b.) OTHER PERTINENT INFORMATION: _____

SIGNED Jack J. Strollo
(field man)
1st Lt Col
M.G.T.

775013

KYOTO MILITARY GOVERNMENT TEAM
APO 713 (Kyoto, Honshu)

18 Nov. 1946

SUBJECT: Plant Cover Sheet

TO : Commanding General, Hq I Corps, APO 301 (Kyoto, Honshu)
Attn: Mil Govt Section, Res & Ind Officer

1. Transmitted herewith are two copies of Kyoto Kosaku Kikai K.K.'s plant cover sheet.
2. Forwarded in compliance with par 5d, 01-1/1, Hq I Corps, dtd 17 June 1946.

FOR THE COMMANDING OFFICER,

ENOS L. COMMONS JR
Capt., Ord.
Res & Ind Officer

775013

KYOTO MILITARY GOVERNMENT TEAM
(HEADQUARTERS OR SIMILAR UNIT)

APC 713 (Kyoto, Honshu)
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-44

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

- 1. a.) NAME OF PLANT: KYOTO KOSAKU KIKAI K.A., Jujo Kojo
- b.) ADDRESS: #103 Ochiai-cho, Kisshoin, Shimokyo-ku, Kyoto City

2. PRINCIPAL PRODUCTS OF PLANT:

- a.) PRE-WAR: Machine tools.
- b.) WARTIME: Machine tools, airplane engine parts.
- c.) PRESENT: Japanese typewriter parts, type-casting machines, street-car parts.

3. PHYSICAL CONDITION OF PLANT:

- a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: None
- b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES X NO

4. a.) SPOT CHECK COMPLETED ON: 9 November 1946

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 187

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 187

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) from KANSAI HAIDEN K.K.

b.) SELF POWERED No
If self powered give following data. HYDRO: THERMAL: DIESEL:
CAPACITY OF PLANT: KILOWATTS

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) 8

b.) OTHER PERTINENT INFORMATION:

SIGNED J. J. to
(Field Man)

*Should be deleted
g.d.*

f. i. e

775013

~~KYOTO MILITARY COVERED TEAM~~
(HEADQUARTERS OR SIMILAR UNIT)

~~MAISURU DEPARTMENT APO 713 (Maizuru)~~
(LOCATION)

PREFECTURAL AND PLANT
CODE NUMBER: 22-24

SUBJECT: PLANT COVER SHEET AND INVENTORY VERIFICATION REPORT.

TO : CHIEF, REPARATIONS BRANCH, INDUSTRIAL DIVISION, ESS, GHQ, TOKYO, JAPAN.

In compliance with instructions, the following report is hereby rendered on the plant specified below:

1. a.) NAME OF PLANT: MAISURU DOCK YARD SANGYO KAISHA LTD.

b.) ADDRESS: Repar Navy Yard Ananba, Maizuru City, Kyoto-shu

2. PRINCIPAL PRODUCTS OF PLANT:

a.) PRE-WAR: Destroyers, Coast Defense ships, war implements engines and its parts.

b.) WARTIME: (SAME AS ABOVE)

c.) PRESENT: Repairs, salvaging & scrapping of ships, construction and repair of freighters, making minesweeping equipment and operation of saw mills.

3. PHYSICAL CONDITION OF PLANT:

a.) ESTIMATE PERCENT OF DAMAGE TO BUILDING BY AIR RAID OR FIRE: 5%

b.) IS NECESSARY PREVENTIVE MAINTENANCE OF EQUIPMENT BEING DONE?
YES NO

4. a.) SPOT CHECK COMPLETED BY: 1 August 1946

b.) TOTAL NUMBER OF ITEMS INVENTORIED AND MARKED: 7030

c.) TOTAL NUMBER OF INVENTORY SHEETS FORWARDED HEREWITH: 7030

5. ELECTRIC POWER SOURCE:

a.) PURCHASED (PUBLIC UTILITIES) 2,100 K.W.

b.) SELF POWERED not in use
If self powered give following data, HYDRO: THERMAL: DIESEL:
CAPACITY OF PLANT: 2,000 KILOWATTS A.C.

6. GENERAL REMARKS:

a.) TOTAL NUMBER OF SALVAGE MACHINES (Not included in 4b.) None

b.) OTHER PERTINENT INFORMATION:

SIGNED [Signature]
(Field Men)

file

Plant cover sheet

GENERAL HEADQUARTERS
SUPREME COMMANDER FOR THE ALLIED POWERS

AFD 500
17 September 1946

AG 004 (17 Sep 46) ESS/IN
(SC/FIN - 1211)

MEMORANDUM FOR: THE IMPERIAL JAPANESE GOVERNMENT

THROUGH : Central Liaison Office, Tokyo

SUBJECT : Revised Listing of Aircraft Factories, Military and
Naval Arsenals and Research Laboratories

1. Reference is made to Memorandum for the Imperial Japanese Government, dated 28 May 1946 (SCAFIN - 987), subject: "Custody, Control and Protective Maintenance of Japanese Aircraft Plants, Arsenals and Laboratories," with inclosure, "List of Aircraft Factories, Army and Navy Arsenals, and Laboratories."

2. Attached as Annexes X and XI are revisions to the list of Aircraft Factories, Army and Navy Arsenals and Laboratories referred to in paragraph 1, above. All plants on Annex X are removed from the list. Plants appearing on Annex XI are added to above mentioned list.

3. Within seventy-two (72) hours of the receipt of this memorandum, the Japanese Government will have qualified representatives report to the Commanding General, Eighth United States Army, and to the Commander Naval Activities, Japan, to receive instructions with regard to establishment of or releasing from custody and control, installations affected by revisions of the lists referred to in paragraph 1, above.

FOR THE SUPREME COMMANDER:

2 Incls:

1. Annex X - Installations removed from list of Aircraft Factories, Army and Navy Arsenals and Laboratories.
2. Annex XI - Installations added to list of Aircraft Factories, etc.

John B. Cooley
JOHN B. COOLEY,
Colonel, AGD,
Adjutant General.

ANNEX X. INSTALLATIONS DELETED FROM REVISED LIST NO.
I. DATED 1 JUNE 1946, "AIRCRAFT FACTORIES MILITARY
AND NAVAL ARSENALS AND RESEARCH LABORATORIES".

<u>NAME</u>	<u>ADDRESS</u>	<u>PAGE</u>
Hitachi Kokuki K.K. Chiba (Concealed)	#6, (1) Aradate Miyazaki Minton	1
Maruyaso Kikai Kogyo K.K. Okaya	Okaya-shi	7
Chichibu Products Co.	#175 Oaza Mino-machi, Chichibu-gun	9
Katakura Kogyo Co.	#110 Omiya-shi	9
NAKAJIMA HIROKI K.K. (Fuji Industrial Co. Ltd) Yoshimatso	Omiya-shi	10
Tanaka Roku Keiki K.K. Omiyo	Yono-machi	10
Toyooka Bussan K.K.	Toyooki-machi	11
NAKAJIMA HIROKI K.K. (Fuji Industrial Co. Ltd) Sano	Sano-shi	12
AKEBONO HEIKI KOGYO K.K. (Akebono Sekimen Kogyo K.K.) Itabashi Kojo	126, 2-Chome, Itabashi-ku	13
Koa Jukogyo K.K. Konsha	#876 Shimura Maino-cho Itabashi-ku	14
Miyata Seisakusho K.K. Konsha	Kamata-ku	15
Riken Kogyo K.K. Arakawa Seisakusho	#7000 6-chome, Motoki-cho Adachi-ku	16
Shingawa Seisakusho K.K. Tokyo	#5-chome, Kita Shinagawa, Shinagawa-ku	16
NAKAJIMA HIROKI K.K. (Fuji Industrial Co. Ltd) Enzan (Branch)	Enzan-machi, Higashi, Yamanashi-gun	18

<u>NAME</u>	<u>ADDRESS</u>	<u>PAGE</u>
Mitsubichi Denki K.K. Koriyama	#1 Sakaibashi-machi, Koriya-shi	21
AICHI KOKUKI K.K. (Aichi Kokuki Kogyo K.K.) Seto Kojo	Togen-cho, Sato-shi	26
NIHON GAKKI SEIZO K.K.		
Honsha Kojo	#250 Nakazawa-cho, Hamamatsu-shi	36
Tenryu Kojo	#283 Aoya, Iida-mura, Hamana-gun	36
Kawanishi Kokuki Seisakusho Kashio (Concealed)	Kashia, Kyogen, Muko-gun	39
Oji Seiki Kogyo K.K. Kobe	#152 Onashi-machi Hayo, Shidoke, Kobe-shi	41
Nihon Nainanki K.K. Amagasaki	Souke 2, Shioe, Amagasaki-shi	41
Tokushu Koku Heiki K.K. Amagasaki	Amagasaki-shi	42
Kanegafushi Kogyo K.K. Kyoto	#1-Higashi Seki-machi, Koya, Kyoto-shi	43
MATSUSHITA KOKU KOGYO K.K. (Matsushita Denko K.K.) Kadoma	#1006 Kadomachie, Kitakawachi-gun, Osaka-shi	45
Teikoku Piston Ring K.K. Osaka	Osaka-shi	47
SANEI SEIKI SEISAKUSHO K.K. (Sanei Precise Industrial Mfg. Co.) Otaru Kojo	#8 Wakatake-cho, Otaru-shi	61
Aeronautical Technological Assn. of Japan	Yodobashi-ku, Nishinokubo-machi, 1-chome #389	LAB.II

ANNEX XI. INSTALLATIONS ADDED TO REVISED LIST NO. I,
1 JUNE 1946, "AIRCRAFT FACTORIES, MILITARY AND
NAVAL ARSENALS AND RESEARCH LABORATORIES".

<u>NAME</u>	<u>ADDRESS</u>	<u>PAGE</u>
FUSO KINZOKU KOGYO K.K. (Sumitomo Metal Industrial Co. Ltd) Toyama Kojo	50 Mori, Toyama City	37
Uozo Kojo	Uozu-Mura	37
NIHON KOKUSAI KOKU GOGYO K.K. (Nippon Kokusai Aircraft Co.) Mikun Kojo	Mikuni	38
Kurashiki Hikoki Sakaida Seisekisho	3800 Sakaide-cho, Sakaide-cho	60
Aeronautical Research Institute of Imperial University	Komaba-cho, Meguro-ku, Tokyo	IAB II

Inclosure 2 to SCAPIN 1211