

CROSS SECTION INDEX MAP




Fig. 6.—Pre-Pennsylvanian structural cross section showing maximum displacement of east-bounding fault. Strata absent from upthrown west side are preserved in normal thickness on downthrown side. Note position of common oil-water contact at -5,400 ft. Location of section shown in Figure 7.