

Bomb Damage

Barracks + Warehouse ^(Aichi Hangars) - slightly damaged
No s/dge. completely destroyed
Bldg. hit about 40% destroyed
4-5 Hqs. hit principally beyond

F/A

- ① Bmt storage
- ② Fuel storage
- ③ Provision storage
- ④ Wood hangars (small)
- ⑤ Taxiway
- ⑥ Concrete hangars (small)
- ⑦ Fighter Director Bldg
- ⑧ Probable control tower
- ⑨ Administration offices
- ⑩ Offices Qts.
- ⑪ Half-undergr. Barracks (new)
- ⑫ Undergr. barracks
- ⑬ Air raid shelter
- ⑭ Water s/dge for fire
- ⑮ m/bn
- ⑯ Transmitting office (V/C) - radio
- ⑰ Generator bldg. - not finished
- ⑱ Warehouse for const. materials
- ⑲ Dispersed revetments

Importance

Especially important for attack on
U.S. carrier task forces

PIC-5-REPORT # 21

ENCLOSURES

- ① ANNOTATED VERTICALS
- ② Jap. FA of Bldgs.
- ③ Jap. Map of Defences
- ④ Jap. map of DISPERSAL

NAGOYA EAST A/F

① FUNCTION: Carrier Bombers (VB) used field
NAVY Suisel - Judy (combat use)
 - overseas flights)
 Some Navy transports
Aichi Planes assembled here (POST-ASSEMBLY)

At end of war 127 planes (25 damaged)
 turned over to U.S.
 + 43 fuselages

Aichi Type 'Suisel' (37) ^{at end of war} brought from 1729

No. of planes NAVY 100 - 50% operational
average Aichi

② Surfacing:

Gravel + dirt runways
 Relatively well drained - generally usable
~~after rains~~, except after heavy rains
 Concrete parking areas

③ Dispersal:

Dispersed ^{for 10 km.} along ~~road~~ ^{highway} to S.E. toward
 Koromo.

Structure:

④ AA - See Photos

⑤ Radar Saku Gate

